

QUESTA TAILINGS PIPELINE REMOVAL STAGE 6 WORK PLAN CHEVRON ENVIRONMENTAL MANAGEMENT COMPANY QUESTA MINE

February 22, 2019

Project #: 476-027-002

SUBMITTED BY: Trihydro Corporation

707 West 1st Street, Casper, WY 82601

ENGINEERING SOLUTIONS. ADVANCING BUSINESS.

Table of Contents

1.0	INTRODUCTION	1-1
2.0	AGENCY PERMITS AND NOTIFICATIONS	2-1
3.0	STAGE 6 AREAS	3-1
4.0	REMOVAL ACTIVITIES	
	4.2 2 nd River Crossing (Thunder Bridge)	
	4.3 3 rd River Crossing (USFS Bridge)	
	4.4 Rael Property	4-3
5.0	RECLAMATION	5-1
6.0	STAKEHOLDER ENGAGEMENT	6-1
7.0	SCHEDULE	7-1
8.0	HEALTH AND SAFETY	8-1
9.0	CONTRACTORS KEY PERSONNEL	9-1
10 0	REFERENCES	10-1

List of Tables

TABLE 1-1. PIPELINE SEGMENT AND STAGE IDENTIFICATION	1-2
TABLE 3-1. AREAS INCLUDED IN STAGE 6 PIPELINE REMOVAL PLAN	3-1
TABLE 4-1. PERTINENT LEAD AND ASBESTOS ANALYTICAL RESULTS	4-1
TABLE 4-2. QUANTITIES OF DEMOLITION MATERIALS	4-4
TABLE 5-1. SEED MIXTURE	5-1
TABLE 7-1. STAGE 6 PIPELINE REMOVAL SCHEDULE	7-1

List of Figures

- 2-1. Red River Temporary Diversion, Thunder Bridge
- 2-2. Red River Temporary Diversion Dam Cross Section
- 3-1. Stage 6 Pipeline Removal Locations
- 3-2. First River Crossing (AKA Columbine Bridge)
- 3-3. Second River Crossing (AKA Thunder Bridge)
- 3-4. Third River Crossing (AKA USFS Bridge)
- 3-5. Stage 6 Pipeline Removal Location, Rael Property
- 4-1. Pipeline Sampling Locations, Existing Site Plan-West Area Detail, CMI Tailings Pipeline
- 4-2. Pipeline Sampling Locations, Existing Site Plan-East Area Detail, CMI Tailings Pipeline

List of Appendices

- A. US ARMY CORPS OF ENGINEERS NATIONWIDE PERMIT PRE-CONSTRUCTION NOTIFICATION
- B. ASBESTOS AND LEAD SAMPLING LAB DATA
- C. BORROW AREA MAP
- D. EXAMPLE FIELD AND HEALTH AND SAFETY FORMS

1.0 INTRODUCTION

Chevron Mining Inc. (CMI) submitted the revised "Questa Tailings Pipeline Removal MMD/NMED Work Plan, Chevron Environmental Management Company, Questa Mine" (Removal Work Plan) (Trihydro 2017) to New Mexico Energy, Minerals and Natural Resources Department (EMNRD), Mining and Minerals Division (MMD), New Mexico Environmental Department's (NMED) Groundwater Bureau and U.S. Environmental Protection Agency, Region 6 (USEPA) on May 19, 2017. Approval for the Removal Work Plan was received from MMD and NMED on June 5, 2017 and from USEPA on June 14, 2017. The Removal Work Plan provides an overarching plan for the removal of the Questa tailings pipeline. The Removal Work Plan states that specific work plans will be developed to detail the removal plans for individual segments of the pipeline.

The pipeline removal project has been divided into eight stages. Stage 1 activities entailed the removal of HDPE and steel pipe from the existing tailings facility. Stage 1 work was performed solely under the process described in the Removal Work Plan. Stage 1 work commenced July 10, 2017 and was completed July 24, 2017. Stage 2 through Stage 8 work activities will be conducted under the Removal Work Plan as well as individual stage specific work plans. Stages 2 through 8 are outlined in Table 1-1 and are not anticipated to be completed in number order. The segment quantities in Table 1-1 have been updated from those presented in earlier work plans.

This document represents the individual plan for Stage 6 removal of the tailings pipeline. The work identified in this plan will result in the removal of approximately 3,500 ft. of pipe. The pipe will be removed principally from private property with a lesser amount from US Forest Service (USFS) and Chevron owned property.



201902_Stage6-WP_RPT.docx 1-1

TABLE 1-1. PIPELINE SEGMENT AND STAGE IDENTIFICATION

Pipeline Segment Description	Approximate Length of Segment (feet)	Stage
Tailing Facility	10,000	1
Columbine Wells Area	4,000	2
Tailing Facility Entrance	2,800	2
Corny's Corner Hillside	1,200	2
Singleton's Cut	2,900	2
Robinson's Property	850	2
East of Molycorp Baseball Field	1,400	2
Upstream of the Lower Dump Sump	1,600	2
Pressure Vessels to Underground	500	3
East of Middle Pile	1,000	3
Goat Hill Entrance Area	2,350	3
Bear Cut	2,500	3
USFS Office Area	3,200	4
Forest Service Property west of Molycorp Field	950	4
East of Sulphur Gulch	1,000	5
West of Sulphur Gulch	1,100	5
Sugar Shack South	4,000	5
1st Road Crossing (East Hwy 38 road)	90	5
Columbine Curve	1,400	5
Columbine Park Entrance-Downstream of 1st River Crossing	600	5
2nd Road Crossing	90	5
Admin Section	1,850	5
Between Goat Hill and Bear Cut	2,500	5
3rd Road Crossing	90	5
Rock Wall (Between Bear Cut and Forest Service) (aka "Rock and Hard Place")	3,300	5
Lower Embargo Road Crossing and Embargo Road	1,100	5
Mill Raw Water Line	200	5
1st River Crossing (by Columbine Park)	120	6
2nd River Crossing (aka Thunder Bridge)	210	6
3rd River Crossing	190	6
Rael Property	550	6
Elevated Trestle	2,160	7
Lower Dump Sump	0	8



2.0 AGENCY PERMITS AND NOTIFICATIONS

The bulk of Stage 6 activities will be covered by the MMD Mining Act Permit TA001RE, Revision 96-1 and NMED Discharge Permit DP-933. Any historic tailing spills encountered during the pipeline removal will be removed pursuant to the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), Administrative Order on Consent for Removal Actions (Removal AOC), Docket No. 06-09-12.

Additional permits/notifications required may include:

- An asbestos notification form under the National Emission Standards for Hazardous Air Pollutants (NESHAP) submitted to the NMED Air Quality Bureau (AQB) will be filed before any asbestos removal is undertaken. The pipeline and associated structures have been sampled for the presence of asbestos and lead under the guidelines presented in the Removal Work Plan. Above ground Stage 6 piping was found to be non-detect for asbestos during August 2017 sampling events. Underground piping (Rael property) will be inspected upon exposure and notification will be made to NMED AQB if necessary prior to asbestos removal.
- Consultation with the United States Fish and Wildlife Service (USFWS) and/or the New Mexico Department of
 Game and Fish (NMDGF) to ensure compliance with the Threatened and Endangered Species Act (USFWS 1973),
 Migratory Bird Treaty Act (USFWS 1918), and the Bald and Golden Eagle Protection Act (U.S.C. 1940).
 Response to this consultation request was received on April 6, 2018.
- Coordination with USFS for access, preservation of ditches, and/or trees that may be affected for that portion of Stage 6 that is located on USFS owned lands.
- A Storm Water Pollution Prevention Plan (SWPPP) has been developed for coverage under the Construction General Permit. The Notice of Intent (NOI) was submitted on January 7, 2019 and authorization from EPA was received on January 21, 2019.
- A roadway work permit will be obtained before work within New Mexico Department of Transportation (NMDOT) right of way begins along NM-38. The NMDOT Environmental Clearance Request was submitted on May 16, 2018. Entact will complete the NMDOT Roadway Work Permit for Segments 6.2 and 6.3 during the late second quarter or early third quarter of 2019.
- Consultation with the New Mexico Historic Preservation Division (NMHPD) of the New Mexico Department of Cultural Affairs regarding the historic structures survey being completed at the site. A survey was completed on May 16, 2018 and submitted to NMHPD on May 29, 2018.
- A Preconstruction Notice (PCN) was submitted to the United States Army Corps of Engineers (USACE) on February 4, 2019 and is pending approval. The draft PCN is included as Appendix A. The design proposed to



201902_Stage6-WP_RPT.docx 2-1

temporarily alter the stream flow in order for equipment to travel over and work within the Red River stream bed is shown on Figures 2-1 and 2-2.

- Coordination with the property owner for access to the Rael property. Chevron met with property owners on February 19, 2019 to discuss access.
- Coordination with Kit Carson Power Cooperative for any electrical utilities work needed at river crossings or the Rael property.
- Courtesy notification to Amigos Bravos, Trout Unlimited, and the Irrigation District regarding work near the pipeline segment.

Work will not begin until approval from appropriate stakeholders to proceed has been received.

2-2 201902_Stage6-WP_RPT.docx

3.0 STAGE 6 AREAS

A description of the areas included in the Stage 6 pipeline removal plan are presented below in Table 3-1. Figure 3-1 provides an overall view of the Stage 6 project areas. More detailed views of individual pipe sections are included as Figures 3-2 through 3-5.

TABLE 3-1. AREAS INCLUDED IN STAGE 6 PIPELINE REMOVAL PLAN

Pipeline Segment Description	Approximate Length of Segment (feet)	Seasonal Considerations or Preferred Months (Alternative 1)	Above (A) or Underground (U)?	CMI Ownership?	Figure
First River Crossing (aka Columbine Park)	120	After peak runoff	А	Y	3-2
Second River Crossing (aka Thunder Bridge)	210	After peak runoff	А	Y	3-3
Third River Crossing (aka USFS Bridge)	190	After peak runoff	Α	N	3-4
Rael Property	550	Property owners discretion	A,U	N	3-5

201902_Stage6-WP_RPT.docx 3-1

4.0 REMOVAL ACTIVITIES

Prior to Stage 6 pipe removal activities, the pipe and associated structures were sampled and analyzed for lead based paint and asbestos using the methods detailed in the Removal Work Plan. Results from analysis showed that lead based paint was used to coat piping along the alignment. Concentrations of lead ranged between 240 mg/kg and 5,600 mg/kg along the Stage 6 pipe alignments. Results from asbestos sampling and analysis indicate non-detect along the Stage 6 alignment. The underground piping on the Rael property will be inspected upon its exposure. If suspect ACM is found on this pipe it will treated as ACM and managed accordingly. Sample locations and results across the entire pipeline alignment are shown in Figures 4-1 and 4-2. Pertinent lead and asbestos sampling results are shown in Table 4-1. Pipe or pipeline structures found to contain lead-based paint or asbestos will be disposed of according to State and Federal requirements as well as Chevron's Third-Party Waste Stewardship (TWS) requirements. A complete data set of lead and asbestos analytical results can be found in Appendix B.

TABLE 4-1. PERTINENT LEAD AND ASBESTOS ANALYTICAL RESULTS

Sample Identification	Pipeline Segment Sample Location	Date Sampled	Asbestos Analytical Result	Lead Analytical Result
BA183017	2 nd River Crossing, Thunder Bridge	8/30/2017	Non-Detect	Non-Detect
BA283017	2 nd River Crossing, Thunder Bridge	8/30/2017	Non-Detect	Non-Detect
BA383017	2 nd River Crossing, Thunder Bridge	8/30/2017	Non-Detect	Non-Detect
BA483017	2 nd River Crossing, Thunder Bridge	8/30/2017	Non-Detect	Non-Detect
BA583017	2 nd River Crossing, Thunder Bridge	8/30/2017	Non-Detect	Non-Detect
BA683017	2 nd River Crossing, Thunder Bridge	8/30/2017	Non-Detect	Non-Detect
BL183017	2 nd River Crossing, Thunder Bridge	8/30/2017	Not Sampled	390 mg/kg
BL283017	2 nd River Crossing, Thunder Bridge	8/30/2017	Not Sampled	340 mg/kg
BL383017	2 nd River Crossing, Thunder Bridge	8/30/2017	Not Sampled	250 mg/kg
BL483017	2 nd River Crossing, Thunder Bridge	8/30/2017	Not Sampled	630 mg/kg
BL583017	2 nd River Crossing, Thunder Bridge	8/30/2017	Not Sampled	240 mg/kg
BL683017	2 nd River Crossing, Thunder Bridge	8/30/2017	Not Sampled	5,600 mg/kg

Utility locates, and any necessary surveying will be conducted prior to pipe removal activities. Stage 6 road closures and traffic control measures will be negotiated with the pertinent stakeholders prior to undertaking any closure activities.

201902_Stage6-WP_RPT.docx 4-1

Pipe removal will be conducted under the guidelines specified under Section 4.1 of the Removal Work Plan (Trihydro 2017). Stage 6 pipeline areas are primarily located on private property with river crossing portions of the pipeline located on USFS and CMI property.

Details of the pipeline removal process for each Stage 6 section can be found below. As outlined in Table 3-1, Stage 6 consists of four sections: three river crossings and buried pipe on property owned by the Rael family.

4.1 1ST RIVER CROSSING (COLUMBINE PARK)

Work at the first river crossing, also known as the Columbine Park Bridge, consists of removing two tailings pipes, the associated spill containment structures from the bridge structure, and relocating the UG and GWW water lines (Figure 3-2). Prior to any removal activities, a geotextile fabric will be temporarily installed beneath the structure to catch any falling debris during the disassembly and removal of the pipe. Couplings at either end of the bridge structure will be removed and the pipeline will be separated. On site personnel will check the open pipe for tailings visually. The existing handrails on the bridge may be improved to facilitate the safe removal of the spill containment structure. The spill containment structure will be disassembled and manually removed from above the pipeline. The pipeline will be dragged off the bridge and then broken into shorter segments by disassembling the Victaulic couplings. The remaining components of the spill containment structure will then be removed. The bridge structure will remain in place to provide support for the existing UG and GWW water lines. The water lines will be relocated closer to the centerline of the bridge in order to shorten the existing cantilevers on the bridge supports. Demolition refuse and pipe will be trucked to an approved disposal facility.

4.2 2ND RIVER CROSSING (THUNDER BRIDGE)

The second river crossing (Thunder Bridge) will be removed in its entirety. This includes the pipe, associated spill containment structures, bridge decking, handrails, concrete piers, and abutments (Figure 3-3). Dewatering and river diversion will take place prior to the removal of pipeline and demolition of the bridge. Sand filled bulk bag diversion structures will be used both up and downstream of the bridge to channelize water flow through an HDPE diversion pipe (Figure 2-1). Residual water between the diversion structures will be removed and pumped downstream. Geotextile fabric will be temporarily installed below the bridge to catch any debris or residual tailings, preventing it from landing in the stream bed. Victaulic couplings will be detached from the pipeline on either end of the bridge. On site personnel will visually check the open pipe for tailings. The pipeline will be dragged off the bridge and broken into shorter segments by disassembling the Victaulic couplings. If couplings separate during the removal of the pipeline, the spill containment structure will be removed to expose the pipe end and the pipe will continue to be dragged out. The remaining bridge superstructure will be detached from the substructure using a pneumatic impact wrench or acetylene



4-2 201902_Stage6-WP_RPT.docx

torch. The detached bridge components will be removed utilizing a crane or piece of heavy machinery placed adjacent to the bridge. The concrete bridge abutments and piers will be broken up with a hydraulic hammer mounted on an excavator. The broken concrete will be removed from the dry stream bed using heavy equipment. Following removal of the bridge, the stream banks and stream bed will be graded to match the surrounding topography and revegetated as necessary with plant species identified in Section 5. The diversion structures will be removed and the natural stream flow will be restored. Demolition refuse and pipe will be trucked to an approved disposal facility.

4.3 3RD RIVER CROSSING (USFS BRIDGE)

The third river crossing to be addressed in Stage 6 is the bridge in the vicinity of the USFS Division Office. This is typically referred to as the Forest Service Bridge. Two tailings pipelines and associated spill containment structures will be removed from this bridge. Prior to pipeline removal a geotextile fabric will be temporarily installed below the bridge and structures to catch any falling debris and prevent it from entering the river. Victaulic couplings will be detached from the pipeline on either end of the bridge. The pipe will be inspected visually to check if tailings are present in the pipe. The spill prevention structure will be disassembled and manually lifted in sections off the bridge. The pipe will be lifted and cribbed so that it can be dragged off of the bridge and broken into shorter segments by disassembling the Victaulic couplings. The bridge structure will remain in place to provide support for existing conduits which house electric and communication utilities owned and operated by Kit Carson Power Cooperative (Figure 3-4). Demolition refuse and pipe will be trucked to an approved disposal facility.

4.4 RAEL PROPERTY

The fourth segment of Stage 6 is the removal of all pipe from property owned by the Rael family. This pipe is both above and underground (Figure 3-5).

The pipeline will be exposed and removed using two excavators working in tandem. Trench slope walls will be at a 1.5:1 slope. The trenched excavation will be barricaded as necessary to prevent un-authorized personnel from entering the work zone. Pipeline will then be cut into manageable sections, as determined by on site field personnel, using an excavator mounted hydraulic shear. Prior to removing the pipe from the trench, the pipes will be inspected for tailings and appropriate measures will be taken to reduce the potential for spills. Typically this will entail covering the ends with plastic prior to transportation or shaking the tailing from the pipe into an approved container for transportation to the tailing facility. The pipe will then be removed from the trench, broken up into individual sections and moved to the adjacent Chevron property. The pipe will be trucked to an approved disposal facility with Stage 7 pipe later in 2019.



201902_Stage6-WP_RPT.docx 4-3

Four pipes are buried along the alignment. It is assumed that the oldest pipes will have an ACM wrap. If wrapping is encountered, it will be characterized as friable or non-friable and appropriate PPE will be donned. Two poly sheets large enough for the pipe segment will be laid out and the ACM coated pipe will be carefully placed on the poly sheets. The pipe will be wrapped and appropriately labeled as ACM, the ends of the piping will be sealed, and the pipe staged for disposal in labeled ACM roll off bins.

Structures such as pipe couplings, anchor structures, pipe bend structures, and concrete thrust blocks will be removed in accordance with Section 4.2 of the Removal Work Plan (Trihydro 2017).

All waste will be disposed of according to the methods outlined in Sections 2.3.3 and 4.0 in the Removal Work Plan.

Approximate quantities of material to be removed are detailed in Table 4-2.

TABLE 4-2. QUANTITIES OF DEMOLITION MATERIALS

Pipeline Segment Description	Approximate Quantity of Pipe to be Removed (feet)	Approximate Quantity of Concrete (tons)	Approximate Quantity of Steel (tons)
1st River Crossing (by Columbine Park)	240	0	0
2nd River Crossing (aka Thunder Bridge)	627	77	5
3rd River Crossing (USFS bridge)	374	0	0
Rael Property	2,196	0	0.4

4-4 201902_Stage6-WP_RPT.docx

5.0 RECLAMATION

Areas disturbed during pipe removal, tailing removal, and other demolition activities conducted under this work plan will be reclaimed according to the procedures outlined in Section 4.2.10 of the Removal Work Plan (Trihydro 2017). The pipeline right of way and other disturbed areas will be regraded to match the natural grade of the area. Clean fill, if necessary, will be imported from previously approved borrow sources. A map indicating the locations of borrow material is included as Appendix C.

Once the grading has been completed disturbed areas will be reseeded using the mix detailed in Table 5-1. Alternate seed mixes may be used for private properties depending upon the anticipated land use or if availability of certain seed species is limited. The seed mix may be negotiated with the proper regulatory agencies based on the area of application.

TABLE 5-1. SEED MIXTURE

Grasses	Scientific Name	Drill Seeding Ibs/acre	Hydroseeding Ibs/acre
Western Wheatgrass, var. Arriba	Pascopryum smithii	4.1	8.2
Slender Wheatgrass, var. San Luis	Elymus trachycaulus	1.7	3.4
Bluebunch Wheatgrass, var. Goldar	Pseudoroegneria spicata	2.3	4.6
Blue Grama, var. Hachita	Bouteloua gracilis	0.5	1.0
Arizona Fescue, var. Redondo	Festuca arizonica	0.7	1.4
Forbs			
Western Yarrow	Achillea millefolium	0.15	0.3
Rocky Mountain Penstemon, var. Bandera	Penstemon strictus	1.2	2.4
Prairie Coneflower	Ratibida columnifera	0.8	1.6
Tufted Evening Primrose	Oenothera speciosa	0.15	0.3
Shrubs			
Mountain Big Sagebrush, var. Hobble Creek	Artemisia tridentata var vaseyana	0.3	0.6
Apache Plume	Fallugia paradoxa	0.3	0.6

201902_Stage6-WP_RPT.docx 5-1

6.0 STAKEHOLDER ENGAGEMENT

The key stakeholders for this stage of pipeline removal include:

- NMDGF
- NMDOT
- USFWS
- USFS (property owner)
- Rael Family (property owner)
- NMHPD
- USACE
- Amigos Bravos/Trout Unlimited
- Kit Carson Power Cooperative
- Village of Questa

Outreach to the key stakeholders has begun and will continue throughout the pipeline removal project. Stage 6 activities will be discussed with the public during the scheduled monthly meeting with the Village of Questa.

201902_Stage6-WP_RPT.docx 6-1

7.0 SCHEDULE

The schedule for Stage 6 of the Questa pipeline removal project is detailed below in Table 7-1.

TABLE 7-1. STAGE 6 PIPELINE REMOVAL SCHEDULE

Pipeline Segment Description	Target Start Date for Pipe Removal	Target End Date for Pipe Removal
1st River Crossing (by Columbine Park)	August 2019	August 2019
2nd River Crossing (aka Thunder Bridge)	August 2019	September 2019
3rd River Crossing	March 2019	March 2019
Rael Property	March 2019	April 2019

201902_Stage6-WP_RPT.docx 7-1

8.0 HEALTH AND SAFETY

CMI, Entact, and Trihydro put safety first and foremost in all operations. A project specific Health and Safety Plan (HASP) will be developed for the pipeline removal activities. The project specific HASP will be similar in scope and detail as presented in the December 20, 2016 HASP (Trihydro 2016) prepared for coordination, sampling, and surveying activities completed in the initial phases of the pipeline dismantling and stabilization. The project specific HASP will include the following details:

- Emergency response procedures and reporting
- Project team organization and responsibilities
- Training, orientation, and medical monitoring requirements
- A site hazard analysis
- Analysis of chemical, physical, and biological hazards
- Required personal protective equipment
- Air monitoring requirements
- Site control measures
- Waste management
- Motor vehicle safety requirements

Other documents used to identify and mitigate hazards associated with the project will include the forms listed below. Examples of the listed forms are included in Appendix D.

- Pre-fieldwork safety readiness reviews. This document provides project management an opportunity to interact
 with field personnel prior to commencement of field activities.
- Job Safety Analyses (JSA). JSAs are drafted for each task. Job steps, potential hazards and mitigation steps are identified and communicated to team members. The JSA form is included in Appendix D.
- Field observations. Observations will be conducted throughout the project to verify compliance with operational safety standards.
- Near Miss investigations. Near misses identified by team members will be investigated to determine root causes
 and means to avoid similar incidents in future operations. The outcome of these investigations will be shared with
 all team members.



201902_Stage6-WP_RPT.docx 8-1

- Daily tailgate safety meetings. Daily tailgate safety meeting will be conducted every day prior to commencement
 of operations. The meetings are an opportunity to review JSAs, discuss changing conditions, lessons learned and
 operational details.
- Weekly management safety meetings. This meeting is an opportunity for the project leadership to discuss upcoming operations, lessons learned, near loss investigations and other potential issues covered in the weekly project meeting.
- Journey management plans (JMP). JMPs are used to identify hazards associated with transportation. These plans identify hazard and provide mitigation steps for enhancing vehicle operational safety.

The use of these documents creates the foundation for hazard awareness and mitigation. Our companies have embedded their use into our respective corporate cultures and freely share best practices and lesson learned.

8-2 201902_Stage6-WP_RPT.docx

9.0 CONTRACTORS KEY PERSONNEL

Entact LLC will be the primary contractor for Stage 6 pipe removal, waste management, and regrading of the right of way. Key Entact personnel include:

- Michael Cinciripini. Michael is the Project Manager and primary operations contact for Entact on the tailings pipeline removal project (Project). Michael holds a Bachelor of Science degree in Civil and Environmental Engineering, a Construction Management Certificate and is a Lean Sigma Green Belt. He has a significant level of experience at the Questa Mine facility. He can be reached at (412) 417-8460 or mcincirpini@entact.com.
- Nicholas Cain. Nicholas fills the role of Health and Safety Officer for Entact on the Project.

Trihydro Corporation will be responsible for engineering, contractor oversight, environmental sampling, permitting and regulatory support. Key Trihydro personnel include:

- Shaun Harshman. Shaun is the Project Manager and primary contact for Trihydro on the Project. Shaun has a Bachelor of Science degree in Soil Science. He has over 30 years of experience in the environmental field, with over 18 years of experience on Chevron projects. He can be reached at (307) 259-5909 or sharshman@trihydro.com.
- Tony Kupilik. Tony will be Trihydro's primary construction oversight and health and safety manager. Tony has over 25 years of experience in heavy construction and mining. He is a certified MSHA instructor, New Mexico Surface Coal Foreman, Excavation Competent Person, 3D Driving instructor and has OSHA 40-hour HAZWOPER training. He is also a certified instructor for Red Cross CPR, AED, and First Aid. He can be reached at (307) 760-8082 or tkupilik@trihydro.com.



201902_Stage6-WP_RPT.docx 9-1

10.0 REFERENCES


Trihydro Corporation. 2016. Health and Safety Plan (HASP), Field Summary, Chevron Environmental Management Company (CEMC), Environmental Activities, Questa Mine. December 20, 2016.


Trihydro. 2017. Questa Tailings Pipeline Removal MMD/NMED Work Plan, Chevron Environmental Management Company, Questa Mine. May 19, 2017.




201902_Stage6-WP_RPT.docx 10-1

FIGURES







-PRE-WELDED SAND FILLED -TEXTURED HDPE SUPER SACS PANELS DIVERSION EXTERIOR ARMORED -WITH QUARRY SPALLS QUARRY SPALL -OUTLET PAD SOIL PRE-WELDED --24 INCH HDPE PIPE TEXTURED HDPE PANELS **TEMPORARY DIVERSION - DOWNSTREAM CROSS SECTION**

EXPLANATION

SANDBAGS SAND FILLED SUPER SACS 24" HDPE DIVERSION PIPE

QUARRY SPALL STREAM FLOWPATH PRE-WELDED TEXTURED HDPE PANELS

SCALE 1" = 5'

NOTES:

- 1. EMBANKMENTS ARE APPROXIMATED.
- 2. THE SAND FILLED SUPER SAC CORE IS WRAPPED WITH PRE-WELDED TEXTURED HDPE PANELS
- 3. DIVERSION STRUCTURE IS SET UPON A LAYER OF PRE-WELDED TEXTURED HDPE PANELS



FIGURE 2-2


RED RIVER TEMPORARY DIVERSION DAM CROSS SECTION


CEMC QUESTA MINE QUESTA, NEW MEXICO www.trihydro.com P) 307/745.7474 (F) 307/745.7729


C


SCALE 1" = 5'


Drawn By: PC Checked By: RN Scale: AS SHOWN Date: 12/21/2018 File: 476-QM-S6-RR_DIV_X-SEC_FIG2-2















Drawn By: PC | Checked By: CS | Scale: 1" = 1000' | Date: 6/18/18 | File: 476-QM-PRMT-SITEDETAIL201806

TAILINGS PIPELINE ALIGNMENT - WEST OF LOWER DUMP SUMP



1252 Commerce Drive

Laramie, Wyoming 82070

www.trihydro.com

Drawn By: PC Checked By: CS Scale: 1" = 1500'

(P) 307/745.7474 (F) 307/745.772

1500'

CEMC QUESTA

QUESTA, NEW MEXICO


Date: 4/26/17 File: 476-QM-PRMT-SITEDETAIL201806

OTHER PROPERTY

PER KILOGRAM (mg/kg)

TAILINGS PIPELINE ALIGNMENT

- EAST OF LOWER DUMP SUMP





January 14, 2019

Ms. Deanna Cummings
Regulatory Project Manager
U.S. Army Corps of Engineers – Albuquerque District
4101 Jefferson Plaza NE
Albuquerque, NM 87109

RE: Pre-construction Notification – Nationwide Permit 12 for the Questa Pipeline Removal Stages 3-7 Project

Taos County, New Mexico

Corps File No.:

Dear Ms. Cummings:

Trihydro Corporation on behalf of Chevron (CEMC or Applicant) is pleased to submit the attached preconstruction notification (PCN) for work activates in wetlands and waters of the United States (WOUS) required for the removal of a decommissioned mill tailings pipeline (utility line) pursuant to nationwide permit (NWP) 12 under Section 404 of the Clean Water Act.

Attached to this PCN is a technical memorandum detailing adherence to guideline 9 of the NWP-12 general conditions (Attachment 1), responses to United States Army Corps of Engineers New Mexico Regional Conditions (Attachment 2), and the New Mexico Environmental Department Clean Water Act Section 401 Water Quality Certification for United State Army Corps of Engineers 2017 Nationwide Permits (Attachment 3).

Also attached to this PCN is a draft Aquatic Resource Inventory (ARI) identifying wetlands and WOUS at four crossings associated with the pipeline removal project (Attachment 4). Based on the ARI and the proposed construction footprints for removal of the pipeline, temporary impacts to wetlands and WOUS are proposed at two of the four crossings, the Elevated Trestle and Thunder Bridge. This PCN requests approval for approximately 0.137 acre of temporary impact to WOUS and 0.171 acre of impact to wetlands.



Ms. Deanna Cummings January 14, 2019 Page 2

Should you require any additional information of have question regarding the attached PCN, please do not hesitate to contact me at (970) 492-6022 or via email at pcoit@trihydro.com.

Sincerely,

Trihydro Corporation

Parker Coit, P.

Assistant Project Geologist

476-027-002

Enclosures

cc: Ms. Cynthia Murray Gulde, CEMC

cgulde@chevron.com

Mr. Gabriel Herrera, CEMC

Gabriel.herrera@chevron.com

Mr. Abraham Franklin, New Mexico Environmental Department

Abraham.franklin@state.nm.us



U.S. Army Corps of Engineers South Pacific Division



Nationwide Permit Pre-Construction Notification (PCN)

This form integrates requirements of the U.S. Army Corps of Engineers (Corps) Nationwide Permit Program within the South Pacific Division (SPD). Boxes 1-10 must be completed to include all information required by General Condition 32. Box 11 (or other sufficient information to show compliance with all General Conditions) must be completed for activities in Arizona, California, Nevada, and Utah, and is recommended for activities in Colorado and New Mexico. If additional space is needed, please provide as a separate attachment. Please refer to the *Instructions for the South Pacific Division Nationwide Permit Pre-Construction Notification (PCN)* (Instructions) for instructions for completing the PCN, as well as additional information on the attachments and tables included with this PCN that may be used

	0. To be	e filled by the C	orps		
Application Number:	Date Received:			Date Complete	:
1. Prospe	Lective Permittee and Ag	gent Name and	Address	es (see Instruc	etions)
a. Prospective Permitte	е				
First -	Middle		_ Last		
Company -		Email Address -			
Address -		City		State	Zip
Phone (Residence/Mobile) -		Phon	e (Busines:	s)	
b. Agent (if applicable)					
First -	Middle		_ Last		
Company -		Email Address -			
Address -		City		State	Zip
)				
c. Statement of Authoriz	zation: I hereby authorize tivity. (Optional, see instructions)				
Signature of	of Applicant	_		Date	

2. Name and Location of the Prop	osed Activity (see Instructions)
☐ The proposed work would involve multiple-single and comple Boxes 2 through 10, and 11, if applicable.	te projects. See attachment for the information required in
a. Project Name or Title:	b. County, State:
c. Name of Waterbody:	
d. Coordinates:	
☐ Unknown (please provide other location descriptions below)	
Latitude - Longitude -	*See attached Table 1 for Lat/Long Coordinates
e. Other Location Description (optional, see instructions):	
f. Driving Directions to the site (optional, see instructions):	
3. Specific NWP(s) you want to use to author	ze the proposed activity (see Instructions)
4. Description of the Proposed	d Activity (see Instructions)
a. Complete description of the Proposed Activity:	
The proposed project entails demolition and reclamation of a decommissioned mi	Il tailings pipeline and ancillary structures associated with the Questa Mine to
pre-mining conditions. The tailings pipeline was constructed to transport mill tailin	
tailings pipeline begins approximately 7 miles east of the Village of Questa, NM, a through the Village of Questa, NM, terminating at the Tailings Facility. The majori	
(CEMC) and the USFS. A portion of the pipeline crosses private property. The pipeline crosses private property.	
Embargo Ditch, and unnamed ditches (see Figure 1 and Attachment 4). The pipe	
Bridge) and the Elevated Trestle. Based on the Aquatic Resource Inventory (Atta	
the United States (WOUS) and wetlands are expected at only the two of Red Rive pacts to WOUS or wetlands will occur at the other river crossings. The bridge at 0	
above ground structures will be removed from the Questa Mine to the Tailings Fa	
to be grouted in place.	
b. Purpose of the Proposed Activity:	
•	

c. Direct and indirect adverse environmental effects the activity would cause, including the anticipated amount of loss of wetlands and other waters of the U.S. expected to result from the NWP(s) activity:
The attached Aquatic Resource Inventory (Attachment 4) provides the context for determining the direct and indirect effects of the proposed pipeline removal on wetlands and waters of the U.S. (WOUS). Ordinary highwater mark for the Red River, and wetlands were delineated at all of the crossings and the Lower Dump Sump to calculate impacts of the proposed project. Direct and indirect impacts are shown in Table 2 and on Figures 2 through 7. The environmental benefits from the project are expected to outweigh the temporary impacts to WOUS and wetlands are expected to be minimal while removing the pipeline and associated structures, and are expected to last for approximately three weeks at both the Elevated Trestle and Thunder Bridge. No permanent loss of wetlands and WOUS will occur from the proposed activity. Both the Elevated Trestle and Thunder Bridge pipeline river crossings will require temporary earthen and bulk bag diversion structures and two 24-inch diversion HDPE pipelines to allow for the removal of the pipeline and associated structures (Figures 2 through 7, Attachment 1, and Attachment 4). The project will also require vehicle and foot traffic through wetlands and WOUS for access to remove the pipeline installed under bridge structures and to remove any unused bridge structures not needed for other purposes.
d. Description of any proposed mitigation measures intended to reduce the adverse environmental effects caused
by the proposed activity:
e. Any other NWP(s), Regional/Programmatic General Permit(s) or Individual Permit(s) used or intended to be used to
authorize any part of the proposed activity or any related activity:
f. Have sketches been provided containing sufficient detail to provide an illustrative description of the proposed activity?
*(See attached Figures 2 through 7 and photographs in Appendix B of Attachment 4)
☐ Yes, Attached ☐ No
☐ N/A; The activity is located in the Los Angeles District boundaries of Arizona and California, See Attachment 1
☐ N/A, The activity is located in the San Francisco District boundaries of California, See Attachment 2
□ N/A, The activity is located in the Sacramento District boundaries of California, Nevada, or Utah, See Attachment 3
5. Aquatic Resource Delineation (see Instructions)
a. Has a delineation of aquatic resources been conducted in accordance with the current method required by the
Corps? Yes No *see Attachment 4
If yes, please attach a copy of the delineation
Note: If no, your PCN is not complete. In accordance with General Condition 32, you may request the Corps delineate the special aquatic sites and other waters on the project site, but there may be a delay. In addition, the PCN will not be considered complete until the delineation has either been submitted to or completed by the Corps, as appropriate.
b. If a delineation has been submitted, would you like the Corps to conduct a jurisdictional determination (preliminary or approved)? ☐ Yes ☐ No
If yes, please complete, sign and return the attached <i>Appendix 1 – Request for Corps Jurisdictional Determination (JD)</i> sheet or provide a separate attachment with the information identified in Appendix 1.

6. Compensatory Mitigation (see Instructions)
a. Will the proposed activity result in the loss of greater than 1/10-acre of wetlands?
If yes, describe how you propose to compensate for the loss of each type of wetland: *see Attachement 1
Note: for the loss of less than 1/10 acre of wetlands, or if no compensatory mitigation is proposed, the Corps may determine on a case-by-case basis that
compensatory mitigation is required to ensure that the activity results in only minimal adverse environmental effects. b. Will the proposed activity result in the loss of streams or other open waters of the U.S.? Yes No
b. Will the proposed activity result in the loss of streams or other open waters of the U.S.? Yes No If yes, provide a description of any proposed compensatory mitigation for the loss of each type of stream or other open water:
Note: if no compensatory mitigation is proposed, the Corps may determine on a case-by-case basis that compensatory mitigation is required to ensure that the activity results in no more than minimal adverse environmental effects.
7. Endangered Species Act (ESA) Compliance (see Instructions)
a. For non-Federal permittees (if Federal permittee, check N/A and skip to 7(d)): N/A
(1) Is there any Federally-listed endangered or threatened species or critical habitat that might be affected or is in the vicinity of the activity? Yes No
(2) Is the activity located in designated critical habitat for Federally-listed endangered or threatened species? 🗌 Yes 🔠 No
If yes to either (1) or (2), include the name(s) of those endangered or threatened species that might be affected by the proposed activity or might utilize the designated critical habitat that might be affected by the proposed activity:
1. 2.
3. 4.
5. 6.
*see Attachment 4 for details If no to both (1) and (2), proceed to Box 8.
Note: If yes to either (1) or (2), note per General Condition 18(c), you shall not begin work on the activity until notified by the Corps that the requirements of

b. Has information sufficient to initiate consultation with the U.S. Fish and Wildlife Service/National Marine Fisheries Service for compliance with Section 7 of the ESA been prepared?		
* see Attachment 4 for details		
If yes, please attach a copy of the information.		
c. Additional information you wish to provide regarding compliance with the ESA, if applicable:		
d. For Federal permittees, you must provide documentation demonstrating compliance with ESA as a separate attachment.		
8. Historic Properties (see Instructions)		
a. For non-Federal permittees (if Federal permittee, check N/A and skip to 8(d)): N/A		
(1) Is there a known historic property listed on, determined to be eligible for listing on, or potentially eligible for listing on, the		
National Register of Historic Places that the NWP may have the potential to affect? Yes No		
If yes to (1), state which historic property may have the potential to be affected by the proposed activity:		
1. 2.		
—·		
3. 4.		
5. 6.		
OR		
☐ A vicinity map indicating the location of the historic property is enclosed *see Appendix E of Attachment 4 for details		
(2) If no to (1), describe the notantial for the proposed work to effect a proviously unidentified historic property.		
(2) If no to (1), describe the potential for the proposed work to affect a previously unidentified historic property:		
Note: If yes to (1), note per General Condition 20(c), you shall not begin the activity until notified by the Corps that the activity has no potential to cause		
effects or that consultation under Section 106 of the National Historic Preservation Act (NHPA) has been completed.		
b. Has information sufficient to initiate consultation with the State Historic Preservation Officer/Tribal Preservation Officer for compliance with Section 106 of the National Historic Preservation Act (NHPA) been prepared?		
Dyn. *see Annendiy F of Attachment 4		
☐ Yes ☐ No *see Appendix E of Attachment 4		
If yes, please attach a copy of the information.		
c. Additional information you wish to provide regarding compliance with the NHPA, if applicable:		
d. For Federal permittees, you must provide documentation demonstrating compliance with NHPA in a separate		
attachment.		

9. National Wild and Scenic Rivers (see Instructions)				
a. Will the proposed activity(s) occur in a component of the National Wild and Scenic River System or a river officially designated by Congress as a "Study River" for possible inclusion in the system while the river is in an official study status?				
☐ Yes, in a component of a National Wild and Scenic River System; ☐ Yes, in a "study" river ☐ No				
If yes, identify the Wild and Scenic River or the "study river"				
The Red River is a tributary to the Rio Grande. The Rio Grande and the lower reach of the Red River are designated as a wild and scenic river in New Mexico, administered by the BLM/USFS. The Elevated Trestle is approximately 2.5 miles upriver and Thunder Bridge approximately 6.65 miles upriver of the Red River Wild and Scenic River designation. The pipeline removal activities are not expected to impact the Wild and Scenic River area.				
Note: per General Condition 16(b), you shall not begin the NWP activity until notified by the Corps that the Federal agency with direct management responsibility for that river has determined in writing that the proposed NWP activity will not adversely affect the Wild and Scenic River designation or study status. If you have received written notification from the Federal agency, please attach the correspondence.				
10. Section 408 Permissions (see Instructions)				
a. Will the NWP also require permissions from the Corps pursuant to 33 U.S.C. 408 because it will alter or temporarily or permanently occupy or use a Corps federally authorized Civil Works project? Yes No				
If yes, have you received Section 408 permission to alter, occupy, or use the Corps project? Yes No				
If yes, please attach the Section 408 permission				
If yes, note per General Condition 31, an activity that requires Section 408 permission is not authorized by NWP until the Corps issues the Section 408 permission to alter, occupy, or use the Corps project, and the Corps issues a written NWP verification.				

11. Compliance with NWP General Conditions (see Instructions)					
Check	General Condition	Rationale for Compliance with General Condition			
	1. Navigation				
	2. Aquatic Life Movements	Minimal impacts are anticipated. The project will result in a temporary barrier to movement up and down the stream by fish or other aquatic species during the construction. Approximately 100 linear feet of stream at both the Elevated Trestle and Thunder Bridge will be blocked off from movement during construction. During placement of the diversion, fish and aquatic species will be allowed to relocate up or downstream out of the diverted area. Following construction, fish and aquatic species will be able re-establish in the construction area (see Attachment 4).			
	3. Spawning Areas	No or very minimal impacts are anticipated. A number of game fish occur in the section of the Red River crossed by the pipeline including triploid (sterile) rainbow trout (Oncorhychus mykiss) raised in a hatchery downstream of the project area and a wild, introduced brown trout (Salmo trutta) population. BMPs designed to control erosion would minimize sedimentation on any gravel beds used by spawning fish. No fish spawning areas were observed at the pipeline crossing of the Red River (see Attachment 4).			
	4. Migratory Bird Breeding Areas	No or very minimal impacts are anticipated. Habitat for nesting birds is present along the pipeline route, especially in wooded areas. No trees will be removed during project activities, which will minimize direct impacts to breeding birds. Any occupied bird nests discovered in shrubs, on the ground, or on human made structures will be avoided during project activities. No raptor nests were observed in teh area, during the aquatic resources survey. Two migratory bird nests were found, but, they were unoccupied. No direct impacts to breeding birds is expected (see Attachment 4)			
	5. Shellfish Beds	No or very minimal impacts are anticipated. BMPs designed to control erosion would minimize sedimentation and any adverse effects on shellfish. The Sangre de Cristo peaclam, a New Mexico Game and Fish threatened species, is only found in Middle Fork Lake in Taos County, which is over 7 miles to the south of the project area near Taos Ski Valley (BISON-M 2017).			
	6. Suitable Material	The project is a pipeline removal/grout-in-place and restoration project. The project is designed to have a zero cut/fill balance. The project is being completed under EPA- and MMD-approval of stage-specific work plans and engineering design drawings.			

7. Water Supply Intakes	
8. Adverse Effects from Impoundments	
9. Management of Water Flows	
10. Fills Within 100-Year Floodplains	
11. Equipment	
12. Soil Erosion and Sediment Controls	

13. Removal of Temporary Fills	
14. Proper Maintenance	
15. Single and Complete Project	
16. Wild and Scenic Rivers	
17. Tribal Rights	
18. Endangered Species	See Box 7 above.
19. Migratory Bird and Bald and Golden Eagle Permits	

П	20. Historic Properties	See Box 8 above.
	20. Historic Properties	*See Appendix E in Attachment 4.
	21. Discovery of Previously Unknown Remains and Artifacts	
	22. Designated Critical Resource Waters	
	23. Mitigation	See Boxes 4(d) and 6 above
	24. Safety of Impoundment Structures	
	25. Water Quality, including status of Section 401 Water Quality Certification	
	26. Coastal Zone Management, including status of CZM Consistency Certification from the State of California (for projects in or affecting the Coastal Zone)	

27. Regional and Case-by-Case Conditions	
28. Use of Multiple Nationwide Permits	
29. Transfer of Nationwide Permit Verifications	
30. Compliance Certification	
31. Activities Affecting Structures or Works Built by the United States	See Box 10 above. Not applicable.
32. Pre-Construction Notification	




TABLE 1. U.S. ARMY CORPS OF ENGINEERS PRECONSTRUCTION NOTIFICATION QUESTA TAILINGS PIPELINE REMOVAL CHEVRON ENVIRONMENTAL MANAGEMENT COMPANY, QUESTA MINE JANUARY 2019


Pipeline Section Name (From Mill Area to Tailings Facility)	Description	Watershed	USGS Watershed Code	Waterbody Name at Crossing	Downstream Tributary	Latitude	Longitude	Expected Impacts
1st Red River Crossing (By Columbine Park)	Red River at confluence with Columbine Creek (tributary)	Upper Rio Grande	13020101	Red River	Red River	36°40'53.33"N	105°30'53.97"W	None
2nd Red River Crossing (Thunder Bridge Crossing)	Red River crossing	Upper Rio Grande	13020101	Red River	Rio Grande	36°41'4.29"N	105°31'47.83"W	Temporary diversion structure and pipline Vehicle and Foot Traffic
3rd Red River Crossing (East of Ranger Station)	Red River crossing	Upper Rio Grande	13020101	Red River	Rio Grande	36°42'6.96"N	105°33'47.96"W	None
Elevated Trestle Red River Crossing	Red River crossing	Upper Rio Grande	13020101	Red River	Rio Grande	36°41'41.97"N	105°35'45.20"W	Temporary diversion structure and pipline Vehicle and Foot Traffic

1 of 1

TABLE 2. U.S. ARMY CORPS OF ENGINEERS PRECONSTRUCTION NOTIFICATION QUESTA TAILINGS PIPELINE REMOVAL CHEVRON ENVIRONMENTAL MANAGEMENT COMPANY, QUESTA MINE DECEMBER 2018

Description	Temporary Impact to Wetlands	Temporary Impact to Waters of the U.S. (WOUS)		
-	Area (acres)	Area (acres)		
1st Red River Crossing (By Columbine Park)	0	0		
2nd Red River Crossing (Thunder Bridge Crossing)	0.067	0.054		
3rd Red River Crossing (East of Ranger Station)	0	0		
Elevated Trestle Red River Crossing	0.104	0.083		
Total	0.171	0.137		





TAILINGS PIPELINE ALIGNMENT AREA ROADS








1252 Commerce Drive Laramie, Wyoming 82070 www.trihydro.com (P) 307/745.7474 (F) 307/745.772


RED RIVER TEMPORARY DIVERSIONS OVERVIEW


PRE-CONSTRUCTION NOTIFICATION
CEMC QUESTA MINE
QUESTA, NEW MEXICO



















technical memorandum

Ms. Cynthia Murray Gulde and Mr. Gabriel Herrera,

To: CEMC

From: Mr. Tyrel Hulet, P.E., Trihydro Corporation

cc: File

Date: January 14, 2018

U.S. Army Corps of Engineers (Corps)

Pre-construction Notification (PCN) Attachment 1 – Questa Pipeline Removal Stage 3-7 Red River

Re: Diversions Design and Execution

Trihydro Corporation (Trihydro) prepared this technical memorandum to summarize recommendations for constructing temporary stream diversions during the removal of a decommissioned tailings pipeline (pipeline) between Questa Mine (Mine) Mill Area and Tailings Facility. The tailings pipeline parallels the Red River for approximately half of the 8.5-mile pipeline length, crossing the Red River at four locations. Stream diversions will be required at two locations (Figure 1); one at the Thunder Bridge (Figure 2) near Highway 38 between Questa, NM and the Mine and one for the Elevated Trestle Crossing/Old Red River Bridge (Figure 3) south of Questa. Entact, LLC has been awarded the decommissioning project, and will perform the stream diversion. As with the greater decommissioning project, Chevron Environmental Management Company (CEMC) will oversee the stream diversion work, ensuring the project is completed in general accordance with the designs and specifications as well as applicable regulations.

The stream diversion design constraints were primarily derived from the United States Army Corps of Engineers (Corps) Nationwide Permit (NWP) 12 General Conditions.

NWP-12 General Conditions (General Condition 9) require diversions be constructed to withstand expected high flows without restricting or impeding flows, and while maintaining benefits to the aquatic environment. In order to fulfill the NWP requirements, Trihydro compiled historic flow data for the Red River using United States Geologic Service (USGS) stream gauging stations located at two points downstream of the proposed diversion locations (Figure 1). The stream gauging stations maintained by the USGS are located sufficiently close to the project areas that either location may have been used as a basis for establishing expected high flows. To estimate flow averages and peaks, Trihydro used averaged flow data between USGS gauging stations 0826500 and 08266820 for the Elevated Trestle Crossing, and used the flow data from downstream USGS station 0826500 for the Thunder Bridge crossing. Trihydro believes using the stream data in this manner serves as a conservative assumption for the flow averages and peaks. USGS monthly flow data for both stations were available from 2000 to 2016. Monthly flow data for the USGS station 08265000 are included in Table 1; those for the USGS station 08266820 are included in Table 2.



Ms. Cynthia Murray Gulde and Mr. Gabriel Herrera January 14, 2018 Page 2

Based on prior experience shared by Trihydro and Entact, a diversion plan was selected where protected berms at each diversion location will temporarily convey flow through two high density polyethylene (HDPE) conveyance pipes. Berms will be constructed using 42"x42"x48" sacks (Super Sacs) of sand. The sand sack structure will be wrapped with an impermeable barrier consisting of pre-welded, textured HDPE panels. The diversion structure will be armored with quarry spalls/riprap or other suitable materials conforming to NWP-12 General Condition 6. The conveyance pipes shall be approximately 100 feet for the Thunder Bridge Crossing and 200 feet for the Elevated Trestle Crossing, to allow for a suitable boundary to be maintained in the river on either side of the planned work areas. The diversion pipe outflows will be secured with a constructed berm that is similar to the upstream berm. Figures 2 through 4 details the proposed diversions including plan views of the structures and standard construction details. Streambanks near the diversion areas will be protected with erosion control features (e.g. straw wattles) while the pipeline and associated structures are decommissioned. Erosion controls conforming to NWP-12 General Condition 12 will remain in place until post-removal grading has been completed, and the areas have been re-vegetated.

The two diversion conveyance pipes at each diversion site were sized to accommodate flow as described in the NWP. In the event of a high-flow discharge while the diversion is in place, water will accumulate behind the upstream diversion driving discharge through the conveyance pipes as the head from the upstream surface increases. Table 3 and Table 4 summarize the upstream high-water depths for three sizes of conveyance pipe: 18-inch, 24-inch, and 30-inch. The water surface elevations were calculated using the Federal Highway Administration's (FHA) HY-8 modeling software. The model outputs suggest a conveyance system using two, 24-inch HDPE pipes will provide adequate relief to prevent excessive headwater height during the low-flow months of August through March. Between April and July, peak flows may cause overtopping of the diversion dams. The features will be constructed to withstand overtopping if the peak flows occur, but construction will be planned during the low flow months as described in the NWP-12 General Conditions. The following caveats will be taken into consideration to more safely manage the diversion project:

At Thunder Bridge:

- The 24-inch configuration will provide sufficient diversion structure height for maximum flow conditions between October and March with the single tier of Super Sacs.
- Overtopping may occur between April and September if peak flow conditions develop.
- Quarry spalls will cap the single tier of Super Sacs to allow for controlled overtopping.

At the Elevated Trestle Crossing:

- The 24-inch configuration will provide sufficient diversion structure height for average flow conditions between August and March with the single tier of Super Sacs; but not for maximum flows.
- Maximum flows during these months may result in overtopping.



Ms. Cynthia Murray Gulde and Mr. Gabriel Herrera January 14, 2018 Page 3

- Average and maximum flows between April and July may result in overtopping.
- Quarry spalls will cap the single tier of Super Sacs to allow for controlled overtopping.

Additional information originating from the 24-inch pipe HY-8 model is included in Attachment A.

Following decommissioning of the tailings pipeline and associated structures, the area will be restored to the pre-diversion state.

476-027-002




TABLE 1. TAOS COUNTY, NEW MEXICO HYDROLOGIC UNIT CODE 13020101 LATITUDE 36°42'11.92", LONGITUDE 105°34'06.35" NAD83 DRAINAGE AREA 113 SQUARE MILES CONTRIBUTING DRAINAGE AREA 113 SQUARE MILES GAGE DATUM 7,451.92 FEET ABOVE NGVD29

	USGS 08265000 RED RIVER NEAR QUESTA, NM											
	00060, Discharge, cubic feet per second,											
	Monthly mean in ft3/s (Calculation Period: 2000-01-01 -> 2016-09-30)											
	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
2000	12.4	13.5	16	28.6	37.9	22.4	13.3	16.5	11.2	13.4	8.66	4.85
2001	8.87	10.5	11.2	39.9	151.9	102	44.3	38.2	25.7	14.9	10.9	9.98
2002	10.4	10.5	10	12	9.61	7.03	8.47	5.64	12.9	12.5	9.75	4.9
2003	5.35	6.87	12	30.7	80.7	70.2	26.6	17.5	28.3	17.5	11.8	6.52
2004	6.6	7.93	15.7	35.3	95.7	51.7	27.8	17.1	18.9	20.9	13.5	7.47
2005	13	13.8	14.3	79.7	255.5	215	74.5	42.6	28	30.7	18.5	11.5
2006	12.6	11.6	11.7	24	35.4	24.5	21.3	25.2	22.8	23.4	16.8	7.92
2007	12.9	11.2	23	46.2	109.8	99.5	48.5	38	32.9	27.5	15.6	19.3
2008	19	19.6	30.9	78.1	162	236.8	107.2	60	42.3	29.9	22	18.2
2009	20.9	22.5	32.7	65.4	231.9	144.1	70.8	37.6	32.4	23.7	18.8	15.3
2010	17.1	16.2	17.6	63.5	152.3	150.5	53.8	37.6	24	18.8	14.3	14.3
2011	11.7	13.2	15.8	18.3	34	52.7	24.7	15.6	17.5	13.6	13.2	11
2012	11.3	11.2	20.5	69	85.7	46.4	24.8	18	14.8	13	10.5	10.6
2013	9.69	11.9	13.4	25.7	47.1	33.7	21.9	16.1	27.2	19.7	16.1	10.6
2014	12	11.1	12.8	34.4	73.4	83.3	35.1	29.4	19.1	18.4	14.9	12.6
2015	12.3	11.5		52.7	122.6	198.1	87.5	47	27.1		20.9	17.6
2016	16.3	17.7	23.5	50.3	127.2	135	52	31.8	22.6			
AVG.	12.49	12.99	17.57	44.34	106.63	98.41	43.68	29.05	23.98	19.86	14.76	11.42
MAX	20.90	22.50	32.70	79.70	255.50	236.80	107.20	60.00	42.30	30.70	22.00	19.30

201901_USGS_RRFlow1and2_TBL.xlsx

TABLE 2. TAOS COUNTY, NEW MEXICO HYDROLOGIC UNIT CODE 13020101 LATITUDE 36°40'58.22", LONGITUDE 105°39'14.84" NAD83 DRAINAGE AREA 185 SQUARE MILES CONTRIBUTING DRAINAGE AREA 185 SQUARE MILES GAGE DATUM 7,105 FEET ABOVE NGVD29

USGS 08266820 RED RIVER BELOW FISH HATCHERY, NEAR QUESTA, NM 00060, Discharge, cubic feet per second, Monthly mean in ft3/s (Calculation Period: 2000-01-01 -> 2016-11-30) Feb Sep Jan Mar Apr May Jun Jul Aug Oct Nov Dec 39.9 39.2 40.5 52.8 59 49 38.2 38.9 41.6 34 33.5 2000 32.3 32.3 58.7 46.7 37.2 2001 37.8 38.5 67.3 176.6 120.8 64.1 40.2 37.1 35.7 32.8 27 27.4 29.3 25.1 34.4 32.3 33.1 29.3 2002 40.4 40.1 2003 30.8 30.9 34.6 52.5 98.7 87.4 46.7 43.2 57 39.4 38.1 39.9 2004 31.7 30.8 42.8 61.7 110.3 66.9 44.2 34.3 38.3 40.1 34.1 30.3 2005 35.2 37.1 38.3 106 280.7 252.7 101.6 71.2 50.6 58.4 50.5 43.5 2006 42.3 37.2 38.3 47 57.3 46 42.5 47.5 46.8 50.3 43.3 36.6 2007 40.2 41.8 52.1 73.6 162.5 136.3 81.8 70.5 63.8 57.7 39.9 55.1 2008 49.1 47.1 65.6 118.7 239.2 285.8 137.7 91.8 73.5 63 53.3 44.9 47.2 49.8 62.5 101.4 285.3 181.7 88.7 56.9 55.8 55.8 52.5 44.1 2009 46 45.9 46.4 98 180.8 169.1 85.2 77.4 50.7 46.3 42.9 42.1 2010 2011 38.2 38.9 35.9 52.8 85.8 46.3 39.2 43.1 47.4 39.8 38.8 46.8 2012 39 35.9 43.7 103.9 108.4 61.1 48.2 38.6 35.2 33 32.2 32.7 27.5 32.9 34.6 63.1 54.6 46.8 45.9 59.7 52.3 48.3 41.7 2013 46.3 2014 34.5 32.9 33.6 56.5 111.6 138.9 57.5 55.6 43.7 49.1 40.1 38.8 50.4 2015 38.5 36 53.1 86.3 160.7 232.7 111.5 72.2 54.2 50.3 45.5 43.4 50.7 70.8 158.6 77 59 46 45.8 2016 45.1 161.7 48.6 AVG. 38.60 38.79 44.11 71.26 137.21 126.94 67.49 54.47 49.08 47.25 42.49 39.69 MAX 49.10 49.80 65.60 118.70 285.30 285.80 137.70 91.80 73.50 63.00 53.30 55.10

201901_USGS_RRFlow1and2_TBL.xlsx 1 of 1

TABLE 3. ELEVATED TRESTLE CROSSING QUESTA MINE RED RIVER DIVERSIONS

	USGS 08266820 RED RIVER BELOW FISH HATCHERY, NEAR QUESTA, NM											
	00060, Discharge, cubic feet per second,											
	Monthly mean in ft3/s (Calculation Period: 2000-01-01 -> 2016-11-30)											
	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
AVG.	38.60	38.79	44.11	71.26	137.21	126.94	67.49	54.47	49.08	47.25	42.49	39.69
MAX	49.10	49.80	65.60	118.70	285.30	285.80	137.70	91.80	73.50	63.00	53.30	55.10
		AVERAGE OF 08265000 & 08266820										
	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
AVG.	25.55	25.89	30.84	57.80	121.92	112.67	55.58	41.76	36.53	33.56	28.63	25.55
MAX	35.00	36.15	49.15	99.20	270.40	261.30	122.45	75.90	57.90	46.85	37.65	37.20
Average Aug -	Average Aug - Mar: 31.04 cfs Dam Height: 6.0 ft											

Average Aug - Mar: 31.04 cfs Dam Height: 6.0 ft

18 in.							
Headwater Height (ft)	Total Discharge (cfs)	Div Pipe Discharg e (cfs)	Overflow Discharg e (cfs)				
1.37	10	10	0				
5.77	31.04	31.04	0				
6.27	62.08	32.56	29.35				
6.41	88.12	32.92	55.02				
6.52	114.16	33.25	80.71				
6.62	140.2	33.58	106.51				
6.71	166.24	33.81	132.1				
6.76	192.28	35.96	156.68				
6.84	218.32	35.87	182.23				
6.91	244.36	35.94	208.33				
6.99	270.4	35.94	234.42				
6	31.74	31.74	0				

24 in.						
Headwater Height (ft)	Total Discharg e (cfs)	Div Pipe Discharg e (cfs)	Overflow Discharg e (cfs)			
1.23	10	10	0			
2.39	31.04	31.04	0			
6.04	62.08	60.4	1.54			
6.25	88.12	61.74	26.23			
6.39	114.16	62.56	51.42			
6.47	140.2	71.2	68.9			
6.57	166.24	71.87	94.04			
6.67	192.28	72.49	119.6			
6.75	218.32	73	143.15			
6.81	244.36	73.31	171.32			
6.88	270.4	73.47	197			
6	60.15	60.15	0			

30 in.						
Headwater Height (ft)	Total Discharg e (cfs)	Div Pipe Discharg e (cfs)	Overflow Discharg e (cfs)			
1.01	10	10	0			
2.12	31.04	31.04	0			
3.31	62.08	62.08	0			
5.29	88.12	88.12	0			
6.18	114.16	98.15	15.98			
6.33	140.2	99.79	40.18			
6.45	166.24	101.02	64.9			
6.56	192.28	102.18	89.99			
6.65	218.32	103.13	114.83			
6.74	244.36	104.07	140.05			
6.79	270.4	104.56	165.99			
6	96.16	96.16	0			

Elevation for overtopping dam

Average flow during construction period is contained by 24-inch configuration with approximatley 2.4 ft. of headwater elevation.

Expected monthly flows during construction months

201901_CulvtSize3and4_TBL.xlsx

TABLE 4. THUNDER BRIDGE QUESTA MINE RED RIVER DIVERSIONS

USGS 08265000 RED RIVER NEAR QUESTA, NM

00060, Discharge, cubic feet per second,
Monthly mean in ft3/s (Calculation Period: 2000-01-01 -> 2016-09-30)

mentally means in these (exhaustions are as 2000 of 5 2000 of 5)												
	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec
AVG.	12.49	12.99	17.57	44.34	106.63	98.41	43.68	29.05	23.98	19.86	14.76	11.42
MAX	20.90	22.50	32.70	79.70	255.50	236.80	107.20	60.00	42.30	30.70	22.00	19.30

Average Aug - Mar:

17.77 cfs

Dam Height:

6.0 ft

18 in.						
Headwater	Total	Div Pipe	Overflow			
Height (ft)	Discharge	Discharge	Discharge			
rioigni (it)	(cfs)	(cfs)	(cfs)			
1.37	10	10	0			
2.1	17.77	17.77	0			
6.19	55.36	37.88	17.26			
6.33	78.04	38.39	39.43			
6.44	100.72	38.81	61.7			
6.53	123.4	39.16	84.13			
6.62	146.08	39.48	106.31			
6.7	168.76	39.77	128.75			
6.75	191.44	39.95	153.34			
6.81	214.12	40.17	173.97			
6.88	236.8	40.41	196.36			
6	37.2	37.2	0			

24 in.						
Headwater Height (ft)	Total Discharge (cfs)	Div Pipe Discharge (cfs)	Overflow Discharge (cfs)			
1.23	10	10	0			
1.69	17.77	17.77	0			
4.5	55.36	55.36	0			
6.13	78.04	68.8	9.15			
6.28	100.72	69.94	30.65			
6.39	123.4	70.7	52.41			
6.49	146.08	71.35	74.59			
6.58	168.76	71.93	96.5			
6.66	191.44	72.46	118.72			
6.74	214.12	72.95	140.95			
6.78	236.8	73.21	163.87			
6	67.97	67.97	0			

30 in.						
Headwater	Total	Div Pipe	Overflow			
Height (ft)	Discharge	Discharge	Discharge			
neight (it)	(cfs)	(cfs)	(cfs)			
1.01	10	10	0			
1.4	17.77	17.77	0			
3.01	55.36	55.36	0			
4.16	78.04	78.04	0			
5.84	100.72	100.72	0			
6.2	123.4	104.92	18.31			
6.33	146.08	106.38	39.52			
6.43	168.76	107.57	60.99			
6.53	191.44	108.61	82.72			
6.61	214.12	109.54	104.29			
6.69	236.8	110.41	126.16			
6	102.63	102.63	0			


Elevation for Overtopping Dam

Average flow during construction period is contained by 24-inch configuration with approximatley 1.7 ft. of headwater elevation.


Expected monthly flows during construction months

201901_CulvtSize3and4_TBL.xlsx





TAILINGS PIPELINE ALIGNMENT AREA ROADS







RED RIVER TEMPORARY DIVERSIONS OVERVIEW


USACE PERMIT MEMO CEMC QUESTA MINE QUESTA, NEW MEXICO


Drawn By: DF | Checked By: TH | Scale: 1"=5,000"

Date: 12/21/18 | File: 476-QM_F-1&TB-2_201812









-PRE-WELDED SAND FILLED -TEXTURED HDPE SUPER SACS PANELS DIVERSION EXTERIOR ARMORED -WITH QUARRY SPALLS QUARRY SPALL -OUTLET PAD SOIL PRE-WELDED --24 INCH HDPE PIPE TEXTURED HDPE PANELS **TEMPORARY DIVERSION - DOWNSTREAM CROSS SECTION**

EXPLANATION

SANDBAGS SAND FILLED SUPER SACS 24" HDPE DIVERSION PIPE

QUARRY SPALL STREAM FLOWPATH PRE-WELDED TEXTURED HDPE PANELS

SCALE 1" = 5'

NOTES:

- 1. EMBANKMENTS ARE APPROXIMATED.
- 2. THE SAND FILLED SUPER SAC CORE IS WRAPPED WITH PRE-WELDED TEXTURED HDPE PANELS
- 3. DIVERSION STRUCTURE IS SET UPON A LAYER OF PRE-WELDED TEXTURED HDPE PANELS



FIGURE 4


RED RIVER TEMPORARY DIVERSION DAM CROSS SECTION

CEMC QUESTA MINE QUESTA, NEW MEXICO www.trihydro.com P) 307/745.7474 (F) 307/745.7729


C


SCALE 1" = 5'


Drawn By: PC | Checked By: RN | Scale: AS SHOWN Date: 12/21/2018 | File: 476-QM-TB_FIG-4_201901




THUNDER BRIDGE - 18-INCH DIAMETER









THUNDER BRIDGE - 24-INCH DIAMETER









* Full Flow Headwater elevation is below inlet invert.
~ Inlet control is shown, but flow profile is substantially FF.

Outlet Control:


Profiles


THUNDER BRIDGE - 30-INCH DIAMETER







ELEVATED TRESTLE - 18-INCH DIAMETER










ELEVATED TRESTLE - 24-INCH DIAMETER










ELEVATED TRESTLE - 30-INCH DIAMETER









ATTACHMENT 2. NEW MEXICO REGIONAL CONDITIONS

This attachment lists the regional conditions applicable for New Mexico.

1. <u>Dredge and Fill Activities in Intermittent and Perennial Streams, and Special Aquatic Sites</u>: (a) For all activities subject to regulation under the CWA Section 404 in intermittent and perennial streams, and special aquatic sites (including wetlands, riffle and pool complexes, and sanctuaries and refuges), Pre-Construction Notification to the District Engineer is required in accordance with General Condition 32.

Response: This application package constitutes the PCN.

(b) For projects in intermittent and perennial streams in which the New Mexico Environment Department (NMED) is the water quality certifying agency, the applicant must also notify the NMED Surface Water Quality Bureau and obtain confirmation of CWA, Section 401 Water Quality Certification prior to commencing work. Electronic submittals are preferred. A copy of NMED's confirmation must be provided to the USACE within 10 days of NMED's receipt of the applicant's notification.

Response: CEMC will notify NMED per Attachment 3.

2. Individual Water Quality Certification and Pre-Construction Notification. For all activities subject to regulation under the CWA Section 404 where Section 401 individual water quality certification is required, the applicant must provide Pre-Construction Notification to the District Engineer in accordance with General Condition 32 at the same time notification is provided to the water quality certifying authority. A copy of the individual 401 water quality certification must be provided to the District Engineer prior to commencing the regulated activity. A list of state agencies and tribes with Section 401 authority is on our website available at: http://www.spa.usace.army.mil/Missions/Regulatory-Program-and-Permits/Water-Quality-Certification/

Response: 401 Water Quality Certification is included in Attachment 3.

4. <u>Special Status Waters in New Mexico</u>. The waters listed in **Attachment 1 of the Regional Conditions** have been designated by the State of New Mexico as waters important for the protection of water quality or the protection and conservation of certain species. For all activities subject to regulation under the CWA Section 404 occurring in these waters, Pre-Construction Notification is required to the USACE in accordance with General Condition 32. The applicant must also provide Pre-Construction Notification to the New Mexico Department of Game and Fish, Ecological and Environmental Planning Division. Electronic submittals are preferred.

Response: The removal project is not in special status waters.

5. <u>Activities in all Waters of the United States</u>. Any activity subject to regulation under the CWA Section 404 that exceeds 1/2 acre of permanent fill in waters of the United States will require Pre-Construction Notification to the USACE in accordance with General Condition 32

Response: No permanent fill is anticipated. Temporary impacts will not exceed 0.171 acre of impact to wetlands and 0.137 acre of WOUS.

6. <u>Springs</u>. For all discharges of dredged or fill material within 100 feet of the point of groundwater discharge of natural springs, Pre-Construction Notification is required to the USACE in accordance with General Condition

ATTACHMENT 2. NEW MEXICO REGIONAL CONDITIONS

32. A natural spring is defined as any location where ground water emanates from a point in the ground and has a defined surface water connection to another waters of the United States. For purposes of this regional condition, springs do not include seeps or other groundwater discharges which lack a defined surface water connection.

Response: No Springs exist within 100 feet of the project area.

7. <u>Channelization</u>. General Condition 9 for Management of Water Flows is amended to add the following: Projects that would result in permanent channelization to previously un-channelized streams require Pre-Construction Notification to the District Engineer in accordance with General Condition 32.

Response: The project would not result in permanent channelization.

8. <u>Suitable Fill</u>. Use of broken concrete as fill or bank stabilization material is prohibited unless the applicant demonstrates that its use is the only practicable material (with respect to cost, existing technology, and logistics). Any applicant who wishes to use broken concrete as bank stabilization must provide notification to the District Engineer in accordance with General Condition 32 (Pre-Construction Notification) along with justification for such use. Use of broken concrete with rebar or used tires (loose or formed into bales) is prohibited in all waters of the United States. See Note 'a' below.


Response: The repairs will not include broken concrete or used tires.

9. <u>Fens.</u> All nationwide permits, except 3, 5, 6, 20, 27, 32 and 38, are revoked in fens and wetlands adjacent to fens. For activities in fens and wetlands adjacent to fens, use of nationwide permits 3, 20, and 27 requires Pre-Construction Notification to the District Engineer, in accordance with General Condition 32. For the purposes of this regional condition, fens are defined as follows:

Fen soils (histosols) are normally saturated throughout the growing season, although they may not be during drought conditions. The primary source of hydrology for fens is groundwater. Histosols are defined in accordance with the U.S. Department of Agriculture, Natural Resources Conservation Service publications on Keys to Soil Taxonomy and Field Indicators of Hydric Soils in the United States (http://soils.usda.gov/technical/classification/taxonomy and http://soils.usda.gov/technical/).

Additionally, peat lands with spongy, water-logged soil containing a histosol or a mineral soil with a histic epipedon that may be termed in some literature as cienagas, marshes, or bogs (for example, the Alamo bog complex and the floating mat fen complex at Santo Domingo Pueblo) are included in this regional condition.

Response: Not applicable.





NEW MEXICO ENVIRONMENT DEPARTMENT

Harold Runnels Building 1190 South St. Francis Drive (87505) P.O. Box 5469, Santa Fe, NM 87502-5469 Phone (505) 827-0187 Fax (505) 827-0160 www.env.nm.gov



BUTCH TONGATE Cabinet Secretary

J. C. BORREGO Deputy Secretary

March 1, 2017

Mr. Allan Steinle U.S. Army Corps of Engineers Albuquerque District, Regulatory Branch 4101 Jefferson Plaza NE Albuquerque, New Mexico 87109-3434

Re: Clean Water Act Section 401 Water Quality Certification

United States Army Corps of Engineers 2017 Nationwide Permits

Dear Mr. Steinle:

The New Mexico Environment Department (NMED) has examined both the January 6, 2017 final notice of the Reissuance of Nationwide Permits (NWPs) under the Clean Water Act (CWA) §404 and Section 10 of the Harbors and Rivers Act, issued by the U.S. Army Corps of Engineers ("Corps") (see 84-4 FR 1860) and the January 6, 2017 Corps Albuquerque District public notice of the final NWPs and NMED's intent to consider certification of those permits under the CWA §401 (Certification). Certification is required by CWA §401 to ensure that the NWPs are consistent with state law, comply with the state Water Quality Standards (20.6.4 NMAC), the Water Quality Management Plan/Continuing Planning Process, including Total Maximum Daily Loads (TMDLs), and the Antidegradation Policy. Certification is also required to comply with General Condition 25 (Water Quality) and General Condition 27 (Regional and Case-By-Case Conditions) of the NWPs.

Pursuant to State regulations for permit certification (20.6.2.2002, NMAC), NMED issued a public notice of this activity and announced a public comment period, posted on the Surface Water Quality Bureau's web site: (www.nmenv.state.nm.us/swqb/WQA/Notice) on January 10, 2017. The public comment period ended on February 7, 2017. No comments were received.

The following conditions are necessary to assure compliance with the applicable provisions of the Clean Water Act §§301, 302, 303, 306, and 307 and with applicable requirements of State law. Compliance with the terms and conditions of the permit and this certification will provide reasonable assurance that the permitted activities will be conducted in a manner which will not violate applicable water quality standards or the Statewide Water Quality Management Plan, and will be in compliance with the state's antidegradation policy. The State of New Mexico certifies that the discharge will comply with these provisions and requirements upon inclusion of the following conditions in the permit:

Conditional Section 401 Certification of NWPs:

The following conditions apply to all uses of NWPs within State of New Mexico 401 certification authority area or region:

- All proposed projects must avoid discharges to the maximum extent practicable; however, if
 discharges cannot be avoided the project must utilize the best available and practicable means to
 minimize adverse impacts. NMED encourages approaches based on natural ecosystem processes.
 Examples of Best Management Practices (BMPs) that may be applicable include:
 - Limit work in the channel to periods of no flow.
 - Store fuel, oil, hydraulic fluid, lubricants, and other petrochemicals in a secondary containment system capable of containing twice the volume of the product.
 - Restrict temporary crossings to a single location and construct perpendicular to and at a narrow point of the stream or wetland to minimize disturbance.
 - Design and install permeable fills in wetlands when practicable.
 - For culvert projects, NMED encourages lower-impact techniques such as bottomless and embedded culverts.
 - Schedule construction activities in wetlands during low water or winter (frozen) conditions.

2. NMED notification:

- a. Activities that require preconstruction notification to NMED can be found in the USACE's New Mexico Regional Condition 2.b. NMED preconstruction notification must include:
 - Detailed project purpose and construction plans, including why the proposed approach does not result in more than minimal impact to the aquatic resource.
 - Notification of projects to maintain or repair existing structures must include a
 description of how the existing structure failed and what will be done to prevent failure in
 the future.
 - Notification of projects to extend existing bank stabilization must include a description of the existing bank stabilization, including the length, location, and the type of materials that were used.
 - Notification of projects to install or repair culverts must include a description of how the culvert sizing was determined.
 - Notification of projects to reshape an existing drainage ditch must describe the handling
 of excavation materials and how the structure, when fully operational, will maintain or
 improve water quality.
 - ii. Description of potential adverse water quality impacts including the project's potential impact on turbidity, an optical measurement of water affected by the amount of suspended material, as well as oil, grease, or hydraulic fluid, and all other potential contaminants.
 - Description of methods to be used to prevent water quality impacts, including BMPs designed to minimize sediment, oil, grease, and other pollutants from entering the water.

Mr. Allan Steinle March 1, 2017 Page 3 of 6

- Projects to remove riparian vegetation must describe methods to prevent subsequent erosion into aquatic resources.
- Projects that would result in dredge or fill in waterbodies listed as impaired under Section 303(d) of the CWA must include specific measures that will be used to avoid causing or contributing to a violation of water quality standards. The current EPA-approved New Mexico list of impaired waters is available at https://www.env.nm.gov/swqb/303d-305b/ (see "All Impairments (Cat. 4 or 5)" spreadsheet).
- b. Additionally, the following types of projects require notification to NMED:
 - NMED must be notified at least five days before starting construction to allow time to schedule monitoring or inspections.
 - NMED must be notified immediately if the project results in an exceedance of applicable water quality standards. This condition applies to projects in any water of the State, including ephemeral waters.
 - iii. NMED must be notified if the project is delayed into times of predictable flooding (seasonal monsoons or snowmelt). Notification must describe BMPs to protect the stream from excessive turbidity, such as diversion structures capable of conveying the potential flood flows.
 - iv. NMED must be notified if the project involves work in standing or flowing surface water. Notification must include a description of planned methods to minimize turbidity in the stream and to avoid spills that would contaminate the surface water.
 - v. NMED must be notified of any proposed project to channelize a stream, whether previously channelized or not. Notification must include the information described under certification condition 2.a, above.
 - vi. NMED must be notified at least five days before starting construction to allow time to schedule monitoring or inspections. The NMED must be notified immediately if the project results in an exceedance of applicable Standards.

Unless approved by NMED:

- a. Projects must not alter the natural stream channel size or shape (width, depth, gradient, direction or meander pattern), streamflow velocity (sediment transport rates), or water flow capacity. Requests for approval of such deviations must include descriptions of planned methods to minimize turbidity and avoid spills, as well as to stabilize the modified hydraulic geometry.
- b. Bank stabilization projects must incorporate native vegetation or other bioengineered design techniques (e.g. willow plantings, root wads, large woody debris, etc.). Requests for such approval must describe why native vegetation or other bioengineered design techniques were rejected.
- c. Stormwater management structures must not be located within natural drainage systems, such as sediment basins within a stream channel. Requests for such approval must include a description of "off-line" designs considered and why they were rejected.
- d. Flowing water must be temporarily diverted around the work area, but remain within the existing channel to minimize erosion and turbidity and to provide for aquatic life movement. Requests for such approval must include descriptions of planned methods to minimize turbidity, to avoid

- spills, and to provide a continuous zone of passage for aquatic life through or around the project area in which the water quality meets all applicable criteria including turbidity.
- e. Heavy equipment must be operated from the bank or work platforms and not enter surface water. Requests for such approval must include a description of BMPs to minimize turbidity and to avoid spills.
- f. Disturbed areas outside stream channels that are not otherwise physically protected from erosion must be reseeded or planted with native vegetation. Requests for approval of deviation from this condition must describe methods to minimize turbidity and avoid spills, as well as final grading plans.
- g. All areas adjacent to the watercourse that are disturbed because of the project, including temporary access roads, stockpiles and staging areas, must be restored to pre-project elevations.
- h. Culvert design must allow for the passage of fish and other aquatic organisms.
- Wetland crossings must be restricted to a single location and constructed perpendicular to and at a narrow point of the wetland.
- The permittee shall allow NMED representatives to inspect the authorized activity and any mitigation areas at any time deemed necessary to determine compliance with applicable State Water Quality Standards.

5. Structure design:

- a. Structures at stream crossings must be properly designed, installed and maintained to allow passage of sediment, bedload, and woody debris, and to prevent erosion problems or postconstruction diversion of the stream from its natural channel.
- b. Culverts at stream crossings must be designed and installed to prevent upstream headcutting, downstream channel incision, and erosion of the stream banks or the crossing. Culverts at stream crossings must also be designed to prevent flood flows from being diverted away from the natural channel when the culvert is overtopped.
- Scheduling: Project activities must avoid times of predictable flooding (seasonal monsoons or snowmelt) to avoid working in high water. Releases from dams must be incorporated into the work schedule to avoid working in high water.
- Construction diversions: Diversion structures must be non-erodible, such as sand bags, water bladders, concrete barriers, or channel lined with geotextile or plastic sheeting. Dirt cofferdams are not acceptable diversion structures.

8. Use of heavy equipment:

- a. All heavy equipment used in the project area must be pressure washed and/or steam cleaned before the start of the project and inspected daily for leaks. A written log of inspections and maintenance must be completed and maintained throughout the project period. Leaking equipment must not be used in or near surface water.
- b. Fuel, oil, hydraulic fluid, lubricants, and other petrochemicals must not be stored within the 100-year floodplain. Refuel equipment at least 100 feet from surface water.

Mr. Allan Steinle March 1, 2017 Page 5 of 6

c. Heavy equipment must not be parked within the stream channel.

9. Construction materials and fuels:

- a. Except as specified in the application, no debris, silt, sand, cement, concrete, oil or petroleum, organic material, or other construction related materials or wastes shall be allowed to enter into or be stored where it may be washed by rainfall or runoff into aquatic resources. Appropriate spill clean-up materials such as booms and absorbent pads must be available on-site at all times during construction. Dumping of any waste materials is prohibited.
- b. Poured concrete must be fully contained in mortar-tight forms and/or placed behind non-erodible cofferdams to prevent contact with surface or ground waters. Appropriate measures must be used to prevent wastewater from concrete batching, vehicle wash-down, or aggregate processing impacting aquatic resources.

10. Construction (temporary) impacts:

- Water used in dust suppression shall not contain contaminants that could violate water quality standards.
- Protective measures must be used to prevent blast, ripped or excavated soil or rock from entering surface waters.
- c. Materials associated with repair, demolition, treatments, or cleaning activities of bridges or associated structures must be kept out of the channel. Generally, impermeable containment material (e.g., plastic sheet, canvas, tarpaulins or other catchment devices) must be secured under the structure to capture falling debris. Sandblasting must include vacuum systems or the structures must be completely bagged to collect all paint and concrete debris. Any debris that falls onto the containment area or channel must be properly disposed in accordance with the New Mexico Solid Waste Regulations (20.9.1 NMAC). Applicable Material Safety Data Sheets of water repellants and surface finish treatments must be maintained at the project area.

11. Trenching:

- Excavated trenches within or adjacent to aquatic resources must be backfilled and compacted to match the adjacent undisturbed soil.
- Except for dewatering activities described in the submitted construction plans, excavated trenches must not result in draining any aquatic resource including wetlands.
- c. Excavation dewatering discharges must be uncontaminated. Aquatic resources must be protected from excessive turbidity associated with dewatering, such as discharging to an uplands area behind a vegetative buffer. Note that dewatering discharges may be subject to NMED Discharge Permits. 20.6.2.1201 NMAC requires any person intending to make a new water contaminant discharge to file a notice of intent to discharge with the Ground Water Quality Bureau (https://www.env.nm.gov/gwb/) for discharges that may affect ground water and/or with the Surface Water Quality Bureau (https://www.env.nm.gov/swqb/) for discharges that may affect surface water. Based on the information provided in the notice of intent, the Bureau will notify the person if a discharge permit is required.

Mr. Allan Steinle March 1, 2017 Page 6 of 6

 Wetlands: Wetland vegetation and excavated top soil must be retained and reused to improve seeding success. Flows to wetlands must not be permanently disrupted.

13. Post-construction stabilization:

- a. Permittees and their contractors shall take necessary steps to minimize channel and bank erosion during and after construction. Where applicable, banks shall be reseeded or replanted with native vegetation.
- b. Disturbed areas outside stream channels that are not otherwise physically protected from erosion must be reseeded or planted with native vegetation. Stabilization measures including vegetation are required at the earliest practicable date, but by the end of the first full growing season following construction. Native woody riparian and/or wetland species must be used in areas that support such vegetation. Plantings must be monitored and replaced for an overall survival rate of at least 80 percent by the end of the second growing season. Once established, native plants adapted to the site must be able to thrive with no supplemental water or treatment. Silt fences, seed free straw mulch, biodegradable straw wattles, and other techniques must be employed as appropriate to protect waters from sedimentation and other pollutants.
- 14. <u>Posting:</u> A copy of this Certification must be kept at the project site during all phases of construction. All contractors involved in the project must be provided a copy of this certification and made aware of the conditions prior to starting construction.

Denial of Certification of NWPs

NMED denies Certification for NWP-37 (Emergency Repair Activities), in favor of handling "emergency repairs" with an Emergency Regional General Permit Number (Repair and Protection Activities in Emergency Situations) or expedited permitting under another NWP permit.

For proposed activities in Outstanding National Resource Waters (ONRW, 20.6.4.9 NMAC) NMED denies Certification of all NWPs <u>except</u> NWP-27. NMED hereby certifies NWP-27 for restoration activities within ONRWs, pursuant to 20.6.4.8.A.4 NMAC. The certification process for activities covered by nationwide permits other than NWP-27 will be conducted pursuant to 20.6.2.2002 NMAC.

Please contact Neal Schaeffer of my staff at (505) 476-3017 should you have any questions.

Sincerely.


Shelly Lemon

Acting Chief

Surface Water Quality Bureau

SL: cns

xc: Tom Nystrom, Wetlands, Region 6, USEPA
Matthew Wunder, New Mexico Department of Game and Fish
U.S. Fish and Wildlife Service
401 Certification File 1299





QUESTA TAILINGS PIPELINE REMOVAL PROJECT AQUATIC RESOURCE INVENTORY REPORT CHEVRON ENVIRONMENTAL MANAGEMENT COMPANY QUESTA, NM

January 14, 2019

Project #: 476-027-003

SUBMITTED BY: Trihydro Corporation

1252 Commerce Drive, Laramie, WY 82070

ENGINEERING SOLUTIONS. ADVANCING BUSINESS.

Table of Contents

1.0	INTRODUCTION				1-1
	1.1	Purpose			1-2
	1.2	Regulatory Authority			1-2
	1.3	Project Area Description			1-2
		1.3.1 Soils			1-3
		1.3.2	Vegetation	on	1-4
		1.3.3	Hydrolog	ıy	1-4
2.0	METHODS				2-1
	2.1	Data Review			2-1
	2.2	Aquatic Resource Delineation Methodology			2-1
3.0	RESI	RESULTS			
	3.1 Aquatic Resource Findings			e Findings	3-1
		3.1.1 Aquatic Resources Impacted by Project			3-2
			3.1.1.1	Lower Dump Sump	3-2
			3.1.1.2	Red River Crossing (Elevated Trestle)	3-2
			3.1.1.3	Red River Crossing (East of Ranger Station)	3-3
			3.1.1.4	Red River Crossing (Thunder Bridge)	3-4
			3.1.1.5	1st Red River CrossinG (by Columbine Park)	3-4
		3.1.2 Terrestrial and Aquatic Wildlife		3-5	
		3.1.3	Other We	etlands Assessment	3-6
	3.2	Cultural Resources			3-6
4.0	CON	ONCLUSIONS			
5.0	RFFF	REFERENCES			

List of Tables

- 1. Soil Map Units in the Project Area
- 2. Aquatic Resources in the Project Area
- 3. Aquatic Resources Impacts Summary

List of Figures

- 1. Soils
- 2. NWI Wetlands Overview
- 3. NWI and Field Verified Wetlands
- 4. NWI and Field Verified Wetlands
- 5. NWI and Field Verified Wetlands
- 6. NWI Wetlands
- 7. NWI and Field Verified Wetlands
- 8. NWI and Verified Wetlands
- 9. NWI Wetlands

List of Appendices

- A. WETLAND DETERMINATION DATA FORMS
- B. PHOTOGRAPH LOG
- C. USFWS OFFICIAL SPECIES LIST
- D. URS QUESTA REMOVAL ACTION WETLAND ASSESSMENT REPORT
- E. CHEVRON QUESTA MINE TAILINGS PIPELINE REMOVAL PROJECT CULTURAL RESOURCES SURVEY

1.0 INTRODUCTION

On behalf of Chevron Environmental Management Company (CEMC), Trihydro Corporation (Trihydro) hereby submits this aquatic resource inventory report for the Questa Tailings Pipeline Removal Project to the United States Army Corps of Engineers (Corps). The Questa Mine is a former underground and open pit molybdenum mine and milling operation owned by Chevron Mining Inc. (CMI). The mine and mill facilities are located approximately 7 miles east of the Village of Questa, New Mexico (Questa), in Taos County along New Mexico Highway 38 and the adjacent Red River. The Questa Mine's Tailing Facility is located approximately 9 miles west of the mine, near Questa, NM. The tailings pipeline was constructed to transport mill tailings, as a slurry, to the tailings facility. Conventional underground mining operations began in 1918 and continued until 1958. Underground mining resumed in 1982 and continued through approximately 2012. Open pit mining was conducted between 1965 and 1983. CMI announced the cessation of operations at the mine on June 2, 2014 and initiated closeout activities.

In the 1960's, the Questa Mine constructed a pipeline from the Mill Area of the mine approximately 9 miles west to the Tailings Facility. From east to west, the pipeline typically consists of two 14-inch outside diameter, rubber lined steel pipes that parallel Highway 38 down the Red River Canyon, through the Village of Questa, to the Tailings Facility on the west side of town (Figure 1). In some areas, additional sections of pipeline were constructed to provide a backup line where access was limited. The pipe transitioned to HDPE at the Tailings Facility Flow Monitoring Building.

The Questa Mine stopped using the pipeline to transfer tailings in April of 2012, but continued to pump mine collected waters from the Mine Site groundwater collection systems and the underground mine to the Tailings Facility. The collected water likely flushed any remaining tailings from the pipeline, but some of the collected water may remain in low areas of the pipeline upon cessation of its use. The currently active pipeline was flushed with fresh water prior to cessation.

The pipeline crosses CMI property, United States Forest Service (USFS) property, New Mexico Department of Transportation (NMDOT) right of way (ROW), along with four private landowners' property. The pipeline crosses over the Red River at four locations and under Highway 38 at four locations. Most of the pipeline is above ground, running along Highway 38 or on CMI or USFS property. Some sections of the pipeline are buried and may either be abandoned in place or excavated and removed, depending on depth of burial and/or ease of access. There are structures along the route including three small pressure vessels, the Upper Dump Sump, the Lower Dump Sump and support buildings, three old bridges, two elevated trestles, and the Tailings Facility Flow Monitoring Building. For this report, bridges are defined as structures crossing streams, and are capable of carrying foot or vehicular traffic as well as pipe and other utilities. A trestle is an above ground structure designed for carrying pipe or other utilities only.



201901_TailingsPipeline-ARI_RPT.docx

1.1 PURPOSE

The purpose of the Tailings Pipeline Removal Project is to remove the entire tailing pipelines from the Mill Area to the Tailings Facility Catchment Pond, or abandon the buried tailing pipeline in place where necessary. The work scope also includes demolition and removal of the three small pressure vessels, the Lower Dump Sump and support buildings, non-utility bearing bridges, the trestle, and the flow monitoring building.

The primary purpose of this report is to present the results of an aquatic resource inventory conducted on May 9 and 10, 2018 which is included as an appendix to the preconstruction notification (PCN) submitted to the Corps

The tailings pipeline parallels the Red River for about half of the 8.5-mile pipeline length, crossing the Red River at four locations. The Red River is a jurisdictional water of the U.S. (WOUS), requiring permitting through the Corps prior to beginning the regulated activity. The pipeline also crosses the Embargo Ditch and other irrigation ditches located near the Tailings Facility. The Embargo Ditch draws water from the Red River and returns water downstream to the Red River. In the State of New Mexico, irrigation ditches that draw water from a WOUS and return water to WOUS remain WOUS. Therefore, the Embargo Ditch (and possibly other irrigation ditches in the area) are considered jurisdictional WOUS. Wetlands associated with jurisdictional waters are WOUS. and are also jurisdictional.

1.2 REGULATORY AUTHORITY

The Corps Nationwide Permit NWP-12 applies to utility line activities. the Corps concurred that NWP-12 should be applicable to the tailings pipeline removal effort. NWP-12 limits loss of wetlands to ½-acres of waters of the U.S. for each completed Project. The Corps has indicated that the tailings pipeline removal Project, including the Lower Dump Sump, is considered to be a single and complete Project. NWP-12 requires PCN submittal. Section 11 of the PCN requires confirmation that all 32 of the NWP general conditions have been adequately addressed by the prospective permittee, including aquatic resources inventory, aquatic life movement and breeding, migratory bird breeding, bat roosting sites, and cultural resources.

1.3 PROJECT AREA DESCRIPTION

The Project Area is located in northern New Mexico on the west slope of the Sangre de Cristo Mountain Range in the Southern Rocky Mountains. The Project Area crosses west to east through four distinct ecoregions including the Taos Plateau, Foothill Woodlands and Shrublands, Volcanic Mid-Elevation Forests and Shrublands, and Crystalline Mid-Elevation Forests and Shrublands (Griffith et al. 2006).

The western extent of the Project Area and tailing ponds area is located in the Taos Plateau, an ecoregion that is characterized by rolling to level plateau, some volcanic cones and the deep Rio Grande River gorge. Most streams within the Taos Plateau are ephemeral and intermittent. The geology of the area comprises Quaternary Eolian deposits, colluvium, piedmont and fan alluvium, and primarily Pliocene basalt and volcanic rocks. Soils comprise Aridisols and Alfisols. Vegetation is dominated by big sagebrush shrub lands with other shrubs, some grasses, and occasional piñon and juniper.

Upslope from the Taos Plateau is the Foothill Woodland and Shrublands ecoregion that consists of hills, ridges, and footslopes with moderate to high gradient perennial, intermittent, and ephemeral streams. The geology of the area is varied and includes Quaternary colluvium and alluvium deposits, sedimentary rock, and various volcanic formations. Soils include Alfisols, Inceptisols, and Entisols. Vegetation in this ecoregion is typically dominated by a combination of piñon and juniper woodlands, sagebrush, mountain mahogany stands, and Gambel oak woodlands. Varied foothill-mountain grasslands are interspersed with blue grama, prairie junegrass, or western wheatgrass.

Volcanic Mid-Elevation Forests and Shrublands occur higher in elevation than Foothill Woodland and Shrublands and are characterized by low mountain ridges, slopes, and outwash fans with moderate to high gradient perennial streams. Geology is similar to the Foothills and Woodlands and soils consist of Alfisols, Mollisols, and Inceptisols. Ponderosa pine forests dominate with understory species that may include Gambel oak, mountain mahogany, and other shrubs and grasses. At the higher elevations in this ecoregion, Douglas and white fir forests and small aspen stands may occur.

The eastern extent of the Project Area is in the Crystalline Mid-Elevation Forests and Shrublands which consists of similar physiography to the Volcanic Mid-Elevation Forests and Shrublands and similar geology though with more granitic rock. Soils comprise Alfisols, Inceptisols, and Entisols. Vegetation is similar to that found in the Volcanic Mid-Elevation Forests and Shrublands and is dominated by ponderosa pine at the lower elevations with a greater amount of Douglas and white fir, limber pine, and small aspen stands found at higher elevations.

1.3.1 **SOILS**

Eleven soil map units are crossed by the Project (NRCS 2017) with the two most prevalent being Cumulic Haploborolls, nearly level (14%) and Rock outcrop-badland complex, very steep (12%). Cumulic Haploborrolls, nearly level, are found in alluvial fans and valley sides. The parent material is alluvium derived from igneous and metamorphic rock. Soil is generally considered well drained and comprises loam and sandy clay loam. Rock outcropbandland complex, very steep, are found on mountain slopes with a typical profile consisting of bedrock. All soil units occurring within the 50-foot buffer area are presented in Table 1 and Figure 1.



201901_TailingsPipeline-ARI_RPT.docx

1.3.2 VEGETATION

Vegetation communities vary across the Project Area and generally transition from sagebrush shrub-steppe dominated communities at the western extent of the tailings pipeline to higher elevation conifer forests at the eastern extend of the tailing pipeline. The primarily vegetation communities within the Project Area include sagebrush-steppe, ponderosa pine forest, riparian, and disturbed.

Sagebrush (*Artemisia tridentata*) shrub-steppe communities are dominated by sagebrush and rabbitbrush (*Ericameria nauseosa*), with a sparse understory of grasses and forbs. These communities may also include piñon and juniper associations. Portions of the soil surface may be covered with cryptogamic crusts. This is the predominant vegetation community along the western extent of the tailing pipeline.

Ponderosa pine forest occurs at elevations from the Lower Dump Sump (7,300 feet) to the east extent of the tailings pipeline at 8,100 feet. This vegetation community is dominated by mature ponderosa pine in open stands with an understory of shrubs and herbaceous cover. Dominant understory species include smooth brome (*Bromus inermis*), Rocky Mountain juniper (*Juniperus scopularum*), big sagebrush, rabbitbrush, Gambel oak (*Quercus gambellii*), skunkbush (*Rhus aromatica*), and Wood's rose (*Rosa woodsii*). White fir (*Abies concolor*), Englemann spruce (*Picea engelmannii*), and quaking aspen (*Populus tremuloides*) increase with elevation from west to east up the Red River Canyon.

Riparian areas are present along the Red River where it is intersected by the tailings pipeline. Riparian areas in the Project Area are dominated by woody species. Narrowleaf cottonwood (*Populus angustifolia*) is the dominant tree species in riparian areas with small trees and shrubs consisting of speckled alder (*Alnus incana*), river birch (*Betula occidentalis*), narrowleaf willow (*Salix exigua*), and Wood's rose. Grasses and forbs along the Red River include redtop (*Agrostis stolonifera*), smooth brome, and field horsetail (*Equisetum arvense*).

Disturbed areas are common along the pipeline route but primarily occur along the western extent of the tailings pipeline near the tailings ponds, at the lower dump sump, and generally along the roadsides. Vegetation comprises a variety of weedy plants with cheatgrass (*Bromus tectorum*), smooth brome, and Mexican fireweed (*Bassia scoparia*) common.

1.3.3 HYDROLOGY

The Project Area is located within Hydrologic Unit Code 13020101, the Upper Rio Grande Watershed, that begins at the Colorado/New Mexico border and drains an area of approximately 3,220 square miles (USGS 2010), including 94.79 percent of Taos County (USDA 2008). The Red River is the primary hydrologic feature in the Project Area. It is

a perennial stream that originates in the Sangre de Cristo Mountains and forms a confluence with the Rio Grande River southwest of Questa. Numerous ephemeral streams designed as R4SBC (Riverine, intermittent, streambed, seasonally flooded) cross under the tailings pipeline and drain into the Red River. These ephemeral streams consist of steep, rocky drainages that flow during high precipitation events.

There are a number of man-made ditches that are crossed by the tailings pipeline including a drainage ditch that generally follows Moly Mine Road from east to west and is designated as R5UBFx (Riverine, unknown perennial, unconsolidated bottom, semi-permanently flooded, excavated) in the National Wetland Inventory (NWI). The Embargo Ditch, an Acequia, also crosses the tailings pipeline along the western portion of the Project. It is classified as R4SBCx (riverine, intermittent, streambed, seasonally flooded, excavated). The Embargo Ditch takes water from the Red River just west of the U.S. Forest Service building and apparently returns water approximately 1.5 miles downstream of Questa.



201901_TailingsPipeline-ARI_RPT.docx 1-5

2.0 METHODS

2.1 DATA REVIEW

A review of available information relative to jurisdictional WOUS was performed in-house prior to visiting the Project Area. Potential wetlands were determined by overlaying the tailings pipeline (including a 50 foot-wide buffer) and all other areas of the Project over aerial photographs of the area, topographic maps, NWI maps (USFWS 2017), and NRCS soil maps (NRCS 2017). In addition, previous environmental reports from the area were reviewed prior to conducting the onsite assessment.

2.2 AQUATIC RESOURCE DELINEATION METHODOLOGY

Trihydro conducted an onsite assessment of aquatic resources on May 9 and 10, 2018. Erik Schmude, a Trihydro biologist, led the onsite assessment. Methods used to delineate aquatic resources in the Project Area were based on a combination of desktop mapping using NWI data, photo documentation of all aquatic features crossed by the tailings pipeline, and onsite delineation of aquatic resources where Project impacts are expected (i.e. bridge crossings, Lower Dump Sump). These methods were discussed with the Corps prior to the onsite assessment.

According to NWI data, the Project Area intersects a number of aquatic resources including the Red River and adjacent wetlands, the Embargo Ditch, a number of unnamed ditches and ephemeral drainages classified as intermittent riverine, and isolated emergent wetlands associated with the Lower Dump Sump. Onsite determination of aquatic resource presence and boundaries were completed only in areas where impacts may have been expected at crossings of the Red River and at the Lower Dump Sump. However, every aquatic resource indicated in the NWI dataset was field checked and photographed.

For areas where impacts are expected, wetland determinations were completed using the Routine Determination protocol described in the *Corps of Engineers Wetland Delineation Manual* (USACE 1987). Wetland determination field methods followed the *Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Western Mountains, Valley, and Coasts* (USACE 2010) based on location and vegetation in the area (primarily ponderosa pine forest). Determinations of wetlands included an evaluation of plant species and percent cover by vegetation strata, digging of a soil pit to observe soil characteristics and presence of hydric soil indicators, and observations of hydrological indicators at the soil pit location. Wetland determination data forms were completed for each wetland and a paired upland observation point. For locations were no wetlands were found, a single upland point was evaluated and documented. If aquatic resources and their boundaries matched NWI data, no field delineation was completed, only



201901_TailingsPipeline-ARI_RPT.docx

verification of the presence of the aquatic resource. If NWI was found to be inaccurate, based on the field assessment, then the aquatic resource information and/or boundaries were updated for the segment of the pipeline (50 foot wide area) crossing the resource. Wetland determination points and any updated aquatic resource boundaries were recorded using a Trimble sub-meter accuracy global positioning system (GPS) and photographs were taken of each feature. A unique ID was given to each determination point. Photographs of additional aquatic resources, with no expected impacts, were also given unique IDs.

Wetlands were identified in the field as areas having positive evidence of three environmental parameters: hydric soils, wetland hydrology, and hydrophytic vegetation as indicated by greater than 50% OBL, FACW, or FAC species or less than or equal to 3.0 prevalence index. Aquatic resources were classified using the Cowardin system (Cowardin et al. 1979). A quatic resources within the Project Area include Palustrine Emergent Wetlands (PEM), Palustrine Scrubshrub (PSS), Palustrine Forested (PFO), and various River classifications streams, ditches, and other drainage features.

PEM wetlands are those aquatic features dominated by herbaceous emergent plants. Plant species commonly found in PEM wetlands in northern New Mexico include hydrophytic grasses, cattails (*Typha angustifolia*), sedges (*Carex* spp.), and rushes (*Juncus* spp.). PSS wetlands are those aquatic features dominated by shrubs under 20 feet tall or with trunks or stems less than 3 inches in diameter. Common PSS plant species found in this region include willow (*Salix* spp.), alder (*Alnus* spp.) and small cottonwoods (*Populus* spp.). PFO wetlands are dominated by trees greater than 20 feet high with stems greater than 3 inches in diameter. PFO wetland species composition commonly includes cottonwood, larger willows, and river birch (*Betula occidentalis*). Combinations of these communities may also be present in a wetland.

3.0 RESULTS

This section provides a discussion of the results of the onsite and desktop aquatic resource inventory including detailed information pertaining to each area where temporary impacts to aquatic resources are expected. Wildlife and cultural resource assessments required for the PCN are presented in section 3.1.2 and 3.2.

3.1 AQUATIC RESOURCE FINDINGS

Aquatic resources intersected by the Project Area include the Red River (4 crossings), 13 ephemeral streams, the Embargo ditch, 4 unnamed man-made ditches, 7 PSS wetlands, and 2 PFF wetlands, according to information gathered during the onsite assessment on May 9 and 10, 2018. The NWI data showed that Columbine Creek, an intermittent stream, was crossed by the Project. However, the onsite assessment indicated this stream intersects the Red River to the east of the NWI location and is not actually crossed by the Project. In addition, NWI data indicated the presence of two PEM wetlands in and adjacent to the Lower Dump Site; however, these areas were checked during the onsite delineation and no wetlands indicators were observed for each area.

A summary of aquatic resources delineated in the onsite wetland assessment are presented in Table 2 which includes a total of 0.53 acres of perennial riverine (R3RB1H, Red River), and 0.06 of PSS wetland present within the 50 foot wide pipeline corridor. These acreage calculations are based NWI data with slight modifications in areas of river crossings where onsite wetland assessments were completed on May 9 and 10, 2018. For the purpose of this project, all areas delineated riverine have been assumed to be WOUS. Figures 2 through 9 show all aquatic resources in the Project Area.

Based on this inventory, and the proposed construction footprints for removal of the pipeline, temporary impacts to wetlands and waters will be limited to two of the Red River bridge crossings, the Elevated Trestle and Thunder Bridge, and include temporary impacts to 0.137 acre of riverine areas (assumed to be WOUS) and 0.171 acre of scrub-shrub wetland (Table 3). No impacts to the Embargo Ditch or any other irrigation ditches are expected to occur. Temporary impact acreage calculations are based on the onsite assessment and delineation of resource boundaries on May 9 and 10 and NWI data. Where construction footprints for the proposed activity extended beyond on the buffer the resource boundary delineated in the field, the NWI dataset was used to calculate impacts. No permanent loss of wetlands or WOUS will occur. Figures 6 and 7 in the PCN show areas where temporary impacts to aquatic resources are expected.

The results from each of the 10 field determination points are included in digital copies of Wetland Determination Data Forms in Appendix A. Photographs of each determination point as well as photographs of each of the ponds and



201901_TailingsPipeline-ARI_RPT.docx 3-1

streams, are provided in Appendix B. All aquatic resources including determination points, NWI data, field verified aquatic resource, and photo points are shown in Figures 3-9.

3.1.1 AQUATIC RESOURCES IMPACTED BY PROJECT

As described in Section 2.0, onsite delineation of aquatic resources was completed in areas where construction activities associated with removal of the tailings pipeline may occur. Temporary impacts will include disturbance to aquatic resources resulting from temporary installation of diversion structures and diversion pipelines, vehicle and foot traffic, removal of concrete supports during pipeline removal. Five distinct areas were assessed. These areas include the crossing of potential wetlands at the Lower Dump Sump (according to NWI data) and four pipeline/bridge crossings of the Red River. A summary of findings for each of these areas is presented below.

3.1.1.1 LOWER DUMP SUMP

According to NWI data, there are two PEM wetlands present at the Lower Dump Sump including one onsite and one offsite, where impacts may occur. Determination points (Q-1 and Q-2) were placed in each of the potential wetlands. No wetland indicators were observed at either location indicating that wetlands are absent from this area (Figure 4). Vegetation, soils, and hydrology were found to be highly disturbed at both locations. Both areas are within man-made, bermed depressions constructed to contain tailings materials. Vegetation in both areas was sparse and inhabited by weedy plant species common associated with disturbed areas including Mexican fireweed, cheatgrass, and hairy golden aster (*Heterotheca villosa*). Soils showed no sign of hydric indicators. Based on the delineation and proposed demolition footprint, no impacts to WOUS or wetlands will occur at this location.

3.1.1.2 RED RIVER CROSSING (ELEVATED TRESTLE)

The tailings pipeline crosses the Red River, on an elevated trestle, from 36°41'41.97"N, 105°35'45.20"W to 36°41'45.07"N, 105°35'48.90"W. From the east, this is the 4th crossing of the Red River as shown in Figure 3. The pipeline is suspended above the river by an elevated steel trestle (Photo 9 and Photo 10 of Appendix B). The river is approximately 26 feet wide at the crossing. In order to perform the pipeline removal, the project will involve the installation of two temporary diversion structures and two 24-inch diversion pipelines. Pipeline removal would consist of removing two 14-inch steel pipes, removal of one 14" wrapped pipe, and removal of concrete supports located at the east and west bank of the river, within the river channel. NWI data indicates that a small amount of PFO wetland occurs approximately 20 feet to the south of the pipeline on both the east and west side of the river.

Two determination points were assessed at this location including Q-3a placed 20 feet and Q-3b placed approximately 100 feet from the edge of the ordinary high-water mark (OHWM) of the river. No wetlands were documented within the 50-foot wide pipeline buffer based on a lack of two or more wetland indicators.

Hydrophytic vegetation was present at Q-3a (primarily water birch); however, no hydrology indicators were observed and hydric soil indicators were weak with no depleted matrix. No wetland indicators were observed at Q-3b; however, hydric soil indicators were lacking at both locations. As is indicated by the NWI data, wetlands are absent beneath the pipeline trestle. The NWI data does indicate that wetland is present just inside the 50-foot buffer, along the south end. However, no wetland was documented in this area based on conditions observed at the determination points and an assessment of onsite conditions. Only WOUS would be affected within the 50-foot buffer. The river boundary indicated by NWI was found to be accurate (Figure 3).

3.1.1.3 RED RIVER CROSSING (EAST OF RANGER STATION)

The tailings pipeline crosses the Red River at approximately 36°42′6.96″N, 105°34′47.96″W east of the ranger station. From the east, this is the 3rd crossing of the Red River as shown in Figure 5. The pipeline is suspended above the river by a steel bridge (Photo 20a and 20b of Appendix B). The river is approximately 21 feet wide at the crossing. Pipeline removal would involve removal of two 14-inch steel pipes from the bridge structure. The bridge structure shall remain in place. Based on the delineation and proposed construction footprint, no impacts to WOUS or wetlands will occur at this location. The two sections of 14-inch steel pipe will be pulled outised of the WOUS.

NWI data indicates that no wetlands occur on either side of the riverine area. Two determination points were assessed at this location including Q-4a placed on the west side of the river and Q-4b placed on the east side of the river. Q-4b was placed in an area just outside of the apparent riparian area. No wetland indicators were observed. Vegetation was dominated by Rocky Mountain juniper. Vegetation has been removed in the 50-foot buffer on the both banks, on the south side of the pipeline. In this area, the river bank consists of river rock and concrete.

Determination point Q-4a was placed within the riparian area, at a low spot along the west band of the river. Hydrophytic vegetation was present with water birch the dominant woody plant. However, hydric soil and hydrology indicators were not met at this location. Some redoximorphic features were observed; however, the soil matrix was not depleted enough to be considered a wetland soil.

NWI was correct in that no wetlands are present, at this crossing. The exact location of the riverine area was found to be inaccurate by approximately 40 feet. The actual boundary of the riverine area was delineated and is shown on Figure 5.



201901_TailingsPipeline-ARI_RPT.docx 3-3

3.1.1.4 RED RIVER CROSSING (THUNDER BRIDGE)

The tailings pipeline crosses the Red River at approximately 36°41'4.29"N, 105°31'47.83"W. From the east, this is the 2nd crossing of the Red River as shown in Figure 7. This is known at the Thunder Bridge crossing. The river is approximately 25 feet wide at the crossing. The pipeline is suspended above the river by a wide steel bridge with wooden planks on top (Photo 21, 21a, and 21b of Appendix B). In order to perform the pipeline removal, the project will involve the installation of two temporary diversion structures and two 24-inch diversion pipelines. Pipeline removal would consist of removing two 14-inch steel pipes, and removal of the concrete supports and abutments located at the east and west bank of the river.

NWI indicates that the 50-foot pipeline corridor intersects a small amount of palustrine forested wetland and palustrine scrub-shrub wetland to the east and north of the crossing and palustrine scrub-shrub wetland to the west and south of the crossing. Two determination points were assessed at this location, one on the west side of the crossing and one on the east side of the crossing. The exact location of the riverine area was found to be inaccurate and was delineated in the field. The area to the east of the river sloped steeply into an upland area. No hydric soil or hydrology indicators were observed at point Q-5b. However, hydrophytic vegetation was observed as evidenced by 80 percent FAC and FACW species with narrowleaf cottonwood, speckled alder and Bebb's willow (*Salix bebbiana*) the dominant woody plants in the riparian zone.

All three wetland indicators were observed at point Q-5a, on the west side of the river. Hydric soil indicators observed include 30 percent redox concentrations in pore linings in a depleted matrix (10YR 4/2). In addition, hydrology indicators were observed including saturation (6" below ground surface), algal mat, iron deposits, water-stained leaves, and drainages patterns. All dominant plant species were FAC, FACW, or OBL species with water birch and willows dominating the shrub stratum. The boundary the PSS wetland as indicated by NWI data was found to be slightly inaccurate and was delineated in the field (Figure 7), within the 50-foot pipeline buffer. The NWI data was correct in classifying the wetland to the west of the river crossing as a PSS wetland.

3.1.1.5 1ST RED RIVER CROSSING (BY COLUMBINE PARK)

The tailings pipeline crosses the Red River at approximately 36°40′53.33″N, 105°30′53.97″W by Columbine Park. From the east, this is the 1st crossing of the Red River as shown in Figure 7. The pipeline is suspended above the river by a steel bridge (Photo 22a and 22b of Appendix B). The river is approximately 26 feet wide at the crossing. Pipeline removal would involve removal of two 14-inch steel pipes, the bridge cantilever, and the GWW liner. NWI data indicates that no wetlands occur on either side of the riverine area. Two determination points were assessed at this location including Q-6a placed 5 feet and Q-6b placed approximately 15 feet from the edge of the OHWM of the river. Hydrophytic vegetation was present at both locations; however, hydric soil indicators were lacking at both locations.



Therefore, NWI was correct in that no wetland is present, adjacent to the Red River, at this crossing. The exact location of the riverine area was found to be inaccurate by approximately 75 feet. The actual boundary of the riverine area was delineated and is shown on Figure 7. Narrowleaf cottonwood is the dominant woody species along the riparian area with sparse shrubs, grasses, and forbs in the understory. Sphagnum moss was observed in an area within 5 or 6 feet of the riverine area.

3.1.2 TERRESTRIAL AND AQUATIC WILDLIFE

During the onsite aquatic resource assessment, a cursory wildlife survey was conducted to identify any potential terrestrial or wildlife issues for the Project. This included documentation of any raptor or migratory bird nests, bat roosts, endangered species, aquatic life movements, or fish spawning areas potentially impacted by the Project. In addition, potential presence of threatened or endangered (T&E) species was assessed for the Project Area.

An official species list was provided by the USFWS New Mexico Ecological Services Field Office and indicates a total of five T&E species may be present in the area of the Project (Appendix C). T&E species on the list include Canada lynx (*Lynx Canadensis*), New Mexico meadow jumping mouse (*Zapus hudsonius luteus*), Mexican spotted owl (*Strix occidentalis lucida*), Southwestern willow flycatcher (*Empidonax traillii extimus*), and yellow-billed cuckoo (*Coccyzus americanus*). There are no Critical Habitats within the Project Area. The New Mexico meadow jumping mouse and southwestern willow flycatcher are also designated as endangered by NMGF. All federal T&E species are considered rare for Taos county and there are no documented occurrences in or near the Project Area. Although riparian and wetland habitat is available, the closest occurrence of New Mexico jumping mouse is an individual trapped at Taos Ski Valley in 1966 (BISON-M 2017). None of these species are expected to occupy habitats affected by the Project.

Wildlife species observed during the survey included a variety of mammals and birds. Mammals in the area included big horn sheep (*Ovis Canadensis*), Abert's squirrel (*Sciurus aberti*), cottontail (*Sylvilagus* sp.), sign of elk (*Cervus elaphus*) and mule deer (*Odocoileus hemionus*), and sign of roosting bats (*Vespertilionidae*). Birds observed included a northern goshawk (*Accipiter gentilis*), western meadowlarks (*Sturnella neglecta*), spotted towhees (*Pipilo maculatus*), northern flickers (*Colaptes auratus*), bushtits (*Psaltriparus minimus*), barn swallows (*Hirundo rustica*), violet-green swallows (Tachycineta thalassina), Canada geese (Branta canadensis), mallard ducks (Anus platyrhyncos), a western tanager (*Piranga ludoviciana*), yellow-rumped warblers (*Setophaga coronate*), dark-eyed juncos (*Junco hyemalis*), house finches (*Haemorhous mexicanus*), American robins (*Turdus migratorius*), American crows (*Corvus brachyrhynchos*), and turkey vultures (*Cathares aura*). No raptor nests were observed in the area. Two unoccupied migratory bird nests were observed; a northern flicker cavity nest near the Embargo Ditch, and a cup nest built by an unknown species, beneath the bridge at the river crossing east of the Ranger Station.



201901_TailingsPipeline-ARI_RPT.docx 3-5

Bridge crossings were checked for potential bat roost sites. With the exception of Thunder Bridge (2nd Red River Crossing) no suitable roosting habitat was observed at the bridges. The Thunder Bridge has a number of microhabitat features which could be used by bats; however, no signs of bat use were observed. An acoustic bat monitor was used during the day to check for ultrasonic vocalizations beneath the bridge. No bat vocalizations were recorded. A bat night roost was observed inside a large concrete culvert adjacent to the tailings pipeline (Photo 26 of Appendix B). This culvert crosses below Highway 38. Bat droppings were prevalent in the culvert indicating this is a commonly used roost site during the summer months. Suitable day roost or hibernacula habitat was not observed at this site. The culvert will not be removed during pipeline removal.

A number of game fish occur in the section of the Red River crossed by the pipeline. These game fish include triploid (sterile) rainbow trout (*Oncorhychus mykiss*), raised in a hatchery downstream of the Project Area, and an introduced, wild brown trout (*Salmo trutta*) population. Stream substrate at the river crossing consisted of primarily cobbles. Spawning areas (i.e. gravel beds) were not observed in areas where concrete structures are to be removed from the stream.

3.1.3 OTHER WETLANDS ASSESSMENT

CEMC contracted with URS Corporation (URS) (URS 2013 and 2014) to assess wetlands in locations near the pipeline removal corridor shown on Figures 1 through 9 of this report. The areas delineated by URS were outside of the scope of this ARI report. Copies of the URS reports are presented in Appendix D. Wetlands were determined to be present outside of the pipeline removal corridor, between the west and east ends of the Questa Tailings Pipeline Removal Project (Figure 1). The pipeline removal project will not impact the wetlands delineated by URS.

3.2 CULTURAL RESOURCES

CEMC contracted with Arcadis to evaluate irrigation ditches within the pipeline removal corridor as potential historic resources and to evaluate if the pipeline removal activities will impact historic ditches. Arcadis submitted two reports (Arcadis 2018a and 2018b) to the New Mexico Minerals and Mining Division (MMD) and the New Mexico Historic Preservation Division (HPD). A summary of the findings as reported in personal communications is presented in Appendix E. Future work plans submitted to MMD and EPA will propose grouting pipeline segments in place if those areas determine to present high risk of impacts to historic irrigation ditches.

3-6 201901_TailingsPipeline-ARI_RPT.docx

4.0 CONCLUSIONS

Temporary impacts to wetlands and waters are limited to two of the four Red River bridge crossings, the Elevated Trestle and Thunder Bridge and include temporary impacts to 0.137 acre of riverine areas (WOUS) and 0.171 acre of wetland. No impacts to the Embargo Ditch or any other irrigation ditches are expected to occur. Temporary impact acreage calculations are based on the onsite assessment and delineation of resource boundaries on May 9 and 10, 2018 and the NWI dataset. No permanent impacts to wetlands or WOUS will occur.

No raptor nests were observed in the area, during the onsite assessment. Two migratory bird nests were found; however, both were unoccupied. Therefore, no direct impacts to breeding birds are expected. An onsite assessment of the bridge crossings indicated that there are no roosting bats in these areas. A bat night roost was identified in a large concrete culvert at Photo Point 26 of Appendix B. This point is where a large number of bat droppings were observed. This culvert will not be removed and because pipeline removal will be short-lived and completed during the daytime. No significant impacts to bats are expected. No fish spawning areas were observed at the pipeline crossing of the Red River. No adverse impacts to aquatic species movements are anticipated during removal of the pipeline because the project will be short-lived.



201901_TailingsPipeline-ARI_RPT.docx 4-1

5.0 REFERENCES

- Arcadis. 2018a. Chevron Questa Mine Tailings Pipeline Removal Project Cultural Resources Survey, Taos County, New Mexico (NMCRIS No. 139651). January 12, 2018.
- Arcadis. 2018b. Chevron Questa Mine Tailings Pipeline Removal Project Cultural Resources Survey, Taos County, New Mexico (NMCRIS No. 140384). May 29, 2018.
- Arcadis. 2018c. Questa Tailings Pipeline Removal. May 18, 2018. Available e-mail: confidential.
- Arcadis. 2018d. Questa Tailings Pipeline Removal. May 25, 2018. Available e-mail: confidential.
- Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. Classification of Wetlands and Deepwater Habitats of the United States. U.S. Fish and Wildlife Service, Office of Biological Services, Washington, D.C. Publ. No. FWS/OBS-79/31. 107 p.
- Griffith, G.E., Omernik, J.M., McGraw, M.M., Jacobi, G.Z., Canavan, C.M., Schrader, T.S., Mercer, D., Hill, R., and B.C. Moran. 2006. Ecoregions of New Mexico (color poster with map, descriptive text, summary tables, and photographs): Reston, Virginia, U.S. Geological Survey (map scale 1:1,400,000).
- URS Corporation (URS). 2013. Questa Removal Action Wetland Assessment Report, Revision 1. June 28, 2013.
- URS. 2014. Historic Tailing Spills Removal Action Completion Report, Chevron Questa Mine Superfund Site, Revision 1, Appendix C, Lower Dump Sump Wetland Delineation Report. September 26, 2014.
- U.S. Army Corps of Engineers (Corps). 1987. Corps of Engineers Wetlands Delineation Manual, Wetlands Research Program Technical Report Y-87-1. Final Report January 1987.
- U.S. Army Corps of Engineers (Corps). 2010. Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Western Mountains, Valley, and Coast Region (Version 2.0). U.S. Army Engineer Research and Development Center, Vicksburg, Mississippi.
- United States Department of Agriculture (USDA). 2008. Upper Rio Grande Watershed Hydrologic Unit Code 13020101 Rapid Assessment. Natural Resources Conservation Service, Lakewood, Co.



201901_TailingsPipeline-ARI_RPT.docx 5-1

U.S. Department of Agriculture, Natural Resources Conservation Service (NRCS). 2017. Soil Survey of Taos County and Parts of Rio Arriba and Mora Counties, New Mexico.

https://websoilsurvey.sc.egov.usda.gov/App/WebSoilSurvey.aspx.

U.S. Department of the Interior Fish and Wildlife Service (FWS). 2017. National Wetlands Inventory. Wetlands Mapper. http://wetlands.fws.gov/.

TABLES



TABLE 1. SOIL MAP UNITS IN THE PROJECT AREA

Soil Code	Soil Map Unit Name	Square Feet	Acres
CUB	Cumulic Haplaquolls, nearly level	232,160.24	5.33
CYB	Cumulic Haploborolls, nearly level	629,025.73	14.44
FeC	Fernando clay loam, 3 to 5 percent slopes	75,972.85	1.74
FLB	Fluvents, nearly level	38,939.44	0.89
LoB	Loveland clay loam, 0 to 3 percent slopes	22,273.01	0.51
RdG	Rock outcrop-Badland complex, very steep	505,220.28	11.60
RUG	Rock outcrop-Ustorthents complex, very steep	279,100.10	6.41
SED	Sedillo-Silva association, strongly sloping	177,506.59	4.08
SmB	Silva loam, 0 to 2 percent slopes	65,450.85	1.50
TeB	Tenorio loam, 0 to 3 percent slopes	13,264.50	0.30
TeC	Tenorio loam, 1 to 5 percent slopes	202,163.02	4.64

This summary is for the 50' Wetland Inventory Area, ending at the west end of the pipeline removal project.

1-201901_Soils_TBL-1.xlsx

TABLE 2. AQUATIC RESOURCES WITHIN THE PROJECT AREA *

Cowardin Code	Wetland Type	Acres	Crossing
	Riverine - Upper Perennial Stream with		1st Red River Crossing (by
R3RB1H	Rock Bottom	0.42	Columbine Park)
PSS1C	Freshwater Scrub-shrub Wetland	0.06	2nd Red River Crossing (Thunder Bridge)
R3RB1H	Riverine - Upper Perennial Stream with Rock Bottom	0.05	2nd Red River Crossing (Thunder Bridge)
R3RB1H	Riverine - Upper Perennial Stream with Rock Bottom	0.03	3rd Red River Crossing (east of Ranger Station)
R3RB1H	Riverine - Upper Perennial Stream with Rock Bottom	0.03	4th Red River Crossing (Elevated Trestle)

Total Riverine (WOUS) 0.53
Total Wetland 0.06

2-201901_AquaticResourceAcres_TBL-2.xlsx

^{*} Project Area = pipeline buffered by 50 feet


TABLE 3. AQUATIC RESOURCES IMPACTS SUMMARY


COWARDIN CODE	RESOURCE TYPE	ACRES	NOTES
	Diversional Harrison Demonstrati Charles		
R3RB1H	Riverine - Upper Perennial Stream with Rock Bottom (from delineation)	0.047	2nd Red River Crossing (Thunder Bridge)
	Di i la		
R3RB1H	Riverine - Upper Perennial Stream with Rock Bottom (from NWI)	0.007	2nd Red River Crossing (Thunder Bridge)
D0040	PSS1C - Freshwater Scrub-shrub	0.0505	0 10 10 0 1 (7)
PSS1C	Wetland (from delineation)	0.0565	2nd Red River Crossing (Thunder Bridge)
PSS1C	PSS1C - Freshwater Scrub-shrub Wetland (from NWI)	0.0105	2nd Red River Crossing (Thunder Bridge)
	Divering Upper December Street		
R3RB1H	Riverine - Upper Perennial Stream with Rock Bottom (from delineation)	0.031	4th Red River Crossing (Elevated Trestle)
	Riverine - Upper Perennial Stream		
R3RB1H	with Rock Bottom (from NWI)	0.052	4th Red River Crossing (Elevated Trestle)
	PSS1C - Freshwater Scrub-shrub		
PSS1C	Wetland (from delineation)	0.00	4th Red River Crossing (Elevated Trestle)
	PSS1C - Freshwater Scrub-shrub		
PSS1C	Wetland (from NWI)	0.104	4th Red River Crossing (Elevated Trestle)
-	TOTAL Riverine	0.137	
	ΓΟΤΑL Wetland	0.171	

3-201901_AquaticResourceImpacts_TBL-3.xls

FIGURES







MAP INDEX

- 2. NWI DATA MAY BE LIMITED TO REMOTE SENSING OF PLANT AND WATER SIGNATURES WITH LIMITED OR NO IN-FIELD CONFIRMATION.
- 3. SOME OF THE AQUATIC FEATURES IN THE NWI DO NOT EXIST DUE TO THE NATURE OF THE DATA, DEVELOPMENT, AND OTHER ACTIVITIES IN THE AREA. FIELD CONFIRMATION OF WETLANDS LOCATIONS IS RECOMMENDED PRIOR TO PROCEEDING WITH PIPELINE REMOVAL PROJECT.




Trihydro


1252 Commerce Drive Laramie, WY 82070 www.trihydro.com (P) 307/745.7474 (F) 307/745.7729


NWI WETLANDS OVERVIEW


CEMC QUESTA MINE QUESTA, NEW MEXICO


Drawn By: DH Checked By: BH Scale: 1 " = 0.6 Miles Date: 5/22/18 File: Fig2_ARI_Overview.mxd























APPENDIX A

WETLAND DETERMINATION DATA FORMS



Project/Site: Questa Pipeline Removal Project	(City/Cou	_{unty:} Questa/T	aos	Sampling Date:	5/9/2018
Chevron Applicant/Owner:		,	,	State: NM	Sampling Point:	Q-1
Erik Schmudo, Tony Kunilik		Section		nge:		
Landform (hillslope, terrace, etc.): man-made depression					Slo	pe (%): 0-1
Subregion (LRR): LRRE						
Soil Map Unit Name: Tenorio loam, 1 to 5 % slopes				NWI classific	PEM1Ch	
Are climatic / hydrologic conditions on the site typical for this	time of yea	ar? Yes	s ✓ No	(If no, explain in R	emarks.)	
Are Vegetation yes, Soil yes, or Hydrology yes significant						/ No
Are Vegetation no , Soil no , or Hydrology no na				eded, explain any answe		
SUMMARY OF FINDINGS – Attach site map s						atures, etc.
Hydrophytic Vegetation Present? Yes No						
Hydric Soil Present? Yes No			s the Sampled vithin a Wetlar		No <u></u> ✓	
Wetland Hydrology Present? Yes No Remarks:						-
Disturbed area, previously created holding pond for to	ailings					
VEGETATION – Use scientific names of plant	s.					
Tree Stratum (Plot size: 30'			nant Indicator	Dominance Test work		
1				Number of Dominant Sport That Are OBL, FACW, or		(A)
2.				Total Number of Domin		
3				Species Across All Stra	_	(B)
4				Percent of Dominant Sp	oecies n	
Sapling/Shrub Stratum (Plot size: 15'	-	= Total	Cover	That Are OBL, FACW,		(A/B)
1. (1 lot size				Prevalence Index wor	ksheet:	
2.				Total % Cover of:		ly by:
3.				OBL species		
4				FACW species1	x 2 = x 3 = _3	
5				FAC species 1 1	x 3 = <u>0</u>	
Herb Stratum (Plot size: 5'		= Total	Cover		x 5 =	
	7	ves	NL	Column Totals: 2		(B)
2. Heterotheca villosa	8	yes	NL			\ /
3. Bassia scoparia	2	no	FAC	Prevalence Index Hydrophytic Vegetation		
4. Crytantha cinera	1	no	NL	1 - Rapid Test for H		ation
5. Verbascum thaspus	1	no	FACU	2 - Dominance Tes		
6				3 - Prevalence Inde	ex is ≤3.0 ¹	
7				4 - Morphological A		
8					s or on a separate	sheet)
9				5 - Wetland Non-Va		(Evoloin)
10				Indicators of hydric soi		
11	40	= Total	Cover	be present, unless distu		
Woody Vine Stratum (Plot size: 30'		_= 10tai	Cover		-	
1				Hydrophytic		
2				Vegetation Present? Yes	s No_ <u>'</u>	/
% Bare Ground in Herb Stratum 81		= Total	Cover		J 140	-
Remarks:				<u> </u>		

SOIL	Sampling Point: Q-1

(inches)	(Olor (mojot)			('- '\			12	T = 0 = 0.0	
	Color (moist)	%_		or (moist)	_ %	Type ¹	Loc ²	Texture	Remarks
0-18	7.5YR 3/2	99	7.5YF	R 5/8	_ 1		M	silty clay loa	n disturbed soil
			_						
								-	
<u> </u>									
Typo: C-Co	ncentration, D=D	nolotion F	M-Poduo	od Matrix C	S-Covere	d or Coate	nd Sand Gr	rains ² Lo	cation: PL=Pore Lining, M=Matrix.
• • • • • • • • • • • • • • • • • • • •	ndicators: (Appl						d Sand Oi		ors for Problematic Hydric Soils ³ :
Histosol				ndy Redox		· · · · · ·			m Muck (A10)
	ipedon (A2)			ipped Matrix	. ,				d Parent Material (TF2)
Black His				amy Mucky		1) (except	MLRA 1)		y Shallow Dark Surface (TF12)
	n Sulfide (A4)			amy Gleyed			,		er (Explain in Remarks)
	Below Dark Surfa	ace (A11)		pleted Matri					
Thick Da	rk Surface (A12)		Re	dox Dark Su	urface (F6)				ors of hydrophytic vegetation and
	ucky Mineral (S1)			pleted Dark		- 7)			and hydrology must be present,
	leyed Matrix (S4)		Re	dox Depres	sions (F8)			unle	ss disturbed or problematic.
Restrictive L	ayer (if present)								
Type:									
	haa\.							Hydric Soi	I Present? Yes No <u></u>
emarks:	hes):								
emarks:	ЭY								
YDROLOG Vetland Hyd	GY Irology Indicator	s:							
YDROLOG Vetland Hyd	GY Irology Indicator ators (minimum o	s:		•	-				ndary Indicators (2 or more required)
YDROLOG Vetland Hyd Primary Indicator Surface N	GY Irology Indicator ators (minimum o Water (A1)	s:		_ Water-Sta	ained Leav		xcept		Vater-Stained Leaves (B9) (MLRA 1, 2
YDROLOG Vetland Hyd Primary Indic Surface \ High Wat	GY Irology Indicator ators (minimum o Water (A1) ter Table (A2)	s:		_ Water-Sta	ained Leav		xcept	V	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B)
YDROLOG Vetland Hyd Primary Indice Surface \ High Wat Saturatio	GY Irology Indicator ators (minimum o Water (A1) ter Table (A2) in (A3)	s:		_ Water-Sta _ MLRA _ Salt Crus	ained Leav 1, 2, 4A, a t (B11)	and 4B)	xcept	·	Vater-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10)
YDROLOG Vetland Hyd Primary Indic Surface \ High Wat Saturatio Water Ma	GY Irology Indicator ators (minimum o Water (A1) ter Table (A2) in (A3) arks (B1)	s:		Water-Sta MLRA Salt Crus Aquatic Ir	ained Leav 1, 2, 4A, a t (B11) nvertebrate	and 4B) es (B13)	xcept	[Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2)
YDROLOG Vetland Hyd Primary Indic Surface \ High Wat Saturatio Water Ma	Irology Indicator ators (minimum o Water (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2)	s:		Water-Sta MLRA Salt Crus Aquatic Ir Hydroger	ained Leav 1, 2, 4A, a t (B11) nvertebrate Sulfide O	es (B13) dor (C1)		\ [[Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (CS
YDROLOG Vetland Hyd Primary Indic Surface N High Wat Saturatio Water Ma Sedimen Drift Dep	Irology Indicator ators (minimum o Water (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3)	s:		Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized	ained Leav 1, 2, 4A, and the (B11) Invertebrated and Sulfide Or Rhizosphe	es (B13) dor (C1) eres along	Living Roc	\ [5 ots (C3) \(\frac{}{} \)	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (CS Geomorphic Position (D2)
YDROLOG Vetland Hyd Primary Indica Surface N High War Saturatio Water Ma Sedimen Drift Dep Algal Ma	Irology Indicator ators (minimum o Water (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4)	s:		Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence	ained Leav 1, 2, 4A, and t (B11) and t (B	es (B13) dor (C1) eres along ed Iron (C4	Living Roc	\\ \text{C3)} \frac{\sqrt{0}}{\sqrt{0}} \text{C3}	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (CS Geomorphic Position (D2) Shallow Aquitard (D3)
YDROLOG Vetland Hyd Primary Indica Surface N High Wat Saturatio Water Ma Sedimen Drift Dep Algal Ma Iron Dep	Irology Indicator ators (minimum o Water (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5)	s:		Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Irr	ained Leav 1, 2, 4A, at t (B11) overtebrate a Sulfide O Rhizosphe of Reduce	es (B13) dor (C1) res along ed Iron (C4 on in Tille	Living Roo I) d Soils (C6	V [[[[[S] S] S]	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C8) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5)
YDROLOG Wetland Hyd Primary Indic Surface N High Wat Saturatio Water Ma Sedimen Drift Dep Algal Mat Iron Depo	Irology Indicator ators (minimum o Water (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5) Soil Cracks (B6)	s: one requ	ired; checl	Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Ir Stunted o	ained Leav a 1, 2, 4A, a t (B11) envertebrate a Sulfide O Rhizosphe of Reduce on Reduction or Stressed	es (B13) dor (C1) dors along ed Iron (C4 on in Tiller Plants (D	Living Roo I) d Soils (C6	V C S ots (C3)	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (CS) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
YDROLOG Vetland Hyd Primary Indic Surface N High War Saturatio Water Ma Sedimen Drift Dep Algal Ma Iron Dep Surface S Inundatio	Irology Indicator ators (minimum o Nater (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5) Soil Cracks (B6) on Visible on Aeria	s: one requ	ired; checl	Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Irr	ained Leav a 1, 2, 4A, a t (B11) envertebrate a Sulfide O Rhizosphe of Reduce on Reduction or Stressed	es (B13) dor (C1) dors along ed Iron (C4 on in Tiller Plants (D	Living Roo I) d Soils (C6	V C S ots (C3)	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C8) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5)
YDROLOG Vetland Hyd Vetland Hyd Vetland Hyd Surface N High Wat Saturatio Water Ma Sedimen Drift Dep Algal Ma Iron Dep Surface S Inundatio Sparsely	Irology Indicator ators (minimum o Water (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5) Soil Cracks (B6) on Visible on Aeria Vegetated Conca	s: one requ	ired; checl	Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Ir Stunted o	ained Leav a 1, 2, 4A, a t (B11) envertebrate a Sulfide O Rhizosphe of Reduce on Reduction or Stressed	es (B13) dor (C1) dors along ed Iron (C4 on in Tiller Plants (D	Living Roo I) d Soils (C6	V C S ots (C3)	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (CS) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
YDROLOG Vetland Hyd Primary Indica Surface N High Wat Saturatio Water Ma Sedimen Drift Dep Algal Ma Iron Depo Surface S Inundatio Sparsely	Irology Indicator ators (minimum o Water (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5) Soil Cracks (B6) on Visible on Aeria Vegetated Conca	s: one requ Il Imagery ve Surfac	ired; checl	Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Ir Stunted of	ained Leav a. 1, 2, 4A, at t (B11) avertebrate a Sulfide O Rhizosphe of Reduce on Reduction or Stressed splain in Re	es (B13) dor (C1) dor (C1) dor (C2) dor in Tiller Plants (Demarks)	Living Roo I) d Soils (C6 1) (LRR A	V C S ots (C3)	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (CS) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
YDROLOG Vetland Hyd Primary Indic Surface N High War Saturatio Water Ma Sedimen Drift Dep Algal Ma Iron Dep Surface S Inundatio Sparsely Field Observ	Irology Indicator ators (minimum o Nater (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5) Soil Cracks (B6) on Visible on Aeria Vegetated Concar ations: er Present?	s: fone requ Il Imagery ve Surfac	ired; checl	Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Ir Stunted of Other (Ex	ained Leav a 1, 2, 4A, at t (B11) avertebrate a Sulfide O Rhizosphe of Reduce on Reduction or Stressed applain in Research	es (B13) dor (C1) dor (C1) dor (C2) dor (C2) on in Tiller Plants (Demarks)	Living Roo I) d Soils (C6 1) (LRR A	V C S ots (C3)	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (CS) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
YDROLOG Vetland Hyd Vetland Hyd Vetland Hyd Surface N High War Saturatio Water Ma Sedimen Drift Dep Algal Ma Iron Dep Surface S Inundatio Sparsely Field Observ Vater Table	Irology Indicator ators (minimum o Nater (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5) Soil Cracks (B6) on Visible on Aeria Vegetated Conca vations: er Present?	s: fone requ I Imagery ve Surfac Yes Yes	ired; checl	Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Irr Stunted of Other (Ex	ained Leava 1, 2, 4A, at (B11) Invertebrate a Sulfide O Rhizosphe of Reduce on Reduction Stressed eplain in References):	es (B13) dor (C1) dores along ed Iron (C4 on in Tilled Plants (D emarks)	Living Roo I) d Soils (C6 1) (LRR A	\\ \text{C3} \\ \text{C3} \\ \text{S} \\ \text{F} \\ \text{F}	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (CS) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
YDROLOG Vetland Hyd Primary Indic Surface V High War Saturatio Water Ma Sedimen Drift Dep Algal Ma Iron Depo Surface S Inundatio Sparsely Field Observ Surface Water Vater Table I Saturation Princludes cap	Irology Indicator ators (minimum o Nater (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5) Soil Cracks (B6) on Visible on Aeria Vegetated Conca vations: er Present? Present? esent? elilary fringe)	s: fone requ I Imagery ve Surfac Yes Yes Yes Yes	ired; checl ————————————————————————————————————	Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Ir Stunted of Other (Ex	ained Leav 1, 2, 4A, 6 t (B11) nvertebrate Sulfide O Rhizosphe of Reduce on Reduction Stressed cplain in Re nches):	es (B13) dor (C1) dores along ed Iron (C4 on in Tilled Plants (D emarks)	Living Root Soils (C6 Colored Colore	\\ \text{C3} \ \ \text{C3} \ \ \text{S} \\ S) \ \ F \\ \text{and Hydrolog}	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C3) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
YDROLOG Wetland Hyd Primary Indic Surface N High War Saturatio Water Ma Sedimen Drift Dep Algal Ma Iron Dep Surface S Inundatio Sparsely Field Observ Surface Water Water Table I	Irology Indicator ators (minimum o Nater (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5) Soil Cracks (B6) on Visible on Aeria Vegetated Concavations: er Present? Present?	s: fone requ I Imagery ve Surfac Yes Yes Yes Yes	ired; checl ————————————————————————————————————	Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Ir Stunted of Other (Ex	ained Leav 1, 2, 4A, 6 t (B11) nvertebrate Sulfide O Rhizosphe of Reduce on Reduction Stressed cplain in Re nches):	es (B13) dor (C1) dores along ed Iron (C4 on in Tilled Plants (D emarks)	Living Root Soils (C6 Colored Colore	\\ \text{C3} \ \ \text{C3} \ \ \text{S} \\ S) \ \ F \\ \text{and Hydrolog}	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C3 Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
YDROLOG Wetland Hyd Primary Indic Surface \(\) High Wat Saturatio Water Ma Sedimen Drift Dep Algal Ma Iron Dep Surface \(\) Inundatio Sparsely Field Observ Surface Water Water Table I Saturation Pr (includes cap	Irology Indicator ators (minimum o Nater (A1) ter Table (A2) in (A3) arks (B1) t Deposits (B2) osits (B3) t or Crust (B4) osits (B5) Soil Cracks (B6) on Visible on Aeria Vegetated Conca vations: er Present? Present? esent? elilary fringe)	s: fone requ I Imagery ve Surfac Yes Yes Yes Yes	ired; checl ————————————————————————————————————	Water-Sta MLRA Salt Crus Aquatic Ir Hydroger Oxidized Presence Recent Ir Stunted of Other (Ex	ained Leav 1, 2, 4A, 6 t (B11) nvertebrate Sulfide O Rhizosphe of Reduce on Reduction Stressed cplain in Re nches):	es (B13) dor (C1) dores along ed Iron (C4 on in Tilled Plants (D emarks)	Living Root Soils (C6 Colored Colore	\\ \text{C3} \ \ \text{C3} \ \ \text{S} \\ S) \ \ F \\ \text{and Hydrolog}	Water-Stained Leaves (B9) (MLRA 1, 2 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (CS) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)

Project/Site: Questa Tailing Pipeline Removal Project	(City/Co	_{unty:} Questa/T	aos	Sampling Date:	5/10/2018
Applicant/Owner: Chevron	-			State: NM	Sampling Point:	Q-2
Investigator(s): Erik Schmude				nge:		
Landform (hillslope, terrace, etc.): man-made depression				_		pe (%):0-1
Subregion (LRR): LRR E						
Soil Map Unit Name: Tenorio loam, 1 to 5% slopes						
Are climatic / hydrologic conditions on the site typical for this						
Are Vegetation yes , Soil yes , or Hydrology yes si						/ No
Are Vegetation no , Soil no , or Hydrology no na				eeded, explain any answe		
SUMMARY OF FINDINGS – Attach site map s						atures, etc.
Hydrophytic Vegetation Present? Yes No	· _ ✓					
Hydric Soil Present? Yes No			s the Sampled within a Wetlar		No <u></u> ✓	
Wetland Hydrology Present? Yes No			within a vvetial	165		
Remarks:						
Disturbed area, previously created holding pond for t	ailings					
VEGETATION - Use scientific names of plant	s.					
Tree Stratum (Plot size: 30'			nant Indicator	Dominance Test work		
1			es? Status	Number of Dominant Sp That Are OBL, FACW, of		(A)
2.						(/,/
3.				Total Number of Domin Species Across All Stra	_	(B)
4						
15'	-	= Tota	l Cover	Percent of Dominant Sp That Are OBL, FACW, of		(A/B)
Sapling/Shrub Stratum (Plot size: 15')				Prevalence Index wor	ksheet:	
1				Total % Cover of:	Multipl	ly by:
2		-		OBL species	x 1 =	
3 4				FACW species		
5.					x 3 = <u>30</u>	
		= Tota	l Cover	FACU species		
Herb Stratum (Plot size: 5'		-			x 5 = (A) 30	
1. Polygonum ramosissimum			FAC	Column Totals: 10	(//)	(D)
2. Bromus tectorum	4	yes	NL	Prevalence Index		
3. Heterotheca villosa 4. Antennaria sp.	5	yes no	NL	Hydrophytic Vegetation		
- Descurainia ninnata	1	no	NL NL	1 - Rapid Test for H		ation
	<u> </u>			2 - Dominance Tes		
6				3 - Prevalence Inde		
7 8				4 - Morphological A data in Remarks	Adaptations (Prov s or on a separate	
9.				5 - Wetland Non-Va	ascular Plants ¹	ŕ
10				Problematic Hydrop		(Explain)
11.				¹ Indicators of hydric soi		
		= Total	Cover	be present, unless distu	irbed or problema	itic.
Woody Vine Stratum (Plot size: 30')						
1				Hydrophytic		
2			_	Vegetation Present? Yes	s No	✓
% Bare Ground in Herb Stratum 79		= Total	Cover			<u>—</u>
Remarks:				1		
Mostly non-listed on sales that are in the time of	l aress					
Mostly non-listed species that are indicative of upland	areas					

	Q-2
Sampling Point:	

Depth (inches) Color (moist) % Color (moist) % Type¹ Loc² Texture Remarks	3 ³ :
Silty clay loam Sandy clay	3 .
5-16 7.5YR 3/2 100 sandy clay loam Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histic Epipedon (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Redox (S5) Loamy Mucky Mineral (S1) Pepleted Dark Surface (F6) Sandy Redox (F7) Sandy Redox (F7) Sandy Redox (F7) Sandy Redox (F7) Indicators Problematic Hydric Soils Location: PL=Pore Lining, M=Matrix. Locat	3 ³ :
¹ Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Redox (S5) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Jandicators of hydrophytic vegetation and wetland hydrology must be present,	3 ³ :
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Hydrogen Sulfide (A2) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 2 cm Muck (A10) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 1 cy cy characteristics of Problematic Hydric Soils ³ : 1 cy cy cy shallow Dark (A10) Red Parent Material (TF2) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	3 .
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Hydrogen Sulfide (A2) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 2 cm Muck (A10) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 1 cy cy characteristics of Problematic Hydric Soils ³ : 1 cy cy cy shallow Dark (A10) Red Parent Material (TF2) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	3 .
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Hydrogen Sulfide (A2) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 2 cm Muck (A10) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 1 cy cy characteristics of Problematic Hydric Soils ³ : 1 cy cy cy shallow Dark (A10) Red Parent Material (TF2) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	3 ³ :
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Hydrogen Sulfide (A2) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 2 cm Muck (A10) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 1 cy cy characteristics of Problematic Hydric Soils ³ : 1 cy cy cy shallow Dark (A10) Red Parent Material (TF2) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	3 ³ :
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Hydrogen Sulfide (A2) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 2 cm Muck (A10) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 1 cy cy characteristics of Problematic Hydric Soils ³ : 1 cy cy cy shallow Dark (A10) Red Parent Material (TF2) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	3 ³ :
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Hydrogen Sulfide (A2) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 2 cm Muck (A10) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 1 cy cy characteristics of Problematic Hydric Soils ³ : 1 cy cy cy shallow Dark (A10) Red Parent Material (TF2) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	3 ³ :
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Hydrogen Sulfide (A2) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 2 cm Muck (A10) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 1 cy cy characteristics of Problematic Hydric Soils ³ : 1 cy cy cy shallow Dark (A10) Red Parent Material (TF2) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	3 ³ :
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Hydrogen Sulfide (A2) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 2 cm Muck (A10) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 1 cy cy characteristics of Problematic Hydric Soils ³ : 1 cy cy cy shallow Dark (A10) Red Parent Material (TF2) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	3 ³ :
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Histosol (A1) Histosol (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Hydrogen Sulfide (A2) Depleted Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 2 cm Muck (A10) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Indicators for Problematic Hydric Soils ³ : 1 cy cy characteristics of Problematic Hydric Soils ³ : 1 cy cy cy shallow Dark (A10) Red Parent Material (TF2) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	3 ³ :
Histosol (A1) Sandy Redox (S5) 2 cm Muck (A10) Histic Epipedon (A2) Stripped Matrix (S6) Red Parent Material (TF2) Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Very Shallow Dark Surface (TF12) Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Other (Explain in Remarks) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) wetland hydrology must be present,	
Histic Epipedon (A2) Black Histic (A3) Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Sandy Mucky Mineral (S1) Stripped Matrix (S6) Loamy Mucky Mineral (F1) (except MLRA 1) Loamy Gleyed Matrix (F2) Other (Explain in Remarks) Other (Explain in Remarks) All Depleted Matrix (F3) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) Red Parent Material (TF2) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) All Depleted Dark Surface (F6) wetland hydrology must be present,	
Black Histic (A3) Loamy Mucky Mineral (F1) (except MLRA 1) Very Shallow Dark Surface (TF12) Other (Explain in Remarks) Depleted Below Dark Surface (A11) Depleted Matrix (F3) Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) wetland hydrology must be present,	
Hydrogen Sulfide (A4) Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Loamy Gleyed Matrix (F2) Depleted Matrix (F3) Redox Dark Surface (F6) Depleted Dark Surface (F7) Other (Explain in Remarks) Indicators of hydrophytic vegetation and wetland hydrology must be present,	
Depleted Below Dark Surface (A11) Thick Dark Surface (A12) Sandy Mucky Mineral (S1) Depleted Matrix (F3) Redox Dark Surface (F6) Selected Dark Surface (F7) Redox Dark Surface (F7) Wetland hydrology must be present,	
Thick Dark Surface (A12) Redox Dark Surface (F6) Sandy Mucky Mineral (S1) Redox Dark Surface (F6) Depleted Dark Surface (F7) wetland hydrology must be present,	
Sandy Mucky Mineral (S1) Depleted Dark Surface (F7) wetland hydrology must be present,	
Restrictive Layer (if present):	
Type:	
Depth (inches): No	✓
Remarks:	
Dietivak od seil asodky oppointent than what	
Disturbed soil mostly consistent throughout	
HYDROLOGY	
Wetland Hydrology Indicators:	
Primary Indicators (minimum of one required; check all that apply) Secondary Indicators (2 or more required)	red)
Surface Water (A1) Water-Stained Leaves (B9) (except Water-Stained Leaves (B9) (MLRA 1	
High Water Table (A2) MLRA 1, 2, 4A, and 4B) 4A, and 4B)	~ 1, _,
Saturation (A3) Salt Crust (B11) ✓ Drainage Patterns (B10)	
Water Marks (B1) Aquatic Invertebrates (B13) Dry-Season Water Table (C2) Sediment Deposits (B2) Hydrogen Sulfide Odor (C1) Saturation Visible on Aerial Imagery (n, (CO)
	ry (C9)
Algal Mat or Crust (B4) Presence of Reduced Iron (C4) Shallow Aquitard (D3)	
Iron Deposits (B5) Recent Iron Reduction in Tilled Soils (C6) FAC-Neutral Test (D5)	
Surface Soil Cracks (B6) Stunted or Stressed Plants (D1) (LRR A) Raised Ant Mounds (D6) (LRR A)	
Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Frost-Heave Hummocks (D7)	
Sparsely Vegetated Concave Surface (B8)	
Field Observations:	
Surface Water Present? Yes No Depth (inches):	
Water Table Present? Yes No _✓ Depth (inches):	
Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No V	
(includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	✓
r Describe Recorded Data (stream dauge, monitoring well, aetial photos, previous inspections), it available:	✓
December New York and Consum gauge, memoring wen, actual prioritor, provided inspections), in available.	<u>√</u>
	✓
Remarks:	√
	<u>✓</u>
Remarks:	<u>✓</u>
	<u> </u>

Project/Site: Questa Tailings Pipeline Removal Project	t (City/County:	Questa/T	aos	Sampling Date: _	5/10/2018
Applicant/Owner: Chevron				State:	Sampling Point:	Q-3a
E 1 O 1 I T 1/ 111	Ş			nge:		
				convex, none): concave		pe (%): ¹
Subregion (LRR): LRR E						
Soil Map Unit Name: Fluvents nearly level				NWI classific		
Are climatic / hydrologic conditions on the site typical for this						
Are Vegetation no , Soil yes , or Hydrology yes si	gnificantly of	disturbed?	Are "l	Normal Circumstances" p	oresent? Yes▼	/ No
Are Vegetation no , Soil no , or Hydrology no na	aturally prol	blematic?	(If ne	eded, explain any answe	rs in Remarks.)	
SUMMARY OF FINDINGS - Attach site map s	showing	sampling	g point lo	ocations, transects	, important fe	atures, etc.
Hydrophytic Vegetation Present? Yes ✓ No.)					
Hydric Soil Present? Yes No			e Sampled in a Wetlan		No <u></u> ✓	
Wetland Hydrology Present? Yes No		WILIII	III a vveuaii	ur res	NO -	-
Remarks: determination point placed below pipeline tressle, ad	jacent to r	iver. Soil i	in this area	a has been disturbed a	and the ground s	surface has
been elevated a couple feet above the river level and	-				_	
VEGETATION – Use scientific names of plant	ts.					
_	Absolute	Dominant	Indicator	Dominance Test work	sheet:	
Tree Stratum (Plot size: 30')	% Cover	Species?		Number of Dominant Sp		
Populus angustifolia Betula occidentalis	10	yes	FACW FACW	That Are OBL, FACW, of	or FAC:	(A)
		yes	17.011	Total Number of Domin	- 1	(D)
3				Species Across All Stra	.la	(B)
	15	= Total Cov	ver	Percent of Dominant Sp That Are OBL, FACW, of		(A/B)
Sapling/Shrub Stratum (Plot size: 15'	60		FACW	Prevalence Index work	<u> </u>	(/(5)
1. Betula occidentalis	20	yes		Total % Cover of:		y by:
2. Salix exigua 3. Alnus incana	5	yes no	FACW FACW	OBL species	x 1 =	
3. Arius ilicalia	-		17.000	FACW species	x 2 =	
5				FAC species	x 3 =	
51	85	= Total Cov	ver	FACU species		-
Herb Stratum (Plot size: 5'				UPL species		
1. Agrostis stolonifera	30	yes	FAC	Column Totals:	(A)	(B)
Poa pratensis Equisetum arvense	3	yes no	FAC FAC	Prevalence Index		
Teraxacum officianle	2	no	NL	Hydrophytic Vegetation		
5. Carex praegracilis	10	yes	FACW	1 - Rapid Test for F✓ 2 - Dominance Tes		ation
6.				3 - Prevalence Inde		
7.				4 - Morphological A		ride supportina
8				data in Remarks	s or on a separate	sheet)
9				5 - Wetland Non-Va		
10				Problematic Hydrop		
11	55			¹ Indicators of hydric soi be present, unless distu		
Woody Vine Stratum (Plot size:)	33	= Total Cov	rer		·	
1				Hydrophytic		
2				Vegetation	- / N-	
% Bare Ground in Herb Stratum 45		= Total Cov		Present? Yes	s No	
% Bare Ground in Herb Stratum						
vegetation is strongly hydrophytic, and typical ripariar	n vegetatio	on for the a	area			

	Q-3a
Sampling Poin	ıt.

Depth	cription: (Descri Matri		pth needed to doo Re	cument the dox Featur		or confirm	n the absence	ot indicators.)
(inches)	Color (moist)		Color (moist)	<u>%</u>	Type ¹	Loc ²	Texture	Remarks
0-6	10YR 3/2	48	10YR 5/8	2	C	M	loam	
0-6	10YR 4/4	48	10YR 5/8	2	С	M	sandy loam	
6-10	10YR 4/3	98	10YR 5/8	2	C	M	sandy	course sand
10-15	10YR 5/3	80	7.5YR 5/8	20	С	M	sandy	fine sand
15-18	10YR 5/3	80	7.5YR 5/8	20	С	M	sandy gavel	small river cobbles below 15"
		· ·				-		
								
¹Type: C=C	oncentration D=[Depletion RN	/=Reduced Matrix,	CS=Cover	ed or Coate	ed Sand G	rains ² l oc	cation: PL=Pore Lining, M=Matrix.
			I LRRs, unless ot			Ja Garia G		rs for Problematic Hydric Soils ³ :
Histosol	(A1)		Sandy Redo	x (S5)			2 cm	n Muck (A10)
	pipedon (A2)		Stripped Mat	, ,				Parent Material (TF2)
	istic (A3)		Loamy Muck	•	, ,	t MLRA 1)		Shallow Dark Surface (TF12)
	en Sulfide (A4)	((() () ()	Loamy Gleye		- 2)		Othe	er (Explain in Remarks)
	d Below Dark Sur ark Surface (A12)	, ,	Depleted Ma Redox Dark		6)		³ Indicato	rs of hydrophytic vegetation and
	лиску Mineral (S1		Depleted Da	,	,			nd hydrology must be present,
	Gleyed Matrix (S4		Redox Depre		. ,			s disturbed or problematic.
Restrictive	Layer (if present):						
Type:								,
Depth (in	ches):						Hydric Soil	Present? Yes No _✓
HYDROLO Wetland Hy	GY drology Indicato	rs:						
Primary India	cators (minimum	of one require	ed; check all that a	oply)			Secor	ndary Indicators (2 or more required)
Surface	Water (A1)		Water-S	Stained Lea	aves (B9) (except	W	/ater-Stained Leaves (B9) (MLRA 1, 2,
-	ater Table (A2)		MLR	RA 1, 2, 4A,	, and 4B)			4A, and 4B)
Saturati			Salt Cru					rainage Patterns (B10)
	1arks (B1)			Invertebra				ry-Season Water Table (C2)
	nt Deposits (B2)		Hydrog			Listen Be	· 	aturation Visible on Aerial Imagery (C9)
	posits (B3) at or Crust (B4)				neres along ced Iron (C	_	. ,	eomorphic Position (D2) hallow Aquitard (D3)
_	oosits (B5)		Recent				,	AC-Neutral Test (D5)
	Soil Cracks (B6)		Stunted				· —	aised Ant Mounds (D6) (LRR A)
	on Visible on Aer	ial Imagery (I				, (rost-Heave Hummocks (D7)
Sparsely	y Vegetated Cond	ave Surface	(B8)					
Field Obser	vations:							
Surface Wat	er Present?		No <u>✓</u> Depth					
Water Table	Present?		No <u>✓</u> Depth					
Saturation P		Yes	No <u>✓</u> Depth	(inches): _		Wetl	and Hydrology	y Present? Yes No
(includes cap Describe Re		am gauge, n	nonitoring well, aeri	al photos, p	previous ins	spections),	if available:	
Remarks:								
No sian of r	ecent water flow	v over this s	ırea. No drift dep	osits or se	ediment			
	223.11 11.0101 1101	. 5.5. 1110 0		23.10 01 00				

Project/Site: Questa Tailings Pipeline Removal Project	ot (City/County	, Questa/T	Taos	Sampling Date:	5/10/2018
Applicant/Owner: Chevron				State:		
Frik Cohmuda, Tany Kunilik				nge:		
				convex, none): concave		20 (0/).3
100 5						
- · · · · · ·						m:
				NWI classifica		
Are climatic / hydrologic conditions on the site typical for this						,
Are Vegetation yes, Soil yes, or Hydrology yes s				'Normal Circumstances" p	resent? Yes <u></u>	No
Are Vegetation no , Soil no , or Hydrology no n	aturally pro	blematic?	(If ne	eeded, explain any answer	s in Remarks.)	
SUMMARY OF FINDINGS - Attach site map	showing	samplin	g point l	ocations, transects,	, important fe	atures, etc.
Hydrophytic Vegetation Present? Yes N						
Hydric Soil Present? Yes N			ne Sampled nin a Wetlar		No √	
Wetland Hydrology Present? Yes N	o <u> </u>	Witi	iiii a vvetiai	10: 165	NO	-
Remarks: determination point placed just west of pipeline tress	le Venets	ation anne	ars to have	e heen maintained at so	ome noint	
determination point placed just west of pipeline tress	io. Vegete	шоп арро	ars to riave	, been maintained at se	And point.	
VEGETATION – Use scientific names of plan	ts.					
30'	Absolute		Indicator	Dominance Test works	sheet:	
Tree Stratum (Plot size: 30')	<u>% Cover</u> 10	Species?	Status FACW	Number of Dominant Sp		
1. Populus angustifolia	20	yes	NL	That Are OBL, FACW, o	or FAC:	(A)
2. juniperus scoparium		yes	- 111	Total Number of Domina	U	(=)
3		-	·	Species Across All Strat	ia:	(B)
4	15			Percent of Dominant Sp		
Sapling/Shrub Stratum (Plot size: 15'	-10	_ = Total Co	over	That Are OBL, FACW, o		(A/B)
1. Ceanothus fendleri	20	yes	NL	Prevalence Index work		
2. Rosa woodsii	30	yes	FACU	Total % Cover of:		y by:
3. Juniperus scoparium	10	yes	NL		x 1 =	
4				FACW species 10	$x^2 = \frac{20}{30}$	
5		-		FAC species 10		
5'	85	= Total Co	over	FACU species 34 UPL species		
Herb Stratum (Plot size: 5' 1. Agrostis stolonifera	0	1/00	FAC	Column Totals: 54	x 5 = (A) 186	
	8			Column Totals. 04		
Bromus tectorum Muhlengergia wrightii	3	yes yes	NL FACU	Prevalence Index		
4. Helianthus annuus	1	no	FACU	Hydrophytic Vegetatio		
Rumex crispus	1	no	FAC	1 - Rapid Test for H		ation
6. Poa pratensis	1	no	FAC	2 - Dominance Test		
7		-	· ———	3 - Prevalence Inde		
8				4 - Morphological A data in Remarks	daptations* (Provi	de supporting sheet)
9.				5 - Wetland Non-Va		,
10				Problematic Hydrop		(Explain)
11.		-		¹ Indicators of hydric soil	-	
30'	55	= Total Co	ver	be present, unless distu	rbed or problemat	tic.
Woody Vine Stratum (Plot size:)	_					
1				Hydrophytic		
2				Vegetation Present? Yes	s No_v	/
of Boar Crown die Hort Charten 45		= Total Co	ver	riesent: 165	, NO <u>v</u>	
% Bare Ground in Herb Stratum						
Tomano.						
vegetation is strongly hydrophytic, and typical riparia	n vegetation	on for the	area			

	Q-3b
Sampling P	oint.

	cription: (Describ	e to the de	pui needed to docu	mont the	a.oato.	or commi	iii tiie abseiice	or marcators.
Depth	Matrix		Redo	ox Feature	s			
(inches)	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²	Texture	Remarks
0-5	7.5YR 3/2	100	· -				clay loam	some small gravel and sand
5-7	7.5YR 3/2	95	7.5YR 5/8	5	С	M	clay loam	some small gravel and sand
7-16	7.5YR 3/3	90	10YR 5/8	10	С	M	sandy loam	some gravel and small cobbles
				_				
	-	_					<u> </u>	
	-		<u></u>					
¹ Type: C=C	oncentration, D=De	epletion, RN	M=Reduced Matrix, C	S=Covere	d or Coate	ed Sand G	Grains. ² Lo	cation: PL=Pore Lining, M=Matrix.
Hydric Soil	Indicators: (Appl	icable to al	II LRRs, unless othe	erwise not	ed.)		Indicate	ors for Problematic Hydric Soils ³ :
Histosol	` '		Sandy Redox (m Muck (A10)
	pipedon (A2)		Stripped Matrix					d Parent Material (TF2)
	istic (A3)		Loamy Mucky			MLRA 1		y Shallow Dark Surface (TF12)
	en Sulfide (A4)		Loamy Gleyed		2)		Oth	er (Explain in Remarks)
-	d Below Dark Surfa	ice (A11)	Depleted Matri				3, ,,	
	ark Surface (A12)		Redox Dark Su	` '				ors of hydrophytic vegetation and
	Mucky Mineral (S1) Gleyed Matrix (S4)		Depleted Dark Redox Depress		-7)			and hydrology must be present, ss disturbed or problematic.
	Layer (if present):		Redox Deples	510115 (F6)			T unite:	ss disturbed of problematic.
Type:	Layer (ii present).							
Depth (in	ches):						Hydric Soi	I Present? Yes No _ ✓
Remarks:	CHES).						Tiyane 301	Triesent: TesNO
Remarks.								
Redox cond	entrations below	5", but so	il matrix has not be	een deple	ted indic	ating upla	and soil	
HYDROLO								
	GY							
Wetland Hy		s:						
_	drology Indicators		ed: check all that app	ılv)			Seco	ndary Indicators (2 or more required)
Primary India	drology Indicators		ed; check all that app		res (RQ) (e	vcent		ndary Indicators (2 or more required)
Primary India Surface	drology Indicators cators (minimum of Water (A1)		Water-Sta	ained Leav		xcept		Vater-Stained Leaves (B9) (MLRA 1, 2,
Primary Indic	drology Indicators cators (minimum of Water (A1) ater Table (A2)		Water-Sta	ained Leav 1, 2, 4A,		xcept	\	Vater-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B)
Primary India Surface High Wa Saturation	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3)		Water-Sta MLRA Salt Crust	ained Leav 1, 2, 4A, t (B11)	and 4B)	xcept	(Vater-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Orainage Patterns (B10)
Primary India Surface High Wa Saturatia	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1)		Water-Sta MLRA Salt Crust Aquatic Ir	ained Leav 1, 2, 4A, t (B11) nvertebrate	and 4B) es (B13)	xcept	[Vater-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2)
Primary India Surface High Wa Saturatia Water M	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) farks (B1) nt Deposits (B2)		Water-Sta MLRA Salt Crust Aquatic Ir Hydrogen	ained Leav 1, 2, 4A, t (B11) nvertebrate Sulfide O	es (B13) dor (C1)		[Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9)
Primary India Surface High Wa Saturatia Water M Sedimer Drift De	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) farks (B1) nt Deposits (B2) posits (B3)		Water-Sta MLRA Salt Crust Aquatic Ir Hydrogen Oxidized	ained Leav 1, 2, 4A, t (B11) nvertebrate Sulfide O Rhizosphe	es (B13) dor (C1) eres along	Living Ro	\ [5 oots (C3) (Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2)
Primary India Surface High Wa Saturatia Water M Sedimei Drift Dep Algal Ma	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) farks (B1) nt Deposits (B2) posits (B3) at or Crust (B4)		Water-Sta MLRA Salt Crust Aquatic Ir Hydrogen Oxidized Presence	ained Leaven 1, 2, 4A, tropic (B11) invertebrate a Sulfide Or Rhizosphe of Reduce	es (B13) dor (C1) eres along ed Iron (C4	Living Ro 4)	\	Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Orainage Patterns (B10) Ory-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3)
Primary India Surface High Wa Saturatia Water M Sedimei Drift Dep Algal Ma	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) Marks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5)		Water-Sta MLRA Salt Crust Aquatic Ir Hydrogen Oxidized Presence Recent Ire	ained Leave 1, 2, 4A, t (B11) envertebrate a Sulfide O Rhizosphe of Reduct	es (B13) dor (C1) eres along ed Iron (C4) ion in Tille	Living Ro 4) d Soils (C	\	Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5)
Primary India Surface High Wa Saturatia Water M Sedimen Drift Dep Algal Ma Iron Dep Surface	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6)	one require	Water-Sta MLRA Salt Crust Aquatic Ir Hydrogen Oxidized Presence Recent Iro Stunted o	ained Leav 1, 2, 4A, t (B11) envertebrate Sulfide O Rhizosphe of Reduct on Reduct or Stressed	es (B13) dor (C1) eres along ed Iron (Colion in Tille I Plants (D	Living Ro 4) d Soils (C	\ [[C3) [S4) [F4]	Vater-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Primary India Surface High Wa Saturatia Water M Sedimer Drift Dep Algal Ma Iron Dep Surface Inundati	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) farks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria	one require	Water-Sta MLRA Salt Crust Aquatic Ir Hydrogen Oxidized Presence Recent Ir Stunted o Other (Ex	ained Leav 1, 2, 4A, t (B11) envertebrate Sulfide O Rhizosphe of Reduct on Reduct or Stressed	es (B13) dor (C1) eres along ed Iron (Colion in Tille I Plants (D	Living Ro 4) d Soils (C	\ [[C3) [S4) [F4]	Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5)
Primary India Surface High Wa Saturatia Water M Sedimer Drift Der Algal Ma Iron Der Surface Inundati	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) farks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria y Vegetated Conca	one require	Water-Sta MLRA Salt Crust Aquatic Ir Hydrogen Oxidized Presence Recent Ir Stunted o Other (Ex	ained Leav 1, 2, 4A, t (B11) envertebrate Sulfide O Rhizosphe of Reduct on Reduct or Stressed	es (B13) dor (C1) eres along ed Iron (Colion in Tille I Plants (D	Living Ro 4) d Soils (C	\ [[C3) [S4) [F4]	Vater-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Primary India Surface High Wa Saturation Water M Sedimen Drift Dep Algal Ma Iron Dep Surface Inundati Sparsely	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) Marks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria y Vegetated Conca	one require I Imagery (I	Water-Sta MLRA Salt Crust Aquatic Ir Hydrogen Oxidized Presence Recent Irc Stunted o 37) (B8)	ained Leav 1, 2, 4A, t (B11) evertebrate Sulfide O Rhizosphe of Reduct on Reduct or Stressed	es (B13) dor (C1) eres along ed Iron (C- ion in Tille I Plants (D emarks)	Living Ro 4) d Soils (C 1) (LRR A	\ [[C3) [S4) [F4]	Vater-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Primary India Surface High Wa Saturatia Water M Sedimen Drift Dep Algal Ma Iron Dep Surface Inundati Sparsely Field Obser Surface Wat	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria by Vegetated Concautations: er Present?	I Imagery (Ive Surface	Water-Star MLRA Salt Crust Aquatic Ir Hydrogen Oxidized Presence Recent Ir Stunted o 37) Other (Ex	ained Leav 1, 2, 4A, t (B11) evertebrate a Sulfide O Rhizosphe of Reduct on Reduct or Stressed eplain in Re	es (B13) dor (C1) eres along ed Iron (C- ion in Tille I Plants (D emarks)	Living Ro 4) d Soils (C 1) (LRR A	\ [[C3) [S4) [F4]	Vater-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Primary India Surface High Wa Saturatia Water M Sedimer Drift Der Algal Ma Iron Der Surface Inundati Sparsely Field Obser Surface Water Table	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria y Vegetated Conca vations: er Present? Present?	I Imagery (Ive Surface Yes	Water-Sta MLRA — Salt Crust — Aquatic Ir — Hydrogen — Oxidized — Presence — Recent Iro — Stunted o 37) — Other (Ex (B8) No ✓ Depth (ir	ained Leavanne Leavan	es (B13) dor (C1) eres along ed Iron (C4 ion in Tille I Plants (D emarks)	Living Ro 4) d Soils (C 1) (LRR A		Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
Primary India Surface High Wa Saturatia Water M Sedimer Drift Der Algal Ma Iron Der Surface Inundati Sparsely Field Obser Surface Water Table Saturation P	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) farks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria y Vegetated Conca vations: er Present? Present?	I Imagery (Ive Surface Yes	Water-Star MLRA Salt Crust Aquatic Ir Hydrogen Oxidized Presence Recent Ir Stunted o 37) Other (Ex	ained Leavanne Leavan	es (B13) dor (C1) eres along ed Iron (C4 ion in Tille I Plants (D emarks)	Living Ro 4) d Soils (C 1) (LRR A		Vater-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A)
Primary India Surface High Wa Saturatia Water M Sedimer Drift Der Algal Ma Iron Der Surface Inundati Sparsely Field Obser Surface Wat Water Table Saturation P (includes car	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria by Vegetated Conca vations: arer Present? Present? present? present?	I Imagery (Ive Surface Yes Yes Yes	Water-Sta MLRA — Salt Crust — Aquatic Ir — Hydrogen — Oxidized — Presence — Recent Iro — Stunted o 37) — Other (Ex (B8) No ✓ Depth (ir	ained Leavanne Leavan	es (B13) dor (C1) eres along ed Iron (C4) ion in Tille I Plants (D4) emarks)	Living Ro 4) d Soils (C 1) (LRR A	— \\	Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
Primary India Surface High Wa Saturatia Water M Sedimer Drift Der Algal Ma Iron Der Surface Inundati Sparsely Field Obser Surface Wat Water Table Saturation P (includes car	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria by Vegetated Conca vations: arer Present? Present? present? present?	I Imagery (Ive Surface Yes Yes Yes	Water-Sta MLRA — Salt Crust — Aquatic Ir — Hydrogen — Oxidized — Presence — Recent Ir — Stunted o 37) — Other (Ex (B8) No ✓ Depth (ir No ✓ Depth (ir No ✓ Depth (ir	ained Leavanne Leavan	es (B13) dor (C1) eres along ed Iron (C4) ion in Tille I Plants (D4) emarks)	Living Ro 4) d Soils (C 1) (LRR A	— \\	Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
Primary India Surface High Wa Saturatio Water M Sedimer Drift Der Algal Ma Iron Der Surface Inundati Sparsely Field Obser Surface Wat Water Table Saturation P (includes car Describe Re	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria by Vegetated Conca vations: arer Present? Present? present? present?	I Imagery (Ive Surface Yes Yes Yes	Water-Sta MLRA — Salt Crust — Aquatic Ir — Hydrogen — Oxidized — Presence — Recent Ir — Stunted o 37) — Other (Ex (B8) No ✓ Depth (ir No ✓ Depth (ir No ✓ Depth (ir	ained Leavanne Leavan	es (B13) dor (C1) eres along ed Iron (C4) ion in Tille I Plants (D4) emarks)	Living Ro 4) d Soils (C 1) (LRR A	— \\	Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
Primary India Surface High Wa Saturatia Water M Sedimer Drift Der Algal Ma Iron Der Surface Inundati Sparsely Field Obser Surface Wat Water Table Saturation P (includes car	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria by Vegetated Conca vations: arer Present? Present? present? present?	I Imagery (Ive Surface Yes Yes Yes	Water-Sta MLRA — Salt Crust — Aquatic Ir — Hydrogen — Oxidized — Presence — Recent Ir — Stunted o 37) — Other (Ex (B8) No ✓ Depth (ir No ✓ Depth (ir No ✓ Depth (ir	ained Leavanne Leavan	es (B13) dor (C1) eres along ed Iron (C4) ion in Tille I Plants (D4) emarks)	Living Ro 4) d Soils (C 1) (LRR A	— \\	Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
Primary India Surface High Wa Saturatio Water M Sedimer Drift Der Algal Ma Iron Der Surface Inundati Sparsely Field Obser Surface Wat Water Table Saturation P (includes car Describe Re	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria by Vegetated Conca vations: arer Present? Present? present? present?	I Imagery (Ive Surface Yes Yes Yes	Water-Sta MLRA — Salt Crust — Aquatic Ir — Hydrogen — Oxidized — Presence — Recent Ir — Stunted o 37) — Other (Ex (B8) No ✓ Depth (ir No ✓ Depth (ir No ✓ Depth (ir	ained Leavanne Leavan	es (B13) dor (C1) eres along ed Iron (C4) ion in Tille I Plants (D4) emarks)	Living Ro 4) d Soils (C 1) (LRR A	— \\	Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)
Primary India Surface High Wa Saturatio Water M Sedimer Drift Der Algal Ma Iron Der Surface Inundati Sparsely Field Obser Surface Wat Water Table Saturation P (includes car Describe Re	drology Indicators cators (minimum of Water (A1) ater Table (A2) on (A3) flarks (B1) nt Deposits (B2) posits (B3) at or Crust (B4) posits (B5) Soil Cracks (B6) on Visible on Aeria by Vegetated Conca vations: arer Present? Present? present? present?	I Imagery (Ive Surface Yes Yes Yes	Water-Sta MLRA — Salt Crust — Aquatic Ir — Hydrogen — Oxidized — Presence — Recent Ir — Stunted o 37) — Other (Ex (B8) No ✓ Depth (ir No ✓ Depth (ir No ✓ Depth (ir	ained Leavanne Leavan	es (B13) dor (C1) eres along ed Iron (C4) ion in Tille I Plants (D4) emarks)	Living Ro 4) d Soils (C 1) (LRR A	— \\	Water-Stained Leaves (B9) (MLRA 1, 2, 4A, and 4B) Drainage Patterns (B10) Dry-Season Water Table (C2) Saturation Visible on Aerial Imagery (C9) Geomorphic Position (D2) Shallow Aquitard (D3) FAC-Neutral Test (D5) Raised Ant Mounds (D6) (LRR A) Frost-Heave Hummocks (D7)

Project/Site: Questa Tailings Pipeline Removal Project	t (Citv/County	,; Questa/T	aos	Sampling Date:	5/10/2018
Applicant/Owner: Chevron		,,,		aos State: NM	Sampling Point:	Q-4a
E 1 O 1 I T 1/ 111				nge:		
Landform (hillslope, terrace, etc.): floodplain				-		ne (%):1-3
Subregion (LRR): LRR E						
Soil Map Unit Name: Rock outcrop-badland complex, vo						
Are climatic / hydrologic conditions on the site typical for this			_			
Are Vegetation <u>yes</u> , Soil <u>yes</u> , or Hydrology <u>no</u> si						/ No
						NO
Are Vegetation <u>no</u> , Soil <u>no</u> , or Hydrology <u>no</u> no SUMMARY OF FINDINGS – Attach site map s				eeded, explain any answer		aturos oto
		Jampini	ig point i	ocations, transcots		atures, etc.
Hydrophytic Vegetation Present? Yes ✓ No Hydric Soil Present? Yes No Yes No No No No No No No No No N		Is th	ne Sampled	Area		
Wetland Hydrology Present? Yes No	√ ·	with	nin a Wetlar	nd? Yes	No <u></u> ✓	_
Remarks:						
VEGETATION - Use scientific names of plant	s.					
30'	Absolute		Indicator	Dominance Test work	sheet:	
· · · · · · · · · · · · · · · · · · ·	% Cover 95	Species?		Number of Dominant Sp	pecies 2	
1. Betula occidentalis		yes	FACW	That Are OBL, FACW, o	or FAC:	(A)
2			·	Total Number of Domina	J	<i>(</i> =)
3				Species Across All Stra	ta:	(B)
4	95	= Total Co		Percent of Dominant Sp		(
Sapling/Shrub Stratum (Plot size: 15')		_= 10tal CC	over	That Are OBL, FACW, o	<u></u>	(A/B)
1. Betula occidentalis	40	yes	FACW	Prevalence Index worl		
2. Abies concolor	2	no	NL	Total % Cover of:		y by:
3				OBL species		
4				FAC species		
5				FACU species		
Herb Stratum (Plot size: 5'	42	= Total Co	over	UPL species		
1. Bromus inermis	25	yes	UPL	Column Totals:		
2. Agrostis stolonifera	2	no	FAC			
3. Geum macrophyllum	2	no	FAC	Prevalence Index Hydrophytic Vegetation		
4. Equisetum arvense	2	no	FAC	1 - Rapid Test for H		ation
5. Maianthemum racemosum	2	no	FAC	2 - Dominance Tes		a
6				3 - Prevalence Inde		
7				4 - Morphological A		ide supporting
8					s or on a separate	sheet)
9				5 - Wetland Non-Va		
10				Problematic Hydrop		` ' '
11	00			¹ Indicators of hydric soil be present, unless distu		
Woody Vine Stratum (Plot size:)	33	= Total Co	ver	bo process, armood area		
1				Livelyonbyttio		
2.				Hydrophytic Vegetation		
		= Total Co		Present? Yes	s <u> </u>	
% Bare Ground in Herb Stratum 67						
Remarks:						
Betula occidentalis dominated riparian area						

		Q-4a
Sampling F	oint.	~

		e to the de	oth needed to docu			or confirn	n the absence	of indicators.)
Depth (inches)	Matrix Color (moist)	%	Color (moist)	ox Featur %	<u>es</u> <u>Type¹</u>	Loc ²	Texture	Remarks
0-7	7.5YR 4/3	92	7.5YR 5/8	8	C		sandy	
7-10	7.5YR 3/2	45	7.5YR 5/8	5		М	sandy loam	
7-10	7.5YR 4/3	45	7.5YR 5/8	10			sand	coarser than 0.7 layer
10-16	7.5YR 4/3	98	7.5YR 5/8	2		M	gravelly sand	·
				_ =	- —		graverry carra	
-							-	
			_					
		•	I=Reduced Matrix, C			ed Sand G		ration: PL=Pore Lining, M=Matrix. rs for Problematic Hydric Soils ³ :
=		icable to al	I LRRs, unless othe		itea.)			•
Histosol	oipedon (A2)		Sandy Redox Stripped Matrix					n Muck (A10) Parent Material (TF2)
	stic (A3)		Loamy Mucky		-1) (except	t MLRA 1)		Shallow Dark Surface (TF12)
	en Sulfide (A4)		Loamy Gleyed			,		er (Explain in Remarks)
	d Below Dark Surfa	ace (A11)	Depleted Matri		,			,
	ark Surface (A12)		Redox Dark S		,			rs of hydrophytic vegetation and
	Mucky Mineral (S1)		Depleted Dark		. ,			nd hydrology must be present,
	Bleyed Matrix (S4) Layer (if present):		Redox Depres	Sions (F8)		unies	s disturbed or problematic.
Type:	Layer (II present).							
	ches):						Hydric Soil	Present? Yes No ✓
Remarks:							i i yano oon	- 1000iii.
HYDROLO	GY							
Wetland Hy	drology Indicator	s:						
Primary India	cators (minimum of	one require	ed; check all that app	oly)			Secon	dary Indicators (2 or more required)
	Water (A1)		✓ Water-Sta			xcept	W	ater-Stained Leaves (B9) (MLRA 1, 2,
-	ater Table (A2)			1, 2, 4A,	and 4B)			4A, and 4B)
Saturati			Salt Crus					rainage Patterns (B10)
	larks (B1)		Aquatic Ir					ry-Season Water Table (C2)
_	nt Deposits (B2) posits (B3)		Hydroger		eres along	Livina Boo		aturation Visible on Aerial Imagery (C9) eomorphic Position (D2)
	at or Crust (B4)				eres along ced Iron (C	_	. ,	hallow Aquitard (D3)
_	posits (B5)				tion in Tille	•		AC-Neutral Test (D5)
	Soil Cracks (B6)		Stunted c			•		aised Ant Mounds (D6) (LRR A)
	on Visible on Aeria	l Imagery (E				, (rost-Heave Hummocks (D7)
	y Vegetated Conca				,			,
Field Obser	vations:							
Surface Wat	er Present?	Yes	No ✓ Depth (ir	nches):				
Water Table	Present?	Yes	No <u>✓</u> Depth (ir	nches):		_		
Saturation P		Yes <u>√</u>	No Depth (in	nches): <u>1</u>	3	Wetl	and Hydrology	/ Present? Yes _ ✓ No
(includes cap Describe Re		m gauge, m	onitoring well, aerial	photos, p	revious ins	pections),	if available:	
	,	- J ,	3 ,	. , , ,		. "		
Remarks:								
noint in lace	tod noor river c-	d sign of	vator flowing and in	nundatio:	a thio ores	io prose	nt	
point is ioca	teu near nver an	u siyii oi W	ater flowing and ir	เนเนสแก้	y uno area	a is prese	III.	

Project/Site: Questa Tailings Pipeline Removal Project	ct (Citv/Cou	_{intv:} Questa/T	aos	Sampling Date:	5/10/2018
Applicant/Owner: Chevron			, <u> </u>	State: NM	Sampling Point:	Q-4b
Fulls Oaksanda Tasas Kasalilla		Section,		nge:		
Landform (hillslope, terrace, etc.): hillslope						pe (%): ³
Subregion (LRR): LRR E						
Soil Map Unit Name: Rock outcrop-badland complex, v						·
Are climatic / hydrologic conditions on the site typical for this			,			
Are Vegetation no , Soil no , or Hydrology no s				Normal Circumstances" p		/ No
Are Vegetation no , Soil no , or Hydrology no n				eded, explain any answe		
SUMMARY OF FINDINGS - Attach site map				ocations, transects	, important fe	atures, etc.
Hydrophytic Vegetation Present? Yes No						
Hydric Soil Present? Yes No	o <u> </u>		s the Sampled vithin a Wetlan		No <u></u> ✓	
Wetland Hydrology Present? Yes No	0 _ ✓	W	vitiliii a vvetiaii	iu: 165	NO	-
Remarks:						
point placed just to west of pipeline tressle. Area ha	s been dis	turbed	and appears	vegetation has been m	naintained in pa	st.
VEGETATION – Use scientific names of plan	ts.					
Tree Stratum (Plot size: 30'	Absolute % Cover		ant Indicator es? Status	Dominance Test work		
1. Juniperus scoparium		yes	NL	Number of Dominant Sp That Are OBL, FACW, of		(A)
2				Total Number of Domin	ant 3	
3				Species Across All Stra	J	(B)
4	80			Percent of Dominant Sp		
Sapling/Shrub Stratum (Plot size: 15'	00	_= Total	Cover	That Are OBL, FACW, o		(A/B)
1. Atriplex canescens	10	yes	NL	Prevalence Index work		ly by
2				Total % Cover of: OBL species		y by:
3				FACW species		
4				FAC species		
5	10			FACU species		
Herb Stratum (Plot size: 5'	10	_= lotal	Cover	UPL species	x 5 =	
1. Bromus inermis	80	yes	UPL	Column Totals:	(A)	(B)
2. Antennaria sp.	5	no	NL	Prevalence Index	= B/A =	
3. Bassia scoparia	5	no	FAC	Hydrophytic Vegetation		
4				1 - Rapid Test for H	Hydrophytic Veget	ation
5				2 - Dominance Tes		
6				3 - Prevalence Inde		
7				4 - Morphological A data in Remarks	daptations' (Prov s or on a separate	
9				5 - Wetland Non-Va		,
10.				Problematic Hydrop	ohytic Vegetation ¹	(Explain)
11				¹ Indicators of hydric soi		
30'	90	= Total	Cover	be present, unless distu	irbed or problema	TIC.
Woody Vine Stratum (Plot size:)						
1				Hydrophytic Vegetation		
			Cover		s No	<u>/</u>
% Bare Ground in Herb Stratum	-					
Remarks:						
Upland species dominate area on hillslope						

	Q-4b
Sampling Point:	

				ment the indicator	or confirm t	the absence	of indicators.)
Depth (inches)	Color (moist)	%	Color (moist)	ox Features%Type ¹ _	Loc²	Texture	Remarks
0-3	10YR 3/3	100	<u>Color (molot)</u>			ay loam	many fibrous roots
3-16	2.5Y 5/3	100	-				
3-10	2.31 3/3				CI	ay	
1T C. C.			Dadward Matrix C			21	estion. DL. Doug Lining, M. Matrix
			=Reduced Matrix, C	S=Covered or Coate	ed Sand Grai		cation: PL=Pore Lining, M=Matrix. ors for Problematic Hydric Soils ³ :
Histosol		iloubic to un	Sandy Redox	,			n Muck (A10)
	oipedon (A2)		Stripped Matri	. ,			Parent Material (TF2)
Black Hi				Mineral (F1) (except	t MLRA 1)		/ Shallow Dark Surface (TF12)
	n Sulfide (A4)		Loamy Gleyed			Oth	er (Explain in Remarks)
	d Below Dark Surf	ace (A11)	Depleted Matr			3	
	ark Surface (A12) Iucky Mineral (S1)		Redox Dark S	, ,			ors of hydrophytic vegetation and nd hydrology must be present,
	Bleyed Matrix (S4)		Depleted Dark Redox Depres				is disturbed or problematic.
	_ayer (if present)			(. 0)		400	
Type:							
Depth (inc	ches):					Hydric Soil	Present? Yes No ✓
Remarks:	<u> </u>						
HYDROLO							
1	drology Indicator						
·	-	f one require	d; check all that app				ndary Indicators (2 or more required)
	Water (A1)			ained Leaves (B9) (e	xcept	W	/ater-Stained Leaves (B9) (MLRA 1, 2,
	iter Table (A2)			1, 2, 4A, and 4B)		5	4A, and 4B)
Saturatio			Salt Crus	, ,			rainage Patterns (B10)
Water M	nt Deposits (B2)			nvertebrates (B13) n Sulfide Odor (C1)			ry-Season Water Table (C2) aturation Visible on Aerial Imagery (C9
Sedimer				, ,	Living Roots	· · · · · · · · · · · · · · · · · · ·	seomorphic Position (D2)
	at or Crust (B4)			of Reduced Iron (C	-		hallow Aquitard (D3)
Iron Dep				on Reduction in Tille			AC-Neutral Test (D5)
	Soil Cracks (B6)			or Stressed Plants (D		· · · · · · · · · · · · · · · · · · ·	aised Ant Mounds (D6) (LRR A)
	on Visible on Aeria	al Imagery (E	·	(plain in Remarks)	, ,		rost-Heave Hummocks (D7)
Sparsely	Vegetated Conca	ave Surface	(B8)				
Field Obser	vations:						
Surface Wat	er Present?	Yes	No Depth (i	nches):			
Water Table	Present?	Yes	No Depth (i	nches):			
Saturation P	resent?	Yes	No Depth (i	nches):	Wetlan	nd Hydrolog	y Present? Yes No _✓
(includes car	oillary fringe)					available:	
Describe Re	colueu Data (Střea	ını gauge, m	onitoring well, aeria	photos, previous ins	pections), if	avaliable:	
Remarks:							

Project/Site: Questa Tailings Pipeline Removal Projec	t (City/County	,. Questa/T	aos	Sampling Date:	5/10/2018
Applicant/Owner: Chevron			•	aos State: NM	Sampling Point:	Q-5a
Frik Schmude Tony Kunilik				nge:		
Landform (hillslope, terrace, etc.): floodplain				•		pe (%):1
Subregion (LRR): LRR E						
Soil Map Unit Name: Cumulic haploborolls, nearly level				NWI classific	ation: R3USC	····
Are climatic / hydrologic conditions on the site typical for this						
Are Vegetation <u>no</u> , Soil <u>no</u> , or Hydrology <u>no</u> si						/ No
						NO
Are Vegetation <u>no</u> , Soil <u>no</u> , or Hydrology <u>no</u> na SUMMARY OF FINDINGS – Attach site map s				eeded, explain any answe		eatures, etc.
Hydrophytic Vegetation Present? Yes ✓ No)					
Hydric Soil Present? Yes No			ne Sampled	/	NI.	
Wetland Hydrology Present? Yes <u>√</u> No	·	With	nin a Wetlar	id? Yes	No	_
Remarks:						
point placed in adjacent area to river, which is only sl	lightly elev	/ated from	the river.	Water clearly flows he	re, on occasion	
VEGETATION – Use scientific names of plant	ts.					
Tree Stratum (Plot size: 30')		Dominant		Dominance Test work	sheet:	
1	% Cover		Status	Number of Dominant S That Are OBL, FACW,		(A)
2				Total Number of Domin	ant 4	
3				Species Across All Stra		(B)
4		= Total Co	over	Percent of Dominant Sp That Are OBL, FACW,		(A/B)
Sapling/Shrub Stratum (Plot size: 15')	20	VOC	FACW	Prevalence Index wor		(-1-)
1. Betula occidentalis	15	yes		Total % Cover of:		ly by:
2. Salix monticola	10	yes	FACW	OBL species		-
3. Salix exigua	10	yes	FACVV	FACW species		
4				FAC species	x 3 =	
5	15			FACU species	x 4 =	
Herb Stratum (Plot size: 5'	45	= Total Co	over	UPL species		
1. Agrostis stolonifera	70	yes	FAC	Column Totals:	(A)	(B)
2. Equisetum arvense	10	no	FAC	Prevalence Index	– R/Λ –	
3. Barbarea vulgaris	4	no	FAC	Hydrophytic Vegetation		
4. Mentha arvensis	2	no	FACW	1 - Rapid Test for H		ation
5				✓ 2 - Dominance Tes		
6				3 - Prevalence Inde		
7				4 - Morphological A		ride supporting
8				data in Remarks	s or on a separate	sheet)
9				5 - Wetland Non-Va		
10				Problematic Hydro	ohytic Vegetation ¹	(Explain)
11				¹ Indicators of hydric soi be present, unless distu		
30'	86	= Total Co	ver	be present, unless dist		
Woody Vine Stratum (Plot size:)						
1				Hydrophytic Vegetation		
2					s <u> </u>	
% Bare Ground in Herb Stratum 14		= Total Co	vei			
Remarks:				1		

	Q-5a
Sampling Point:	

Profile Desc	cription: (Describe	to the de	oth needed to docur	nent the i	ndicator	or confirm	n the absence	of indicators.)
Depth	Matrix			x Features				
(inches)	Color (moist)	%	Color (moist)		Type ¹	Loc ²	<u>Texture</u>	Remarks
0-3	10YR 4/3	90	5YR 5/8	10		M/PL	sandy loam	
3-5	10YR 4/2	70	5YR 5/8	30	С	M/PL	s <u>ilty clay loa</u> n	1
5-6	10YR 4/2	70	5YR 5/8	30	С	PL	silty clay	
6-9	7.5YR 4/3	60	5YR 5/8	40	С	M/PL	loamy sand	small gravel
							,	
			-	- ——				
		_	-				-	
1Typo: C-C	oncontration D-Do	olotion PM	=Reduced Matrix, CS	S-Covered		d Sand G	rains ² l oc	ation: PL=Pore Lining, M=Matrix.
			LRRs, unless other			u Sanu G		rs for Problematic Hydric Soils ³ :
Histosol			Sandy Redox (,			n Muck (A10)
	oipedon (A2)		Stripped Matrix	,				Parent Material (TF2)
	stic (A3)		Loamy Mucky N) (except	MLRA 1)		Shallow Dark Surface (TF12)
	en Sulfide (A4)		Loamy Gleyed			,		er (Explain in Remarks)
	d Below Dark Surfa	ce (A11)	✓ Depleted Matrix					
Thick Da	ark Surface (A12)		Redox Dark Su	rface (F6)			³ Indicato	rs of hydrophytic vegetation and
Sandy M	Mucky Mineral (S1)		Depleted Dark		7)		wetlar	nd hydrology must be present,
	Bleyed Matrix (S4)		Redox Depress	ions (F8)			unles	s disturbed or problematic.
	Layer (if present):							
Type: Riv	ver rock							
Depth (in	ches): <u>9</u>						Hydric Soil	Present? Yes No
HYDROLO	GV							
	drology Indicators							
_			ed; check all that appl	v)			Secon	dary Indicators (2 or more required)
	•	one require	<u>√</u> Water-Sta		oo (PO) (o o	voont		
	Water (A1)					ксері	vv	dater-Stained Leaves (B9) (MLRA 1, 2,
✓ Saturation	ater Table (A2)		Salt Crust	1, 2, 4A, a	ina 46)		/ D	4A, and 4B)
	, ,			` '	- (D40)		· · · · · · · · · · · · · · · · · · ·	rainage Patterns (B10)
	larks (B1)		Aquatic In		, ,			ry-Season Water Table (C2)
	nt Deposits (B2)		Hydrogen			Linder D		aturation Visible on Aerial Imagery (C9)
	posits (B3)		Oxidized F		_	-	· / 	eomorphic Position (D2)
	at or Crust (B4)		Presence					nallow Aquitard (D3)
	oosits (B5) Soil Cracks (B6)		Recent Iro			•		AC-Neutral Test (D5)
· 	, ,	Imagan, /F	Stunted or			I) (LKK A		aised Ant Mounds (D6) (LRR A)
	on Visible on Aerial			nam in Ke	marks)		Fr	rost-Heave Hummocks (D7)
	Vegetated Concav	e Suriace	(00)					
Field Obser			No. / Double Co.	-1>				
Surface Wat			No ✓ Depth (in			-		
Water Table			No <u>✓</u> Depth (in					
Saturation P	oillary fringe)		No Depth (in					Present? Yes ✓ No
Describe Re	colded Data (strear	n gauge, m	onitoring well, aerial	priotos, pr	evious ins	pections),	ıı avalladle:	
Domortica								
Remarks:								
rtomanto.								
romano.								

Project/Site: Questa Tailings Pipeline Removal Project	ct	City/Count	y: Questa/T	aos	Sampling Date:	5/10/2018	
Applicant/Owner: Chevron	_			State: NM	Sampling Point:	Q-5b	
Frik Cohmudo, Tony Kunilik				nge:			
Landform (hillslope, terrace, etc.): terrace						pe (%): ⁴⁻⁵	
Subregion (LRR): LRR E							
Soil Map Unit Name: Cumulic haploborolls, nearly leve				NWI classific			
Are climatic / hydrologic conditions on the site typical for thi							
Are Vegetation no , Soil no , or Hydrology no s	-				•	/ No	
Are Vegetation no , Soil no , or Hydrology no r				eded, explain any answe		110	
SUMMARY OF FINDINGS – Attach site map						eatures, etc.	
Hydrophytic Vegetation Present? Yes✓ N	lo						
Hydric Soil Present? Yes N	lo <u> </u>	Is the Sampled Area					
Wetland Hydrology Present? Yes N	lo	wit	hin a Wetlan	nd? Yes	No <u></u>	-	
Remarks:							
VEGETATION – Use scientific names of plan	its.						
Tree Stratum (Plot size: 30')	Absolute		t Indicator	Dominance Test work			
1. Populus angustifolia	% Cover 50	yes	FACW	Number of Dominant S That Are OBL, FACW,		(A)	
2.						(^)	
3.				Total Number of Domin Species Across All Stra	J	(B)	
4.						(5)	
	50	= Total C	over	Percent of Dominant S That Are OBL, FACW,		(A/B)	
Sapling/Shrub Stratum (Plot size: 15'	50	_		Prevalence Index wor	<u> </u>	(,,,,)	
1. Alnus incana		yes	FACW	Total % Cover of:		ly by:	
2. Salix bebbiana	20 10	yes no	FACU FACU	OBL species			
3. Rosa woodsii	_ 10	110	FACU	FACW species			
4	80	-		FAC species	x 3 =		
5		= Total C		FACU species	x 4 =		
Herb Stratum (Plot size: 5'		_= 10(a) C	ovei	UPL species	x 5 =		
1. Agrostis stolonifera	40	yes	FAC	Column Totals:	(A)	(B)	
2. Bromus inermis	40	yes	UPL	Prevalence Index	c = B/A =		
3. Taraxacum officianale	5	no	NL	Hydrophytic Vegetation			
4				1 - Rapid Test for I	Hydrophytic Veget	tation	
5				✓ 2 - Dominance Tes			
6				3 - Prevalence Inde			
7				4 - Morphological A	Adaptations ¹ (Prov s or on a separate		
8				5 - Wetland Non-V	•	; sileet)	
9				Problematic Hydro		¹ (Explain)	
10.				¹Indicators of hydric so			
11.	85	= Total Co		be present, unless distr			
Woody Vine Stratum (Plot size:)		_= Total CC	ovei				
1				Hydrophytic			
2				Vegetation	es_√_ No		
		= Total Co		Present? Ye	5 <u>▼</u> NO _		
% Bare Ground in Herb Stratum 15 Remarks:							
Tomano.							
						l	

		Q-5b
Sampling	Point:	-,

Profile Des	cription: (Descri	be to the de	pth needed to docur	nent the	indicator	or confirn	n the absen	ce of indicators.)
Depth	Matrix	X	Redo	x Feature	S			
(inches)	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²	Texture	Remarks
0-4	10YR 3/2	100					clay loam	
4-6	10YR 7/6	100					loam	
6-16	10YR 4/3	99	10YR 5/6	1	С	M	sandy loan	1
							<u> </u>	·
								
	-							
	-							
					·			
1Typo: C-C	oncontration D-F	Donlotion PM	l=Reduced Matrix, CS	S-Covere	d or Coato	d Sand G	raine ² I	ocation: PL=Pore Lining, M=Matrix.
			I LRRs, unless other			u Sanu Gi		ntors for Problematic Hydric Soils ³ :
Histosol		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Sandy Redox (ou.,			cm Muck (A10)
	pipedon (A2)		Stripped Matrix					ed Parent Material (TF2)
	istic (A3)		Loamy Mucky N		1) (except	MLRA 1)		ery Shallow Dark Surface (TF12)
	en Sulfide (A4)		Loamy Gleyed			,		ther (Explain in Remarks)
Deplete	d Below Dark Sur	face (A11)	Depleted Matrix	(F3)				
	ark Surface (A12)		Redox Dark Su	, ,				ators of hydrophytic vegetation and
	Mucky Mineral (S1		Depleted Dark		- 7)			tland hydrology must be present,
	Gleyed Matrix (S4)		Redox Depress	ions (F8)			unl	ess disturbed or problematic.
	Layer (if present):						
Type:								
	ches):						Hydric So	oil Present? Yes No _ ✓
Remarks:								
HYDROLO	GY							
	drology Indicato	re						
_			ed; check all that appl	v)			Sac	condary Indicators (2 or more required)
	Water (A1)	or one require	Water-Sta		ros (B0) (o s	vcont		Water-Stained Leaves (B9) (MLRA 1, 2,
	ater Table (A2)			1, 2, 4A, a		kcept	_	4A, and 4B)
Saturati			Salt Crust		anu 46)			Drainage Patterns (B10)
_	/larks (B1)		Aquatic In		s (B13)		_	Dry-Season Water Table (C2)
·	nt Deposits (B2)		Hydrogen		, ,		_	Saturation Visible on Aerial Imagery (C9)
	posits (B3)		Oxidized F		. ,	Livina Roc	nts (C3)	Geomorphic Position (D2)
	at or Crust (B4)		Presence		_	_		Shallow Aquitard (D3)
_	posits (B5)		Recent Iro		•	•	s)	FAC-Neutral Test (D5)
	Soil Cracks (B6)		Stunted or				-	Raised Ant Mounds (D6) (LRR A)
	ion Visible on Aer	ial Imagery (E				., (=:::::		Frost-Heave Hummocks (D7)
	y Vegetated Cond		, <u> </u>		,		_	,
Field Obser	-		(- /					
Surface Wat		Yes	No <u>√</u> Depth (in	ches):				
Water Table			No ✓ Depth (in					
Saturation P			No ✓ Depth (in				and Hydrold	ogy Present? Yes No _✓_
(includes ca	pillary fringe)							795 . 1636Ht: 163 NO
		am gauge, m	onitoring well, aerial	photos, pr	evious ins	pections),	if available:	
Remarks:								

Project/Site: Questa Tailings Pipeline Removal Project	ect	City/Cou	nty: Questa/T	aos	Sampling Date:	5/10/2018
Applicant/Owner: Chevron	_		, <u> </u>	aos State: NM	Sampling Point	Q-6a
Investigator(s): Erik Schmude, Tony Kupilik		Section,	Township, Rai	nge:		
				convex, none): concav		ope (%):1-2
Subregion (LRR): LRR E	Lat:		,	Long:	Dat	:um:
Soil Map Unit Name: Cumulic haploborolls, nearly lev	vel			NWI classif	rication: none	
Are climatic / hydrologic conditions on the site typical for th						
Are Vegetation yes , Soil yes , or Hydrology no						√ No
Are Vegetation no , Soil no , or Hydrology no	-					
SUMMARY OF FINDINGS – Attach site map						eatures, etc.
Hydrophytic Vegetation Present? Yes✓ I						
Hydric Soil Present? Yes I	Vo <u> </u>		the Sampled vithin a Wetlar		No <u></u> ✓	
Wetland Hydrology Present? Yes I	No	VV	illilli a vvetiai	iu: Tes	NO	_
Remarks:						
Point placed a few feet from river edge in area of fa	irly sparse	vegetat	ion, with sph	agnum moss the dom	ninant herbaceou	ıs species.
VEGETATION – Use scientific names of plan	nts.					
Tree Stratum (Plot size: 30'	Absolute		ant Indicator	Dominance Test wor	rksheet:	
1. Populus angustifolia	40	yes	s? Status FACW	Number of Dominant		(A)
2.				That Are OBL, FACW	, 01 FAC	(A)
3.				Total Number of Dom Species Across All St		(B)
4.						(=)
	40	= Total	Cover	Percent of Dominant S That Are OBL, FACW		(A/B)
Sapling/Shrub Stratum (Plot size: 15'	10	yes	FACW	Prevalence Index wo	· · · · · · · · · · · · · · · · · · ·	
Salix amygdaloides Betula occidentalis	10	yes	FACW	Total % Cover of:	Multip	oly by:
3. Acer glabrum	$-\frac{10}{2}$	no	FACU	OBL species	x 1 =	
4. Quercus gambelii	_ _	no	NL	FACW species	x 2 =	
5.				FAC species		
	24	= Total	Cover	FACU species		
Herb Stratum (Plot size: 5'				UPL species		
1. Agrostis stolonifera	5	no	FAC NL	Column Totals:	(A)	(B)
Sphagnum spp. Trifolium repens	<u>40</u> 3	yes no	FAC		ex = B/A =	
4. Descuriana sp.	_ 3	no	NL	Hydrophytic Vegetat		
5. Achillea millefoium		no	FACU	1 - Rapid Test for 2 - Dominance Te		etation
6. Bromus inermis	2	no	UPL	3 - Prevalence In		
7.					Adaptations ¹ (Pro	vide supporting
8				data in Remar	ks or on a separat	
9				5 - Wetland Non-		4
10				Problematic Hydr		
11	E0.			¹ Indicators of hydric so be present, unless dis	oil and wetland hysturbed or problem	drology must atic.
Woody Vine Stratum (Plot size:)	52	_= Total (Cover	' '	<u>.</u>	
1				Hydrophytic		
2				Vegetation	, ,	
				Present? Y	'es <u>√</u> No _	
% Bare Ground in Herb Stratum 48 Remarks:						
Tronding.						
moss spp. primary vegetation in the herbaceous lay	er er					

	Q-6a	
Sampling F	oint:	

Profile Desc	ription: (Describe	e to the de	pth neede	d to docun	nent the	indicator o	r confir	m the abse	nce o	of indicators.)
Depth	Matrix				x Feature		. 2	_		_
(inches)	Color (moist)	%		(moist)	<u>%</u>	Type ¹	Loc ²	Textur		Remarks
0-3	10YR 6/4	85	7.5YR (15	<u>C</u>	PL	loamy sa	ind	
3-5	10YR 3/2	85	7.5YR (6/8	15	С	PL	clay		some organics (dark leaves)
5-7	7.5YR 4/3	55	7.5YR (6/8	45	С	M	loamy sa	ınd	
,										
			-							
	-									
¹ Type: C=C	oncentration, D=De	pletion, RM	1=Reduced	d Matrix, CS	S=Covere	d or Coate	d Sand G	Grains.	² Loca	ation: PL=Pore Lining, M=Matrix.
Hydric Soil	Indicators: (Appli	cable to al	I LRRs, ur	nless other	wise not	ed.)				s for Problematic Hydric Soils ³ :
Histosol	(A1)			dy Redox (S				_	2 cm	Muck (A10)
	pipedon (A2)			ped Matrix						Parent Material (TF2)
	stic (A3)			ny Mucky N			MLRA 1			Shallow Dark Surface (TF12)
	n Sulfide (A4)	(044)		my Gleyed I		2)			Othe	r (Explain in Remarks)
	d Below Dark Surfa ark Surface (A12)	ce (A11)		leted Matrix ox Dark Su				3100	icata-	s of hydrophytic vegetation and
	fucky Mineral (S1)			leted Dark Sui	, ,					d hydrology must be present,
	Gleyed Matrix (S4)			ox Depress		.,				disturbed or problematic.
	_ayer (if present):		<u> </u>	· ·	, ,					·
Type: Riv	er rock									
Depth (in	ches): 7							Hydric	Soil F	Present? Yes No <u>√</u>
Remarks:	,									
Redox featu	res present, but	no depleti	on on the	matrix ob	served.					
HYDROLO	GY									
Wetland Hy	drology Indicators	s:								
Primary India	cators (minimum of	one require	ed; check a	all that apply	/)			<u>S</u>	econ	dary Indicators (2 or more required)
Surface	Water (A1)			Water-Stai	ned Leav	es (B9) (e :	cept	_	Wa	ater-Stained Leaves (B9) (MLRA 1, 2,
High Wa	iter Table (A2)			MLRA	1, 2, 4A, a	and 4B)				4A, and 4B)
Saturation	on (A3)			Salt Crust	(B11)			_	_ Dr	ainage Patterns (B10)
Water M	arks (B1)			Aquatic Inv	ertebrate/	es (B13)		_	_ Dr	y-Season Water Table (C2)
✓ Sedimer	nt Deposits (B2)			Hydrogen				_	_ Sa	turation Visible on Aerial Imagery (C9)
Drift Dep	oosits (B3)		✓	Oxidized R	Rhizosphe	res along l	iving Ro	oots (C3) _v	<u> </u>	eomorphic Position (D2)
Algal Ma	at or Crust (B4)			Presence of	of Reduce	ed Iron (C4)	_	_	allow Aquitard (D3)
	oosits (B5)			Recent Iro						C-Neutral Test (D5)
	Soil Cracks (B6)			Stunted or) (LRR /	A)		iised Ant Mounds (D6) (LRR A)
	on Visible on Aeria			Other (Exp	lain in Re	emarks)		-	Fro	ost-Heave Hummocks (D7)
	Vegetated Conca	ve Surface	(B8)							
Field Obser										
Surface Wat				Depth (inc		.1	-			
Water Table				Depth (inc			_			
Saturation P		Yes	No	Depth (inc	ches): un	ıknown	_ Wet	tland Hydro	ology	Present? Yes No
(includes cap Describe Re	ollary fringe) corded Data (strea	m gauge. m	nonitorina v	vell, aerial r	ohotos, pr	evious ins	pections)), if available	e:	
	(4.1.1.	33,	3	, ,	,,,		,	,		
Remarks:										
Could not di	g below 7" due to	river rock	k. This po	oint appea	rs to be	occasiona	ally inun	dated with	flow	ing water from stream.

Project/Site: Questa Tailings Pipeline Removal Project	ect	City/Cou	_{inty:} Questa/T	aos	Sampling Date:	5/10/2018
Applicant/Owner: Chevron	State: NM	Sampling Point:	Q-6b			
Fails O alamanda Tamas Kanalilla		Section.		nge:		
Landform (hillslope, terrace, etc.): terrace						pe (%): ⁴
Subregion (LRR): LRR E						
Soil Map Unit Name: Cumulic haploborolls, nearly lev				NWI classific		
Are climatic / hydrologic conditions on the site typical for the			,			
				"Normal Circumstances" p		/ No
Are Vegetation no , Soil no , or Hydrology no						NO
Are Vegetation <u>no</u> , Soil <u>no</u> , or Hydrology <u>no</u> SUMMARY OF FINDINGS – Attach site map				eeded, explain any answe	,	eatures, etc.
Hydrophytic Vegetation Present? Yes✓				·	· •	<u> </u>
Hydric Soil Present? Yes	No √		s the Sampled			
Wetland Hydrology Present? Yes	No <u> </u>	W	vithin a Wetlar	nd? Yes	No <u></u>	_
Remarks:						
Point placed on terrace elevated slightly above rive	er level, but	in ripari	ian vegetatior	n		
VEGETATION – Use scientific names of pla	nts.					
Tree Stratum (Plot size: 30'	Absolute		ant Indicator	Dominance Test work		
1. Populus angustifolia	65	yes	FACW	Number of Dominant S That Are OBL, FACW,		(A)
2. Abies concolor	10	no	NL			(A)
3. Juniperus scoparium	5	no	NL	Total Number of Domin Species Across All Stra		(B)
4.						(5)
15'	80	= Total	Cover	Percent of Dominant Sp That Are OBL, FACW,		(A/B)
Sapling/Shrub Stratum (Plot size: 15' Abies concolor	2	no	NL	Prevalence Index wor	ksheet:	
2. Salix exigua	2	no	FACW	Total % Cover of:	Multip	ly by:
3. Holodiscus discolor		yes	FACU		x 1 =	
4. Acer glabrum	5	yes	FACU	FACW species 67	x 2 = <u>13</u>	4
5. Rosa woodsi	1	no	FACU		x 3 =	
	15	= Total	Cover	FACU species 11		
Herb Stratum (Plot size: 5'					$x 5 = \frac{5}{18}$	^
1. Clematis occidentalis	_ 5	yes		Column Totals: 79	(^)	(B)
2. Bromus inermis	_ 1	no no	<u>UPL</u> NL	Prevalence Index		
3. Acnatherum robustum				Hydrophytic Vegetation		
4				1 - Rapid Test for I	-	tation
5				2 - Dominance Tes		
6				✓ 3 - Prevalence Inde		
8.				4 - Morphological A data in Remarks	daptations (Prov	
9.				5 - Wetland Non-Va	ascular Plants ¹	
10.				Problematic Hydro	ohytic Vegetation	(Explain)
11.				¹ Indicators of hydric soi		
30'	_	= Total	Cover	be present, unless distu	irbed or problema	itic.
Woody Vine Stratum (Plot size:)						
1				Hydrophytic		
2				Vegetation Present? Ye	s <u> </u>	
% Bare Ground in Herb Stratum 93		_= rotal	Cover			
Remarks:				1		
Populus angustifolia dominated riparian area						

		Q-6b
Sampling	Point:	~ 0.5

SOIL

Profile Desc	ription: (Describ	be to the de	pth needed to docu	ment the	indicator	or confir	m the absence	of indicators.)	
Depth	Matrix	(Redo	ox Feature	s				
(inches)	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²	Texture	Remarks	
0-2	10YR 2/2	100					loam	mostly organic	
2-12	10YR 4/2	98	7.5YR 6/8	2	С	M	sandy		
				_					
	-				· ——		· -		
-			-		· ——			·	
				_					
			-						
1Tunor C. C.		landation DA	1 Dadward Matrix C	C Covers	d or Coots	d Cond C	roino ² l o	notion. DI Doro Lining M Matrix	
			I=Reduced Matrix, C I LRRs, unless othe			a Sana G		cation: PL=Pore Lining, M=Matrix. prs for Problematic Hydric Soils ³ :	
Histosol		ilicable to al	Sandy Redox (m Muck (A10)	
	oipedon (A2)		Stripped Matrix	. ,				Parent Material (TF2)	
Black Hi			Loamy Mucky		1) (except	MLRA 1		y Shallow Dark Surface (TF12)	
	n Sulfide (A4)		Loamy Gleyed	,			. —	er (Explain in Remarks)	
	d Below Dark Surf	ace (A11)	Depleted Matri	x (F3)	,				
	ark Surface (A12)		Redox Dark Su	, ,				ors of hydrophytic vegetation and	
	lucky Mineral (S1		Depleted Dark		- 7)			and hydrology must be present,	
	Bleyed Matrix (S4)		Redox Depress	sions (F8)			unles	ss disturbed or problematic.	
	Layer (if present)):							
Type: roc								,	
Depth (inc	ches): <u>12"</u>						Hydric Soil	Present? Yes No _✓	
Remarks:									
HYDROLO	GY								
	drology Indicator	rs.							
_			ed; check all that app	lv)			Seco	ndary Indicators (2 or more required)	
-	Water (A1)	n one require	Water-Sta		os (BQ) (a	vcont		Vater-Stained Leaves (B9) (MLRA 1, 2,	
	ater Table (A2)			1, 2, 4A, a		kcept	v	4A, and 4B)	
Saturation			Salt Crust		anu 46)		г	Orainage Patterns (B10)	
	larks (B1)		Aquatic In	, ,	s (B13)		Drainage Fatterns (B10) Dry-Season Water Table (C2)		
· 	nt Deposits (B2)			Sulfide O	, ,			Saturation Visible on Aerial Imagery (C9)	
	posits (B3)				eres along	Livina Ro		Geomorphic Position (D2)	
	at or Crust (B4)				ed Iron (C4			Shallow Aquitard (D3)	
	oosits (B5)				ion in Tille			AC-Neutral Test (D5)	
	Soil Cracks (B6)				l Plants (D			Raised Ant Mounds (D6) (LRR A)	
	on Visible on Aeria	al Imagery (F				., (=		rost-Heave Hummocks (D7)	
· 	/ Vegetated Conc		,		,			,	
Field Obser			(- /						
Surface Water	er Present?	Yes	No <u>✓</u> Depth (in	ches):					
Water Table									
					land Hydrolog	y Present? Yes No _✓			
(includes cap		103	No _ · Dopui (ii			_ ****	iana myarolog	y resent: res No	
Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:									
Remarks:									

APPENDIX B

PHOTOGRAPH LOG





Photo 1. Photo 2.





Photo 3. Photo 4.



Photo 5.



Photo 7.



Photo 6. Flicker Nest



7. Photo 8.



Photo 9.



Photo 11.



Photo 10. 4th Red River Crossing



Photo 12.

3 of 13



Photo 13.



Photo 15.



Photo 14.



Photo 16.



Photo 17.



Photo 19.



Photo 18.



Photo 20a. 3rd Red River Crossing



Photo 20b. 3rd Red River Crossing



Photo 21a. 2nd Red River Crossing (Thunder Bridge)



Photo 21. 2nd Red River Crossing (Thunder Bridge)



Photo 21b. 2nd Red River Crossing (Thunder Bridge)



Photo 22a. 1st Red River Crossing



Photo 23a.



Photo 22b. 1st Red River Crossing



23a. Photo 23b.





Photo 24. Photo 25.








Photo 27.

8 of 13 201806_PhotoLog_APP-B.doc



Photo 28a. Culverts Under Road



Photo 28b.







Photo Q-1.

9 of 13 201806_PhotoLog_APP-B.doc





Photo Q-2



Photo Q-3a. Non-hydric Soil



Photo Q-3a.

Photo Q-3b. General Area



Photo Q-3b. Toward River



Photo Q-4. Non-hydric Soil (Chroma greater than 2)



Photo Q-3b Under Trestle – Away From River



Photo Q-4a





Photo Q-4b.



Photo Q-5a. Iron Deposits



Photo Q-5a. PSS Wetland

Photo Q-5a



Photo Q-5b. Non-hydric Coil (High Chroma)





Photo Q-5b.



Photo Q-6a. Photo Q-6b

13 of 13 201806_PhotoLog_APP-B.doc

APPENDIX C

USFWS OFFICIAL SPECIES LIST



United States Department of the Interior

FISH AND WILDLIFE SERVICE

New Mexico Ecological Services Field Office 2105 Osuna Road Ne Albuquerque, NM 87113-1001 Phone: (505) 346-2525 Fax: (505) 346-2542

http://www.fws.gov/southwest/es/NewMexico/ http://www.fws.gov/southwest/es/ES Lists Main2.html



In Reply Refer To: April 06, 2018

Consultation Code: 02ENNM00-2018-SLI-0619

Event Code: 02ENNM00-2018-E-01355

Project Name: Questa Tailings Pipeline Removal

Subject: List of threatened and endangered species that may occur in your proposed project

location, and/or may be affected by your proposed project

To Whom It May Concern:

Thank you for your recent request for information on federally listed species and important wildlife habitats that may occur in your project area. The U.S. Fish and Wildlife Service (Service) has responsibility for certain species of New Mexico wildlife under the Endangered Species Act (ESA) of 1973 as amended (16 USC 1531 et seq.), the Migratory Bird Treaty Act (MBTA) as amended (16 USC 701-715), and the Bald and Golden Eagle Protection Act (BGEPA) as amended (16 USC 668-668c). We are providing the following guidance to assist you in determining which federally imperiled species may or may not occur within your project area and to recommend some conservation measures that can be included in your project design.

FEDERALLY-LISTED SPECIES AND DESIGNATED CRITICAL HABITAT

Attached is a list of endangered, threatened, and proposed species that may occur in your project area. Your project area may not necessarily include all or any of these species. Under the ESA, it is the responsibility of the Federal action agency or its designated representative to determine if a proposed action "may affect" endangered, threatened, or proposed species, or designated critical habitat, and if so, to consult with the Service further. Similarly, it is the responsibility of the Federal action agency or project proponent, not the Service, to make "no effect" determinations. If you determine that your proposed action will have "no effect" on threatened or endangered species or their respective critical habitat, you do not need to seek concurrence with the Service. Nevertheless, it is a violation of Federal law to harm or harass any federally-listed threatened or endangered fish or wildlife species without the appropriate permit.

If you determine that your proposed action may affect federally-listed species, consultation with the Service will be necessary. Through the consultation process, we will analyze information contained in a biological assessment that you provide. If your proposed action is associated with Federal funding or permitting, consultation will occur with the Federal agency under section 7(a) (2) of the ESA. Otherwise, an incidental take permit pursuant to section 10(a)(1)(B) of the ESA (also known as a habitat conservation plan) is necessary to harm or harass federally listed threatened or endangered fish or wildlife species. In either case, there is no mechanism for authorizing incidental take "after-the-fact." For more information regarding formal consultation and HCPs, please see the Service's Consultation Handbook and Habitat Conservation Plans at www.fws.gov/endangered/esa-library/index.html#consultations.

The scope of federally listed species compliance not only includes direct effects, but also any interrelated or interdependent project activities (e.g., equipment staging areas, offsite borrow material areas, or utility relocations) and any indirect or cumulative effects that may occur in the action area. The action area includes all areas to be affected, not merely the immediate area involved in the action. Large projects may have effects outside the immediate area to species not listed here that should be addressed. If your action area has suitable habitat for any of the attached species, we recommend that species-specific surveys be conducted during the flowering season for plants and at the appropriate time for wildlife to evaluate any possible project-related impacts.

Candidate Species and Other Sensitive Species

A list of candidate and other sensitive species in your area is also attached. Candidate species and other sensitive species are species that have no legal protection under the ESA, although we recommend that candidate and other sensitive species be included in your surveys and considered for planning purposes. The Service monitors the status of these species. If significant declines occur, these species could potentially be listed. Therefore, actions that may contribute to their decline should be avoided.

Lists of sensitive species including State-listed endangered and threatened species are compiled by New Mexico state agencies. These lists, along with species information, can be found at the following websites:

Biota Information System of New Mexico (BISON-M): www.bison-m.org

New Mexico State Forestry. The New Mexico Endangered Plant Program: www.emnrd.state.nm.us/SFD/ForestMgt/Endangered.html

New Mexico Rare Plant Technical Council, New Mexico Rare Plants: nmrareplants.unm.edu

Natural Heritage New Mexico, online species database: nhnm.unm.edu

WETLANDS AND FLOODPLAINS

Under Executive Orders 11988 and 11990, Federal agencies are required to minimize the destruction, loss, or degradation of wetlands and floodplains, and preserve and enhance their natural and beneficial values. These habitats should be conserved through avoidance, or mitigated to ensure that there would be no net loss of wetlands function and value.

We encourage you to use the National Wetland Inventory (NWI) maps in conjunction with ground-truthing to identify wetlands occurring in your project area. The Service's NWI program website, www.fws.gov/wetlands/Data/Mapper.html integrates digital map data with other resource information. We also recommend you contact the U.S. Army Corps of Engineers for permitting requirements under section 404 of the Clean Water Act if your proposed action could impact floodplains or wetlands.

MIGRATORY BIRDS

The MBTA prohibits the taking of migratory birds, nests, and eggs, except as permitted by the Service's Migratory Bird Office. To minimize the likelihood of adverse impacts to migratory birds, we recommend construction activities occur outside the general bird nesting season from March through August, or that areas proposed for construction during the nesting season be surveyed, and when occupied, avoided until the young have fledged.

We recommend review of Birds of Conservation Concern at website www.fws.gov/migratorybirds/CurrentBirdIssues/Management/BCC.html to fully evaluate the effects to the birds at your site. This list identifies birds that are potentially threatened by disturbance and construction.

BALD AND GOLDEN EAGLES

The bald eagle (*Haliaeetus leucocephalus*) was delisted under the ESA on August 9, 2007. Both the bald eagle and golden eagle (*Aquila chrysaetos*) are still protected under the MBTA and BGEPA. The BGEPA affords both eagles protection in addition to that provided by the MBTA, in particular, by making it unlawful to "disturb" eagles. Under the BGEPA, the Service may issue limited permits to incidentally "take" eagles (e.g., injury, interfering with normal breeding, feeding, or sheltering behavior nest abandonment). For information on bald and golden eagle management guidelines, we recommend you review information provided at www.fws.gov/midwest/eagle/guidelines/bgepa.html.

On our web site www.fws.gov/southwest/es/NewMexico/SBC_intro.cfm, we have included conservation measures that can minimize impacts to federally listed and other sensitive species. These include measures for communication towers, power line safety for raptors, road and highway improvements, spring developments and livestock watering facilities, wastewater facilities, and trenching operations.

We also suggest you contact the New Mexico Department of Game and Fish, and the New Mexico Energy, Minerals, and Natural Resources Department, Forestry Division for information regarding State fish, wildlife, and plants.

Thank you for your concern for endangered and threatened species and New Mexico's wildlife habitats. We appreciate your efforts to identify and avoid impacts to listed and sensitive species in your project area. For further consultation on your proposed activity, please call 505-346-2525 or email nmesfo@fws.gov and reference your Service Consultation Tracking Number.

Attachment(s):

Official Species List

Official Species List

This list is provided pursuant to Section 7 of the Endangered Species Act, and fulfills the requirement for Federal agencies to "request of the Secretary of the Interior information whether any species which is listed or proposed to be listed may be present in the area of a proposed action".

This species list is provided by:

New Mexico Ecological Services Field Office 2105 Osuna Road Ne Albuquerque, NM 87113-1001 (505) 346-2525

Project Summary

Consultation Code: 02ENNM00-2018-SLI-0619

Event Code: 02ENNM00-2018-E-01355

Project Name: **Questa Tailings Pipeline Removal**

** OTHER ** Project Type:

Project Description: The proposed project entails demolition of a decommissioned mill tailings

pipeline and ancillary structures associated with the Questa MIne. The tailings pipeline was constructed to transport mill tailings, as a slurry, from the mine to the Tailings Facility. The tailings pipeline begins approximately 7 miles east of the Village of Questa, NM, at the Questa Mine, parallels Highway 38, down the Red River Canyon, through the Village of Questa, NM, terminating at the Tailings Facility. The majority of the tailings pipeline was constructed on property owned by Chevron (CEMC) and the USFS (see Figure 10). A portion of the pipeline crosses private property. The pipeline crosses Red River, Columbine Creek (a tributary to the Red River), Embargo Ditch, and unnamed ditches (see Table 1). Structures associated with the pipeline will also be removed, including the Lower Dump Sump and support buildings, three old bridges, and two elevated trestles. The pipeline and associated above ground structures will be removed from the Questa Mine to the Tailings

Facility.

Project Location:

Approximate location of the project can be viewed in Google Maps: https:// www.google.com/maps/place/36.69288813708551N105.49927318090664W



3

Counties: Taos, NM

Endangered Species Act Species

There is a total of 5 threatened, endangered, or candidate species on this species list.

Species on this list should be considered in an effects analysis for your project and could include species that exist in another geographic area. For example, certain fish may appear on the species list because a project could affect downstream species. Note that 1 of these species should be considered only under certain conditions.

IPaC does not display listed species or critical habitats under the sole jurisdiction of NOAA Fisheries¹, as USFWS does not have the authority to speak on behalf of NOAA and the Department of Commerce.

See the "Critical habitats" section below for those critical habitats that lie wholly or partially within your project area under this office's jurisdiction. Please contact the designated FWS office if you have questions.

1. <u>NOAA Fisheries</u>, also known as the National Marine Fisheries Service (NMFS), is an office of the National Oceanic and Atmospheric Administration within the Department of Commerce

Mammals

NAME STATUS

Canada Lynx *Lynx canadensis*

Threatened

Population: Wherever Found in Contiguous U.S.

There is **final** critical habitat for this species. Your location is outside the critical habitat.

Species profile: https://ecos.fws.gov/ecp/species/3652

New Mexico Meadow Jumping Mouse Zapus hudsonius luteus

Endangered

There is **final** critical habitat for this species. Your location is outside the critical habitat.

This species only needs to be considered under the following conditions:

• If project affects dense herbaceous riparian vegetation along waterways (stream, seep, canal/ditch).

Species profile: https://ecos.fws.gov/ecp/species/7965

Birds

NAME STATUS

Mexican Spotted Owl Strix occidentalis lucida

Threatened

There is **final** critical habitat for this species. Your location is outside the critical habitat.

Species profile: https://ecos.fws.gov/ecp/species/8196

Southwestern Willow Flycatcher Empidonax traillii extimus

Endangered

There is **final** critical habitat for this species. Your location is outside the critical habitat.

Species profile: https://ecos.fws.gov/ecp/species/6749

Yellow-billed Cuckoo Coccyzus americanus

Threatened

Population: Western U.S. DPS

There is **proposed** critical habitat for this species. Your location is outside the critical habitat.

Species profile: https://ecos.fws.gov/ecp/species/3911

Critical habitats

THERE ARE NO CRITICAL HABITATS WITHIN YOUR PROJECT AREA UNDER THIS OFFICE'S JURISDICTION.

APPENDIX D

URS QUESTA REMOVAL ACTION WETLAND ASSESSMENT REPORT



REPORT

QUESTA REMOVAL ACTION WETLAND ASSESSMENT REPORT

REVISION 1

Prepared for Chevron Mining Inc. Questa, New Mexico

June 28, 2013

URS

URS Corporation 8181 E. Tufts Avenue Denver, CO 80237

Project No. 22242831

TABLE OF CONTENTS

Section 1	Introd	ductionduction	1-1			
	1.1 Removal Action					
	1.2	Regulatory Authority	1-2			
		1.2.1 Regulatory Requirements	1-2			
Section 2	Existi	ing Conditions	2-1			
	2.1	Site Description	2-1			
		2.1.1 Soils				
		2.1.2 Vegetation				
		2.1.3 Hydrology				
0 (0	3.5 (1					
Section 3	wetno	odology	3-1			
Section 4	Resul	lts	4-1			
	4.1	Tailing Spill Deposits	4-2			
	4.2	Eagle Rock Lake				
	4.3	Eastern Diversion Channel				
	4.4	Wetland Functional Assessment	4-4			
	4.5	Jurisdiction	4-4			
Section 5	Impac	ct Analysis	5-1			
Section 6	Mitiga	ation	6-1			
Section 7	Concl	lusion	7-1			
Section 8	Litera	ture Cited	8-1			
List of Tabl	es					
Table 1 Delin	eated V	Wetlands in the Removal Action Areas	4-1			
Table 2 Delin	eated S	Surface Water Features in the Removal Action Areas	4-1			
List of App	endice	es e				
Appendix A	Figure	res				
Appendix B	Photo	ographs				
Appendix C	Indivi	idual Wetland Data Forms				

ACRONYMS

APD Approved Jurisdictional Determination

CERCLA Comprehensive Environmental Response, Compensation, and Liability Act

CFR Code of Federal Regulations

CMI Chevron Mining, Inc.

CWA Clean Water Act

EDC Eastern Diversion Channel

E.O. Executive Order

EPA Environmental Protection Agency (United States)

ERL Eagle Rock Lake

GPS Global positioning system

HTS Historic Tailing Spills

mg/kg Milligram per kilogram

N North

NRCS Natural Resource Conservation Service

OW Other water

PCB Polychlorinated biphenyls

PEM Palustrine Emergent
PFO Palustrine Forested

PJD Preliminary Jurisdictional Determination

PSS Palustrine Scrub-shrub

R Range

RA Removal Action

RI/FS Remedial Investigation/Feasibility Study

SOW Statement of Work

T Township

URS URS Corporation

USACE United States Army Corps of Engineers
USDA United States Department of Agriculture
USFWS United States Fish and Wildlife Service

USF WS United States Fish and Whalle Service

USGS United States Geological Survey

W West

WUS Waters of the United States

1-1

The Chevron Questa Mine, which is owned and operated by Chevron Mining Inc. (CMI), includes an active underground molybdenum mine, a milling facility, a historic open pit, and waste rock piles. The Questa Mine encompasses approximately three square miles of land located 3.5 miles east of the village of Questa, New Mexico. The Questa Mine property also includes tailing disposal impoundments (Tailing Facility) covering approximately 2 square miles of land located west of the village of Questa.

The Questa Mine site was the focus of the CMI Remedial Investigation/Feasibility Study (RI/FS) (URS 2009a, URS 2009b). The Removal Action (RA) was required by the United States Environmental Protection Agency (EPA) Administrative Settlement Agreement and Order on Consent for Removal Actions, CERCLA Docket No. 06-09-12 and its appended Statement of Work (SOW) (EPA 2012). The RA to be conducted includes:

- Installation of inlet storm water controls at Eagle Rock Lake, removal of sediment from the lake, and on-site disposal of excavated material
- Removal of polychlorinated biphenyl (PCB) –contaminated soil in the Mill Area and offsite disposal of the evacuated soil
- Installation of pipe to convey unused irrigation water in the Eastern Diversion Channel (EDC) to prevent infiltration through historic buried tailing
- Removal of historic tailing spill deposits along the Red River riparian area and on-site disposal at the Tailing Facility.

The RA work to be accomplished in compliance with the SOW has the potential to impact wetlands and surface water features. This Wetland Assessment Report discusses the regulatory framework, substantive requirements, methodology, and results of wetland delineations within areas subject to RA. The report does not include the analysis of impacts and mitigation strategies to avoid and minimize any impacts to wetlands, or to compensate for wetland impacts that cannot be minimized by other methods. Project Specific Technical Memorandum addressing impacts and mitigation will be submitted under separate cover. This report was prepared by URS Corporation (URS) on behalf of Chevron Environmental Management Company (CEMC).

1.1 REMOVAL ACTION

Three RA areas were considered in this report. These include the Historic Tailing Spills (HTS) Deposits (Tailing Spill Deposits), Eagle Rock Lake, and Eastern Diversion Channel. The RA areas are located near the Village of Questa, Taos County, New Mexico (Appendix A, Figure 1) and can be found on the Questa United States Geological Survey (USGS) 7.5-minute topographic quadrangle map (USGS 1963) within Township (T) 29 North (N), Range (R) 12 West (W), Sections 25 and 36 (Eastern Diversion Channel), and T 28 N, R 13 W (Eagle Rock Lake and HTS). Eagle Rock Lake is located along Highway 38, east of Questa. The Eastern Diversion Channel is located within the Questa Mine Tailing Facility, adjacent to the west of Questa.

The tailing spill deposit sites occur at various locations along the tailing pipeline between the mill and the Tailing Facility. The tailing pipeline is 9 miles long, but most of the sites are

URS

located in the first 2.5 miles below the mill. The senior wetland delineator was part of the field team that initially identified the HTS sites in 2002, and subsequently re-visited the HTS sites in 2010, 2011, 2012, and 2013. Based on these previous field visits, only one of the HTS sites was considered to have a potential to be a wetland, Tailing Spill Deposit 1, and was included in the wetland delineation field work. All of the other sites are dominated by upland vegetation and have no evidence of wetland hydrology and were not re-visited for the wetland delineation.

Descriptions of activities related to the RA are provided in the respective RA work plans - Historic Tailing Spills RA Work Plan (URS 2012), Eagle Rock Lake RA Work Plan (Arcadis 2012), and Eastern Diversion Channel RA Work Plan (AECOM 2012). At this time, proposed remedial action activities within the Eastern Diversion Channel have not been approved by the EPA.

1.2 REGULATORY AUTHORITY

The following provides a summary of applicable regulatory requirements pertinent to wetlands.

1.2.1 Regulatory Requirements

Office of Solid Waste Management Response Directive 9280.0-02 (August 1985)

Under the Office of Solid Waste Management Response Directive 9280.0-02, the Environmental Protection Agency (EPA) must meet the substantive requirements of Executive Order (E.O.) 11988 (Floodplain Management Executive Order) and E.O. 11990 (Executive Order for the Protection of Wetlands). The EPA is directed to avoid the short- and long-term destruction or modification of wetlands and to avoid direct or indirect support of new construction in wetlands when there is a practicable alternative within CERCLA sites.

Clean Water Act

Section 404 of the Clean Water Act (CWA), implemented by the U.S. Army Corps of Engineers (USACE) and EPA, regulates discharges of dredged of fill material into waters of the United States (WUS), including special aquatic sites such as wetlands. Federal regulations promulgated under Section 404 define wetlands as "areas that are inundated or saturated by surface or ground water at a frequency and duration sufficient to support, and that under normal circumstances do support, a prevalence of vegetation typically adapted for life in saturated soil conditions. Wetlands generally include swamps, marshes, bogs, and similar areas." (33 Code of Federal Regulations [CFR] 328.3(b).) Section 404 also protects a variety of surface waters such as lakes, ponds, streams, and rivers.

In general, response actions selected under CERCLA that involve the discharge of dredge or fill material into waters of the United States or associated areas under CWA Section 404 jurisdiction must meet the substantive requirements of Section 404. RAs must seek to avoid or minimize impacts to WUS whenever practicable, as long as the alternative does not have other significant adverse environmental consequences. When unavoidable impacts to WUS occur, these impacts must be mitigated.

URS

New Mexico State Regulations and Guidance

The State of New Mexico does not have state regulations equivalent to the Section 404 permit program operated by the USACE; however, the State reviews 404 projects under CWA Section 401 state certification provisions. An individual state Water Quality Certification is required for discharges to all intermittent, perennial, and wetland surface waters. This program is administered by the Surface Water Quality Bureau of the New Mexico Environment Department.

URS 1-3

2.1 SITE DESCRIPTION

The Tailing Spill Deposit 1 and Eagle Rock Lake RA areas are located in the Volcanic Mid-Elevation Forests of New Mexico (Griffith et al. 2006). The Volcanic Mid-Elevation Forest ecoregion is a region of mostly Pliocene basaltic lavas with distinct cones of Pliocene composite volcanoes in an area of low mountain ridges, slopes, and outwash fans. Dominant vegetative communities in the region are ponderosa pine (*Pinus ponderosa*) forests with an understory of shrubs and a sparsely vegetated herbaceous stratum.

The Eastern Diversion Channel is located within the Taos Plateau ecoregion (Griffith et al. 2006) and is characterized by a rolling to level plateau with volcanic cones. A dominant feature of the Taos Plateau is the Rio Grande River Gorge and its steep side canyons. The geology of the area comprises Quaternary eolian deposits, colluvium, piedmont and fan alluvium, block-rubble colluvium, and Tertiary (mostly Pliocene) basalt and volcanic rocks. Big sagebrush (*Artemisia tridentata*) is the dominant vegetative community in the ecoregion.

2.1.1 Soils

Soils within the RA areas comprise two dominant types. Sedillo-Silva association, strongly sloping, are loamy-skeletal or fine, mixed, mesic Ustollic Haplargids, consisting of loams, with rooting depths of more than 60 inches. The parent material comprises alluvium derived from igneous and metamorphic rock and eolian material (NRCS 2012). These are the dominant soils within the Eastern Diversion Channel. Cumulic Haplaquolls, nearly level, are the taxonomic type whose parent material is alluvium derived from igneous and metamorphic rock. This soil is classified as predominantly hydric and is found around Eagle Rock Lake and Tailing Spill Deposit 1.

2.1.2 Vegetation

General vegetation communities in the study areas include ponderosa pine forest, mixed conifer/riparian forest, sagebrush shrub steppe, wetlands/riparian, and disturbed/barren.

Ponderosa pine forest vegetative community occurs at the elevation of Eagle Rock Lake and is dominated by mature ponderosa pine in open stands with an understory of shrubs and herbaceous cover. Typical shrub cover varies from 10 to 40 percent, with approximately 25 percent herbaceous cover. Dominant understory species include smooth brome (*Bromus inermis*), Apache plume (*Fallugia paradoxa*), Rocky Mountain juniper (*Juniperus scopularum*), silvery lupine (*Lupinus argenteus*), Gambel oak (*Quercus gambellii*), skunkbush (*Rhus aromatica*), and Wood's rose (*Rosa woodsii*).

Mixed conifer/riparian is the dominant vegetative community around Tailing Spill Deposit 1. Engelmann spruce (*Picea engelmanii*) and narrowleaf cottonwood (*Salix angustifolia*) comprise the dominant tree species. Understory shrub species include Rocky Mountain juniper, smooth brome, Wood's rose, mountain snowberry (*Symphoricarpos oreophilis*), Rocky Mountain maple (*Acer glabrum*), field sagewort (*Artemisia campestris*), fringed sage (*Artemisia frigida*), rubber rabbitbrush (*Ericameria nauseosus*), ninebark (*Physocarpos monogynus*), and intermediate wheatgrass (*Thinopryum intermedium*). Approximately half of the soil cover comprises small rocks and litter.

URS 2-1

Sagebrush (*Artemisia tridentata*) **shrub steppe** communities are dominated by sagebrush and rabbitbrush (*Ericameria nauseosa*), with a sparse understory of grasses and caespitose forbs. These communities may also include pinyon/juniper associations. Portions of the soil surface may be covered with cryptogamic crusts. This is the predominant vegetation community on the slopes of the EDC.

Wetland/riparian areas are found within all the RA areas. This vegetative community occurs as two distinct classifications: emergent or marsh dominated, and tree dominated. Emergent wetlands are dominated by sedges (*Carex* spp.), rushes (*Juncus* spp.) and other hydrophytic grasses and forbs. These areas may also support a small percentage of shrub cover. Tree dominated wetlands are dominated by woody species providing about 50 to 75 percent cover, primarily of narrowleaf cottonwood, speckled alder (*Alnus incana*), river birch (*Betula occidentalis*), and sandbar willow (*Salix exigua*). Wetland/riparian areas are discussed in more detail in Section 4, Results.

Barren/disturbed areas are the result of human-made disturbance and include two-track and paved roads, buildings, and other structures. These areas may support some weedy or landscape vegetation.

2.1.3 Hydrology

The RA areas are located within Hydrologic Unit Code 13020101, the Upper Rio Grande Watershed, that begins at the Colorado/New Mexico border and drains an area of approximately 3,220 square miles (USGS 2010), including 94.79 percent of Taos County (USDA 2008). The largest waterbody associated with the RA areas is the Red River, a perennial stream that originates in the Sangre de Cristo Mountains and forms a confluence with the Rio Grande River southwest of Questa.

2.1.4 Wildlife

Dominant life forms in the region include large and small mammals and birds. Wildlife or their signs observed within the RA areas included North American beaver (*Castor canadensis*), elk (*Cervus elaphus*), belted kingfisher (*Ceryle alcyon*), pocket gopher (*Geomys bursarius*), junco (*Junco hyemalis*), mule deer (*Odocoileus hemionus*), raccoon (*Procyon lotor*), and bushtit (*Psaltriparus minimus*).

URS 2-2

Study areas were determined by overlaying the Project drawings over aerial photographs and applying a buffer. Buffer widths varied depending on topography. Field maps were created with ESRI® ArcGIS® software (1 inch equals 200 feet). Pre-field research included the review of National Wetland Inventory maps (USFWS 2012), topographic maps (USGS 1963), and previous environmental reports from the area.

URS ecologists Jeffrey Dawson and Susan Hall walked the RA areas between October 15 and 18, 2012, to delineate wetlands and surface water features. Ambient temperatures averaged between approximately 45 and 70 degrees Fahrenheit. Weather was sunny throughout the delineation period.

Wetland delineations were conducted using the Routine Determination protocol discussed in the Corps of Engineers Wetland Delineation Manual Technical Report 4-87-1 (Environmental Laboratory 1987) and two supplemental delineation manuals. The Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Western Mountains, Valleys, and Coasts (Environmental Laboratory 2010) was used within the ponderosa forest and mixed conifer/riparian upland vegetative communities. The Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Arid West Region Environmental Laboratory 2008) was used in the sagebrush shrub steppe upland vegetative community. Delineation field methods included evaluation of dominant plant species and percent cover, digging of a soil pit to observe soil characteristics, and observations of hydrological indicators in the soil pit and on the surface. Standard data sheets were completed for each wetland and a nearby paired upland observation point.

Wetlands were identified in the field as areas having positive evidence of three environmental parameters: hydric soils, wetland hydrology, and greater than five percent hydrophytic vegetation. Some wetlands can be difficult to identify because wetland indicators are missing due to natural processes or recent disturbances. The supplemental delineation manuals include procedures to follow for wetlands that naturally lack indicators and for atypical situations where indicators are absent due to disturbance. Wetland data were recorded on USACE approved individual wetland data forms. Features delineated but subsequently excluded as wetlands were also recorded on data forms.

During field surveys, wetland vegetation was classified using the Cowardin classification system (Cowardin, et al. 1979), a USACE accepted vegetation classification system. Wetlands within the RA areas were classified as Palustrine Emergent (PEM), Palustrine Scrub-shrub (PSS), or Palustrine Forested (PFO), or combinations of these classifications.

PEM wetlands are those aquatic features dominated by herbaceous emergent plants. Plant species commonly found in PEM wetlands in northern New Mexico include cattails (*Typha angustifolia*), sedges (*Carex* spp.), and rushes (*Juncus* spp.). PSS wetlands are those aquatic features dominated by shrubs under 20 feet tall or with trunks or stems less than 3 inches in diameter. Common PSS plant species found in this region include willow (*Salix* spp.), alder (*Alnus* spp.) and small cottonwoods (*Populus* spp.). PFO wetlands are dominated by trees greater than 20 feet high with stems greater than 3 inches in diameter. PFO wetland species composition commonly includes cottonwood, larger willows, and river birch (*Betula occidentalis*). Combinations of these communities may also be present in a wetland.

URS 3-1

Surface water features (i.e., streams and ponds) were identified by the presence of a defined bed and bank, evidence of an ordinary high water or bankfull indicator, and less than 50 percent vegetative cover within the bed. Information recorded for each surface water feature included depth and width of the average ordinary high water mark, average bankfull depth, bank slope, substrate composition, source of hydrology, dominant vegetation, other vegetation, percent overstory, and any wildlife or their signs observed.

The boundaries of wetlands and surface water features were recorded using a Trimble[®] submeter hand-held global positioning system (GPS) and photographs were taken of each feature. Unique identifiers were assigned to each feature delineated based on location. For example, the first wetland identified within the Eastern Diversion Channel was assigned a unique identifier of EDC-1.

URS 3-2

A total of eight aquatic features encompassing approximately 5.9 acres occur within the RA areas. Characteristics of wetland and surface water features are included in Tables 1 and 2 respectively, and are briefly discussed according to RA area below. RA area figures and associated photographs are included in Appendices A and B, respectively. Additional information regarding each wetland and surface water feature is included in the individual data forms in Appendix C.

Table 1
Delineated Wetlands in the Removal Action Areas

Type/ Classification	Wetland Identifier	Location (Latitude, Longitude)*	Size (acres)*	Proximity	Figure Number	Photograp h Number
PEM wetland	HTS-2	36.5949/- 105.4958	0.04	Adjacent to Red River	1	2
PEM wetland	ERL-PEM	36.7032/- 105.5730	0.24	Abuts OW-ERL-1	2	4
PFO wetland	ERL-PFO	36.7035/- 105.5727	0.31	Abuts OW-ERL-3	2	6, 7, 8
PEM wetland	EDC-1/ EDC-2	36.7086/- 105.6096, 36.7077/- 105.6099	2.71	Isolated	3	13, 14, 15
PEM/PSS wetland	EDC-3	36.6993/- 105.6195	<0.01	Isolated	4	21
	T	otal Wetlands	3.3			

^{*} All measurements are approximate.

Table 2
Delineated Surface Water Features in the Removal Action Areas

Type/ Classification	Surface Water Identifier	Location (Latitude, Longitude)*	Size (lf / acres)*	Flow Frequency	Flows to	Figure Number	Photograph Number
Impoundment	OW-ERL-1	36.7034/- 105.5742	2.42	Perennial	Red River	2	3, 4, 5
Perennial Stream	OW-ERL-2	36.7030/- 105.5751	759 / 0.18	Perennial	Rio Grande	2	9, 10, 11, 12
Ditch	OW-ERL-3	36.7035/- 105.5725	468 / 0.04	Perennial	Eagle Rock Lake	2	7,8

Total Surface Water Features 1,227 / 2.64

ERL = Eagle Rock Lake

If = linear feet

OW = Other Water

EDC = Eastern Diversion Channel

ERL = Eagle Rock Lake

HTS = Historic Tailing Spills

 $OW = Other\ Water$

PEM = Palustrine Emergent (Cowardin et al. 1979)

PSS = Palustrine Scrub-Shrub (Cowardin et al. 1979)

PFO = Palustrine Forested (Cowardin et al. 1979)

^{*} All measurements are approximate.

4.1 TAILING SPILL DEPOSITS

One wetland, identified as HTS-2 and totaling 0.04 acre was delineated within Tailing Spill Deposit 1. Wetland HTS-2 is a perched depression that formed between Highway 38 and a two-track road within the Red River riparian buffer. Although much of the feature is barren, a fringe of PEM vegetation is present around the edges of the feature, and dominated by Arctic rush (*Juncus arcticus*).

A second area within Tailing Deposit 1 that supports hydrophytic vegetation was also investigated as a wetland; however, it was determined that this feature did not meet the USACE wetland criteria for hydric soils and lacked evidence of hydrology. The soil pit for this feature (HTS-1) is included on Appendix A, Figure 2 and described in an Individual Wetland Data Form included in Appendix C.

No surface water features were delineated within the Tailing Spill Deposits area. Native soils occurring within the Tailing Spill Deposits area are not listed as hydric by the Natural Resource Conservation Service (NRCS 2012).

4.2 EAGLE ROCK LAKE

Eagle Rock Lake was originally a borrow pit for aggregate during the 1950's, used for construction of New Mexico State Highway 38 (Arcadis 2012). Subsequently, the depression was filled with water and a small park was established. The lake is currently maintained by the U.S. Forest Service and is used for recreation including fishing. Water is supplied from the Red River and discharge of water back to the Red River is controlled by outlet culverts.

Two wetlands totaling 0.55 acre and three surface water features totaling approximately 2.64 acres occur within the Eagle Rock Lake RA area. Eagle Rock Lake (OW-ERL-1) and its diversion channel (OW-ERL-3) support both PEM and PFO wetlands in distinct communities. A PEM wetland (ERL-PEM) (0.24 acre), dominated by beaked sedge (*Carex utriculuta*) and aquatic sedge (*Carex aquatilis*) occurs at the eastern edge of the lake. A discontinuous PEM fringe abuts the remainder of the shoreline and comprises redtop (*Agrostis gigantea*), creeping bentgrass (*Agrostis stolonifera*), showy milkweed (*Asclepias speciosa*), Nebraska sedge (*Carex nebrascensis*), orchardgrass (*Dactylis glomerata*), quackgrass (*Elymus repens*), finged willowherb (*Epilobium ciliatum*), knotted rush (*Juncus nodosus*), bog orchis (*Limnorchis* sp.), and narrowleaf cattail (*Typha angustifolia*). Small populations of sandbar willow and park willow (*Salix monticola*) are scattered throughout the feature.

Mature PFO wetlands are generally uncommon in western states, but can be found in the mountains of New Mexico, where they abut perennial streams in the lower reaches of canyons. The PFO wetland ERL-PFO primarily occurs along the Eagle Rock Lake diversion channel (OW-ERL-3) and encompasses 0.31 acre within the Eagle Rock Lake RA area. The wetland is characterized by a mature stand of narrowleaf cottonwood and speckled alder and this mature overstory cover comprises approximately 35 percent of the canopy. Understory shrubs make up approximately 67 percent of cover, and are dominated by narrowleaf cottonwood, speckled alder, sandbar willow and river birch. The herbaceous understory is sparse, evident only in forest openings and edges. Herbaceous species observed include redtop, fringed willow-herb, wintercress (*Barbarea vulgaris*), and reed canarygrass (*Phalaris arundinacea*).

URS 4-2

Surface water features delineated within the Eagle Rock Lake RA area include Eagle Rock Lake (OW-ERL-1), the Red River (OW-ERL-2), and the Eagle Rock Lake diversion channel (OW-ERL-3). Eagle Rock Lake is a 2.5 acre manmade pond that is almost completely sustained by a diversion of the Red River, returning flows to the river via a restricted outlet. Water clarity in the lake is poor due to dissolved solids. The lake is used primarily for recreation, although it provides wildlife habitat, including habitat for North American beaver, which maintain a lodge on the north side of the lake. Recent conversations with the USFS indicate that the beaver habitat is undesirable in its current location and has been detrimental to mature vegetation around the lake. The USFS plans to remove the beaver lodge during some planned future work in the Red River stream bed. The Eagle Rock Lake diversion channel (OW-ERL-3) is a straight reach supporting a mature riparian buffer for approximately half its length. Where the channel grade reaches lake elevation, the channel supports a large PFO wetland (ERL-PFO described earlier).

The Red River is a perennial tributary of the Red River. Outside the Eagle Rock Lake RA area, the river maintains a low gradient and slow flows, and supports a mature woody overstory along shallow banks. Riffle-pool-run complexes occur regularly within the river in these reaches. Within the RA area, channel banks are severely downcut with evidence of erosion, flow velocity increases, and the banks are predominantly mature open ponderosa pine with no riparian buffer until the river reaches the western end of the lake. The Red River is not anticipated to be impacted by RA activities.

Native soils occurring within Eagle Rock Lake are listed as hydric by the Natural Resource Conservation Service (NRCS 2012). Soils exhibited a typical matrix hue of 10YR and high oxidized redox concentrations were the most common sign of hydric conditions. Evidence of gleying was only observed in small concentrations.

4.3 EASTERN DIVERSION CHANNEL

The Eastern Diversion channel is part of the tailing facility and was constructed in 1975 (AECOM 2012). Modifications were made to the channel over the years; most notably the channel embankments were excavated and used as borrow material for dam raises, which resulted in widening of the channel bottom in certain areas. Historically, the diversion channel was dry except after substantial rainfall, and was observed to be dry during the Remedial Investigations (RI) (2002 - 2004) (URS, 2009a). Beginning in 2004, water began to accumulate in the channel due to flood irrigation practices in the fields east of the tailing facility, and from discharge of unused irrigation water from the Cabresto Creek Ditch Lateral No. 4. The channel typically begins to fill with water in May and water has been observed in the channel throughout the year.

The largest wetland occurs within the Eastern Diversion Channel (EDC-1/EDC-2), totaling 2.71 acres. EDC-1 and EDC-2 were initially separated based on the presence of water and density of vegetation, but were subsequently determined to be part of the same feature. Data were collected to record changes in vegetation composition and other indicators. The wetland covers most of the channel bed. Dominant vegetation includes foxtail barley (*Hordeum jubatum*), narrowleaf cattail), and willow dock (*Rumex salicifolius*), with sandbar willow lining the edges of the channel bed. This feature supports three species of freshwater snail including disk gyro (*Gyraulus circumstriatus*), marsh pond snail (*Lymnaea elodes*), and pygmy fossaria (*Lymnaea parva*). Wetland vegetation is also present within the Eastern Diversion Channel upstream of the delineated area and within a side channel that is separated by a berm.

URS

Inundation, which occurs from the ponding of surface runoff and shallower grades, was observed in EDC-1 but was absent in EDC-2 at the time of the survey. It is likely that EDC-2 is inundated less frequently and/or for shorter periods than EDC-1.

The area immediately down-channel from EDC-1 and EDC-2 was investigated for wetland characteristics. This area is physically separated by a mine road and culverts, which are perched on the upslope side and partially filled with sediment. Although hydrology was observed in two of the five years for which aerial photography is available, this area did not meet the criteria to be delineated as a wetland. The soil pit for this feature (EDC-6) is included on Appendix A, Figure 5 and described in an Individual Wetland Data Form included in Appendix C.

To the south of EDC-6, the bottom of the EDC is much narrower and has little apparent gradient until it drops off steeply. Small to medium sized cottonwoods are common along the bottom of the channel in the level areas but no wetlands or stream channels are present. The steep portion of the channel is mostly rock.

A PEM/PSS wetland (EDC-3) totaling less than 0.01 acre was delineated near the southern end of the Eastern Diversion Channel, on a slope above the lower part the steep portion of the channel. EDC-3 is supported by a small spring that outflows to the Eastern Diversion Channel and wets a small portion of the channel bottom. The channel does not have an ordinary high water mark and the wetland is isolated. Two additional spring-supported wetlands were also observed along the slope of this area outside of the Study Area (Appendix A, Figure 6). The three spring-supported wetlands are located within a grove of cottonwoods and other woody plants.

Hydric soils were not observed in any soil pits within the Eastern Diversion Channel.

4.4 WETLAND FUNCTIONAL ASSESSMENT

A wetland functional assessment was not conducted because the areas delineated were either not natural wetlands or did not meet the size requirements of the New Mexico Rapid Assessment Method (Muldavin et al. 2011).

4.5 JURISDICTION

The decision in *Rapanos v. United States*, 547 U.S. 715 (2006), and the post-*Rapanos* guidance issued by the USACE and the EPA (2007), addressed the geographic extent of USACE jurisdiction. Under the guidance, traditional navigable waters, perennial or relatively permanent surface water features forming a confluence with a WUS, or features formed as a result of diversions from WUS and returning to WUS would also be considered jurisdictional by the USACE, as would wetlands abutting jurisdictional waterways. Under *Rapanos*, intermittent or ephemeral waterways, their abutting or adjacent wetlands, or wetlands adjacent to WUS are subject to additional review to determine if the feature has a "significant nexus" to a WUS.

As stated previously, CERCLA actions must meet the substantive requirements of other federal environmental laws. As such, Eagle Rock Lake (OW-ERL-1), the Red River (OW-ERL-2), the Eagle Rock Lake diversion channel (OW-ERL-3), and their abutting wetlands (ERL-PEM and ERL-PFO) would be considered USACE jurisdictional aquatic features. Conversely, upland ditches that are excavated wholly in and draining only uplands and without relatively permanent flow are excluded from jurisdiction under the *Rapanos* decision and guidance. Wetland

URS

SECTIONFOUR Results

EDC-1/EDC-2 falls under this category and would not be considered jurisdictional by the USACE. Determining the jurisdiction of wetland HTS-2 based on the USACE criteria is not conclusive; while it is located adjacent to the Red River it is perched above it and has no surface connection to the river.

The USACE defines isolated waters as those that are not traditionally navigable or interstate, including their tributaries, and abutting and adjacent wetlands. Isolated wetlands and surface water features were removed from USACE jurisdiction under the Solid Waste Agency of Northern Cook County (SWANCC) decision (SWANCC v. USACE, 531 U.S. 159 [2001]). Therefore, wetland EDC-3 would be excluded from USACE jurisdiction.

URS 4-5

SECTIONFIVE

Impact Analysis

Please refer to the Project Specific Technical Memorandum prepared to address the impact analysis for each individual removal action project and submitted under separate cover.

URS 5-1

SECTIONS IX Mitigation

Please refer to the Project Specific Technical Memorandum prepared to address mitigation for each individual removal action project and submitted under separate cover.

URS 6-1

Five wetlands and three surface water features totaling approximately 3.3 acres were identified and delineated within the RA areas. Of these, approximately 2.99 acres comprise PEM wetland, with approximately 0.31 acre of PFO wetlands present. A total of approximately 2.6 acres, or 1,227 linear feet of surface water features occur within the Eagle Rock Lake RA area. Surface water features include Eagle Rock Lake, the Red River, and the Eagle Rock Lake diversion channel.

CERCLA actions must meet the substantive requirements of other federal environmental laws, including Section 404 regulations. The determination of jurisdiction is a required element of the Section 404 program. Of the aquatic features, Eagle Rock Lake, the Red River, the Eagle Rock Lake diversion channel, and their abutting wetlands would be considered USACE jurisdictional aquatic features. Conversely, wetland EDC-1/EDC-2 would not be considered jurisdictional by the USACE due to its landscape position, construction, and lack of connectivity. EDC-3 would not be considered jurisdictional because it is an isolated feature. Determining the jurisdiction of wetland HTS-2 based on the USACE criteria is not conclusive.

URS 7-1

References

- AECOM. 2012. Eastern Diversion Channel Removal Action Work Plan for the Chevron Questa Mine Superfund Site, Questa, New Mexico. Prepared for Chevron Mining Inc., Questa, New Mexico. June.
- Arcadis. 2012. Final Eagle Rock Lake Removal Action Work Plan. Chevron Questa Mine Superfund Site, Questa, New Mexico. Prepared for Chevron Mining Inc. Questa Mine, Questa, New Mexico. Revision 1. June.
- Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. *Classification of Wetlands and Deepwater Habitats of the United States*. US Department of the Interior, Fish and Wildlife.
- Environmental Laboratory. 1987. *Corps of Engineers Wetland Delineation Manual Technical Report Y-87-1*. Prepared for the US Army Corps of Engineers, Washington, DC. Final Report. January.
- ______. 2008. Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Arid West Region (Version 2.0). ERDC/EL TR-08-28. U.S. Army Engineer Research and Development Center, 3909 Halls Ferry Road, Vicksburg, MS 39180-6199. September.
- ______. 2010. Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Western Mountains, Valleys, and Coasts (Version 2.0). ERDC/EL TR-10-3. U.S. Army Engineer Research and Development Center, 3909 Halls Ferry Road, Vicksburg, MS 39180-6199. May.
- Environmental Protection Agency (EPA). 1980. *Title 40: Protection of Environment Part 230—Section 404(b)(1) Guidelines for Specification of Disposal Sites for Dredged or Fill Material*. 45 FR 85344, Dec. 24, 1980. Available at http://www.epa.gov/owow/wetlands/pdf/40cfrPart230.pdf. Date of last update May 18, 2011. Date accessed November 26, 2012.
- ______. 2012. In re Chevron Mining Inc., Administrative Settlement Agreement and Order on Consent for Removal Actions, Chevron Questa Mine Superfund Site, Questa, New Mexico. CERCLA Docket 06-09-12 CERCLIS ID No. NMD002899094. March 8.
- Griffith, G.E., Omernik, J.M., McGraw, M.M., Jacobi, G.Z., Canavan, C.M., Schrader, T.S., Mercer, D., Hill, R., and B.C. Moran. 2006. *Ecoregions of New Mexico* (color poster with map, descriptive text, summary tables, and photographs): Reston, Virginia, U.S. Geological Survey (map scale 1:1,400,000).
- Muldavin, E.H., B. Bader, E.R. Milford, M. McGraw, D. Lightfoot, B. Nicholson, and G. Larson. 2011. *New Mexico Rapid Assessment Method: Montane Riverine Wetlands. Field Guide Version 1.1.* Final report to the New Mexico Environment Department, Surface Water Quality Bureau, Santa Fe New Mexico. 39 pp. and appendices.
- Natural Resource Conservation Service (NRCS). 2012. Web Soil Survey. Available at http://websoilsurvey.nrcs.usda.gov/app/HomePage.htm. Date of last update February 17, 2012. Date accessed November 27, 2012.

URS 8-1


SECTIONEIGHT


- United States Department of Agriculture (USDA). 2008. *Upper Rio Grande Watershed Hydrologic Unit Code 13020101 Rapid Assessment*. Natural Resources Conservation Service, Lakewood, Co. April.
- United States Fish and Wildlife Service (USFWS). 2012a. *National Wetlands Inventory*. Available at: http://www.fws.gov/wetlands/Data/Mapper.html. Accessed on October 12, 2012.
- United States Geological Survey (USGS). 1963. 7.5 Minute Quadrangle: Questa, New Mexico.
- USGS. 2010. Water Resources of the United States. *Boundary Descriptions and Names of Regions, Subregions, Accounting Units and Cataloging Units*. Available at http://water.usgs.gov/GIS/huc_name.html#Region10. Date of last update July 29, 2010. *Accessed December* 22, 2010.
- URS. 2009a. *Molycorp Remedial Investigation Report. Revision 2*. Prepared for Questa Mine, Chevron Mining Inc. Questa, New Mexico. July.
- ______. 2009b. *Chevron Mining Inc. Feasibility Study Report, Revision 3.0.* Prepared for Chevron Mining Inc. Questa Mine, Questa, New Mexico. November.
- ______. 2012. *Historic Tailing Spills Removal Action Work Plan*. Chevron Questa Mine Superfund Site. Prepared for Chevron Mining Inc. Questa Mine, Questa, New Mexico. May.


URS 8-2


Appendix A Figures


URS A-1














Appendix B Photographs



Photograph 1. To Southwest. View of feature HTS-1. This area did not meet the three substantive criteria for wetlands.



Photograph 2. To East. View of wetland HTS-2.



Photograph 3. To East. View of Eagle Rock Lake (OW-ERL1).



Photograph 4. To Southeast. View of wetland ERL-PEM at the mouth of the diversion ditch (OW-ERL3). Wetland ERL-PFO can be seen behind the feature. Eagle Rock Lake (OW-ERL1) in foreground.



Photograph 5. To West. Beaver lodge on the north shore of Eagle Rock Lake (OW-ERL1).



Photograph 6. To Northeast. View of wetland ERL-PFO. Wetland ERL-PEM occurs in photograph foreground.



Photograph 7. To West. View of wetland ERL-PFO and Eagle Rock Lake diversion channel (OW-ERL3) near Eagle Rock Lake.



Photograph 8. To West. View of diversion channel OW-ERL3 upstream of wetland ERL-PFO.



Photograph 9. To East. View upstream of Red River (OW-ERL2) at the headgate of the diversion channel (OW-ERL3).



Photograph 10. To South. View of a reach of the Red River (OW-ERL2) adjacent to Eagle Rock Lake (OW-ERL1).



Photograph 11. To South. View of beaver dam within Red River (OW-ERL2) at the western end of the Eagle Rock Lake remediation area.



Photograph 12. To West. View of the Red River (OW-ERL2) downstream of the Eagle Rock Lake remediation area.




Photograph 13. To South. Overview of wetland EDC-1/EDC-2 within the Eastern Diversion Channel remediation area.



Photograph 14. To North. View of wetland EDC-1 within the Eastern Diversion Channel.



Photograph 15. To North. View of EDC-2.



Photograph 16. To East. View of upland above Eastern Diversion Channel EDC-1/EDC-2.



Photograph 17. To North. View of feature EDC-6 within the Eastern Diversion Channel. This area did not meet the three substantive criteria for wetlands.




Photograph 18. To East. Overview of the Eastern Diversion Channel and surrounding upland south of feature EDC-6.



Photograph 19. To Southwest. View within the Eastern Diversion Channel below EDC-6.



Photograph 20. To Northeast. View of Eastern Diversion Channel along the channel's lower reach.



Photograph 21. To North. View of wetland EDC-3.



Photograph 22. To Northeast. View of the upland near EDC-3. A portion of the Eastern Diversion lower channel appears in the photograph center.

Appendix C Individual Wetland Data Forms

URS C-1

WETLAND DETERMINATION DATA FORM - Western Mountains, Valleys, and Coast

Project/Site: Questa Mine Remediation Removal Ac	tion	City/Cour	nty: Questa/	Γaos	Samplir	ng Date: 10-1:	5-12
Applicant/Owner: Chevron Mining, Inc.	-		State:NM	— Samplir	Sampling Point: HTS-1		
Investigator(s): J. Dawson/S. Hall		Section,	Township, Ra	 nge: T28N	_		
Landform (hillslope, terrace, etc.): Depression		_		convex, none): None		Slope (%	%): 1:1
Subregion (LRR): MLRA 39 - Arizona and New Mexico Mts.	Lat: 36	- 5.694758	(,	Long: -105.496439		Datum: N	-
Soil Map Unit Name: Cumulic Haploborolls, nearly 1		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			fication: N		112 00
			O No C				
Are climatic / hydrologic conditions on the site typical for t					,	,	
Are Vegetation Soil or Hydrology	•	ly disturbed		'Normal Circumstances	•		No (
Are Vegetation Soil or Hydrology	naturally p	roblematic?	? (If ne	eded, explain any ansv	vers in Ren	narks.)	
SUMMARY OF FINDINGS - Attach site map	showing	g sampli	ng point lo	ocations, transect	s, impor	tant featur	es, etc.
Hydrophytic Vegetation Present? Yes (•)	No 🔘	Is	the Sampled	Area			
Hydric Soil Present? Yes	No 💿	wi	ithin a Wetlar	nd? Yes	No	•	
Wetland Hydrology Present? Yes	No 💿						
Remarks: Feature lies between Hy. 38 and the Ro			•			-	I
PSS vegetation present; no evidence of	•	•		-			PSS
portion almost barren understory. Soil	sample yie	elded 1 po	tential conc	entration, likely oxid	ized tailir	igs.	
VEGETATION - Use scientific names of pla	nts.						
Tree Stratum Plot size: 30 x 30	Absolute % Cover		nt Indicator ? Status	Dominance Test wo	rkehoot		
1. Populus angustifolia	5	Yes	FACW	Number of Dominant			
2.				That Are OBL, FACV		2	(4)
3.				(excluding FAC-):		3	(A)
4.		_		Total Number of Don Species Across All S		4	(B)
	5	= Total Co	over	Percent of Dominant		7	(5)
Sapling/Shrub Stratum Plot size: 30 x 30				That Are OBL, FACV		75.0 %	(A/B)
1. Salix monticola	_ 10	Yes	OBL	Prevalence Index w	orkobooti		
2. Salix exigua	5	No No	FACW	Total % Cover of		Multiply by:	
3. Salix lucida	$-\frac{5}{2}$	No	FAC	OBL species			.2
4. Betula occidentalis		No	FACW	FACW species			58
5. Cornus sericea	- 4	= No	FACW	FAC species			.5
Herb Stratum Plot size 30 x 30	29	= Total Co	vei	FACU species	40 x	4 = 10	60
1. Bromus inermis	40	Yes	FACU	UPL species		5 = 1	.5
2. Juncus arcticus	14	Yes	FACW	Column Totals:	89 (A	A) 20	60 (B)
3. Agrostis stolonifera	1	No	FACW				0.2
4. Artemisia frigida	1	No	Not Listed	Prevalence Ind			92
5. Carex nebrascensis	2	No	OBL	Hydrophytic Vegeta 1 - Rapid Test for			
6. Achnatherum perplexum	_ 1	No	Not Listed	× 2 - Dominance			
7. Thinopyrum intermedium	1	No	Not Listed	× 3 - Prevalence Ir			
8				4 - Morphologica	l Adaptatio	ns¹(Provide su	pporting
9				data in Rema 5 - Wetland Non		separate shee	et)
10.				Problematic Hyd			olain)
Woody Vine Stratum Plot size:	60	= Total Co	over	¹ Indicators of hydric be present, unless d	soil and we	etland hydrolo	
1.				Hydrophytic	- Istarbea or	problematio.	
2				Vegetation Yes	s •	No 🔘	
		= Total Co	over	Present?			
% Bare Ground in Herb Stratum 40 %				· 			
Remarks: Distinct Salix/ Juncus communities. Sa							
Minors include Elymus lanceolatus, Ro	sa woodsii	, verbascu	ım thapsus,	vicia americana, Poa	ı sp.		
Two pair of juncos observed.							

SOIL Sampling Point: HTS-1

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)										
Depth	Matrix			x Features						
(inches)	Color (moist)	<u></u> %	Color (moist)		Type ¹	_Loc ²	<u>Texture</u>	Remarks		
<u>SP1/0 - 5</u>	10YR 5/2	99	7.5YR 5/8		C	M	Sa	Some organic streaking		
5 - 14	10YR 6.5/1	100	-				Ash sand	Tailings		
SP2/0 - 1	10YR 3/2	50	-				Sa	Some organic streaking		
SP2/0 - 1	10YR 6.5/1	50	-	-			Sa			
1 - 14	10YR 6.5/1	100	-	-			Ash sand	Tailings		
								-		
								_		
¹ Type: C=Cor	centration, D=Depletion	 , RM=Redu	ced Matrix, CS=Covere	d or Coated	I Sand Gra	ins		² Location: PL=Pore Lining, M=Matrix		
Hydric Soil I	ndicators: (Applicable	e to all LR	Rs, unless otherwise	e noted.)			Indicators for	Problematic Hydric Soils ³ :		
Histosol	(A1)		Sandy Redox	(S5)			2 cm Mu			
	oipedon (A2)		Stripped Ma	` ,			Red Parent Material (TF2)			
=	stic (A3)		Loamy Muck	-		ept MLRA1		allow Dark Surface (TF12)		
	en Sulfide (A4) d Below Dark Surface	(A11)	Loamy Gley Depleted Ma		F2)		Uther (Ex	xplain in Remarks)		
	ark Surface (A12)	(, (, , , ,	Redox Dark		- 6)					
Sandy N	Nucky Mineral (S1)		Depleted Da	ırk Surface	(F7)		³ Indicators of hydrophytic vegetation and wetland hydrology must be present,			
Sandy 0	Sleyed Matrix (S4)		Redox Depre	essions (F	8)			listurbed or problematic.		
Restrictive I	ayer (if present):									
Type:							Hydric Soil Pr	esent? Yes No 💿		
Depth (inc	ches):									
Remarks: Lo	ow chroma results i	rom col	or of tailings, not r	eduction	Vegeta	tion at pit	: SP1 - barren.	SP2 - Juncus arcticus. Reduction		
								t soil pit. Likely oxidized tailings.		
A	dditional soil pits d	ug in are	a with results sim	ilar to SP	2. Ash s	and is a pu	ulverized mate	rial.		
HYDROLO	GY									
	drology Indicators:		-lll 4b4l)				0	Indicator (minimum of the manifest)		
i <u>— </u>	tors (minimum of one rec	quirea; cned			- (DO) (<u> </u>	r-Stained Leaves (B9) (except		
l <u>—</u>	Water (A1) Iter Table (A2)		Water-Stair		, , ,	cept		A 1, 2, 4a, and 4b)		
Saturation			Salt Crust		,		Drain	age Patterns (B10)		
Water M	larks (B1)		Aquatic In		s (B13)			Season Water Table (C2)		
Sedime	nt Deposits (B2)		Hydrogen		, ,			ation Visible on Aerial Imagery (C9)		
Drift De	oosits (B3)		Oxidized F	Rhizosphei	es on Livi	ng Roots (0	C3) Geon	norphic Position (D2)		
Algai Ma	at or Crust (B4)		Presence		•	,		ow Aquitard (D3)		
	oosits (B5)		<u> </u>			led Soils (C6) FAC-Neutral Test (D5)				
I =	Soil Cracks (B6)		=		,	1) (LRR A)	· <u>—</u>			
	on Visible on Aerial In	0 , (, <u> </u>	olain in Re	marks)		Frost	-Heave Hummocks (D7) (LRR F)		
Field Obser	Vegetated Concave	Suпасе (38)							
Surface Wat		s (No Depth (in	ches).						
Water Table			No Depth (in	· —		Wetla	nd Hydrology F	Present? Yes No •		
Saturation P			No Depth (in	· · · · · · · · · · · · · · · · · · ·						
(includes cap	oillary fringe)									
None.	corded Data (stream of	gauge, mo	onitoring well, aerial	photos, pre	evious ins	pections), it	f available:			
Remarks: Co	oncrete runoff conv	evance f	rom roadway slon	es to the	site Site	is nerche	d above Red R	tiver and restricted by a two-track		
	id. Surveyors have	•			one. Ditt	is perene	a above Red N	area and resure to do a two-track		

WETLAND DETERMINATION DATA FORM - Western Mountains, Valleys, and Coast

Project/Site: Questa Mine Remediation Removal Ad	City/Cou	inty:Questa/Ta	aos	Sampling Date: 10-16-12				
Applicant/Owner: Chevron Mining, Inc.	-		State:NM	Sampling Point: HTS-1-UP				
Investigator(s): J. Dawson/ S. Hall		Section,	Township, Ra	nge: T28N R13E				
Landform (hillslope, terrace, etc.): Hillslope			·	convex, none): Hillsl	ope	SI	ope (%): 2	5
Subregion (LRR): MLRA 39 - Arizona and New Mexico Mts	. Lat [.] 36	- .694872	,	Long: -105.495723	1		tum: NAD	
Soil Map Unit Name: Cumulic Haploborolls, nearly					sification:			
Are climatic / hydrologic conditions on the site typical for		ear? Ves	No (-			
	significantly			'Normal Circumstance		,	No ($\overline{}$
o or riyurology		•			•) INU (
Are Vegetation Soil or Hydrology	naturally p			eded, explain any ans				-4-
SUMMARY OF FINDINGS - Attach site ma	o snowing	g sampi	ing point ic	ocations, transed	ts, imp	ortant to	eatures,	etc.
Hydrophytic Vegetation Present? Yes	No 💿	Is	s the Sampled	Area				
Hydric Soil Present? Yes	No 💿	v	vithin a Wetlar	nd? Yes	\circ .	No 💿		
Wetland Hydrology Present? Yes	No 💿							
Remarks: Upland soil pit for HTS-1 and HTS-2.	Pit located	d on sout	th side slope	of HTS-2.				
VEGETATION - Use scientific names of pla	nto							
VEGETATION - Use scientific frames of pla	Absolute	Domina	nt Indicator					
Tree Stratum Plot size: 30 x 30	% Cover			Dominance Test w	orkshee	t:		
1. Picea engelmanii	2	Yes	FAC	Number of Dominar				
2. Populus deltoides	5	Yes	FAC	That Are OBL, FAC (excluding FAC-):	W, or FA	C	2	A)
3. Juniperus scopularum	1	No	Not Listed	Total Number of Do	minant		_ (-	-,
4.				Species Across All			6 (1	В)
Sapling/Shrub Stratum Plot size: 30 x 30	8	= Total C	over	Percent of Dominar				
1. Symphoricarpos oreophilis	5	Yes	Not Listed	That Are OBL, FAC	W, or FA	C: 3	3.3 % (A	4/B)
2. Acer glabrum	$-\frac{3}{3}$	Yes	FACU	Prevalence Index v	workshee	et:		
3. Ericameria nauseosus	$-\frac{3}{1}$	No	Not Listed	Total % Cover	of:	Multip	oly by:	
4. Physocarpos monogynus	$-\frac{1}{1}$	No	UPL	OBL species		x 1 =	0	
5. Rosa woodsii	1	No	FACU	FACW species		x 2 =	0	
20. 20	11	= Total C	over	FAC species	10	x 3 =	30	
Herb Stratum Plot size 30 x 30				FACU species	19	x 4 =	76	
1. Artemisia campestris	$-\frac{25}{1.5}$	Yes	Not Listed	UPL species	41	x 5 =	205	
2 Bromus inermis		Yes	FACU	Column Totals:	70	(A)	311	(B)
3. Thinopryum intermedium	13	No No	Not Listed	Prevalence In	dex = B//	A =	4.44	
4. Artemisia frigida 5. Antennaria sp.	$-\frac{1}{1}$	No No	Not Listed Not Listed	Hydrophytic Veget	tation Inc	licators:		
6. Amerinaria sp.		100	Not Listed	1 - Rapid Test			etation	
7.				2 - Dominance				
8.				3 - Prevalence 4 - Morphologic			.:	4:
9.				data in Rem				ung
10.				5 - Wetland No				
Woody Vine Stratum Plot size:	55	= Total C	over	Problematic Hy		-		
				¹ Indicators of hydric be present, unless				iust
1. 2.				Hydrophytic		· ·		
				Vegetation Y	es 🔘	No	lacksquare	
0/ Page Crowd in Hart Ottature 47		= Total C	over	Present?				
% Bare Ground in Herb Stratum 45 %	. 1 00	C.1 =	1 D:	- , ,	. , .		1 ~	\longrightarrow
Remarks: Plot located on a terrace within the ripa		of the R	ed River. Tr	ee strata occurs with	nın obvi	ous uplan	d areas. E	sare
ground comprised of little and small ro	CKS.							

SOIL Sampling Point: HTS-1-UP

		-	th needed to docu			or confirm	the absence of	indicators.)
Depth (inches)	Matrix Color (moist)	%	Color (moist)	x Feature	s Type ¹	Loc ²	Texture	Remarks
0 - 6	10YR 3/4	100	-	-			Si	Many roots, organic mottles
6 - 14	10YR 5/3	100	-				GrSi	
								-
								•
								-
								-
								-
¹ Type: C=Cor		ion, RM=Redu	ced Matrix, CS=Cover	ed or Coate	d Sand Grai			² Location: PL=Pore Lining, M=Matrix
			Rs, unless otherwis				Indicators for	Problematic Hydric Soils ³ :
Histosol		abio to all Eli	Sandy Redo	-			2 cm Muc	•
Histic E	pipedon (A2)		Stripped Ma				Red Pare	ent Material (TF2)
	istic (A3)		Loamy Muc	-		ept MLRA1		llow Dark Surface (TF12)
= -	en Sulfide (A4)	200 (411)	Loamy Gley		(F2)		Other (Ex	plain in Remarks)
= .	d Below Dark Surfa ark Surface (A12)	ace (ATT)	Depleted M Redox Dark	, ,	F6)			
	Mucky Mineral (S1)		Depleted Da	,	•			s of hydrophytic vegetation and
Sandy 0	Gleyed Matrix (S4)		Redox Depi		, ,			hydrology must be present, isturbed or problematic.
Restrictive I	_ayer (if present):							
Type:							Hydric Soil Pre	esent? Yes No 💿
Depth (inc	ches):							
So			eet up from floor terial from road c			tation at p	oit: Rosa woods	sii, Bromus inermis, Artemisia
IVDDOLO	· CV							
HYDROLO	drology Indicators							
-	itors (minimum of one		ck all that apply)				Secondary	Indicators (minimum of two required)
Surface	Water (A1)		Water-Sta	ined Leave	es (B9) (ex	cept		-Stained Leaves (B9) (except
High Wa	ater Table (A2)		MLRA 1,	2, 4a, and	l 4b)		☐ MLR	A 1, 2, 4a, and 4b)
Saturation	` '		Salt Crust					age Patterns (B10)
	larks (B1)		Aquatic In		, ,		= '	eason Water Table (C2)
	nt Deposits (B2)		Hydrogen				= -	ation Visible on Aerial Imagery (C9)
= '	posits (B3)			•		ng Roots (· · ·	norphic Position (D2)
	at or Crust (B4) posits (B5)				ed Iron (C4	•		ow Aquitard (D3) Neutral Test (D5)
	Soil Cracks (B6)					ed Soils (C6 1) (LRR A)	<i>'</i> \sqsubseteq	ed Ant Mounds (D6) (LRR A)
=	on Visible on Aeria	I Imagery (B	=			1) (LIXIX A)	<u> </u>	-Heave Hummocks (D7) (LRR F)
	Vegetated Conca	0 , (` .	,	,			(= 1, (= 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,
Field Obser	, ,		,					
Surface Wat	er Present?	Yes 🔘	No Depth (ir	nches):				
Water Table	Present?	Yes 🔘	No Depth (ir	nches):		Wetla	nd Hydrology P	resent? Yes O No 💿
Saturation P	resent? pillary fringe)	Yes 🔘	No Depth (ir	nches):				
		m gauge, mo	onitoring well, aerial	photos, pi	revious ins	pections), i	f available:	
None.								
Remarks: N	o hydrologic ind	icators.						

WETLAND DETERMINATION DATA FORM - Western Mountains, Valleys, and Coast

Project/Site: Questa Mine Remediation Removal A	Action	City/Cour	nty: Questa/	Taos	Sampling D	Date: 10-16-12
Applicant/Owner: Chevron Mining, Inc.		-		State:NM	_	Point: HTS-2
Investigator(s): J. Dawson/ S. Hall		Section.	Township, Ra	ange: T28N R13E		
Landform (hillslope, terrace, etc.): Depression		-	•	convex, none): None		Slope (%): 1:1
Subregion (LRR): MLRA 39 - Arizona and New Mexico M	ts 1 at: 36	_ 5.694878	ioi (ooiioavo,	Long: -105.495816		Datum: NAD83
		.074070		_	instinu Mon	-
Soil Map Unit Name: Cumulic Haploborolls, nearly			<u> </u>		ication: None	3
Are climatic / hydrologic conditions on the site typical for				, , ,	,	
Are Vegetation Soil X or Hydrology	significantl	y disturbed	l? Are	"Normal Circumstances"	present? Ye	es No 💿
Are Vegetation Soil or Hydrology	naturally p	roblematic?	? (If n	eeded, explain any answ	ers in Remark	(S.)
SUMMARY OF FINDINGS - Attach site ma	ap showing	g sampli	ng point l	ocations, transects	s, importar	nt features, etc.
Hydrophytic Vegetation Present? Yes (•	No 🔘	Is	the Sample	d Area		
Hydric Soil Present? Yes •	No 🔘	wi	ithin a Wetla	nd? Yes •	No C)
Wetland Hydrology Present? Yes	No 🔘					
Remarks: Barren depression with herbaceous/v						
spill area. Feature perched above Re			•		fill on three	sides. Two track
road likely older than 50 years. Som		barren po	rtion of the	feature.		
VEGETATION - Use scientific names of p				+		
Tree Stratum Plot size: 30 x 30	Absolute % Cover		nt Indicator ? Status	Dominance Test wor	ksheet	
1. Populus angustifolia	5	Yes	FACW	Number of Dominant S		
2.				That Are OBL, FACW		2 (A)
3.			-	(excluding FAC-):		2 (A)
4.		-	-	Total Number of Domi Species Across All Str		2 (B)
	5	= Total Co	ver	Percent of Dominant S	Species	, ,
Sapling/Shrub Stratum Plot size:				That Are OBL, FACW		100.0 % (A/B)
1				Prevalence Index wo	rksheet:	
3.				Total % Cover of:	N	/ultiply by:
4.				OBL species	x 1 =	0
5.				FACW species	22 x 2 =	44
		= Total Co	ver	FAC species	x 3 =	0
Herb Stratum Plot size 30 x 30				FACU species	x 4 =	0
1. Juncus arcticus		Yes	FACW	UPL species	x 5 =	0
2. Agrostis stolonifera	4	No	FACW	Column Totals:	22 (A)	44 (B)
3				Prevalence Inde	x = B/A =	2.00
5.				Hydrophytic Vegetat	ion Indicator	
6.				1 - Rapid Test for		
7.				X 2 - Dominance Te		
8.	<u>.</u>			× 3 - Prevalence Inc		
9.				data in Remar	Adaptations (ks or on a ser	Provide supporting parate sheet)
10.				5 - Wetland Non-		
	22	= Total Co	 over	Problematic Hydro		
Woody Vine Stratum Plot size:				¹ Indicators of hydric s be present, unless dis		
1				Hydrophytic	starbea or pro	bicinatic.
2				Vegetation Yes	(•) I	No (
		= Total Co	over	Present?		-
% Bare Ground in Herb Stratum 78 %						
Remarks: A substantial portion of the wetland is	s a sparsely v	regetated	depression.	Wetland vegetation r	learest to bar	rren area is dead/
blackened.	Datula aasi	dontelle I	Oogo 11100-4-	ii Calin ariona Cali-	monticele	
Minors include Artemesia campestris Deer tracks and scat observed.	, Detuia OCCI	uciitalis, f	xosa woods	ii, saiix exigua, saiix	пописота.	

SOIL Sampling Point: HTS-2

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)										
Depth	Matrix			Features	s					
(inches)	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²	Texture	Remarks		
SP1/0 - 6	5Y 8/3	70	7.5YR 6/8	_30_	C	M	Si	Tailings		
			10YR 5/3	2	RM	M	Cl	One area		
SP1/6 - 18	10YR 5.5/3.5	55	7.5YR 5/8	_ 5	C	M	Cobbly GrLo	High sand content, native soil		
			7.5YR 5/6	_40_	C	M	_			
SP2/0 - 6	10YR 5/3	_100	-				SiLo			
SP2/6 - 9			-				Cobbles			
SP2/9 - 16	10YR 5/3	_100	-				GrLo			
¹ Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains ² Location: PL=Pore Lining, M=Matrix										
Hydric Soil I	ndicators: (Applicabl	e to all LRR	s, unless otherwise	noted.)			Indicators for I	Problematic Hydric Soils ³ :		
Histosol	(A1)		Sandy Redox	(S5)			2 cm Muc	k (A10)		
Histic E	pipedon (A2)		Stripped Mat	rix (S6)			Red Pare	nt Material (TF2)		
Black Hi	stic (A3)		Loamy Muck	y Mineral	(F1) (exc	ept MLRA	1) Very Shal	low Dark Surface (TF12)		
Hydroge	n Sulfide (A4)		Loamy Gleye	ed Matrix	(F2)			olain in Remarks) `		
Depleted	d Below Dark Surface	(A11)	Depleted Ma	trix (F3)				,		
Thick Da	ark Surface (A12)	` '	Redox Dark		F6)					
	lucky Mineral (S1)		Depleted Da	•	,			s of hydrophytic vegetation and		
	Gleyed Matrix (S4)		Redox Depre					ydrology must be present,		
	ayer (if present):		Tredox Bepre	1) 0110100			unless di	sturbed or problematic.		
Type:	ayer (ii present).						Hydric Soil Pre	sent? Yes ● No ○		
Depth (inc	hae).						injunio com i ro			
										
Remarks: Patchy clay loam surface in spots. Mottles in tailings were also observed at soil surface. SP3 - 0-4: Matrix -10YR 6/2 75%; Redox 7.5YR 5/8. 25%; RC, C; PL, M. Tailings, root matter. Restrictive layer of cobble at 4 inches. Atypical soils - may be fill. Only SP3 was hydric.										
	•									
HYDROLO	GY									
Wetland Hyd	drology Indicators:									
Primary Indica	tors (minimum of one red	quired; check	all that apply)				Secondary	Indicators (minimum of two required)		
	Water (A1)		Water-Stair		` , `	cept		Stained Leaves (B9) (except		
Saturation	ter Table (A2)		Salt Crust		40)			ge Patterns (B10)		
	arks (B1)		Aguatic Inv	. ,	e (B13)			eason Water Table (C2)		
	nt Deposits (B2)		Hydrogen		` ,		=	tion Visible on Aerial Imagery (C9)		
	oosits (B3)		Oxidized R			na Poots /		orphic Position (D2)		
	it or Crust (B4)		Presence			-	` ' 🖃	w Aquitard (D3)		
□	` ,		Recent Iron			•		Neutral Test (D5)		
	osits (B5)					•	′ 🖳	• ,		
	Soil Cracks (B6)		Stunted or			1) (LRR A)	' <u>Ш</u>	d Ant Mounds (D6) (LRR A)		
Inundation	on Visible on Aerial In	nagery (B7)	Other (Exp	ilain in Re	emarks)		Frost-	Heave Hummocks (D7) (LRR F)		
★ Sparsely	Vegetated Concave	Surface (B	8)							
Field Obser	vations:									
Surface Water	er Present? Ye	s ON	lo 💿 Depth (ind	ches):	-					
Water Table	Present? Ye	es O N	lo Depth (inc	ches):	-	Wetla	and Hydrology Pi	resent? Yes No		
Saturation Pi		es O N	lo Depth (inc	ches):	-					
Describe Re	corded Data (stream	gauge, mor	nitoring well, aerial p	hotos, pr	evious ins	pections),	if available:			
None.										
Remarks: Ol	oserved saturated n	nud at sur	face. Rain occurr	ed 3 day	\sqrt{s} prior. \overline{A}	Area appe	ears to collect wa	nter due to topographic position.		

WETLAND DETERMINATION DATA FORM - Western Mountains, Valleys, and Coast

Project/Site: Questa Mine Remediation Removal Acti	ion	City/C	County: Questa/	Γaos	Sampling	Date: 10-16-	12
Applicant/Owner: Chevron Mining, Inc.		_		State:NM	Sampling	Point: ERL-P	EM
Investigator(s): J. Dawson/ S. Hall		Section	on, Township, Ra	ange: T29N R13W S32	2		
Landform (hillslope, terrace, etc.): Floodplain		_		convex, none): Concav		Slope (%):	1
Subregion (LRR): MLRA 39 - Arizona and New Mexico Mts.	Lat: 30	_ 5.70322		Long: -105.572951		Datum: NA	
Soil Map Unit Name: Cumulic Haplaquolls, nearly lev		00-2			ication: No		
			/ (C) N- (
Are climatic / hydrologic conditions on the site typical for the					,		
	significant	•		"Normal Circumstances"	•		o ()
Are Vegetation Soil or Hydrology	naturally p	roblema	atic? (If n	eeded, explain any answ	ers in Rema	ırks.)	
SUMMARY OF FINDINGS - Attach site map	showin	g sam	pling point l	ocations, transects	, importa	ant features	s, etc.
Hydrophytic Vegetation Present? Yes N	No (Is the Sample	d Area			
Hydric Soil Present? Yes N	4o (within a Wetla		No (\supset	
Wetland Hydrology Present? Yes N	No 🔘						
Remarks: PEM wetland fringe abutting Eagle Roc							
discontinuous wetland fringe of approxi	mately 2	feet w	ide occurring a	around the lake perime	ter. Beave	er lodge obse	rved on
north side of lake.							
VEGETATION - Use scientific names of plan							
Tree Stratum Plot size:	Absolute		inant Indicator cies? Status	Deminance Test wer	lrahaat.		
1.	<u> 70 00VC</u>	_ <u>Орсс</u>	olatus Otatus	Number of Dominant S			
2.	-	-		That Are OBL, FACW,		•	
3.	-	_		(excluding FAC-):		2	(A)
4.	. ———	_		Total Number of Domi Species Across All Str		2.	(B)
		= Tota	I Cover	Percent of Dominant S		2	(D)
Sapling/Shrub Stratum Plot size:		. 0 10	. 0010.	That Are OBL, FACW	•	100.0 %	(A/B)
1.				Prevalence Index wo	rkehoot:		
2	-			Total % Cover of:		Multiply by:	
3.	_			OBL species	53 x 1		
4		-		FACW species	31 x 2		
5		- Tota	l Cover	FAC species	16 x 3	= 48	
Herb Stratum Plot size 0.25 acre		- 10ta	Covei	FACU species	x 4	= 0	
1. Carex aquatilis	25	Ye	s FACW	UPL species	x 5	= 0	
2. Agrostis gigantea	10	No	FAC	Column Totals:	100 (A)	163	(B)
3. Carex utriculata	50	Ye	s OBL	Dravalance Indo	v - D/A -	1.00	2
4. Agrostis stolonifera	3	No	FACW	Prevalence Inde Hydrophytic Vegetat		1.63)
5. Ascelpias speciosa	1	No.		1 - Rapid Test for			
6. Carex nebrascensis	3	No.		× 2 - Dominance Te			
7. Eleocharis palustris	3	No		× 3 - Prevalence Inc	lex is ≤3.0 ¹		
8. Phleum pratense	5	No	FAC FAC	4 - Morphological data in Remark	Adaptations	(Provide supp	orting
9.	-	-		5 - Wetland Non-			
10.	100	- Tota	l Cover	Problematic Hydro			in)
Woody Vine Stratum Plot size:	100	- 10ta	Cover	¹Indicators of hydric s			must
1				be present, unless dis	sturbed or pi	roblematic.	
2				Hydrophytic Vegetation Yes	•	No (
		= Tota	l Cover	Present?	•	.10	
% Bare Ground in Herb Stratum				1			
Remarks: Minors include Dactylis glomerata, Elyn							
Salix exigua, Salix monticola, Typha ang	gustifolia	, Trifol	ium pratense.	Beaver lodge and trail	s through	wetland, racc	coon
tracks.							

SOIL Sampling Point: <u>ERL-PEM</u>

Profile Desc	cription: (Describe	to the dep	th needed to docu	ment the	indicator o	or confirm	the absence of	indicators.)				
Depth (inches)	Matrix Color (moist)	%	Redo Color (moist)	x Feature:	s Type ¹	Loc ²	Texture	Remarks				
0 - 3	10YR 4/2	88	2.5/5B	2	RM	M	Cl					
0-3	-		7.5YR 4/6	10		M	Cl					
3 - 4	10YR 7/6	60	10YR 5/8	40			Cl					
4 - 7	10YR 4/2	60	7.5 YR 5/4	40			Cl					
7 - 15	5Y 7/3	40	10YR 5/6	30			Cl	Many tiny roots				
7 - 15			10YR 7/6	30			ClSi					
			10111 770									
								-				
¹ Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains ² Location: PL=Pore Lining, M=Matrix												
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Indicators for Problematic Hydric Soils ³ :												
Histosol	` '		Sandy Redox	x (S5)			2 cm Mu	ck (A10)				
	pipedon (A2)		Stripped Ma	, ,			🛏	ent Material (TF2)				
	istic (A3) en Sulfide (A4)		Loamy Muc	-		ept MLRA	,	allow Dark Surface (TF12)				
	d Below Dark Surfa	ce (A11)	Depleted Ma		(Г2)		U Other (Ex	xplain in Remarks)				
ı <u>—</u>	ark Surface (A12)	(, , , ,	Redox Dark		F6)							
Sandy N	Mucky Mineral (S1)				s of hydrophytic vegetation and hydrology must be present,							
Sandy C	Gleyed Matrix (S4)		isturbed or problematic.									
Restrictive L	ayer (if present):											
Type:							Hydric Soil Pre	esent? Yes No				
Depth (inc												
Remarks: V	egetation at pit -	Carex utric	culata.									
HYDROLO												
-	drology Indicators tors (minimum of one		ck all that apply)				Secondary	Indicators (minimum of two required)				
Surface	Water (A1)				es (B9) (ex	cept		-Stained Leaves (B9) (except				
l 😑 📑	iter Table (A2)		MLRA 1,		l 4b)			A 1, 2, 4a, and 4b)				
X Saturation	` ,		Salt Crust	. ,			Drainage Patterns (B10)					
	larks (B1)		Aquatic In					eason Water Table (C2)				
=	nt Deposits (B2) posits (B3)		Hydrogen			D4- /	= -	ation Visible on Aerial Imagery (C9) norphic Position (D2)				
ı <u> </u>	at or Crust (B4)				eres on Livi ed Iron (C4	•	· / 🖳	ow Aquitard (D3)				
l 🖳 📑	posits (B5)				ons in Tille	•		Neutral Test (D5)				
l <u>—</u>	Soil Cracks (B6)				Plants (D1		- /	ed Ant Mounds (D6) (LRR A)				
	on Visible on Aerial	Imagery (B	—			., (=:::::,	<u> </u>	-Heave Hummocks (D7) (LRR F)				
	Vegetated Concav		, <u> </u>									
Field Obser	vations:											
Surface Wat	er Present?	Yes 🔘	No Depth (in	iches):	-							
Water Table			No Depth (in	<i>′</i> —	-	Wetla	and Hydrology P	resent? Yes No				
Saturation P (includes car	oillary fringe)		No Depth (in	· —	0							
Describe Re Aerial phot		m gauge, mo	onitoring well, aerial	photos, pr	revious insp	pections),	if available:					
_	-	v is Fanla	Rock Lake and so	me orou	ndwater f	rom the	liversion chann	el (OW-FRL3)				
r comand. 50	Juice of flydrolog	y is Eagle	NOCK Lake and SC	mic grou	nawater 1	rom the C	ii vei sioii eiiaiiii	or (OW-LINES).				

WETLAND DETERMINATION DATA FORM - Western Mountains, Valleys, and Coast

Project/Site: Questa Mine Remediation Removal Ad	ction	City/Count	y: Questa/	Γaos	Samplin	ng Date: 10-10	6-12
Applicant/Owner: Chevron Mining, Inc. State:NM Sampling Point: ERL-PFG							-PFO
Investigator(s): J. Dawson/ S. Hall Section, Township, Range: T29N R13W S32							
Landform (hillslope, terrace, etc.): Floodplain		Local relie	ef (concave,	convex, none): Concav	/e	Slope (%	6) : 1
Subregion (LRR): MLRA 39 - Arizona and New Mexico Mts	. Lat: 36	5.703471		Long: -105.572715		—— Datum: N	AD83
Soil Map Unit Name: Cumulic Haplaquolls, nearly le				NWI classi	fication: N	one —	
Are climatic / hydrologic conditions on the site typical for		ear? Yes	No ((If no, explain in	Remarks)		
Are Vegetation Soil or Hydrology		y disturbed?		"Normal Circumstances	,	_	No (
Are Vegetation Soil X or Hydrology	Ü	roblematic?		eeded, explain any answ	•		
SUMMARY OF FINDINGS - Attach site ma							es, etc.
Hydrophytic Vegetation Present? Yes (•)	No (·			
Hydric Soil Present? Yes	No (he Sample hin a Wetla		No	\circ	
Wetland Hydrology Present? Yes	No (W10	illii a vvetia	iiu: 163 (c	, 110		
Remarks: PSS/PFO wetland at and around the E	agle Rock	Lake diver	sion chann	el (see surface water	feature da	ta sheet for	OW-
ERL3). Land rises to east; wetland ch			midway be	tween the lake and th	e diversio	on channel he	eadgate.
Hydric soils not present; area appears	to drop sed	liment.					
VEGETATION - Use scientific names of pla	ants.						
Tree Stratum Plot size: 30 x 30	Absolute % Cover	Dominant Species?		Dominance Test wo	rksheet.		
1. Populus angustifolia	25	Yes	FACW	Number of Dominant			
2. Alnus incana	10	Yes	FACW	That Are OBL, FACW	, or FAC	5	(A)
3.				(excluding FAC-): Total Number of Dom	inant	3	(^)
4.				Species Across All St		5	(B)
Sapling/Shrub Stratum Plot size: 30 x 30	35	= Total Cov	er	Percent of Dominant	Species		
1. Populus angustifolia	30	Yes	FACW	That Are OBL, FACW	, or FAC:	100.0 %	(A/B)
2. Alnus incana	$-\frac{30}{15}$	Yes	FACW	Prevalence Index wo	orksheet:		
3. Salix exigua	$-\frac{15}{15}$	Yes	FACW	Total % Cover of	<u> </u>	Multiply by:	
4. Betula occidentalis	5	No	FACW	OBL species	х	1 = (0
5. Prunus virginiana	2	No	FACU	FACW species			56
Herb Stratum Plot size 30 x 30	67	= Total Cov	er	FAC species	_		6
1. Phalaris arundinacea	2	M-	EACW	FACU species UPL species	_		8
2. Agrostis gigantea	$-\frac{2}{1}$	No No	FACW FAC				5 75 (B)
3. Arctium minus	1	No	UPL	Column Totals:	83 (A	.) 1	75 (6)
4. Epilobium ciliatum	$-\frac{1}{1}$	No	FACW	Prevalence Inde			11
5. Barbarea vulgaris	1	No	FAC	Hydrophytic Vegeta			
6.		-		1 - Rapid Test fo		_	
7.				× 3 - Prevalence In			
8.				4 - Morphologica	l Adaptation	ns¹(Provide su	pporting
9				data in Remai			et)
10.				5 - Wetland Non- Problematic Hydi			olain)
Woody Vine Stratum Plot size:	6	= Total Cov	er	¹Indicators of hydric			
1.				be present, unless di	sturbed or	problematic.	
2.				Hydrophytic			
		= Total Cov	ver	Vegetation Yes Present?	•	No 🔘	
% Bare Ground in Herb Stratum %				I			
Remarks: Minors include Heracleum maximum,	Equisetem	arvense, Ca	ardamine o	cordifolia, Cirsium arv	ense, Lei	 ucanthemum	vulgare,
Maianthemum stellatum, Ratibida sp.,			xifrage odo	ontoloma, Urtica dioio	ea, Viola s	sp.	
Kingfisher, junco, bushtit observed. B	eaver cut al	ders.					

SOIL Sampling Point: ERL-PFO

	ription: (Describe	to the dep	th needed to				or confirn	n the absence o	f indicators.)
Depth (inches)	Color (moist)	%	Color (mo	Redox I	Feature %	s Type ¹	Loc ²	Texture	Remarks
0 - 2	10YR 3/2	100			_			SaLo	Roots
2 - 7	10YR 4/4	100						LoSa	Coarse sand - alluvium
7 - 15	10YR 6/4	30	7.5 YR	5/8	40			ClSi	
	10 TR 0/4 10 YR 4/3	30	7.3 TK	<u> </u>	-10			Cisi	
	101 K 4/3		-						
								-	-
1- 0.0									21 21. 21. 21. 21. 21. 21. 21.
	centration, D=Depletion					ed Sand Grai	ins		² Location: PL=Pore Lining, M=Matrix
Hydric Soil II	ndicators: (Applica	ble to all LF	_		-				r Problematic Hydric Soils ³ :
=	oipedon (A2)			y Redox (ped Matri	•			—	uck (A10) rent Material (TF2)
Black Hi					` '	l (F1) (exc	ept MLRA		allow Dark Surface (TF12)
Hydroge	n Sulfide (A4)			ny Gleyec			•		xplain in Remarks)
_ :	d Below Dark Surfa	ce (A11)	X Depl	eted Matr	ix (F3)				
	ark Surface (A12)			x Dark S	,	,		³ Indicato	ors of hydrophytic vegetation and
	flucky Mineral (S1) Gleyed Matrix (S4)			eted Dark ox Depres		. ,		wetland	hydrology must be present,
			Reuc	Depres	SSIONS (I	-0)		unless	disturbed or problematic.
Type:	ayer (if present):							Hydric Soil P	resent? Yes No
Depth (inc	hes):							Hydric 30ii Fi	resent: les 😉 NO
	ternating layers	of coarse o	ravel and cl						
	egetation at pit: A				S				
	oblematic hydric			_					
	00101114010 117 0110	3011 .08		ana gra	01 0 011				
HYDROLO	GY								
Wetland Hyd	drology Indicators	:							
Primary Indicat	ors (minimum of one	required; che	ck all that apply	')					y Indicators (minimum of two required)
	Water (A1)					es (B9) (ex	cept		er-Stained Leaves (B9) (except RA 1, 2, 4a, and 4b)
= 1	ter Table (A2)			.RA 1, 2,		1 4D)		_	•
Saturation	arks (B1)			It Crust (E		- (D40)			nage Patterns (B10)
	arks (BT) it Deposits (B2)			uatic Inve					Season Water Table (C2) ration Visible on Aerial Imagery (C9)
	oosits (B3)			drogen S			ina Dooto	₩ -	morphic Position (D2)
	t or Crust (B4)				•	eres on Livi ed Iron (C4	•	``' =	low Aquitard (D3)
_ •	osits (B5)					ions in Tille	•		C-Neutral Test (D5)
	Soil Cracks (B6)					l Plants (D	•	, L	ed Ant Mounds (D6) (LRR A)
=	on Visible on Aerial	Imagery (B	= -	ner (Expla			., (=,	_	t-Heave Hummocks (D7) (LRR F)
	Vegetated Conca	0 , \	<i>,</i>	- (,			, , , ,
Field Observ	vations:		<u>, </u>						
Surface Water	er Present?	Yes 🔘	No 💿 Do	epth (inch	nes):				
Water Table	Present?	Yes 🔘	No 💿 Do	epth (inch	nes):		Wetl	and Hydrology	Present? Yes 💿 No 🔘
Saturation Projection (includes cap		Yes 🔘	No Do	epth (inch	nes):				
Describe Red	corded Data (strear		onitoring well,	aerial ph	notos, pi	revious ins	pections),	if available:	
NHD shows	s diversion chann	iel.							
	y season delinea		er areas in th	ne wetlai	nd are	saturated.			
Als	so see OW-ERL-	3.							

WETLAND DETERMINATION DATA FORM - Western Mountains, Valleys, and Coast

Project/Site: Questa Mine Remediation Removal	City/County: Questa/Taos				Sampling Date: 10-16-12			
Applicant/Owner: Chevron Mining, Inc.	_		State:NM Sampling Point: ERL-UP)	
Investigator(s): J. Dawson/S. Hall	n, Township, Ra	nge: T29N R13W	S32					
Landform (hillslope, terrace, etc.): Hillslope		_	·	convex, none): Hills		S	slope (%): 4	15
Subregion (LRR): MLRA 39 - Arizona and New Mexico M	Ats. Lat: 30	- 6.703167		Long: -105.57263			itum: NAD	
Soil Map Unit Name: Cumulic Haplaquolls, nearly					ssification			
Are climatic / hydrologic conditions on the site typical f		vear? Ve	s No (
				"Normal Circumstand		,	No	
	significant	•			•		•) INO	
Are Vegetation Soil or Hydrology	naturally p			eeded, explain any ar				-4-
SUMMARY OF FINDINGS - Attach site m	ap snowin	g samp	oling point id	ocations, transe	cts, im	portant i	eatures,	etc.
Hydrophytic Vegetation Present? Yes	No 💿		Is the Sampled	I Area				
Hydric Soil Present? Yes	No 💿	,	within a Wetla	nd? Yes	\circ	No 💿		
Wetland Hydrology Present? Yes	No 💿							
Remarks: Upland soil pit for ERL-PEM and E	ERL-PFO. Po	oint take	n on side slop	e south of wetland	and div	ersion cha	nnel.	
VEGETATION Has account to a name of the								
VEGETATION - Use scientific names of p		Domin	ant Indicator					
Tree Stratum Plot size:	Absolute <u>% Cove</u>			Dominance Test	workshee	et:		
1. Pinus ponderosa	10	Yes	FACU	Number of Domina				
2. Populus angustifolia	1	No	FACW	That Are OBL, FAC	CW, or FA	AC .	0	(A)
3. Juniperus scopularum		No	Not Listed	(excluding FAC-): Total Number of D	ominant		U	(/\)
4.				Species Across All			3	(B)
One lie of Ohanda Ohanda and Died oine	13	= Total (Cover	Percent of Domina	nt Specie	es		
Sapling/Shrub Stratum Plot size:	25	* 7	37 . 71 . 1	That Are OBL, FAC			0.0 %	(A/B)
1. Fallugia paradoxa		Yes No	Not Listed	Prevalence Index	workshe	eet:		
Rhus aromatica Quercus gambellii	$\frac{1}{1}$	$-\frac{\text{No}}{\text{No}}$	UPL Not Listed	Total % Cover			iply by:	
4. Pinus edulis	$\frac{1}{1}$	- No No	Not Listed Not Listed	OBL species		x 1 =	0	
5. Rosa woodsii	$\frac{1}{2}$	No	FACU	FACW species	1	x 2 =	2	
Nosu woodsti	40	= Total (FAC species		x 3 =	0	
Herb Stratum Plot size	10			FACU species	18	x 4 =	72	
1. Bromus inermis	15	Yes	FACU	UPL species	9	x 5 =	45	
2. Chrysopsis villosa	1	No	Not Listed	Column Totals:	28	(A)	119	(B)
3. Thinopyrum intermedium	1	No	Not Listed	Prevalence I	ndex = B	/A =	4.25	
4. Lupinus argenteus	5	No	Not Listed	Hydrophytic Vege			7.23	
5. Carex sp.	1	No		1 - Rapid Test			getation	
6. Cirsium sp.		No		2 - Dominance	e Test is	>50%		
7. 8.				3 - Prevalence				
9.				4 - Morphologi data in Rer				orting
10.				5 - Wetland N		• .	ic silect)	
	24	= Total (Cover	Problematic H	ydrophyti	c Vegetatio	n¹ (Explain	1)
Woody Vine Stratum Plot size:	24	Total	30701	¹Indicators of hydr				must
1.				be present, unless	s disturbe	a or proble	natic.	
2				Hydrophytic Vegetation	es (No	•	
		= Total (Cover	Present?		, 110	~	
% Bare Ground in Herb Stratum 76 %								
Remarks: Minors include Antennaria sp. Evide	nce of beave	r damage	e. Bare ground	d is rock and litter.				
I .								

SOIL Sampling Point: ERL-UP

			oth needed to docu			or confirm	the absence of	indicators.)
Depth (inches)	Color (moist)	<u>(</u> %	Color (moist)	x Feature %	s Type¹	Loc ²	Texture	Remarks
0 - 12	10YR 5/4	100					Sa	
								-
								-
								-
								-
1Type: C=Cor		tion RM=Red	uced Matrix, CS=Covere	ed or Coate	ed Sand Gra			² Location: PL=Pore Lining, M=Matrix
					o Garia Gra		Indicators for	Problematic Hydric Soils ³ :
Histosol		cable to all Li	RRs, unless otherwis	-				•
=	pipedon (A2)		Sandy Redox	. ,			2 cm Mu	ent Material (TF2)
=	istic (A3)		Loamy Mucl	` '	l (F1) (exc	ept MLRA1	🛏	illow Dark Surface (TF12)
Hydroge	en Sulfide (A4)		Loamy Gley	-		•	,	plain in Remarks)
Deplete	d Below Dark Sur	face (A11)	Depleted Ma	atrix (F3)				
=	ark Surface (A12)		Redox Dark	,	,		³ Indicator	s of hydrophytic vegetation and
	Mucky Mineral (S1	,	Depleted Da		` '			hydrology must be present,
	Gleyed Matrix (S4)		Redox Depr	essions (I	-8)		unless d	isturbed or problematic.
Restrictive I	_ayer (if present)	:						
Type:							Hydric Soil Pre	esent? Yes No •
Depth (inc	arren at pit.							
HYDROLO	GY							
•	drology Indicator							
	tors (minimum of on	e required; che						Indicators (minimum of two required)
<u> </u>	Water (A1)		Water-Stai MLRA 1,		` ' '	cept		Stained Leaves (B9) (except A 1, 2, 4a, and 4b)
=	ater Table (A2)				1 10)			
Saturation Natural	larks (B1)		Salt Crust Aquatic In	` '	oo (D12)			age Patterns (B10) eason Water Table (C2)
	nt Deposits (B2)		Hydrogen		. ,		= '	ation Visible on Aerial Imagery (C9)
	posits (B3)					ng Roots (= -	orphic Position (D2)
<u>'</u>	at or Crust (B4)		<u> </u>	•	ed Iron (C4	•	′ 🖳	ow Aquitard (D3)
	posits (B5)				•	, ed Soils (C6		Neutral Test (D5)
	Soil Cracks (B6)					1) (LRR A)	′ 🖳	ed Ant Mounds (D6) (LRR A)
	on Visible on Aeria	al Imagery (E	=			, ,		-Heave Hummocks (D7) (LRR F)
Sparsely	Vegetated Conc	ave Surface	(B8)					
Field Obser	vations:		•					
Surface Wat	er Present?	Yes 🔘	No Depth (in	ches):	-			
Water Table	Present?	Yes 🔘	No Depth (in	ches):	-	Wetla	nd Hydrology P	resent? Yes O No 💿
Saturation P (includes cap		Yes 🔘	No Depth (in	ches):	-			
		am gauge, m	onitoring well, aerial	photos, pi	revious ins	pections), i	f available:	
Aerial phot				•		,		
Remarks: N	o hydrologic ind	licator. Pit	located approxima	telv 10 fe	eet vertica	ally above	ERL-PFO.	
	, ,		11	,		,		

Project -	Questa Mine Remediation Removal Action
Date -	Tuesday, October 16, 2012
Investigators -	J. Dawson/ S. Hall
Area ID -	OW-ERL1 (Eagle Rock Lake)
Centerpoint coordinates -	36.7034/-105.5742
HUC -	13020101
Land Use -	Recreation
Physical	
Type of feature (pond or stream)-	Pond
Source-	Red River
Connectivity -	Red River
Water Clarity (clear, murky, turbid)-	Cloudy
Water Color (if obvious)-	Turquoise
or Streams Only	
Average Width of OHWM (bankfull)-	N/A
Average observed width-	N/A
Bankfull depth-	N/A
Observed Depth-	N/A
Bank Slope (X:X) (on each side if different - use N/S or E/W)-	N/A
Evidence of undercutting or excessive erosion-	N/A
Occurrance of riffle-pool-run complexes (Natural hydro only)-	N/A
Channelized or meandering (Natural hydro only)-	
Bed substrate composition-	N/A
Velocity (slow, moderate, fast)-	N/A
Flow Direction (to)-	N/A
or Ponds Only	
Inlet/Outlet present?	Yes, inlet is diversion channel from Red River
Restricted outlet?	Yes, outlets to Red River through culvert.
Biological	
Percent estimated bank cover-	80, discontinuous fringe around feature
Bank vegetation (dominant species/if associated with wetland refer to data sheet)-	See wetland data sheet WL-ERL-PEM
Aquatic vegetation present (Y/N, list species if known)-	No
Percent overstory (amount hanging over the channel, streams only)-	0
Evidence of rafted/submerged large woody debris-	No
Evidence of other rafting (smaller debris, etc.)-	No
Aquatic or terrestrial wildlife present (list species)-	Kingfisher, beaver lodge

	Г
Surface Waters Features Data Sheet	
Project -	Questa Mine Remediation Removal Action
Date -	Tuesday, October 16, 2012
Investigators -	J. Dawson/ S. Hall
Area ID -	OW-ERL2 (Red River)
Centerpoint coordinates -	36.7030/-105.5751
HUC -	13020101
Land Use -	Recreation
Physical	
Type of feature (pond or stream)-	Stream
Source-	Confluence of several high altitude Sangre de Christo streams
Connectivity -	Rio Grande
Water Clarity (clear, murky, turbid)-	Slightly cloudy
Water Color (if obvious)-	N/A
For Streams Only	· ·
Average Width of OHWM (bankfull)-	18', widens to 20' at southern end of Study Area
Average observed width-	15'
Bankfull depth-	18 to 24"
Observed Depth-	6-18"
Bank Slope (X:X) (on each side if different - use N/S or E/W)-	
Evidence of undercutting or excessive erosion-	In places. More evident upstream near diversion.
Occurrance of riffle-pool-run complexes (Natural	some human made obstructions, and a beaver dam. More
hydro only)-	pronounced downstream of Study Area.
Channelized or meandering (Natural hydro only)-	Slight meandering.
Bed substrate composition-	Cobble
Velocity (slow, moderate, fast)-	Moderate flow adjacent to lake, slows below beaver dam.
Flow Direction (to)-	West
For Ponds Only	
Inlet/Outlet present?	
Restricted outlet?	
Biological	
Percent estimated bank cover-	70
Bank vegetation (dominant species/if associated with wetland refer to data sheet)-	Alnus sp., Bromus inermis, Populus angustifolia
Aquatic vegetation present (Y/N, list species if known)-	NO
Percent overstory (amount hanging over the channel, streams only)-	10, predominantly south of beaver dam
Evidence of rafted/submerged large woody debris-	Yes
Evidence of other rafting (smaller debris, etc.)-	Yes
Aquatic or terrestrial wildlife present (list species)-	Kingfisher, beaver dam
	verted when Eagle Rock Lake was constructed. This reach is

Notes: It appears that the channel may have been diverted when Eagle Rock Lake was constructed. This reach is distinctly different from the channel above the lake and again below the bridge. Flows are higher and the channel sides appear to be cut deep into the substrate.

urface Waters Features Data Sheet	
Project -	Questa Mine Remediation Removal Action
Date -	Tuesday, October 16, 2012
Investigators -	J. Dawson/ S. Hall
Area ID -	OW-ERL3 (Eagle Rock Lake Diversion Ditch)
Centerpoint coordinates -	36.7035/-105.5725
HUC -	13020101
Land Use -	Recreation
Physical	
Type of feature (pond or stream)-	Stream
Source-	Red River
Connectivity -	Eagle Rock Lake
Water Clarity (clear, murky, turbid)-	Milky (dissolved aluminum)
Water Color (if obvious)-	None
For Streams Only	
Average Width of OHWM (bankfull)-	2 feet
Average observed width-	2 feet, widens to 6 feet at inlet to lake
Bankfull depth-	18 inches
Observed Depth-	12 inches
Bank Slope (X:X) (on each side if different - use N/S or E/W)-	1:1 sloping to level at confluence
Evidence of undercutting or excessive erosion-	No
Occurrance of riffle-pool-run complexes (Natural	N/A
hydro only)-	
Channelized or meandering (Natural hydro only)-	N/A
Bed substrate composition-	Unconsolidated
Velocity (slow, moderate, fast)-	Slow
Flow Direction (to)-	West
or Ponds Only	
Inlet/Outlet present?	
Restricted outlet?	
Biological	
Percent estimated bank cover-	100
Bank vegetation (dominant species/if associated with wetland refer to data sheet)-	Alnus sp., also see wetland data sheet WL-ERL-PFO
Aquatic vegetation present (Y/N, list species if known)-	No
Percent overstory (amount hanging over the channel, streams only)-	100
Evidence of rafted/submerged large woody debris-	No
Evidence of other rafting (smaller debris, etc.)-	No
Aquatic or terrestrial wildlife present (list species)-	

WETLAND DETERMINATION DATA FORM - Arid West Region

Project/Site: Questa Mine Remediation Removal	Action	City/C	ounty: Questa/	Taos	Sar	npling Date:	10-17-2012
Applicant/Owner: Chevron Mining, Inc.		State:NM	EDC-1				
Investigator(s): J. Dawson/ S. Hall		Section	on, Township, Ra	ange: T29N R12W S	325, 36	-	
Landform (hillslope, terrace, etc.): Constructed char	nnel	Local	relief (concave,	, convex, none): None Slope (%): <1			
Subregion (LRR): D - Interior Deserts	Lat: 36	.70866	58	Long: -105.609575	;	Dati	um: NAD83
Soil Map Unit Name: FfC, SED, SmB				NWI class	sificatior	n: None	
Are climatic / hydrologic conditions on the site typical for	or this time of ye	ear? Y	es No ((If no, explain i	n Rema	rks.)	
Are Vegetation Soil or Hydrology	significantly	disturt	ped? Are	"Normal Circumstance	s" prese	ent? Yes	No 🔘
Are Vegetation Soil X or Hydrology	naturally pr			eeded, explain any ans			
SUMMARY OF FINDINGS - Attach site m							eatures, etc.
Hydrophytic Vegetation Present? Yes (•)	No 🔘		Is the Sample	d Area			
Hydric Soil Present? Yes •	No 🔘		within a Wetla	nd? Yes (•	No 🔘	
Wetland Hydrology Present? Yes •	No 🔘						
Remarks: PEM wetland within a constructed ch Portions of the ditch were inundated a remnants, shells, and previous aerial p VEGETATION - Use scientific names of p	and evidence on the photos. Hydri	of inur	ndation is prese	ent during the growi			
VEGETATION - OSC SCICILITIE Harnes OF p	Absolute	Domi	nant Indicator	Dominance Test w	orksher	ət·	
Tree Stratum Plot size: N/A 1.			ies? Status	Number of Dominan That Are OBL, FAC	t Specie	es	2 (A)
2				Total Number of Do	minant		
3				Species Across All S		,	2 (B)
4Sapling/Shrub Stratum Plot size:		= Tota	al Cover	Percent of Dominan That Are OBL, FAC			0.0 % (A/B)
1.				Prevalence Index v	vorkshe	et:	
2.		-		Total % Cover o	of:	Multip	oly by:
3.				OBL species	32	x 1 =	32
4.				FACW species	12	x 2 =	24
5				FAC species	35	x 3 =	105
Herb Stratum Plot size: 100 x 60		= Tota	al Cover	FACU species		x 4 =	0
1. Hordeum jubatum	35	Yes	FAC	UPL species	=0	x 5 =	0
2. Typha angustifolia	25	Yes	OBL	Column Totals:	79	(A)	161 (B)
3. Rumex salicifolius	12	No	FACW	Prevalence Inc	dex = B	/A =	2.04
4. Rorippa curvipes	4	No	OBL	Hydrophytic Veget	ation In	dicators:	
5. Carex nebrascensis	2	No	OBL	X Dominance Tes			
6. Eleocharis palustris	1	No	OBL	× Prevalence Inde			
7				Morphological <i>A</i>			
8.		-		Problematic Hy	drophyti	c Vegetation	ı¹ (Explain)
9				_			
10 Woody Vine Stratum Plot size: N/A	79	= Tota	al Cover	 Indicators of hydric be present. 	; soil an	d wetland h	ydrology must
1. 2.				Hydrophytic			
	- (D) ()		al Cover	Vegetation Ye Present?	es 💿	No (
% Bare Ground in Herb Stratum 21 % % G Remarks: Salix exigua and scattered Populus sp	Cover of Biotic (_	ones into non	wetland areas Will	10320 0	a pact adas	of channal
are clearly out of the wetland. Willow Minors include Beckmannia syzigach Polygonum ramosissimum.	ws on west sid	le occi	ır approx. 1 fo	ot into the wetland.	PEM v	egetation i	s dominant.

SOIL Sampling Point: EDC-1

Depth Matrix Redox Features	
(inches) Color (moist) % Color (moist) % Type¹ Loc² Texture Remarks	
0 - 0.5 10YR 3/2 100 Gravels Organic, fibrous, shell	S
0.5 - 3 7.5 YR 5/3 100 GrSaCl	
3 - 14 7.5 YR 5/3 96 7.5 YR 4/6 2 C M GrSaCl	
5YR 4/6 2 C M	
1Turner C-Consentration D-Doubtion DM-Dadwood Matrix 21 anation DI-Doubting DC-Doubt Channel M-Matrix	
¹ Type: C=Concentration, D=Depletion, RM=Reduced Matrix. ² Location: PL=Pore Lining, RC=Root Channel, M=Matrix.	
Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.) Indicators for Problematic Hydric Soils:	
Histosol (A1) Sandy Redox (S5) 1 cm Muck (A9) (LRR C)	
Histic Epipedon (A2) Stripped Matrix (S6) 2 cm Muck (A10) (LRR B)	
Black Histic (A3) Loamy Mucky Mineral (F1) Reduced Vertic (F18)	
Hydrogen Sulfide (A4) Loamy Gleyed Matrix (F2) Red Parent Material (TF2)	
Stratified Layers (A5) (LRR C) Depleted Matrix (F3) X Other (Explain in Remarks)	
1 cm Muck (A9) (LRR D) Redox Dark Surface (F6)	
Depleted Below Dark Surface (A11) Depleted Dark Surface (F7)	
Thick Dark Surface (A12) Redox Depressions (F8)	
Sandy Mucky Mineral (S1) Vernal Pools (F9) 3Indicators of hydrophytic vegetation and	l
Sandy Gleyed Matrix (S4) wetland hydrology must be present. Restrictive Layer (if present):	
	lo 🔘
Depth (inches): Departure Manainal hydria sails. Vacatation at mits Handaum inhatum.	
Remarks: Marginal hydric soils. Vegetation at pit: Hordeum jubatum	
Problematic soil - recently developed/seasonally flooded (based on historic photos).	
HYDROLOGY	
Wetland Hydrology Indicators:	
Primary Indicators (any one indicator is sufficient) Secondary Indicators (2 or more re	nuired)
	quirca
	ina)
	ine)
Water Marks (B1) (Nonriverine)	
Sediment Deposits (B2) (Nonriverine) Oxidized Rhizospheres along Living Roots (C3) Dry-Season Water Table (C2) Dry-Season Water Table (C2)	
Drift Deposits (B3) (Nonriverine) Presence of Reduced Iron (C4) Crayfish Burrows (C8)	(00)
Surface Soil Cracks (B6) Recent Iron Reduction in Plowed Soils (C6) Saturation Visible on Aerial Images	agery (C9)
Inundation Visible on Aerial Imagery (B7) Thin Muck Surface (C7) Shallow Aquitard (D3)	
Water-Stained Leaves (B9) Uther (Explain in Remarks) FAC-Neutral Test (D5)	
Field Observations:	
Surface Water Present? Yes No Depth (inches): 1.5	
, , ,	No (
Saturation Present? Yes No Depth (inches): 0	
Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	
Aerial photographs.	
Remarks: Three species of gastropod present in surface layer.	
Flat sided construction channel approx. 60' wide. No evidence of directional flow. West side - 3-4' wide vegetated	ditch
inundated to 6" with standing water. ditch appears slightly elevated. Approx. 35 percent standing water 1-2" deep	
pit. More inundation on the eastern side of the channel then on the west. Previous aerial photographs show this fe	
completely inundated in previous years.	

WETLAND DETERMINATION DATA FORM - Arid West Region

Project/Site: Questa Mine Remediation Removal Actio	n	City/Cour	ty: Questa/T	Caos	Sampling Date:	10-17-2012
Applicant/Owner: Chevron Mining, INC.				State:NM	Sampling Point:	EDC-1-UP
Investigator(s): J. Dawson/ S. Hall		Section,	Γownship, Rar	nge: T29N R12W S36)	
Landform (hillslope, terrace, etc.): Terrace		Local rel	ef (concave, c	convex, none): None	SI	ope (%):
Subregion (LRR): D - Interior Deserts	Lat: 36.	708926		Long: -105.609871	 Dat	um: NAD83
Soil Map Unit Name: Ffc, Sep, SmB				NWI classific	cation: None	
Are climatic / hydrologic conditions on the site typical for this	time of ye	ar? Yes	No ((If no, explain in R	temarks.)	
	-	disturbed		Normal Circumstances" p		No (
	aturally pro	oblematic?	(If ne	eded, explain any answe	rs in Remarks.)	
SUMMARY OF FINDINGS - Attach site map s						eatures, etc.
Hydrophytic Vegetation Present? Yes No		Is	the Sampled	Δrea .		
Hydric Soil Present? Yes No	•		thin a Wetlan	_	No 💿	
Wetland Hydrology Present? Yes No						
Remarks: Upland soil pit for EDC-1. Terrace on eas the Eastern Diversion Channel. Greater that	n 1:1 slc	_	•		he opposite top	o of bank of
VEGETATION - Use scientific names of plants		Danis	A loodinates	D	-tt	
	Absolute % Cover		t Indicator Status	Dominance Test work Number of Dominant S		
1.				That Are OBL, FACW,		0 (A)
2		,		Total Number of Domin	ant	
3				Species Across All Stra		1 (B)
4		= Total C	over	Percent of Dominant Sp That Are OBL, FACW, o).0 % (A/B)
Sapling/Shrub Stratum Plot size: 25 x 25 1. Artemisia tridentata	28	Yes	Not Listed	Prevalence Index wor	ksheet:	
2. Ericameria nauseosus	5	No	Not Listed	Total % Cover of:		oly by:
3.				OBL species	x 1 =	0
4.				FACW species	x 2 =	0
5.				FAC species	x 3 =	0
	33	= Total C	over	FACU species	x 4 =	0
Herb Stratum Plot size:				UPL species	x 5 =	0
1		·	_	Column Totals:	(A)	0 (B)
3.				Prevalence Index	= B/A =	
4.				Hydrophytic Vegetation	on Indicators:	
5.			_	Dominance Test is		
6.				Prevalence Index is	s ≤3.0 ¹	
7.		-	_	Morphological Ada	ptations ¹ (Provide	e supporting
8.				data in Remarks Problematic Hydro	s or on a separat	,
9.					priytic vegetation	i' (Explaili)
10.						
Woody Vine Stratum Plot size:		= Total C	over	¹ Indicators of hydric so be present.	il and wetland h	ydrology must
2.				Hydrophytic		
		= Total C	over	Vegetation Yes	O No (•
% Bare Ground in Herb Stratum 96 % % Cover	of Biotic C		1 %	Present?		
Remarks: Artemesia tridentata to 4 feet tall. Minors i			, .	ides, Agropryon crista	atum, Elymus e	elymoides.
Juniperus monosperma, Heterotheca villos cryptogamic crust community.						

US Army Corps of Engineers

SOIL Sampling Point: EDC-1-I

Depth (inches) 0 - 14		% Colo 00	r (moist)	x Features	Type ¹	Loc ²	Texture GrS	, ,	Re Alluvium - cob	emarks bles
0 - 14	7.5 YR 5/3 1	00	-	- <u>-</u> .			GrS	Si	Alluvium - cob	bles
Type: C=Con-	centration, D=Depletion	n, RM=Reduce	ed Matrix.	² Location	: PL=Pore	Lining, RC	=Root Ch	nannel, M	=Matrix.	
										3
	cators: (Applicable to	all LRRs, unle							oblematic Hydric	Soils':
Histosol (A	•		Sandy Redo	. ,					(A9) (LRR C)	
Histic Epip Black Histi		\vdash	Stripped Ma Loamy Muc	, ,	I /E1)			cm Muck (educed Ve	(A10) (LRR B)	
	Sulfide (A4)	H	Loamy Gley	-					Material (TF2)	
	ayers (A5) (LRR C)	H	Depleted M		(1 2)				ain in Remarks)	
	(A9) (LRR D)	H	Redox Dark	. ,	(F6)		Ш		,	
Depleted E	Below Dark Surface (A1	11)	Depleted D		. ,					
Thick Dark	Surface (A12)		Redox Dep	ressions (F8)					
	cky Mineral (S1)		Vernal Pool	ls (F9)					drophytic vegeta	
	yed Matrix (S4)						wet	land hydro	ology must be pr	esent.
Restrictive La	yer (if present):									
Type:							Hydric	Soil Pres	ent? Yes	No 💿
Depth (inche	es):ndicators. Numerou									
HYDROLOG	Y									
Wetland Hydro	ology Indicators:									
Primary Indicat	ors (any one indicator i	is sufficient)					<u>S</u>	econdary	Indicators (2 or r	more required)
Surface W	ater (A1)		Salt Crust	(B11)				Water I	Marks (B1) (Rive	erine)
High Wate	r Table (A2)		Biotic Crus	st (B12)				Sedime	ent Deposits (B2)) (Riverine)
Saturation	(A3)		Aquatic In	vertebrate	s (B13)			Drift De	eposits (B3) (Riv	erine)
Water Mar	ks (B1) (Nonriverine)		Hydrogen	Sulfide O	dor (C1)			Draina	ge Patterns (B10))
Sediment I	Deposits (B2) (Nonrive	erine)	Oxidized F	Rhizosphe	res along	Living Root	s (C3)	Dry-Se	ason Water Tabl	le (C2)
Drift Depos	sits (B3) (Nonriverine)		Presence	of Reduce	ed Iron (C4	4)		Crayfis	h Burrows (C8)	
	oil Cracks (B6)		Recent Iro	n Reducti	on in Plow	ed Soils (C	6)	Saturat	tion Visible on A	erial Imagery (C9
Inundation	Visible on Aerial Image	ery (B7)	Thin Muck					Shallov	w Aquitard (D3)	
Water-Stai	ned Leaves (B9)		Other (Exp	olain in Re	emarks)			FAC-N	eutral Test (D5)	
Field Observa	tions:									
	Present? Yes (No ●	Depth (in	ches):						
Surface Water	resent? Yes (No (Depth (in	ches):		Wetla	nd Hydro	ology Pre	sent? Yes (○ No ●
Surface Water Water Table Pr		No •	Depth (in	ches):						
Water Table Pr Saturation Pres	100 (nections) it	available	9:		
Water Table Pr Saturation Pres (includes capillador) Describe Reco	100 (ge, monitoring	well, aerial	photos, pr	evious ins	pcollo110), 11				
Water Table Pr Saturation Pres (includes capilla Describe Reco None.	ary fringe) rded Data (stream gau		ı well, aerial	photos, pr	evious ins	, peditorio), ii				
Water Table Pr Saturation Pres (includes capilla Describe Reco None.	ary fringe)		well, aerial	photos, pr	evious ins	pedilo113), 11				
Water Table Pr Saturation Pres (includes capilla Describe Reco None.	ary fringe) rded Data (stream gau		ı well, aerial	photos, pr	evious ins	peouono), n				
Water Table Pr Saturation Pres (includes capilla Describe Reco None.	ary fringe) rded Data (stream gau) well, aerial	photos, pr	evious ins	podiono), ii				

WETLAND DETERMINATION DATA FORM - Arid West Region

Project/Site: Questa Mine Remediation Removal Action	1	City/Cou	unty: Questa/7	Γaos	Sampl	ling Date: 10	-17-20	12
Applicant/Owner: Chevron Mining, Inc.				State:NM	- Sampl	ling Point: E	DC-2	
Investigator(s): J. Dawson/ S. Hall		Section,	, Township, Rai	nge: T29N R12W S3	6			
Landform (hillslope, terrace, etc.): Constructed channel		Local re	elief (concave, o	convex, none): None		Slope	e (%):_<1	ĺ
Subregion (LRR): D - Interior Deserts	Lat: 36.	707669		Long: -105.609874		Datum	NAD	83
Soil Map Unit Name: Sedillo-Silva association, strongly	sloping			NWI classif	ication: N	None		
Are climatic / hydrologic conditions on the site typical for this t	ime of ye	ar? Yes	No C	(If no, explain in	Remarks	s.)		
Are Vegetation Soil or Hydrology sig	nificantly	disturbe	d? Are "	Normal Circumstances"	present	? Yes 🖯	No (•
Are Vegetation Soil On Hydrology nat	turally pro	blematio	c? (If ne	eded, explain any answ	ers in Re	emarks.)		
SUMMARY OF FINDINGS - Attach site map sh	nowing	sampl	ling point lo	ocations, transects	s, impo	ortant feat	ures, e	etc.
Hydrophytic Vegetation Present? Yes No	\circ		s the Sampled	Aron				
Hydric Soil Present? Yes No	_		s the Sampled vithin a Wetlar) N	• (
Wetland Hydrology Present? Yes No	$\tilde{\circ}$	•	vitiliii a vvetiai	iu: les e	140			
Remarks: Continuation of EDC-1. Willow communit	v extend	ls along	edges of cha	nnel with salt deposi	ts, algal	mats and s	hells or	1
channel floor. Aerial photographs show are								
recent precipitation may explain inundation	. Soils h	ave not	fully develop	ped hydric characteris	stics.			
VEGETATION - Use scientific names of plants								
	bsolute		ant Indicator	Dominance Test wor	ksheet:			
Tree Stratum Plot size:	6 Cover	Species	s? Status	Number of Dominant That Are OBL, FACW		3	(A	۹)
2				Total Number of Dom	inant			
3				Species Across All St		3	(E	3)
4				Percent of Dominant S	Species			
Sapling/Shrub Stratum Plot size:		= Total (That Are OBL, FACW) % (A	VB)
1. Salix exigua	8	Yes	FACW	Prevalence Index wo				
2				Total % Cover of:		Multiply I		
3				OBL species		x 1 =	3	
4				FACW species		x 2 =	48 111	
5	8	= Total		FAC species FACU species	0,	x 3 = x 4 =	0	
Herb Stratum Plot size: 60 x 100	0	= Total t	Cover	UPL species		x 5 =	5	
1. Hordeum jubatum	35	Yes	FAC	Column Totals:	1	(A)	167	(B)
2. Rorippa curvipes	15	Yes	FACW	Column Totals.	03	(八)		(5)
3. Rumex triangularis	1	No	FACW	Prevalence Inde			2.57	
4. Polygonum ramosissimum	2	No	FAC	Hydrophytic Vegetat		cators:		
5. Koeleria macrantha	1	No	Not Listed	X Dominance Test				
6. Typha angustifolia		No	OBL	× Prevalence Index		1.00		
7. Eleocharis obtusa	2	No	OBL	Morphological Add	aptations	s (Provide si a separate sl	upporting heet)	9
8.				Problematic Hydr			,	
9								
10	57	= Total	Cover					
Woody Vine Stratum Plot size: N/A 1.	37	- Total	Covei	¹ Indicators of hydric s be present.	oil and v	wetland hydr	ology m	ust
2.				Hydrophytic				
		= Total	— ———— Cover	Vegetation Yes Present?	\bullet	No 🔘		
% Bare Ground in Herb Stratum 45 % % Cover of	of Biotic C	crust	%	i resent:				
Remarks: Relatively sparsely vegetated area. Biotic c				d to be an Eleocharis	obtusa.	Minors inc	clude	
Beckmannia syzigachne, Chenopodium gla		J .						

SOIL Sampling Point: EDC-2

Profile Des	cription: (Describe t	to the depth n	eeded to docu	ment the i	ndicator o	or confirm	the absence of	indicators.)
Depth	Matrix			x Features				
(inches)	Color (moist)	<u></u> % (Color (moist)	%	Type ¹	Loc ²	<u>Texture</u>	Remarks
0 - 1	10YR 8/2	100	-				Si	
1 - 14	7.5YR 5/6	100	-	-			See Remarks	Cobbly gravelly silt
	-							
-								
								-
	-							-
-								
1 _{T. max} C=C	 Concentration, D=Depl		desard Matrice	21	DIDa	Lining DC	D-Deet Channel	NA-NA-Miss
Type: C=C	oncentration, D=Depi	etion, Rivi=Re	duced Matrix.	Location	i: PL=Pore	Lining, RC	C=Root Channel,	M=Matrix.
Hydric Soil	Indicators: (Applicabl	e to all LRRs. I	unless otherwise	e noted.)			Indicators for	Problematic Hydric Soils:
Histoso		0 to all 21tho, t	Sandy Redo					ck (A9) (LRR C)
	pipedon (A2)		Stripped M				<u> </u>	ck (A10) (LRR B)
Black H	listic (A3)		Loamy Mud		I (F1)			Vertic (F18)
Hydrog	en Sulfide (A4)		Loamy Gle	-				ent Material (TF2)
Stratifie	d Layers (A5) (LRR C	;)	Depleted M	latrix (F3)			X Other (Ex	plain in Remarks)
	uck (A9) (LRR D)		Redox Darl	k Surface	(F6)		_	
	ed Below Dark Surface	e (A11)	Depleted D	ark Surfac	e (F7)			
	ark Surface (A12)		Redox Dep	•	F8)			
=	Mucky Mineral (S1)		Vernal Poo	ls (F9)				hydrophytic vegetation and
	Gleyed Matrix (S4)						wetland hy	drology must be present.
	Layer (if present):							
Type:			_				Hydric Soil Pr	esent? Yes No
Depth (ir								
	Vegetation at pit: H			_				
P	roblematic soils - re	ecently devel	loped/seasonal	lly floode	ed (based	on aerial	photos).	
HYDROLO)GY							
	drology Indicators:							
-	icators (any one indica	ator io gufficion	.+\				Sacanda	in Indicators (2 or more required)
	· · ·	ator is sufficien	· <u> </u>	(D44)				ry Indicators (2 or more required)
	Water (A1)		X Salt Crust	, ,			=	er Marks (B1) (Riverine)
	ater Table (A2)		Biotic Cru		(D40)			iment Deposits (B2) (Riverine)
	ion (A3)		X Aquatic In					Deposits (B3) (Riverine)
	Marks (B1) (Nonriveri		Hydrogen					nage Patterns (B10)
=	ent Deposits (B2) (Nor				_	Living Root		Season Water Table (C2)
	posits (B3) (Nonriver	ine)	=		ed Iron (C4	,		/fish Burrows (C8)
	e Soil Cracks (B6)		=			ed Soils (C	· 🖳	ration Visible on Aerial Imagery (C9)
=	ion Visible on Aerial Ir	magery (B7)		(Surface (, ,			llow Aquitard (D3)
	Stained Leaves (B9)		Uther (Ex	plain in Re	emarks)		FAC	-Neutral Test (D5)
Field Obse								
Surface Wa		es O No		iches):				
Water Table	Present? Ye	es No	Depth (in	iches):		Wetla	and Hydrology P	Present? Yes No
Saturation F		es O No	Depth (in	ches):				
•	pillary fringe) ecorded Data (stream	gauge monito	ring well aerial	nhotos nr	evious insi	nections) i	f available:	
	tos show inundation			priotos, pr	CVIOGO IIIO	pcotionio), i	available.	
		7 T						
Remarks:								

WETLAND DETERMINATION DATA FORM - Arid West Region

Project/Site: Questa Mine Remediation Removal Acti	ion	City/Coun	ty: Questa/	Taos	Sampling Date: 1	0-17-2012
Applicant/Owner: Chevron Mining, INC.				State:NM	Sampling Point: I	EDC-3
Investigator(s): J. Dawson/S. Hall		Section, 7	Гownship, Ra	nge: T29N R12W S36	· —	
Landform (hillslope, terrace, etc.): Hillslope		Local reli	ef (concave,	convex, none): Terrace	Slop	oe (%): 45
Subregion (LRR): D - Interior Deserts	Lat: 36.	708668		Long: -105.609575	 Datun	n: NAD83
Soil Map Unit Name: Sedillo-Silva association, strong	ly sloping			NWI classifi	cation: None	
Are climatic / hydrologic conditions on the site typical for th	is time of ye	ear? Yes (• No ((If no, explain in F	Remarks.)	
	significantly			"Normal Circumstances"		No (
	naturally pr	oblematic?	' (If ne	eeded, explain any answe	ers in Remarks.)	
SUMMARY OF FINDINGS - Attach site map						itures, etc.
Hydrophytic Vegetation Present? Yes Yes	No (Is	the Sampled	I Area		
	No O		thin a Wetlar		No 🔘	
Wetland Hydrology Present? Yes • 1	No 🔘					
Remarks: PEM/PSS wetland formed from a hillside additional spring wetlands occur north of	this featu		flows to Eas	stern Diversion Chann	el. No distinct ch	hannel. Three
VEGETATION - Use scientific names of plan				,		
Tree Stratum Plot size:	Absolute % Cover	Dominan Species?	t Indicator Status	Dominance Test worl		
1.	70 00101	_орсою:	<u> </u>	Number of Dominant S That Are OBL, FACW,		(A)
2.		-	-	Total Number of Domir		,
3.				Species Across All Stra		(B)
4.				Percent of Dominant S	inecies	
Sapling/Shrub Stratum Plot size: 30 x 20		= Total Co	over	That Are OBL, FACW,	or FAC: 100.	.0 % (A/B)
1. Salix exigua	10	Yes	FACW	Prevalence Index wo		
2. Populus angustifolia	5	Yes	FACW	Total % Cover of:	Multiply	
3. Eleagnus angustifolia	2	No	OBL	OBL species	2 x 1 =	2
5.		-		FACW species FAC species	95 x 2 = x 3 =	190
0	17	= Total Co			10 x 4 =	40
Herb Stratum Plot size: 30 x 20	17	- Total Ct	Jvei	UPL species	x 5 =	0
1. Agrostis stolonifera	80	Yes	FACW		107 (A)	232 (B)
2. Bromus inermis	10	No	FACU			
3.				Prevalence Index		2.17
4			_	Hydrophytic Vegetati Dominance Test is		
5.			_	X Dominance Test isX Prevalence Index		
6.			_		aptations ¹ (Provide s	supporting
7. 8.		-		data in Remark	s or on a separate	sheet)
9.			_	Problematic Hydro	ophytic Vegetation ¹	(Explain)
10	_		_			
Woody Vine Stratum Plot size:	90	= Total Co	over	¹ Indicators of hydric so be present.	oil and wetland hyd	drology must
2.	_	-	_	Hydrophytic		
		= Total Co	 over	Vegetation Yes	No	
% Bare Ground in Herb Stratum 10 % % Cove	er of Biotic (%	Present?		
Remarks: Predominantly PEM around spring with s				opulus angustifolia and	d Eleagnus angus	tifolia line
the perimeter of the feature.	-		-	-	- 3	

SOIL Sampling Point: EDC-3

Profile Desc	ription: (Describe t	to the depth r	eeded to docun	nent the	indicator	or confirm	the absence o	of indicators.)
Depth	Matrix			C Feature				
(inches)	Color (moist)		Color (moist)	%	Type ¹	Loc ²	<u>Texture</u>	Remarks
0 - 5	10YR 4/2	_100	-				Cl	Organic streaking
5 - 14	2.5YR 6/3	80	10YR 6/8	20	C	M	Cl	
					-			
					-			
¹ Type: C=C	oncentration, D=Depl	etion, RM=Re	duced Matrix.	² Locatio	n: PL=Pore	Lining, R	C=Root Channe	I, M=Matrix.
Hydric Soil I	ndicators: (Applicabl	e to all LRRs.	unless otherwise	noted.)			Indicators fo	or Problematic Hydric Soils:
Histosol		• 10 u.io,	Sandy Redox	-				uck (A9) (LRR C)
	oipedon (A2)		Stripped Ma				<u> </u>	uck (A10) (LRR B)
Black Hi	stic (A3)		Loamy Muc	ky Miner	al (F1)		Reduce	d Vertic (F18)
	n Sulfide (A4)		Loamy Gley	ed Matri	x (F2)		Red Par	rent Material (TF2)
	d Layers (A5) (LRR C	;)	Depleted Ma		•		X Other (E	Explain in Remarks)
	ick (A9) (LRR D)	(4.44)	Redox Dark					
	d Below Dark Surface	e (A11)	Depleted Da					
l 🗀	ark Surface (A12) Nucky Mineral (S1)		Redox Depr		(F8)		31	£ budge about a constation and
I 🗀 -	Bleyed Matrix (S4)		Vernal Pool	S (F9)				of hydrophytic vegetation and hydrology must be present.
	Layer (if present):						Welland	lydrology must be present.
	Layer (ii present).						Hydric Soil F	Present? Yes No No
Type:	ahaa);		_				nyuric 30ii F	resent? res No
Depth (in	· <u> </u>		:C					
	egetation at pit: Ag							
F1	oblematic soil - re	centry devel	oped wettand.					
HYDROLO	GY							
	drology Indicators:							
· ·	cators (anv one indica	ator io gufficion	.+\				Sacara	dary Indicators (2 or more required)
	, , , , , , , , , , , , , , , , , , , ,	ator is sufficier	·	(D44)				, , ,
l 💳	Water (A1)		Salt Crust				=	ater Marks (B1) (Riverine)
	ater Table (A2)		Biotic Crus		(D42)			diment Deposits (B2) (Riverine)
Saturation Natural			Aquatic Inv					ift Deposits (B3) (Riverine)
==	larks (B1) (Nonriveri		Hydrogen			Livina Dee		ainage Patterns (B10)
l =	nt Deposits (B2) (Nor	•	=		eres along	_		y-Season Water Table (C2)
	posits (B3) (Nonriver	ine)	=		ced Iron (C			ayfish Burrows (C8)
l <u>—</u>	Soil Cracks (B6)	(DZ)	=		tion in Plov	rea Solis (C	· <u>–</u>	turation Visible on Aerial Imagery (C9)
	on Visible on Aerial Ir	magery (B7)	Thin Muck Other (Exp					allow Aquitard (D3)
	tained Leaves (B9)		Other (EXP	naiii iii iv	erriarks)			.C-Neutral Test (D5)
Field Obser		<u> </u>	<u> </u>		1			
Surface Wat		es No	• • •		1			
Water Table	Present? Ye	es No		· -	10	Wetla	and Hydrology	Present? Yes No
Saturation P (includes car	oillary fringe)	es No			0			
Describe Re	corded Data (stream	gauge, monito	ring well, aerial p	onotos, p	previous ins	pections),	ıt available:	
								outflows to the Eastern Diversion
			_				ed. Three oth	her seeps and springs were observed
on	this hillslope; this	is the smalle	est, but closest	to the re	emediatio	n area.		

WETLAND DETERMINATION DATA FORM - Arid West Region

Project/Site: Questa Mine Remediation Removal Ac	etion	City/Co	ounty: Questa/	Taos	Sampling Date: 10-18	3-2012
Applicant/Owner: Chevron Mining, INC.				State:NM	Sampling Point: EDC	-3-UP
Investigator(s): J. Dawson/ S. Hall		Section	n, Township, Ra	inge: T29N R12W S36		
Landform (hillslope, terrace, etc.): Hillslope		Local	relief (concave,	convex, none): Terrace	Slope (%):
Subregion (LRR):D - Interior Deserts	Lat: 36	.69957	1	Long: -105.619925	Datum: N	AD83
Soil Map Unit Name: Sedillo-Silva association, stron	gly sloping			NWI classific	ation: None	
Are climatic / hydrologic conditions on the site typical for	this time of ye	ear? Ye	s (• No ((If no, explain in R	emarks.)	
Are Vegetation Soil or Hydrology	significantly			"Normal Circumstances" p		No 🔘
Are Vegetation Soil or Hydrology	naturally pr			eeded, explain any answe		
SUMMARY OF FINDINGS - Attach site map						es. etc.
	_					
Hydrophytic Vegetation Present? Yes Hydric Soil Present? Yes Yes	No (•)		Is the Sampled		No 💿	
Wetland Hydrology Present?	No (within a Wetlai	nd? Yes	NO 🛡	
Remarks: Upland soil pit for EDC-3.	110					
epidid son pit for EBC 3.						
VEGETATION - Use scientific names of pla	ints.					
Torra Otractional Plant single	Absolute		ant Indicator	Dominance Test work	sheet:	
Tree Stratum Plot size:	% Cover	Specie	es? Status	Number of Dominant Sp That Are OBL, FACW, of		(A)
2.		-				(-)
3.				 Total Number of Domin Species Across All Stra 		(B)
4.				- Percent of Dominant Sp	necies	
Sapling/Shrub Stratum Plot size: 20 x 20		= Total	Cover	That Are OBL, FACW, o		(A/B)
1. Artemisia tridentata	54	Yes	Not Listed	Prevalence Index wor	ksheet:	
2. Ericameria nauseosus		No	Not Listed	Total % Cover of:	Multiply by:	
3. Juniperus monosperma	3	No	Not Listed	OBL species	x 1 = 0	
4		-	 	FACW species	x 2 = 0	
5		_ Tatal	<u> </u>	FAC species FACU species	x 3 = () x 4 = ()	
Herb Stratum Plot size: 20 x 20	67	= Total	Cover		x = 5 = 20	
1. Agropyron cristatum	25	Yes	Not Listed		10 (A) 20	
2. Thinopyrum intermedium	12	Yes	Not Listed	- Column Foldio.		
3. Heterotheca villosa	2	No	Not Listed	Prevalence Index		00
4. Bahia absinthifolia	1	No	Not Listed	Hydrophytic Vegetation		
5.				Dominance Test is		
6.				Prevalence Index is	s <u>s</u> 3.0 ptations¹ (Provide suppo	orting
7				data in Remarks	s or on a separate sheet	t)
8. 9.				Problematic Hydro	phytic Vegetation¹ (Expl	ain)
10.		-		-		
	40	= Total	Cover	-	il and waterd by declar	
Woody Vine Stratum Plot size:				¹ Indicators of hydric so be present.	ii and wetiand nydrolog	gy must
1. 2.				Hydrophytic		
		= Total	Cover	Vegetation Yes	○ No •	
% Bare Ground in Herb Stratum 60 % % Co	ver of Biotic (Present?		
Remarks: Artemisia tridentata heights to 6 feet. B			es up to 14 per	rcent moss.		
The more than the man the man to be the the	are ground		-5 ap to 17 pc			

SOIL Sampling Point: EDC-3-1

Profile Desc	cription: (Describe	to the depth ne	eded to docu	ment the i	ndicator	or confirm	the abs	ence of indic	ators.)	
Depth (inches)	Matrix	0/		x Features		1.5.2	T t.		Damarilia	
(inches)	Color (moist)		olor (moist)	%	Type ¹	Loc ²	Textu		Remarks	
0 - 13	7.5YR 4/4		-				SaG	rLo		
		· ——								
Type: C=C	oncentration, D=Dep	letion, RM=Red	uced Matrix.	² Location	ı: PL=Pore	e Lining, RO	C=Root C	Channel, M=Ma	atrix.	
Hydria Sail I	ndicators: (Applicabl	lo to all I BBs u	nlace othorwice	noted \			Indiaa	tors for Broble	ematic Hydric Soils ³ :	
Histosol		le to all Lixixs, u	Sandy Redo					cm Muck (A9		
	pipedon (A2)	Ī	Stripped Ma	. ,				cm Muck (A1		
Black H	istic (A3)	Ţ	Loamy Mud	ky Minera	I (F1)		R	Reduced Vertic	(F18)	
	en Sulfide (A4)		Loamy Gle		(F2)			led Parent Ma	, ,	
l <u> </u>	d Layers (A5) (LRR C)	Depleted M	, ,	(E0)		∐ o	ther (Explain	in Remarks)	
	uck (A9) (LRR D) d Below Dark Surface	_ (A11)	Redox Darl Depleted D		. ,					
I 🗀 '	ark Surface (A12)	(A11) [Redox Dep		. ,					
l 🖳	/lucky Mineral (S1)	L [Vernal Poo	•	. 0)		³ Indica	ators of hydro	phytic vegetation and	
Sandy C	Gleyed Matrix (S4)	L		. ,					gy must be present.	
Restrictive	Layer (if present):									
Type:			_				Hydric	Soil Present	? Yes (No (•	
Depth (in										
Remarks: N	o indicators. Vege	etation at pit:	Гhinopyrum i	ntermedi	um.					
HYDROLO	GY									
	drology Indicators:									
_	cators (any one indica	ator is sufficient)				9	Secondary Ind	icators (2 or more required	d)
	Water (A1)	<u> </u>	Salt Crust	(B11)					rks (B1) (Riverine)	→
	ater Table (A2)		Biotic Cru	` '				=	Deposits (B2) (Riverine)	
Saturati	, ,		Aquatic In		s (B13)		[===	sits (B3) (Riverine)	
l = =	larks (B1) (Nonriveri	ine)	Hydrogen				Ĭ	=	Patterns (B10)	
Sedime	nt Deposits (B2) (Nor	nriverine)	Oxidized I	Rhizosphe	res along	Living Roo	ts (C3)		on Water Table (C2)	
Drift De	posits (B3) (Nonriver	rine)	Presence	of Reduce	ed Iron (C4	4)	Ī	Crayfish B	urrows (C8)	
	Soil Cracks (B6)		Recent Iro	n Reducti	on in Plow	ed Soils (C	C6) [Saturation	Visible on Aerial Imagery	(C9)
l = =	on Visible on Aerial I	magery (B7)	Thin Muck						quitard (D3)	
	tained Leaves (B9)		Other (Ex	plain in Re	emarks)			FAC-Neut	ral Test (D5)	
Field Obser										
Surface Wat		es No (
Water Table	_	es O No (<i>′</i> —		Wetla	and Hydr	ology Preser	it? Yes () No	•
Saturation P (includes ca	•	es O No 🤄	Depth (in	ches):						
	corded Data (stream	gauge, monitor	ing well, aerial	photos, pr	evious ins	pections), i	if availabl	le:		
Remarks: N	lo hydrologic indic	ators present.								
	-									

WETLAND DETERMINATION DATA FORM - Arid West Region

Project/Site: Questa Mine Remediation Removal Action	1	City/C	ounty: Questa/7	Γaos	Sampling	Date: 10-18-	-2012
Applicant/Owner: Chevron Mining, Inc.				State:NM	- Sampling	Point: EDC-	-6
Investigator(s): J. Dawson/ S. Hall		Section	on, Township, Rai	nge: T29N R12W S3	5		
Landform (hillslope, terrace, etc.): Constructed channel		Local	relief (concave, o	convex, none): None		Slope (%)): <1
Subregion (LRR):D - Interior Deserts	Lat: 36.	7047 <i>6</i>	55	Long: -105.609659		Datum: NA	AD83
Soil Map Unit Name: Sedillo-Silva association, strongly	sloping			NWI classifi	cation: No	ne	
Are climatic / hydrologic conditions on the site typical for this t	time of ye	ear? Y	es No	(If no, explain in F	Remarks.)		
	nificantly			Normal Circumstances"		Yes ● N	10 ()
	turally pr			eded, explain any answe	•		
SUMMARY OF FINDINGS - Attach site map sh							s. etc.
				· · · · · · · · · · · · · · · · · · ·	,		, 5151
Hydrophytic Vegetation Present? Yes No Hydric Soil Present? Yes No	_		Is the Sampled	_		2	
Wetland Hydrology Present? Yes No	•		within a Wetlan	nd? Yes	No (•	
Remarks: Continuation of EDC-1 and EDC-2 downst	\sim	mine	road This feat	ure lacks the wetland	integrity r	oresent in EI	DC-1
and EDC-2. Marginal wetland vegetation:					0 1		
six years aerials are available, but no other		-		1 0 1 0			
VEGETATION - Use scientific names of plants	S.						
	bsolute		nant Indicator	Dominance Test worl	ksheet:		
Tree Stratum Plot size: 9	<u>% Cover</u>	Spec	ies? Status	Number of Dominant S That Are OBL, FACW,		1	(A)
2.							()
3.				Total Number of Domir Species Across All Stra		2	(B)
4		- Tota	al Cover	Percent of Dominant S	pecies	50.0	(4.17)
Sapling/Shrub Stratum Plot size:		- 100	ai Covei	That Are OBL, FACW,		50.0 %	(A/B)
1				Prevalence Index wor	rksheet:	NA - Ition by the co	
2				Total % Cover of:		Multiply by: = 0	
3				OBL species	x 1		
4				FACW species FAC species	37 x 2 6 x 3		
5		- Tot	al Cover		24 x 4		
Herb Stratum Plot size: 60 x 100		- 100	ai Covei	UPL species	3 x 5		
1. Heleanthus annuus	22	Yes	FACU		70 (A)	20:	
2. Polygonum aviculare	30	Yes	FACW				
3. Persicaria penslyvanica	5	No	FACW	Prevalence Index		2.9	00
4. Hordeum jubatum	3	No	FAC	Hydrophytic Vegetati		ors:	
5. Polygonum ramosissimum	3	No	FAC	X Dominance Test is			
6. Conyza canadensis	2	No	FACU	X Prevalence Index		Danida	
7. Rumex triangularis	2	No	FACW	Morphological Ada			
8. Bromus japonicus	1	No	Not Listed	Problematic Hydro	phytic Veg	etation¹ (Expla	ain)
9. Thinopyrum intermedium	2	No	Not Listed				
10	70	= Tota	al Cover				
Woody Vine Stratum Plot size:	70	- 100	ai Covei	¹ Indicators of hydric so be present.	oil and wetl	land hydrolog	y must
2.				Hydrophytic			
		= Tota	al Cover	Vegetation Yes	•	No 🔘	
% Bare Ground in Herb Stratum 30 % % Cover of	of Riotic C			Present?			
Remarks: Minors include Grindelia squarrosa. Gophe			sent				
Tomaino. Trimoro merude orindena squarrosa. Oopiie	or moull	as pre	5011t.				

SOIL Sampling Point: EDC-6

Profile Des	cription: (Describe	to the depth nee	ded to docui	ment the i	indicator o	or confirn	n the abs	ence of	indicators.	.)
Depth	Matrix			x Features						
(inches)	Color (moist)		or (moist)	%	Type ¹	Loc ²	Textu	ıre	· -	Remarks
0 - 9	10YR 5/3						Si	CL	Dry	
9 - 14	10YR 5/3	100					Si	CL	Mixed w	rith tailings
		· — — — — — — — — — — — — — — — — — — —								
		·							-	
1		Latina DM Danku	1 1 1 4 - 4 - 5 -	21 4:			O D10	N 1	NA NA-4	
Type: C=C	concentration, D=Depl	letion, RM=Reduc	ed Matrix.	Location	n: PL=Pore	Lining, R	C=Root C	Jnannei,	M=Matrix.	
Hydric Soil I	ndicators: (Applicabl	lo to all I DDs unl	nee othorwied	noted)			Indic	atore for	Problematic	c Hydric Soils ³ :
Histoso		le to all Lixixs, ulli	Sandy Redo	-					k (A9) (LRF	
	pipedon (A2)		Stripped Ma	. ,					k (A10) (LF	
	istic (A3)		Loamy Muc	. ,	ıl (F1)				Vertic (F18	
	en Sulfide (A4)		Loamy Gley	-					nt Material	<i>'</i>
	d Layers (A5) (LRR C		Depleted M		` '				plain in Rer	
1 cm M	uck (A9) (LRR D)		Redox Dark	Surface	(F6)			·		,
Deplete	d Below Dark Surface	e (A11)	Depleted D	ark Surfac	ce (F7)					
	ark Surface (A12)		Redox Dep	ressions (F8)					
	Mucky Mineral (S1)		Vernal Poo	ls (F9)						vegetation and
	Gleyed Matrix (S4)						We	etland hy	drology mu	st be present.
Restrictive	Layer (if present):									
Type:							Hydrid	Soil Pr	esent? Y	res ○ No ●
Depth (in	iches):									
Remarks: B	etween 9 and 14 in	ches, soil mixe	d with oxidi	zed rock	, no real 1	reduction	or conc	centratio	ns observ	ed. Part of this area has
a	cracked clay surface	ce, part has surf	ace tailings	visible v	vith many	gopher	mounds	. Soil ir	ndicators c	consistent with the
n	narginal hydric indi	cators within th	e entirety o	f the ED	C.					
HYDROLC)GY									
Wetland Hy	drology Indicators:									
Primary Indi	cators (any one indica	ator is sufficient)						Seconda	ry Indicator	s (2 or more required)
Surface	Water (A1)	Γ	Salt Crust	(B11)				Wate	er Marks (B	1) (Riverine)
High W	ater Table (A2)	Ī	Biotic Crus	st (B12)				 Sedi	ment Depo	sits (B2) (Riverine)
Saturati		Ī	Aquatic In	vertebrate	es (B13)					B3) (Riverine)
	Marks (B1) (Nonriveri	ine)	Hydrogen					_	nage Patter	
	nt Deposits (B2) (Nor	· ·	= -		res along l	Living Roo	ots (C3)		-	iter Table (C2)
	posits (B3) (Nonriver	· _			ed Iron (C4	_	, ,	_ '	fish Burrow	, ,
	Soil Cracks (B6)	Í	=		on in Plow		C6)			le on Aerial Imagery (C9)
	ion Visible on Aerial I	magery (B7)	Thin Muck			`	,	_	low Aquitar	
=	Stained Leaves (B9)		Other (Ex						-Neutral Te	` '
Field Obser										
		es O No 💿	Depth (in	ches):						
Water Table		es No	Depth (in			Wetl	and Hyd	rology P	resent? `	Yes No •
Saturation F				· · · · · · · · · · · · · · · · · · ·		- "	una nya	lology i	rosont.	
	pillary fringe)	es No 💿	Depth (in	cries)						
Describe Re	ecorded Data (stream			photos, pr	evious insp	pections),	if availab	le:		
Three of si	x photos available	show inundatio	n.							
Remarks: /	Aerial taken in sum	mers of 2004. 2	009 and 20	10 show	this featu	re to he f	flooded	Curren	ıtly, no evi	idence of an OHWM,
	anneling, or draina								J, J	
	oil cracking consist					es not res	semble a	racks fr	om pondi	ng.
	<i>G</i> 100	, , , , , , , , , , , , , , , , , , ,			, 20	.,			r	

FINAL

HISTORIC TAILING SPILLS REMOVAL ACTION COMPLETION REPORT CHEVRON QUESTA MINE SUPERFUND SITE

Revision 1

Prepared for Chevron Mining Inc. Questa, New Mexico

September 26, 2014

URS

URS Corporation 8181 E. Tufts Avenue Denver, CO 80237

Project No. 22242874

Appendix C Lower Dump Sump Wetland Delineation

DRAFT

LOWER DUMP SUMP WETLAND DELINEATION REPORT CHEVRON QUESTA MINE SUPERFUND SITE

Revision 0

Prepared for Chevron Mining Inc. Questa, New Mexico

February 5, 2014

URS

URS Corporation 8181 E. Tufts Avenue Denver, CO 80237

Project No. 22242874

1.0 INTRODUCTION

URS conducted a wetland delineation on July 24, 2013 to support removal of the historic tailing spill at the Lower Dump Sump (LDS). Wetland delineation is the evaluation process used to determine whether wetlands meeting the Section 404 definition are present or absent in an area, as described in the Overall Site Plan for Removal Actions, Chevron Questa Mine Superfund Site (URS 2012).

Tailing was removed at the LDS site in 2013 under the United States Environmental Protection Agency (EPA) Administrative Settlement Agreement and Order on Consent for Removal Actions, Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) Docket No. 06-09-12 and its appended Statement of Work (EPA 2012). During the EPA final inspection of the removal at the LDS, EPA requested an exploratory trench down-gradient and west of the LDS to evaluate whether tailing was present in that area. Because the area was observed to contain potential wetland vegetation, EPA requested wetland delineation be conducted prior to excavation of the exploratory trench.

No wetlands were identified. A map of the study is provided in Attachment A.

2.0 SITE DESCRIPTION

The study area for the delineation included about 2 acres of land west of the LDS, including about 300 feet of the Gallegos Ditch, wooded and shrubby areas along the ditch and in the Red River riparian area, and meadows. The study area boundary is shown on Figure 1, along with the location of soil pit locations and the exploratory trench. The study area extended about 250 feet west from the edge of the LDS to the edge of the property and included a minimum of 100 feet along the southwestern and western edge of the LDS. It was designed to include potential areas that could be affected by excavation of an exploratory trench and a minimum 50 foot buffer. Photographs of the study area are provided in Attachment B.

Soils

Three soil map units are present within the study area, according to soils maps included in the Soil Survey of Taos County and Parts of Arriba and Mora Counties [Natural Resource Conservation Service (NRCS) 2013]. Tenorio loam, 0 to 3 percent slopes and 1 to 5 percent slopes, are soils of valley sides. They are deep, well-drained non-saline soils that are formed in alluvium derived from igneous and metamorphic rock. They are classified as farmland of statewide importance. Based on the NRCS 1:24,000 scale mapping, they occupy most of the study area. A small portion of the study area on the north edge is mapped as Fluvents, nearly level. These are deep, well-drained, non-saline soils comprised of gravelly sand, with a water table at 0 to 24 inches below ground surface. They occur on floodplains. About 20 percent of the Fluvents map unit has a loam or clay loam subsoil.

Vegetation

Vegetation types present in the study area include riparian woodland and shrub, mesic meadow, wet meadow, disturbed, and upland shrub. All of the vegetation types have been strongly affected by past human activities or result from human activity.

Riparian Woodland and Shrub occupies most of the northern third of the study area and is part of a large area of riparian woodland (bosque) associated with the Red River at Questa. Common species in these areas are listed below in Table 1. The common grass species are non-native, while the shrubs and trees are all native. The wetland status of the common species ranges from upland (UPL) to facultative wetland species (FACW).

Table 1 **Common Species in Riparian Woodland and Shrub**

Name	Species	Wetland Indicator ¹
Grasses and Grass-like Pla	nnts	
Creeping wildrye	Elymus repens	FAC
Kentucky bluegrass	Poa pratensis	FAC
Shrubs and Trees		
Deciduous traveller's joy	Clematis ligusticifolia	FAC
Narrow-leaf cottonwood	Populus angustifolia	FACW
Chokecherry	Prunus virginiana	FACU
Woods' rose	Rosa woodsii	FACU
Narrow-leaf willow	Salix exigua	OBL
Round-leaf snowberry	Symphoricarpos rotundifolius	UPL

¹Lichvar 2013.

Wetland indicator categories:

Obligate (OBL) – occurs almost always in wetlands under natural conditions (estimated probability >99%) Facultative wetland (FACW) – usually occurs in wetlands (estimated probability 67-99%)

Facultative (FAC) – equally likely to occur in wetlands or non-wetlands (estimated probability 34-66%) Facultative upland (FACU) – usually occurs in non-wetlands but occasionally found in wetlands (estimated probability 1-33%)

Obligate upland (UPL) – Almost always occurs in uplands in the region (estimated probability >99% in non-wetlands).

Mesic meadow vegetation occupies most of the study area. Mesic meadow vegetation occurs on relatively level areas on both sides of the Gallegos Ditch. The vegetation is a mixture of grasses and forbs, and of native and non-native species. Forbs provide a larger portion of the cover than grasses. Thickets of the shrub Wood's rose (Rosa woodsii) occur in two areas.

Most of the common species are facultative (FAC) indicators, meaning they occur equally in wetland and non-wetland areas, but indicator status ranges from UPL to FACW. The majority of vegetation cover is comprised of wetland indicator species (FAC and FACW). Several of the common species are non-native including smooth brome (*Bromus inermis*), creeping wildrye (Elymus repens), Kentucky bluegrass (Poa pratensis), and Mexican fireweed (Kochia scoparia). Common species are listed in Table 2.

Table 2 **Common Species in Mesic Meadow**

Name	Species	Wetland Indicator ¹	
Grasses and Grass-like Plants			
Sleepygrass	Acnatherum robustum	UPL	
Smooth brome	Bromus inermis	FAC	
Creeping wildrye (quackgrass)	Elymus repens	FAC	
Smooth scouring rush	Equisetum laevigatum	FACW	
Kentucky bluegrass	Poa pratensis	FAC	
Forbs			
Tarragon	Artemisia dracunculus	UPL	
Mexican fireweed	Bassia scoparia	FAC	
Shrubs			
Woods' rose	Rosa woodsii	FACU	

¹Lichvar 2013

Wetland indicator categories:

Obligate (OBL) – occurs almost always in wetlands under natural conditions (estimated probability >99%) Facultative wetland (FACW) – usually occurs in wetlands (estimated probability 67-99%)

Facultative (FAC) – equally likely to occur in wetlands or non-wetlands (estimated probability 34-66%) Facultative upland (FACU) – usually occurs in non-wetlands but occasionally found in wetlands (estimated probability 1-33%)

Obligate upland (UPL) - Almost always occurs in uplands in the region (estimated probability >99% in non-wetlands).

Wet meadow vegetation occurs in limited and narrow areas within and along the banks of the Gallegos Ditch. Common species in these areas are listed in the Table 3. Most of the vegetation in these areas was comprised of FAC and obligate (OBL) wetland indicators, and therefore these areas were evaluated in the wetland delineation, as described in Section 4.0 Results. Several of the common species are non-native, including spreading bent, common timothy and Kentucky bluegrass. Other portions of the Gallegos Ditch banks were dominated by non-wetland vegetation.

Table 3 **Common Species in Wet Meadow**

Name	Species	Wetland Indicator ¹
Grasses and Grass-like Plants		
Spreading bent	Agrostis stolonifera	FAC
Water sedge	Carex aquatilis	OBL
Nebraska sedge	Carex nebrascensis	OBL

Table 3 **Common Species in Wet Meadow**

Name	Species	Wetland Indicator ¹	
Common timothy	Phleum pretense	FAC	
Kentucky bluegrass	Poa pratensis	FAC	
Shrubs			
Wood's rose	Rosa woodsii	FACU	

Lichvar 2013

Wetland indicator categories:

Obligate (OBL) – occurs almost always in wetlands under natural conditions (estimated probability >99%) Facultative wetland (FACW) – usually occurs in wetlands (estimated probability 67-99%)

Facultative (FAC) – equally likely to occur in wetlands or non-wetlands (estimated probability 34-66%) Facultative upland (FACU) – usually occurs in non-wetlands but occasionally found in wetlands (estimated probability 1-33%)

Obligate upland (UPL) – Almost always occurs in uplands in the region (estimated probability >99% in non-wetlands).

Disturbed occurs at the edge of the northern portion of the study area and west of the Gallegos Ditch at the former Reddell residence. It occurs around the former residence, a shed, former canal, and driveway. Vegetation is patchy with nearly 50 percent bare ground. A large number of species are present but most occur in limited amounts. The vegetation includes both native and introduced species, but the most common species are weedy. Wetland indicator status ranges from FAC to UPL. All of the common species are non-native with the exception of narrow-leaf willow (Salix exigua) and mealy goosefoot (Chenopodium incanum). Common species are shown in Table 4.

Table 4 **Common Species in Disturbed**

Name	Species	Wetland Indicator ¹	
Grasses and Grass-like Plants			
Quackgrass, creeping wild-rye	Elymus repens	FAC	
Forbs			
Mexican fireweed	Bassia scoparia	FAC	
Mealy goosefoot	Chenopodium incanum	UPL	
Tall hedge-mustard	Sisymbrium altissumum	FACU	
Shrubs			
Narrow-leaf willow	Salix exigua	FACW	

¹Lichvar 2013

Wetland indicator categories:

Obligate (OBL) – occurs almost always in wetlands under natural conditions (estimated probability >99%)

Facultative wetland (FACW) – usually occurs in wetlands (estimated probability 67-99%)

Facultative (FAC) – equally likely to occur in wetlands or non-wetlands (estimated probability 34-66%) Facultative upland (FACU) – usually occurs in non-wetlands but occasionally found in wetlands (estimated probability 1-33%)

Obligate upland (UPL) - Almost always occurs in uplands in the region (estimated probability >99% in non-wetlands).

Upland shrub occurs on slopes at the south end of the study area. The only wetland indicator species are weedy FAC species, including Mexican fireweed and Russian olive. Scattered Russian olive (Elaeagus angustifolia) and Rocky Mountain juniper (Juniperus scopulorum) trees are present. Most of the species are native. Common species are listed in Table 5.

Table 5 **Common Species in Upland**

Species	Name	Wetland Indicator ¹
Grasses and Grass-like Plants		
Blue grama	Bouteloua gacilis	UPL
Forbs		
Tarragon	Artemisia dracunculus	UPL
Mexican fireweed	Bassia scoparia	FAC
Shrubs and Trees		
Fringed sage	Artemisia frigida	UPL
Rubber rabbitbrush	Ericameria nauseosa	UPL
Russian olive	Elaeagnus angustifolia	FAC
Rocky Mountain juniper	Juniperus scopulorum	UPL
Twisted spine prickly pear	Opuntia macrorhiza	UPL

¹Lichvar 2013

Wetland indicator categories:

Obligate (OBL) – occurs almost always in wetlands under natural conditions (estimated probability >99%) Facultative wetland (FACW) – usually occurs in wetlands (estimated probability 67-99%)

Facultative (FAC) – equally likely to occur in wetlands or non-wetlands (estimated probability 34-66%) Facultative upland (FACU) - usually occurs in non-wetlands but occasionally found in wetlands (estimated probability 1-33%)

Obligate upland (UPL) - Almost always occurs in uplands in the region (estimated probability >99% in non-wetlands).

Hydrology

The study area is located in the Upper Rio Grande Watershed (HUC 13020101) and is a short distance from the Red River. The only feature mapped by the National Wetlands Inventory (NWI) (USFWS 2010) in the study area is Gallegos Ditch. Gallegos Ditch is mapped as R4SBC - riverine, intermittent, streambed, seasonally flooded, which is consistent with observations

made during the delineation. The NWI map unit includes two small drainages that are intercepted by the Gallegos Ditch outside of the study area. The Gallegos Ditch originates from the Red River just east of the LDS, and terminates in uplands just east of Four Hill Road, west of the study area. Its' total length is about 2, 900 feet, of which about 300 feet are located within the study area.

Wildlife

American elk (Cervus elaphi) droppings were common in the study area. A number of bird species were observed, including black-billed magpie (*Pica pica*), American kestrel (*Falco* sparverius), house wren (Troglodytes aedon), and violet-green swallow (Tachycineta thalassina).

3.0 **METHODS**

The study area was determined in the field by including potential areas that could be affected by excavation of an exploratory trench and a minimum 50 foot buffer. Field maps were created with ESRI® ArcGIS® software (1 inch equals 50 feet). Pre-field research included review of NWI maps, detailed air photos, topographic maps (USGS 1995), and previous environmental reports from the area.

The wetland delineation was conducted on July 24, 2013, by Jeffrey Dawson and Eric Bunnell. Wetland delineations were conducted using the Routine Determination protocol discussed in the Corps of Engineers Wetland Delineation Manual Technical Report 4-87-1 (Environmental Laboratory 1987) and the Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Western Mountains, Valleys, and Coasts (Environmental Laboratory 2010). Wetlands are identified in the field as areas having positive evidence of three environmental parameters: hydric soils, wetland hydrology, and greater than five percent hydrophytic vegetation. Data for potential wetlands (Attachment C) were recorded on wetland data forms provided in the regional supplement.

Surface water features (i.e., streams and ponds) were identified by the presence of a defined bed and bank, evidence of an ordinary high water or bankfull indicator, and less than 50 percent vegetative cover within the bed. Field information recorded for surface water features included depth and width of the average ordinary high water mark, average bankfull depth, bank slope, substrate composition, source of hydrology, dominant vegetation, other vegetation, percent overstory, and any wildlife or their signs observed.

Locations of soil pits and other GPS data were recorded using a Trimble® sub-meter hand-held global positioning system (GPS). Photographs were taken of each feature. Unique identifiers were assigned to each feature delineated based on location. For example, the first potential wetland was assigned a unique identifier of WL-1.

Plant species were identified using Allred and Ivey (2012) and other botanical sources. Plant names follow Lichvar (2013) for wetland indicator species, and Allred (2003) for common names of upland species.

4.0 **RESULTS**

No wetlands were delineated in the study area and one surface water feature (Gallegos Ditch) was delineated. Based on an initial reconnaissance, two potential wetlands were identified – an herbaceous area (WL-1) along a portion of the Gallegos Ditch and a scrub-shrub area (WL-2) below a section of the ditch. During the field assessment, these areas did not meet the requirements to be considered wetlands under the applicable Corps Manuals because they lacked indicators for soils and hydrology.

The potential herbaceous wetland area is identified as WL-1 in the data sheets and is shown in Photos 1 and 2 in Attachment B. This was an area about 75 feet long and about 2 to 3 feet wide on each side of the Gallegos Ditch in the central part of the study area. The area of potential wetland was bounded by the open water of the ditch and by raised berms of soil and sediment excavated from the ditch, which are visible on the aerial photo. The vegetation was dominated by hydrophytic sedges and grasses, with all 3 dominant species having wetland indicators, Nebraska sedge, Kentucky bluegrass and timothy. Three soil pits were dug and no hydric soil indicators were found. No water or saturation was found in the soil pits, and no evidence of hydrology was found in vegetated areas immediately adjacent to Gallegos Ditch. The irrigation channel was flowing at the time of the survey, but did not provide wetland hydrology to adjoining soils.

The potential scrub-shrub wetland area (WL-2 in the data sheets) consisted of a dense thicket of narrow-leaf willow located on a slope the east side of Gallegos Ditch and extending to the terrace below the ditch (Attachment B Photos 4 and 5). The vegetation was hydrophytic, with 3 of 4 species having wetland indicators, including narrow-leaf willow, deciduous traveller's joy (Clematis ligusticifolia), and Kentucky bluegrass. One soil pit was dug, located at the bottom of the slope about 5 feet vertically below Gallegos Ditch. No soil or hydrology indicators were observed. There was no observed evidence of overflow, leaks, or seepage from the ditch.

Water flowing in Gallegos Ditch was about 4 feet wide, about 8 inches deep, and flowing slowly at the time of the survey. The ditch is mostly elevated above the surrounding terrace in the study area. More information is provided on the surface water features data sheet in Attachment C. There were no irrigation turnouts or places that appeared to regularly receive irrigation in the study area. According to the US Geological Survey (USGS) map (USGS 1995) and air photos, Gallegos Ditch ends in an upland area. The downstream portions of the ditch were not observed during this field survey.

In addition to WL-1 and WL-2, the meadows and riparian forest in the study area were also dominated by plant species that are considered hydrophytic, including several meadow grasses, a common annual weed (Mexican fireweed), and the dominant tree species in the Red River riparian area (narrowleaf cottonwood, *Populus angustifolia*). These areas were not addressed in data sheets because they had no FACW or OBL species with the exception of narrowleaf cottonwood; there was no evidence of wetland hydrology with the exception of yellow sediment discussed below; and soils were non-hydric.

Thin deposits of yellow sediment were found on vegetation and surface soils along the ditch and in the meadow north of the ditch (Attachment B, Photo 10. The sediment deposits appear to have resulted from a recent storm event that sent excess water down the ditch from the Red River and overtopped the edges of the ditch. There was no apparent relationship between areas of sediment deposition and presence of wetland plant species. The sediment deposits and presumed overtopping were interpreted as an uncommon event that does not result in wetland hydrology.

5.0 CONCLUSION

No wetlands were delineated in the study area. Gallegos Ditch was delineated as an "other water" feature, and may be under the jurisdiction of the Clean Water Act.

LITERATURE CITED 6.0

Allred, Kelly W. 2003. A Working Index of New Mexico Vascular Plant Names. New Mexico State University Range Science Herbarium.

Allred, Kelly W., and Robert DeWitt Ivey. 2012. Flora Neomexicana III: An Illustrated Identification Manual. Available at www.lulu.com

Environmental Laboratory. 1987. Corps of Engineers Wetland Delineation Manual Technical Report Y-87-1. Prepared for the US Army Corps of Engineers, Washington, DC. Final Report. January.

Environmental Laboratory. 2010. Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Western Mountains, Valleys, and Coasts (Version 2.0). ERDC/EL TR-10-3. U.S. Army Engineer Research and Development Center, 3909 Halls Ferry Road, Vicksburg, MS 39180-6199. May.

Environmental Protection Agency. 2012. In re Chevron Mining Inc., Administrative Settlement Agreement and Order on Consent for Removal Actions, Chevron Questa Mine Superfund Site, Questa, New Mexico. CERCLA Docket 06-09-12 CERCLIS ID No. NMD002899094. March 8.

Natural Resource Conservation Service. 2013. Soil Survey of Taos County and Parts of Rio Arriba and Mora Counties, New Mexico. Version 9, December 27, 2013. Natural Resources Conservation Service.

Web Soil Survey URL: http://websoilsurvey.nrcs.usda.gov. Accessed January 15, 2013.

Lichvar, R.W. 2013. 2013 Wetland Ratings. Phytoneuron: In Press New Mexico 2013 State Wetland Plant List available from U.S. Army Corps of Engineers, Cold Regions Research and Engineering Laboratory. http://wetland_plants.us.ace.army.mil.

URS. 2012. Overall Site Plan for Removal Actions, Chevron Questa Mine Superfund Site, Rev. 1. Prepared for Chevron Mining Inc., Questa, New Mexico.

US Geological Survey (USGS). 1995. Questa, NM 1:24,000 topographic map.

US Fish and Wildlife Service. 2010. National Wetlands Inventory, Wetlands Mapper. Data for Questa 1:24,000 quad. http://www.fws.gov/wetlands/Data/Mapper.html






Photo 1. WL-1, looking west along Gallegos Ditch. Shrub on right is Wood's rose.



Photo 2. WL-1, looking east along Gallegos Ditch.



Photo 3. Upland shrub on slope south of WL-1.



Photo 4. WL-2, looking west.



Photo 5. WL-2 (on left), looking north. LDS excavation is on right.



Photo 6. Weedy area and shed at former Reddell Residence, looking southeast. Gallegos Ditch is behind shed.



Photo 7. Riparian woodland and shrub, Gallegos Ditch and back of shed, looking south.



Photo 8. Riparian woodland east of former Reddell residence, looking northwest. Elevated tailing pipeline is in right background.



Photo 9. Meadow north of Gallegos Ditch, looking west.



Photo 10. Recent sediment deposits in meadow.



Photo 11. Meadow north of Gallegos Ditch, looking east.



Photo 12. Meadow adjacent to LDS, looking south.

Attachment C Data Forms

Irface Waters Features Data Sheet			
Project -	HTS Project		
Date -	Wednesday, July 24, 2013		
Investigators -	Jeff Dawson		
Area ID -	Gallegos Ditch		
Centerpoint coordinates -			
HUC -	13020101 (Upper Rio Grande)		
Land Use -	Dispersed residential		
Physical			
Type of feature (pond or stream)-	irrigation ditch		
Source-	Red River		
Connectivity -	unknown, appears to end in upland		
Water Clarity (clear, murky, turbid)-	cloudy		
Water Color (if obvious)-	whitish		
For Streams Only			
Average Width of OHWM (bankfull)-	4 feet		
Average observed width-	4 feet		
Bankfull depth-	14 inches		
Observed Depth-	8 inches		
Bank Slope (X:X) (on each side if different - use N/S or E/W)-	vertical		
Evidence of undercutting or excessive erosion-	No		
Occurrance of riffle-pool-run complexes (Natural hydro only)-	NA		
Channelized or meandering (Natural hydro only)-	NA		
Bed substrate composition-	clayey silt		
Velocity (slow, moderate, fast)-	slow		
Flow Direction (to)-	west		
For Ponds Only			
Inlet/Outlet present?			
Restricted outlet?			
Biological			
Percent estimated bank cover-	100		
Bank vegetation (dominant species/if associated with wetland refer to data sheet)-	sedges and grasses		
Aquatic vegetation present (Y/N, list species if known)-	none		
Percent overstory (amount hanging over the channel, streams only)-	10		
Evidence of rafted/submerged large woody debris-	NA		
Evidence of other rafting (smaller debris, etc.)-	NA		
Aquatic or terrestrial wildlife present (list species)-	magpie, kestrel, house wren, violet-green swallow		

WETLAND DETERMINATION DATA FORM - Western Mountains, Valleys, and Coast

Project/Site: HTS Project/Lower Dump Sump	Kiggelini Chiro	City/Cou	nty:Questa, T	Taos County	San	npling Date:	7/24/13
Applicant/Owner: Chevron	= 1539-11			State:NM	San	npling Point:	WL-1
Investigator(s):Jeff Dawson, Eric Bunnell		Section,	Township, Ra	inge:Section 6, T28	N, R13E	E RELEASE	The May
Landform (hillslope, terrace, etc.): terrace		Local re	lief (concave,	convex, none):conve	ex	Si	ope (%):2
Subregion (LRR):E - Rocky Mountain Forests and Rangelan	nd Lat:36	.69401	SH	Long: -105.5292		Dat	um:NAD 1983
Soil Map Unit Name: Tenorio loam, 1-3% slope	, ma 11 4			NWI clas	ssification	:NA	a facility
Are climatic / hydrologic conditions on the site typical for	this time of y	rear? Yes	● No ((If no, explain	in Rema	rks.)	
Are Vegetation Soil or Hydrology	significantl	y disturbe	d? Are	"Normal Circumstance	es" prese	nt? Yes	No C
Are Vegetation Soil or Hydrology	naturally p	roblematic		eeded, explain any an			
SUMMARY OF FINDINGS - Attach site ma	p showing	g sampl	ing point l	ocations, transe	cts, im	portant fe	eatures, etc.
Hydrophytic Vegetation Present? Yes (• Hydric Soil Present? Yes (• Wetland Hydrology Present? Yes (•	No (No ()		the Sampled		C	No (
Remarks: Potential wetland along a portion of C west is at the base of a 4:1 slope to th River Valley. To the north is a mesic	e south. To meadow ab	the east,	the ditch is	elevated above the			
VEGETATION - Use scientific names of plants					4.8	ppier Wee	an eers v
Tree Stratum Plot size:	Absolute % Cover		nt Indicator Status	Dominance Test v	vorkshee	et:	
1.				Number of Domina	nt Specie	es	
2.		NT.		That Are OBL, FAC (excluding FAC-):	CW, or FA		3 (A)
3		0.1		Total Number of Do	nminant		
4. 0.000 0.00	: (M) 1/2071	IIII NELOGIE	YEART LESS	Species Across All		ALIATA PARAME	3 (B)
Sapting/Shrub Stratum Plot size:	-244	= Total C	over	Percent of Dominal That Are OBL, FAC			00.0 % (A/B)
2.			W2	Prevalence Index	workshe	et:	di Tuskuv
3.				Total % Cover	of:	Multip	oly by:
4.		الإركاء	GIR TO TE	OBL species	31	x 1 =	31
5. Organia may a dea continua accumina	Marian San	J. 479 . 4.18	PELENCE (FACW species	4	x 2 =	8
Herb Stratum Plot size 10 x 2 m		= Total C	over	FAC species	69	x 3 =	207
1. Carex aquatilis	6	No	ODI	FACU species UPL species		x 4 =	0
2. Poa pratensis		No Yes	OBL FAC		104	x 5 =	0 246 (B)
3. Geum macrophyllum	2	No	FAC	Column Totals:	104	(A)	246 (B)
4. Epilobium ciliatum	4	No	FACW	Prevalence Ir	ndex = B	/A =	2.37
5. Rumex crispus	4	No	FAC	Hydrophytic Vege			Keny Topphonia
6. Agrostis stolonifera	5	No	FAC	1 - Rapid Test	5300		etation
7.Bromus inermis	3	No	FAC	X 2 - Dominance X 3 - Prevalence			
8 Carex nebrascensis	25	Yes	OBL	4 - Morphologi	the state of the		ride supporting
9.Phleum pratense	25	Yes	FAC	data in Ren	narks or o	on a separat	
10. # doll for those grant (Sale		Y <u>w</u> ==	10000170	5 - Wetland No			1 (Evolaio)
Woody Vine Stratum Plot size: 1.	104	= Total C	over	Problematic Hy Indicators of hydri be present, unless	ic soil an	d wetland h	ydrology must
2		= Total C	over	Hydrophytic Vegetation Present?	'es (•	No (0

0-14 14-18	Color (moist) 10YR4/4	%		Redox F								
	10YR4/4		Color (m	oist)	<u>%</u>	Type ¹	_Loc2	Text	ure		Remarks	willia :
14-18		95	Truy, a	pressi word	All N	1588		silty cl	ay loam	mixed mat	rix	Anterior I
14-18	10YR2/1	3		odina Sur.	12.5	Eine V		silty cl	ay loam	11 E21 E36 &	and inches	si l
14-18	10YR7/4	2	2011		6		mai L	silty cl	lay loam	a Kontonio (4 o	No.22 401	nie jūrasi
	10YR4/3	95		- 0						mixed mat	rix	lu si
	7.5YR6/6	5			BAT LA T		in the		lay loam	S. 2.1139		34,21
717 _	English Language	ure rigili	Alghara	nachatta.	, and		113-104	Sitty Ci	n shirt	Har Se Ville		nuae de
3/4 ¥/	dere drog for the		resigna les Se paresse			ene ar		A-z-		e de la compansión de l		
ype: C=Conce	ntration, D=Depletion	n, RM=Redu	ced Matrix, C	S=Covered o	r Coated	Sand Grai	ns		1.43	² Location: PL:	=Pore Lining,	M=Matrix
dric Soil Indi	icators: (Applicab	le to all LR	Rs, unless	otherwise n	oted.)		- A	Indic	ators for	Problematic H	lydric Soils ³	LUMPHIE
Histosol (A			San	dy Redox (S	5)				2 cm Mud	k (A10)		
Histic Epip			Stri	pped Matrix	(S6)				Red Pare	nt Material (T	F2)	161 174
Black Histi	Declaration of the Control of the Co		Loa	my Mucky I	Mineral ((F1) (exc	ept MLR	A1)	Very Sha	llow Dark Sur	face (TF12)	
CAPACITY AND ASSOCIATION	Sulfide (A4)	11413	100	my Gleyed	THE PAPEL C. U. THE LO	F2)			Other (Ex	pl ai n in Rema	arks)	
	Below Dark Surface	e (A11)		oleted Matrix		La rece						
=	Surface (A12)			dox Dark Su				3	Indicator	s of hydrophy	tic vegetation	n and
	cky Mineral (S1)			oleted Dark		. ,				nydrology mu		
_ Sandy Gle	yed Matrix (S4)	to an	☐ Red	dox Depress	SIONS (F	3)			unless di	sturbed or pro	oblematic.	
strictive Lay	er (if present):										, A .	
Type:	The state of							Hydrie	c Soil Pre	sent? Yes	C	0
	1											
Depth (inche	nydric indicators	Soils m	nay be mod	dified by d	itch ma	nintenano	ce, altho	ough spoi	il from n	nost recent d	litch cleani	ng is
Depth (inche emarks: No h depo simi	nydric indicators osited outside are lar. All soil pits	ea of pote	ential wetla	and. Yello	wish m	naterial a	ppears t	ough spoi	il from n ses of fin	nost recent d	litch cleani il pits 2 and	ng is
Depth (inche emarks: No h depo simi	nydric indicators osited outside ard lar. All soil pits	ea of potes within 2	ential wetla	and. Yello	wish m	naterial a	ppears t	ough spoi	il from n ses of fin	nost recent due sand. Soi	litch cleani il pits 2 and	ng is
Depth (inche marks: No h depo simi	nydric indicators osited outside are lar. All soil pits	ea of pote s within 2	ential wetla to 3 feet o	and. Yello	wish m	naterial a	ppears t	ough spoi	ses of fin	nost recent de sand. Soi	il pits 2 and	ng is
Depth (inche emarks: No h depo simil DROLOGY etland Hydro imary Indicators	nydric indicators osited outside ar lar. All soil pits Y blogy Indicators: s (minimum of one re	ea of pote s within 2	ential wetla to 3 feet o	and. Yello of edge of o	owish m	naterial a ater in d	uppears t	ough spoi	ses of fin	ne sand. Soi	il pits 2 and	ng is d 3 were
Depth (inche emarks: No h depo simil DROLOGY etland Hydro imary Indicators Surface Wa	nydric indicators osited outside ar lar. All soil pits Y blogy Indicators: s (minimum of one re	ea of pote s within 2	ential wetla to 3 feet o	and. Yello	owish mopen w	naterial a ater in d	uppears t	ough spoi	ses of fin	ne sand. Soi	il pits 2 and	ng is d 3 were
Depth (inche emarks: No h depo simil DROLOGY etland Hydro imary Indicators Surface Wa	nydric indicators osited outside are lar. All soil pits Y plogy Indicators: s (minimum of one re later (A1) r Table (A2)	ea of pote s within 2	ential wetla to 3 feet o	and. Yello of edge of o	bwish mopen was	naterial a ater in d	uppears t	ough spoi	Secondary Water	Indicators (min	il pits 2 and	ng is d 3 were
Depth (inche marks: No h depo simil DROLOGY etland Hydro imary Indicators Surface Wa High Water	nydric indicators osited outside ard lar. All soil pits Y blogy Indicators: s (minimum of one relater (A1) r Table (A2) (A3)	ea of pote s within 2	ck all that app	and. Yelloof edge of o	bwish mopen was Leaves a, and 4	naterial a ater in d s (B9) (ex 4b)	uppears t	ough spoi	Secondary Water MLR	Indicators (mini-Stained Leav	il pits 2 and imum of two noves (B9) (ex. d 4b)	ng is d 3 were
Depth (inche marks: No h depo simil DROLOGY etland Hydro imary Indicators Surface Wa High Water Saturation Water Mark	nydric indicators osited outside are lar. All soil pits Y Dlogy Indicators: s (minimum of one relater (A1) r Table (A2) (A3) ks (B1)	ea of pote s within 2	ck all that app	of edge of o	d Leaves a, and 4	naterial a ater in d s (B9) (ex 4b)	uppears t	ough spoi	Secondary Water MLR Draina	Indicators (mini-Stained Leav A 1, 2, 4a, and age Patterns (eason Water	inum of two noves (B9) (ex. d 4b) (B10) Table (C2)	ng is d 3 were
Depth (inche emarks: No hadepo similar depo	ydric indicators osited outside are lar. All soil pits Y Dlogy Indicators: s (minimum of one relater (A1) r Table (A2) (A3) ks (B1) Deposits (B2)	ea of pote s within 2	ential wetlated to 3 feet of the second seco	and. Yello of edge of o oly) ater-Stained ILRA 1, 2, 4 alt Crust (B quatic Inver	d Leaves a, and 4 11) tebrates	s (B9) (ex (B13) or (C1)	ppears titch.	ough spoi	Secondary Water MLR Draina Dry-S Satura	Indicators (mini-Stained Leava 1, 2, 4a, and age Patterns (eason Water ation Visible of	imum of two noves (B9) (ex. d 4b) (B10) Table (C2) on Aerial Ima	ng is d 3 were
Depth (inche emarks: No hadeposimi) Depth (inch	nydric indicators osited outside are lar. All soil pits Y Dlogy Indicators: s (minimum of one relater (A1) r Table (A2) (A3) ks (B1) Deposits (B2) sits (B3)	ea of potes within 2	ck all that app Ck all that app M M H	and. Yello of edge of o livity) ater-Stained lLRA 1, 2, 4 alt Crust (B' quatic Inver	Leaves a, and 4 11) tebrates lifide Od	s (B9) (ex (B13) or (C1) es on Livi	ppears titch.	ough spoi	Secondary Water MLR Draina Dry-S Satura Geom	Indicators (mini- Stained Leava 1, 2, 4a, and age Patterns (eason Water ation Visible corphic Positic	imum of two noves (B9) (exc d 4b) (B10) Table (C2) on Aerial Ima on (D2)	ng is 1 3 were
Depth (inche emarks: No hadeposimii) DROLOGY etland Hydro imary Indicators Surface Wa High Water Saturation Water Mark Sediment D Drift Deposimal Mark of the control of	rydric indicators osited outside are lar. All soil pits Y Dlogy Indicators: s (minimum of one re later (A1) r Table (A2) (A3) ks (B1) Deposits (B2) sits (B3) or Crust (B4)	ea of potes within 2	ck all that app	and. Yello of edge of o livity) later-Stained lLRA 1, 2, 4 alt Crust (B quatic Inver lydrogen Su lydrogen Su lydrogen Su lydrogen Su lydrogen Su lydrogen Su	d Leaves da, and 4 11) tebrates liide Od zosphen	s (B9) (ex (B13) or (C1) es on Livi	nppears titch.	ough spoi to be len	Secondary Water MLR Draina Dry-S Satura Geom	Indicators (minimals) -Stained Leaver A 1, 2, 4a, and age Patterns (eason Water attion Visible of corphic Position Waquitard (Eason Waquitard	imum of two noves (B9) (exceed 4b) (B10) Table (C2) on Aerial Imaton (D2) (D3)	ng is d 3 were
Depth (inche marks: No hadeposimii) DROLOGY etland Hydro imary Indicators Surface Wall High Water Saturation Water Mark Sediment D Drift Deposimant D Iron Deposimant D	rydric indicators osited outside are lar. All soil pits Y plogy Indicators: s (minimum of one re later (A1) r Table (A2) (A3) ks (B1) Deposits (B2) sits (B3) or Crust (B4)	ea of potes within 2	ck all that app	and. Yello of edge of o leading	d Leaves a, and 4 11) tebrates lfide Od zosphere Reduced	s (B9) (ex (B13) or (C1) es on Livid Iron (C4	ppears titch.	ough spoi to be len	Secondary Water MLR Draina Dry-S Satura Geom Shallo	Indicators (mini-Stained Leav A 1, 2, 4a, and age Patterns (eason Water attion Visible of corphic Position Water Aquitard (ENeutral Test (imum of two noves (B9) (except decoration) (B10) Table (C2) on Aerial Imaton (D2) (D3) (D5)	ng is 1 3 were equired) cept
Depth (inche marks: No hadeposimi) DROLOGY etland Hydro imary Indicators Surface Wall High Water Saturation Water Mark Sediment D Drift Depos Algai Mat of Iron Depos Surface So	rydric indicators osited outside are lar. All soil pits Y Diogy Indicators: s (minimum of one re later (A1) r Table (A2) (A3) ks (B1) Deposits (B2) sits (B3) or Crust (B4) sits (B5) oil Cracks (B6)	ea of potes within 2	ck all that app	and. Yello of edge of o later-Stained lika 1, 2, 4 alt Crust (Bi quatic Inver- lydrogen Su exidized Rhi resence of I ecent Iron F tunted or St	d Leaves a, and 4 11) tebrates lfide Od zosphere Reduceo Reductio	s (B9) (ex s (B13) or (C1) es on Livi d Iron (C4 ns in Tille	ppears titch.	ough spoi to be len	Secondary Water MLR Draina Dry-S Satura Geom Shallo FAC-	Indicators (mini-Stained Leav A 1, 2, 4a, and age Patterns (eason Water ation Visible of corphic Position Water ation Visible of the Water at Test (do Ant Mounds)	imum of two n wes (B9) (exc d 4b) (B10) Table (C2) on Aerial Ima on (D2) D3) (D5) s (D6) (LRR	ng is d 3 were equired) cept
Depth (inche emarks: No hadeposimi) DROLOGY Total Hydro dimary Indicators Surface Wash High Water Saturation Water Mark Sediment Dorift Deposiment Deposiment Dorift Deposiment Deposiment Dorift Deposiment Deposiment Deposime	rydric indicators osited outside are lar. All soil pits Y Diogy Indicators: s (minimum of one re later (A1) r Table (A2) (A3) ks (B1) Deposits (B2) sits (B3) or Crust (B4) sits (B5) Visible on Aerial In	ea of potes within 2	ck all that app Ck all that app W M S A D P R S T O O O O O O O O O O O O O O O O O O	and. Yello of edge of o leading	d Leaves a, and 4 11) tebrates lfide Od zosphere Reduceo Reductio	s (B9) (ex s (B13) or (C1) es on Livi d Iron (C4 ns in Tille	ppears titch.	ough spoi to be len	Secondary Water MLR Draina Dry-S Satura Geom Shallo FAC-	Indicators (mini-Stained Leav A 1, 2, 4a, and age Patterns (eason Water attion Visible of corphic Position Water Aquitard (ENeutral Test (imum of two n wes (B9) (exc d 4b) (B10) Table (C2) on Aerial Ima on (D2) D3) (D5) s (D6) (LRR	ng is d 3 were equired) cept
Depth (inche emarks: No hadepo simility) (DROLOGY etland Hydro imary Indicators Surface Wash High Water Saturation Water Mark Sediment Dorift Depos Algai Mat of Iron Depos Surface Soll Inundation Sparsely Water Sparsely Water Saturation Sparsely Water Mark Sediment Dorift Depos Algai Mat of Iron Depos Surface Soll Inundation Sparsely Water Mark Sediment Dorift Depos Surface Soll Inundation Sparsely Water Mark Sediment Depos Sparsely Water	rydric indicators osited outside ard lar. All soil pits Y Dlogy Indicators: s (minimum of one relater (A1) r Table (A2) (A3) ks (B1) Deposits (B2) sits (B3) or Crust (B4) sits (B5) bil Cracks (B6) Visible on Aerial In	ea of potes within 2	ck all that app Ck all that app W M S A D P R S T O O O O O O O O O O O O O O O O O O	and. Yello of edge of o later-Stained lika 1, 2, 4 alt Crust (Bi quatic Inver- lydrogen Su exidized Rhi resence of I ecent Iron F tunted or St	d Leaves a, and 4 11) tebrates lfide Od zosphere Reduceo Reductio	s (B9) (ex s (B13) or (C1) es on Livi d Iron (C4 ns in Tille	ppears titch.	ough spoi to be len	Secondary Water MLR Draina Dry-S Satura Geom Shallo FAC-	Indicators (mini-Stained Leav A 1, 2, 4a, and age Patterns (eason Water ation Visible of corphic Position Water ation Visible of the Water at Test (do Ant Mounds)	imum of two n wes (B9) (exc d 4b) (B10) Table (C2) on Aerial Ima on (D2) D3) (D5) s (D6) (LRR	ng is d 3 were equired) cept
Depth (inche emarks: No hadeposimii) (DROLOGY) (etland Hydro imary Indicators) Surface War High Water Saturation Water Mark Sediment Darift Deposiment Deposiment Darift Deposiment Darift Deposiment Darift Deposiment Darift Deposiment Deposiment Darift Deposiment Darift Deposiment Deposiment Darift Deposiment Deposiment Darift Deposiment Darift Deposiment Deposiment Darift Deposiment Deposiment Deposiment Darift Deposiment Depo	rydric indicators osited outside ard lar. All soil pits Y Dlogy Indicators: s (minimum of one relater (A1) r Table (A2) (A3) ks (B1) Deposits (B2) sits (B3) or Crust (B4) sits (B5) oil Cracks (B6) Visible on Aerial Indepetated Concave stions:	ea of potes within 2 equired; checomagery (B7) e Surface (B)	ck all that app W M S A H O P R S 7) O	and. Yello of edge of o later-Stained ILRA 1, 2, 4 alt Crust (B quatic Inver lydrogen Su exidized Rhiz resence of I ecent Iron F tunted or St tunted or St	d Leaves a, and 4 11) tebrates lfide Od zosphere Reduceto ressed f n in Rer	s (B9) (ex s (B13) or (C1) es on Livi d Iron (C4 ns in Tille	ppears titch.	ough spoi to be len	Secondary Water MLR Draina Dry-S Satura Geom Shallo FAC-	Indicators (mini-Stained Leav A 1, 2, 4a, and age Patterns (eason Water ation Visible of corphic Position Water ation Visible of the Water at Test (do Ant Mounds)	imum of two n wes (B9) (exc d 4b) (B10) Table (C2) on Aerial Ima on (D2) D3) (D5) s (D6) (LRR	ng is d 3 were equired) cept
Depth (inche emarks: No hadeposimii) **DROLOG** **Jetland Hydro imary Indicators* Surface Water Saturation Water Mark Sediment Darift Deposition Drift Deposition Surface Solution Iron Deposition Sparsely Voleid Observation Sp	rydric indicators osited outside are lar. All soil pits Y Dlogy Indicators: s (minimum of one relater (A1) r Table (A2) (A3) ks (B1) Deposits (B2) sits (B3) or Crust (B4) sits (B5) oil Cracks (B6) Visible on Aerial Indicators: Present?	ea of potes within 2 equired; checked magery (B7) e Surface (I	chtial wetlat to 3 feet of the set all that app	and. Yello of edge of of edge of of edge of of later-Stained later-Stained later-Stained later-Stained later-Stained edge of later- later edge of later- edge of later- edg	d Leaves a, and 4 11) tebrates lfide Od zosphere Reduceo Reductio ressed I n in Rer	s (B9) (ex s (B13) or (C1) es on Livi d Iron (C4 ns in Tille	ng Roots d Soils ((ough spoi to be len	Secondary Water MLR Draina Dry-S Satura Geom Shallo FAC- Raise	Indicators (mini- Stained Leavan, 1, 2, 4a, and age Patterns (eason Water ation Visible of corphic Position Water at Test (d. Neutral Test (d. Ant Moundard Heave Humn	imum of two noves (B9) (except description) (B10) Table (C2) on Aerial Imaton (D2) D3) (D5) s (D6) (LRR nocks (D7) (ng is d 3 were equired) cept A) LRR F)
Depth (inche emarks: No hadeposimii) **Toronomarks: No hadeposimii **Toronomarks: No hadeposimii **Toronomarks: No hadeposimii **Surface Water Mark Saturation **Water Mark Sediment Darift Deposiment Darift Darift Deposiment Darift Deposiment Darift Deposiment Darift Deposiment Darift Deposiment Darift Darift Deposiment Darift Darift Deposiment Darift Deposiment Darift Darift Deposiment Darift Darift Deposiment Darift Darift Deposiment Darift	rydric indicators osited outside are lar. All soil pits Y Diogy Indicators: s (minimum of one re later (A1) r Table (A2) (A3) ks (B1) Deposits (B2) sits (B3) or Crust (B4) sits (B5) Visible on Aerial Indicated Concave later (A1) regetated Concave laters: Present?	magery (B)	ck all that app Ck all that app W M S A A B B B B B B B B B B B B B B B B B	and. Yello of edge of o later-Stained ILRA 1, 2, 4 alt Crust (B quatic Inver lydrogen Su exidized Rhiz resence of I ecent Iron F tunted or St tunted or St	d Leaves a, and 4 11) tebrates lfide Od zosphere Reduceo Reductio ressed in in Rer	s (B9) (ex s (B13) or (C1) es on Livi d Iron (C4 ns in Tille	ng Roots d Soils ((ough spoi to be len	Secondary Water MLR Draina Dry-S Satura Geom Shallo FAC- Raise	Indicators (mini-Stained Leava A 1, 2, 4a, and age Patterns (eason Water ation Visible coorphic Position Waquitard (ENeutral Test (d Ant Mounds Heave Humn	imum of two noves (B9) (except description) (B10) Table (C2) on Aerial Imaton (D2) D3) (D5) s (D6) (LRR nocks (D7) (ng is d 3 were equired) cept A) LRR F)

WETLAND DETERMINATION DATA FORM - Western Mountains, Valleys, and Coast

Project/Site: HTS Project/Lower Dump Sump		City/Count	y:Questa,	Γaos County	Sar	npling Date	:7/24/13	
Applicant/Owner: Chevron		NO.	(P)	State:NM	San	npling Point	:WL-2	U.H.
Investigator(s):Jeff Dawson, Eric Bunnell		Section, T	ownship, Ra	ange:Section 6, T28	N, R13E	E BERRET		
Landform (hillslope, terrace, etc.): terrace		Local relie	ef (concave,	convex, none):conve	ex	S	lope (%):2	
Subregion (LRR): E - Rocky Mountain Forests and Rangela	nd Lat:36.	69432		Long: -105.5949		Dat	tum:NAD	1983
Soil Map Unit Name: Tenorio loam, 1-3% slope	8= 7			NWI cla	ssification	:NA		
Are climatic / hydrologic conditions on the site typical fo	r this time of y	ear? Yes (No ((If no, explain	in Rema	rks.)		
Are Vegetation Soil or Hydrology	significantly	disturbed?	Are	"Normal Circumstance	es" prese	ent? Yes	No	\circ
Are Vegetation Soil or Hydrology	naturally pr	oblematic?	(If n	eeded, explain any ar	nswers in	Remarks.)	-1-	
SUMMARY OF FINDINGS - Attach site ma	ap showing	samplin	g point l	ocations, transe	cts, im	portant f	eatures	, etc.
Hydrophytic Vegetation Present? Hydric Soil Present? Wetland Hydrology Present? Remarks: Yes Yes Yes Remarks:	No (No ()		he Sample hin a Wetla		C	No @		
VEGETATION - Use scientific names of pl	ants.		A Des	Lower Till -	1/2			e Tij
Tree Stratum Plot size:	Absolute % Cover	Dominant Species?	Indicator	10e5/		= nashiran		9 4
1.	70 00101	Ороско.	Oldido	Number of Domina				
2.	E 25			That Are OBL, FAC				(0)
3.			II. I west	(excluding FAC-): Total Number of D	ominant		3	(A)
4.				Species Across All	1000 H MILES		4	(B)
Sapling/Shrub Stratum Plot size: 10 x 5 m		= Total Cov	er er	Percent of Domina That Are OBL, FAC			5.0 %	(A/B)
1. Salix exigua	100	Yes	FACW	S PIPIE			J.U %	(~0)
2. Clematis ligustififolia	25	Yes	FAC	Prevalence Index			nedau	
3.			Tia.	OBL species	Or:	x 1 =	ply by:	GC-NH
4. Valuation in the second of		O)	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	FACW species	100	x 2 =	200	
5. The process of the second s	106	- T-4-1 O-		FAC species	33	x3=	99	
Herb Stratum Plot size 10 x 5 m	125	= Total Cov	er	FACU species	6	x 4 =	24	
1. Cynoglossum officinale	6	Yes	FACU	UPL species		x 5 =	0	
2. Poa pratensis	6	Yes	FAC	Column Totals:	139	(A)	323	(B)
3. Cirsium arvense	2	No	FAC	Prevalence li	ndev = B	/Δ =	2.32	
4.		The state of the s		Hydrophytic Vege		2.00/11/2022/11/20	2.32	
5.				1 - Rapid Tes			etation	
6		Levocreus P	ni B	× 2 - Dominano				
8.				× 3 - Prevalence			No among	
9.			Tel. Sa. 1025	4 - Morpholog data in Rer		tations'(Pro on a separa		orting
10. spill and Street Francisco III.		, V	manufacture of	5 - Wetland N	on-Vascu	lar Plants		
Woody Vine Stratum Plot size:	14	= Total Cov	er	Problematic H Indicators of hydr be present, unless	ic soil an	d wetland t	rydrology	
2.		= Total Cov	ver	Hydrophytic Vegetation	res 🕞	No	С	ikingga sa

Depth Matrix	Redo	x Features				
(inches) Color (moist) %	Color (moist)	%	_Type ¹	Loc ²	Texture	Remarks
0-14 10YR4/4 100					Loam	slightly moist, crumb structure
- New acas	The head of			**		rene disconstruit des statues de
A Tree Administration of the Comment	Sto Liste 1				angen Villey	
			= 311610	e that a s		THE RESERVE SERVE THE BUILDING
The state of the s	11				3 (0)	Pale of the court of the state of the
The Bridge of the Beauty	<u>anglish diku</u> a	100		58 L 116	ru – krymytr	100 - 100 -
mast 15 and Crew State Commission						
The state of the s	ne neakween			of a second	THE COLLEGE	CLAU TONE S LONGE
	100.00.00.00					
NA SEED III DE CONSEGUI DIN SEEL.	8 (61-124-15)	7 7 7		122 W. 27	Single Belleville	Elegation with a first transport to the second
Type: C=Concentration, D=Depletion, RM=Reduc	ced Matrix, CS=Cover	ed or Coate	d Sand Gra	ins		² Location: PL=Pore Lining, M=Matrix
lydric Soll Indicators: (Applicable to all LRI	Rs, unless otherwis	e noted.)			Indicators for	or Problematic Hydric Solls ³ :
Histosol (A1)	Sandy Redo	, ,				fluck (A10)
Histic Epipedon (A2)	Stripped Ma	, ,		an volt		arent Material (TF2)
Black Histic (A3)	Loamy Muc	-		ept MLRA		hallow Dark Surface (TF12)
Hydrogen Sulfide (A4)	Loamy Gle		(F2)		Other (Explain in Remarks)
Depleted Below Dark Surface (A11)	Depleted M	. ,	1			
Thick Dark Surface (A12)	Redox Darl	,			3 Indica	tors of hydrophytic vegetation and
Sandy Mucky Mineral (S1)	Depleted D					d hydrology must be present.
Sandy Gleyed Matrix (S4)	Redox Dep	ressions (F	-8)		unless	disturbed or problematic.
estrictive Layer (if present):	The state of the s	T				
Type:					Hydric Soil I	Present? Yes No 🖲
Depth (inches):	4 2.27				Hydric Soli I	Present? Yes No 🖲
Depth (inches):					Hydric Soil I	Present? Yes No
Depth (inches): emarks: No hydric indicators					Hydric Soil I	Present? Yes No (
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators:	V- 1 FINE	Ton a			ga S	
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: imary Indicators (minimum of one required; checi	V- 1 FINE	Head 2			Seconda	ary Indicators (minimum of two required)
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators:	k all that apply)	ined Leave	` ' '		Seconda	
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: imary Indicators (minimum of one required; chec Surface Water (A1) High Water Table (A2)	k all that apply) Water-Sta MLRA 1,	2, 4a, and	` ' '		Seconda Wa	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b)
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: imary Indicators (minimum of one required; chec Surface Water (A1) High Water Table (A2) Saturation (A3)	k all that apply) Water-Sta MLRA 1, Salt Crus	2, 4a, and t (B11)	4b)		Seconda Wa ML	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) tinage Patterns (B10)
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: nimary Indicators (minimum of one required; checility) Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1)	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II	2, 4a, and t (B11) nvertebrate	4b)		Seconda Wa ML Dra Dra	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) iinage Patterns (B10) -Season Water Table (C2)
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: nimary Indicators (minimum of one required; checiling the company of th	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger	2, 4a, and t (B11) nvertebrate i Sulfide O	4b) es (B13) dor (C1)	cept	Seconda Wa ML Dra Dry Sat	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) tinage Patterns (B10) -Season Water Table (C2) uration Visible on Aerial Imagery (C9)
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: nimary Indicators (minimum of one required; chec Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3)	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger Oxidized	2, 4a, and t (B11) nvertebrate i Sulfide O Rhizosphe	4b) es (B13) dor (C1) eres on Liv	ccept	Seconda Wa ML Dra Dra Sat CC3)	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) sinage Patterns (B10) -Season Water Table (C2) uration Visible on Aerial Imagery (C9) comorphic Position (D2)
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: nimary Indicators (minimum of one required; chece Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algai Mat or Crust (B4)	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger Oxidized Presence	2, 4a, and t (B11) nvertebrate s Sulfide O Rhizosphe of Reduce	es (B13) dor (C1) eres on Lived Iron (C4	ccept ing Roots (Seconda Wa ML Dra Dry Sat C3) Gee	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) sinage Patterns (B10) -Season Water Table (C2) uration Visible on Aerial Imagery (C9) omorphic Position (D2) allow Aquitard (D3)
Depth (inches): emarks: No hydric indicators (DROLOGY (etland Hydrology Indicators: rimary Indicators (minimum of one required; chec) Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algai Mat or Crust (B4) Iron Deposits (B5)	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic In Hydroger Oxidized Presence Recent In	2, 4a, and t (B11) nvertebrate a Sulfide O Rhizosphe of Reduce on Reducti	es (B13) dor (C1) eres on Liv ed Iron (C4 ons in Tille	ing Roots	Seconda	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) ainage Patterns (B10) -Season Water Table (C2) uration Visible on Aerial Imagery (C9) comorphic Position (D2) allow Aquitard (D3) .C-Neutral Test (D5)
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: imary Indicators (minimum of one required; chec Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algai Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6)	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger Oxidized Presence Recent In	2, 4a, and t (B11) overtebrate a Sulfide O Rhizosphe of Reduction r Stressed	es (B13) dor (C1) eres on Lived Iron (C4 ons in Tille Plants (D	ccept ing Roots (Seconda Wa ML	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) tinage Patterns (B10) -Season Water Table (C2) turation Visible on Aerial Imagery (C9) turation Aerial Imagery (C9)
Depth (inches): emarks: No hydric indicators (DROLOGY (etland Hydrology Indicators: imary Indicators (minimum of one required; chec) Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algai Mat or Crust (B4) Iron Deposits (B5)	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger Oxidized Presence Recent In	2, 4a, and t (B11) nvertebrate a Sulfide O Rhizosphe of Reduce on Reducti	es (B13) dor (C1) eres on Lived Iron (C4 ons in Tille Plants (D	ing Roots	Seconda Wa ML	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) ainage Patterns (B10) -Season Water Table (C2) uration Visible on Aerial Imagery (C9) comorphic Position (D2) allow Aquitard (D3) .C-Neutral Test (D5)
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: imary Indicators (minimum of one required; chec Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algai Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6)	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger Oxidized Presence Recent In Stunted c	2, 4a, and t (B11) overtebrate a Sulfide O Rhizosphe of Reduction r Stressed	es (B13) dor (C1) eres on Lived Iron (C4 ons in Tille Plants (D	ing Roots	Seconda Wa ML	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) tinage Patterns (B10) -Season Water Table (C2) turation Visible on Aerial Imagery (C9) turation (D2) turation (D3)
Depth (inches): emarks: No hydric indicators (DROLOGY Vetland Hydrology Indicators: imary Indicators (minimum of one required; checil Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algai Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8)	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger Oxidized Presence Recent In Stunted c	2, 4a, and t (B11) overtebrate a Sulfide O Rhizosphe of Reduction r Stressed	es (B13) dor (C1) eres on Lived Iron (C4 ons in Tille Plants (D	ing Roots	Seconda Wa ML	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) tinage Patterns (B10) -Season Water Table (C2) turation Visible on Aerial Imagery (C9) turation Aerial Imagery (C9)
Depth (inches): emarks: No hydric indicators /DROLOGY /etland Hydrology Indicators: nimary Indicators (minimum of one required; check Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algai Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7 Sparsely Vegetated Concave Surface (Eleid Observations:	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger Oxidized Presence Recent In Stunted c	2, 4a, and t (B11) overtebrate a Sulfide O Rhizosphe of Reduction Reduction or Stressed plain in Re	es (B13) dor (C1) eres on Lived Iron (C4 ons in Tille Plants (D	ing Roots	Seconda Wa ML	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) tinage Patterns (B10) -Season Water Table (C2) turation Visible on Aerial Imagery (C9) turation (D2) turation (D3)
Perph (inches): emarks: No hydric indicators YDROLOGY Vetland Hydrology Indicators: nimary Indicators (minimum of one required; chect Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algai Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (Bield Observations: surface Water Present? Yes Conservations	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger Oxidized Presence Recent In Stunted co Other (Ex	2, 4a, and t (B11) evertebrate a Sulfide O Rhizosphe of Reducti or Reducti or Stressed plain in Re	es (B13) dor (C1) eres on Lived Iron (C4 ons in Tille Plants (D	ing Roots (1) ed Soils (C	Seconda Wa ML Dra Sat Stat Sha FA From	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) tinage Patterns (B10) -Season Water Table (C2) turation Visible on Aerial Imagery (C9) turation (D2) turation (D3)
Depth (inches): emarks: No hydric indicators POROLOGY Vetland Hydrology Indicators: nimary Indicators (minimum of one required; check Surface Water (A1) High Water Table (A2) Saturation (A3) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Algai Mat or Crust (B4) Iron Deposits (B5) Surface Soil Cracks (B6) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (Eleid Observations: urface Water Present? Vater Table Present? Yes C	k all that apply) Water-Sta MLRA 1, Salt Crus Aquatic II Hydroger Oxidized Presence Recent In Stunted of Other (Ex	2, 4a, and t (B11) nvertebrate a Sulfide O Rhizosphe of Reduct on Reducti or Stressed aplain in Re	es (B13) dor (C1) eres on Lived Iron (C4 ons in Tille Plants (D	ing Roots (1) ed Soils (C	Seconda Wa ML Dra Sat Stat Sha FA From	ary Indicators (minimum of two required) ter-Stained Leaves (B9) (except .RA 1, 2, 4a, and 4b) sinage Patterns (B10) -Season Water Table (C2) uration Visible on Aerial Imagery (C9) comorphic Position (D2) allow Aquitard (D3) .C-Neutral Test (D5) ised Ant Mounds (D6) (LRR A) ost-Heave Hummocks (D7) (LRR F)

APPENDIX E

CHEVRON QUESTA MINE TAILINGS PIPELINE REMOVAL PROJECT
CULTURAL RESOURCES SURVEY



APPENDIX E. AQUATIC RESOURCES REPORT, QUESTA TAILINGS PIPELINE REMOVAL PROJECT

1.0 CULTURAL RESOURCES SURVEY SUMMARY

At the request of Chevron Environmental Management Company (CEMC), Arcadis surveyed ditches and other cultural resources along the Tailings Pipeline removal corridor in December 2017 and in April and May 2018. The survey results were submitted to the New Mexico Historic Preservation Office (SHPO) under New Mexico Cultural Resource Information System (NMCRIS) numbers 139651 and 140384 (ARCADIS 2018a and 2018b). The cultural resources were surveyed in or near the pipeline removal stages shown in Attachment A. A finding of No Adverse Effect on Historic Properties was documented by Arcadis in both surveys.

This document summarizes the cultural survey results as they pertain to the Chevron Questa Mine Tailings Pipeline Removal Project. Excerpts from the Arcadis cultural surveys are attached to this summary, including the report cover letters, NMCRIS Investigation Abstract Forms (NIAF), and select report figures. The following historic structures were found and evaluated for eligibility in the National Register of Historic Places (NRHP) during the cultural surveys.

NMCRIS No.: 139651 (see attached Cover Letter, NIAF, and FIG-4)

South Ditch (aka: Questa Citizens South Ditch, South Side Ditch, HCPI 44457/LA83968)

Thunder Bridge (aka: Second River Crossing, HCPI 44458/CQTP-01)

NMCRIS 140384 (see attached Cover Letter, NIAF, FIG-2, and FIG-3)

Elevated Trestle (aka: HCPI 44844) Lower Dump Sump (aka: HCPI 44845)

North Ditch (aka: Embargo Ditch, Embargo Acequia, HCPI 44846)

Acequia Del Molina (aka: Molina Ditch, HCPI 44847)

Middle Ditch (aka: HCPI 44848)

Two of the historic structures found during the cultural surveys are considered eligible for inclusion in the NRHP. The two eligible structures are the South Ditch and the North Ditch (Embargo Ditch). All other historic structures found during the surveys are recommended as not eligible for inclusion in the NRHP as they fail to meet any of the Eligibility Criteria.

The South Ditch has been previously documented and evaluated as eligible for inclusion in the National Register of Historic Places. The extent of the South Ditch on Chevron property was documented in December 2017 and the effects of the project upon it evaluated (ARCADIS 2018a). Only non-significant portions of the ditch were potentially to be impacted by the Tailings Pipeline Removal project. A finding of No Adverse Effect on a Historic Property received concurrence from the New Mexico SHPO. The Forest Service did not indicate any adverse effects to the portion of the South Ditch on their property in their report.

The North Ditch (Embargo Ditch) was evaluated by Arcadis in May 2018 and has not been formally documented or evaluated for NRHP eligibility by the New Mexico SHPO. The North Ditch is primarily located on private lands with short portions located on NM Department of Highways lands where it crosses NM State Highway 38 and NM State Highway 522 in Questa. A portion of the North Ditch is in the Tailings Pipeline Removal project Area of Potential Effect (APE) where it parallels Lower Embargo Road and crosses underneath State Highway 522. The North Ditch is recommended as eligible for the NRHP. The Chevron former tailing pipeline


APPENDIX E. AQUATIC RESOURCES REPORT, QUESTA TAILINGS PIPELINE REMOVAL PROJECT

will be abandoned in place where it crosses the North Ditch. Therefore, the project will have No Adverse Effect on Historic Properties.

2.0 REFERENCES

ARCADIS. 2018a. Chevron Questa Mine Tailings Pipeline Removal Project, Cultural Resources Survey, Taos County, New Mexico (NMCRIS No. 139651). January 12, 2018.

ARCADIS. 2018b. Chevron Questa Mine Tailings Pipeline Removal Project, Cultural Resources Survey, Taos County, New Mexico (NMCRIS No. 140384). May 29, 2018.





Mr. Clinton Chisler
Mining Act Reclamation Program
Mining and Minerals Division
Energy, Minerals, and Natural Resources Department
1220 South St. Francis Drive
Santa Fe, NM 87505

Subject:

Chevron Questa Mine Tailings Pipeline Removal Project Cultural Resources Survey, Taos County, New Mexico (NMCRIS No. 139651)

Dear Mr. Chisler:

Enclosed please find our cultural resources inventory report for the Chevron Mining, Inc. (CMI) Questa Tailings Pipeline Removal Project in Taos County, New Mexico. The enclosed report covers four segments of Stage 2 that are located on CMI property (Above Lower Dump Sump, East of Molycorp Baseball Field, Singleton's Cut and Columbine Wells Area) and one segment on private property (Robinson's Property). One previously recorded historic ditch (Questa Citizens South Ditch/HCPI 44457/LA83968) is located within the Area of Effect (APE) of the project crossing through the Above Lower Dump Sump, East of Molycorp Baseball Field, Robinson Property, and Singleton's Cut segments. The Ditch has been determined to be eligible for the National Register of Historic Places (NRHP) by the New Mexico Historic Preservation Office (SHPO). Only non-contributing portions of the Ditch are located within the project APE and no further work is recommended. One newly recorded historic structure is located within the APE of the project segments. The Thunder Bridge (HCPI 44458) is located in Red River Canyon at the west end of the Columbine Wells Area segment. This structure has been evaluated as not eligible for inclusion in the NRHP as it meets none of the NRHP eligibility criteria. No further work is recommended. Nine historic isolated finds (IF #s 1-9) were also documented during this investigation, all of which are recommended as not eligible for the NRHP. The proposed project will therefore have No Adverse Effect on Historic Properties.

The report has been filed electronically with the New Mexico SHPO through the New Mexico Cultural Resources Information System (NMCRIS). A hard copy of this report has also been forwarded to Bob Estes, Staff Archaeologist at the New Mexico Historic Preservation Division, for concurrence with the recommendations of eligibility and effect. The SHPO will have up to 30 days to comment and/or

Environmental Business Consulting

Date

January 12, 2018

Contact:

Dulaney Barclay

Phone:

720-344-3830

Email:

dulaney.barclay@arcadis.co

Our ref:

B0046795.0075

arcadis.com

Page:

Mr. Clinton Chisler January 12, 2018

concur with these findings. Please feel free to contact me if you have any questions or concerns.

Sincerely,

Dulaney Barclay Senior Archaeologist

Arcadis U.S., Inc.

Copies:

Bob Estes, New Mexico Historic Preservation Division, Santa Fe, NM

NMCRIS No.: 139651

NMCRIS INVESTIGATION ABSTRACT FORM (NIAF)

1. NMCRIS	2a. Lead Agency:	2b. Other Age	ncy(ies):	3. Lead Agen	cy Report No.:
Activity No.:	NM Energy, Minerals & Natl.				
139651	Res. Dept. Mining and Minerals Division				
4. Title of Report	•			5. Ty	pe of Report
Chevron Questa T	ailings Pipeline Cultural Resource	es Inventory Stage 2 S	ections B Thru D	□Ne	egative ,
				₩ D	ositive
Author(s)					ositive
Dulaney Barclay					
6. Investigation 7	уре				
Research Design	gn Archaeological Survey/Inv	entory Architectural	Survey/Inventory	Test Excavation	on Excavation
Collections/Non	-Field Study Compliance Dec			erview/Lit Revie	Name of
 ☐ Ethnographic S	tudy Site/Property Specific V	isit Historic Stru	ctures Report C	other	-
7. Description of	Undertaking (what does the pro	ject entail?):			18 18 18 18 18 18 18 18 18 18 18 18 18 1
Project involves th	ne removal of a slurry pipeline that	extends between the	Questa Mine and the	Tailings Facility	y. The current
investigation focus	sed on inventory of the portion of t	ne pipeline on Chevro	n property and one p	nvate parcei	
					[] Continuation
8. Dates of Inves	tigation: from: 12-Dec-2017	to: 13-Dec-2017	9. Report Date:	12-Jan-2018	
10. Performing A	gency/Consultant: ARCADIS	Vice Paris (Control of the Control o			
Principal Invest	igator: Dulaney Barclay				
Field Superviso	r: Dulaney Barclay				
Field Personnel	Names:				
Historian / Othe	r:				
11. Performing A	gency/Consultant Report No.:			#T	
12. Applicable C	ultural Resource Permit No(s):				
			(E)		
The property of the second					

NINCKIS NO.: 159051						
13. Client/Customer (project pro	oponent):					
NM Energy, Minerals & Natl. Res	s. Dept. Mining and f	Minerals D				
Contact:						
Address:				Phone:		
14. Client/Customer Project No).:					
15. Land Ownership Status (mu	ust be indicated on	project map):				
Land Owner (By Agency)			А	Acres Surveyed Ac		
Private Corporation (see records	for company name)			24.80	24.80	
			TOTALS	24.80	24.80	
16. Records Search(es):	en e				****	
Date(s) of HPD/ARMS File Review	w: N	ame of Reviewer(s):				
November 30, 2017		Dulaney Barclay				
		ame of Reviewer(s):		Agency:		
Date(s) of Other Agency File Revi	ew: N	ame of Neviewer(3).				
A	27 [X] NAI	D 83 Note: NAD 8 map, Scale:	3 is the NMCRI		to(s)	
17. Survey Data: a. Source Graphics [] NAD ✓ USGS 7.5' (1:24,000) topo r ✓ GPS Unit Accuracy <	27 [X] NAI map	D 83 Note: NAD 8 map, Scale:		S standard.		
17. Survey Data: a. Source Graphics [] NAD ✓ USGS 7.5' (1:24,000) topo r ✓ GPS Unit Accuracy Other Source Graphic(s):	27 [X] NAI map	D 83 Note: NAD 8 map, Scale:	3 is the NMCRI	S standard. ☐ Aerial Pho		
17. Survey Data: a. Source Graphics [] NAD USGS 7.5' (1:24,000) topo of the couracy (1.24,000) Other Source Graphic(s): b. USGS 7.5' Topographic Map	27 [X] NAI map	D 83 Note: NAD 8 map, Scale:	3 is the NMCRI	S standard. Aerial Pho		
17. Survey Data: a. Source Graphics [] NAD USGS 7.5' (1:24,000) topo r GPS Unit Accuracy [<1 Other Source Graphic(s): b. USGS 7.5' Topographic Mag Questa, NM c. County(ies): TAOS d. Nearest City or Town: Questa	27 [X] NAI map	D 83 Note: NAD 8 map, Scale:	3 is the NMCRI	S standard. Aerial Pho		
17. Survey Data: a. Source Graphics [] NAD USGS 7.5' (1:24,000) topo of the cource Graphic of the cource Graphic of the cource Graphic of the cource Graphic of the courty of the cour	27 [X] NAI map ☐ Other topo 1.0m ☑ 1-10m ☐ p Name	D 83 Note: NAD 8: map, Scale:]10-100m	3 is the NMCRI	S standard. Aerial Pho		
17. Survey Data: a. Source Graphics [] NAD USGS 7.5' (1:24,000) topo r GPS Unit Accuracy [<1 Other Source Graphic(s): b. USGS 7.5' Topographic Map Questa, NM c. County(ies): TAOS d. Nearest City or Town: Queste. Legal Description: Township (N/S)	27 [X] NAI map Other topo 1.0m 1-10m p Name sta, NM Range (E/W)	D 83 Note: NAD 8: map, Scale:]10-100m	3 is the NMCRI	S standard. Aerial Pho		
17. Survey Data: a. Source Graphics [] NAD USGS 7.5' (1:24,000) topo of the cource Graphic of the cource Graphic of the cource Graphic of the cource Graphic of the courty of the cour	27 [X] NAI map ☐ Other topo 1.0m ☑ 1-10m ☐ p Name	D 83 Note: NAD 8: map, Scale:]10-100m	3 is the NMCRI	S standard. Aerial Pho		
17. Survey Data: a. Source Graphics [] NAD USGS 7.5' (1:24,000) topo r GPS Unit Accuracy [<1 Other Source Graphic(s): b. USGS 7.5' Topographic Map Questa, NM c. County(ies): TAOS d. Nearest City or Town: Queste. Legal Description: Township (N/S)	27 [X] NAI map Other topo 1.0m 1-10m p Name sta, NM Range (E/W)	D 83 Note: NAD 8: map, Scale:]10-100m	3 is the NMCRI	S standard. Aerial Pho		
17. Survey Data: a. Source Graphics [] NAD USGS 7.5' (1:24,000) topo r GPS Unit Accuracy [<1 Other Source Graphic(s): b. USGS 7.5' Topographic Mag Questa, NM c. County(ies): TAOS d. Nearest City or Town: Queste. Legal Description: Township (N/S)	27 [X] NAI map ☐ Other topo 1.0m ☑ 1-10m ☐ p Name sta, NM Range (E/W)	D 83 Note: NAD 83 map, Scale:]10-100m	3 is the NMCRI	S standard. Aerial Pho		

f. Other Description (e.g. well pad footages, mile markers, plats, land grant name, etc.):

NMCRIS No.: 139651 18. Survey Field Methods: Intensity: ✓ 100% coverage <100% coverage</p> Configuration: block survey units ✓ linear survey units (I x w): other survey units (specify): Scope: non-selective (all sites/properties recorded) selective/thematic (selected sites/properties recorded) Coverage Method: systematic pedestrian coverage other method (describe): Survey Interval (m): 15 Crew Size: 1 Fieldwork Dates: from: 12-Dec-2017 to: 13-Dec-2017 Survey Person Hours: 8.00 Recording Person Hours: 4.00 Total Hours: 12.00 **Additional Narrative:**] Continuation 19. Environmental Setting (NRCS soil designation; vegetative community; elevation; etc.): Elevations vary from approximately 7400 to 7600 feet AMSL. Vegetation consists of an overstory of pine and juniper trees with understory of low shrubs, mixed forbs, cactus, and grasses. Soils consist of gravelly sandy loams derived from alluvium and colluvium. Project area is located in the Red River Canyon and on the gentle slopes at the base of the Taos Mountains, an extension of the Sangre DeCristo Range.] Continuation 20.a. Percent Ground Visibility: b. Condition of Survey Area (grazed, bladed, undistributed, etc.): Ranges from 100 % on bladed road to Survey corridor was primarily along a bladed access road that runs 50% on slopes above pipeline; averages parallel to the pipeline on norths side. Eroded along steep slopes on south side of pipeline. Pipeline parallels transmission line in places. 70-80%.] Continuation 21. CULTURAL RESOURCE FINDINGS ✓ Yes, see next report section No, discuss why:] Continuation 22. Attachments (check all appropriate boxes): [X] USGS 7.5 Topographic Map with sites, isolates, and survey area clearly drawn (required) [X] Copy of NMCRIS Map Check (required) [] LA Site Forms - new sites (with sketch map & topographic map) if applicable [] LA Site Forms (update) - previously recorded & un-relocated sites (first 2 pages minimum) [X] Historic Cultural Property Inventory Forms, if applicable] List and Description of Isolates, if applicable

NMCRIS No.: 139651 [X] Photographs and Log [] Other Attachments (Describe): 24. I certify the information provided above is correct and accurate and meets all applicable agency standards. Principal Investigator/Qualified Supervisor: Printed Name: Dulaney Barclay Date: 1/12/18 Principal Investigator 26. SHPO Reviewer's Name/Date: Reviewer's Name/Date: HPD Log #: Accepted [Rejected [] Date sent to ARMS: **CULTURAL RESOURCE FINDINGS** [fill in appropriate section(s)] SURVEY RESULTS: Archaeological Sites discovered and registered: 0 Archaeological Sites discovered and NOT registered: 0 Previously recorded archaeological sites revisited (site update form required): 0 Previously recorded archaeological sites not relocated (site update form required): 0 TOTAL ARCHAEOLOGICAL SITES (visited & recorded): 0 Total isolates recorded: 9 Non-selective isolate recording? HCPI properties discovered and registered: 2 HCPI properties discovered and NOT registered: 0 Previously recorded HCPI properties revisited: 0 Previously recorded HCPI properties not relocated: 0 TOTAL HCPI PROPERTIES (visited & recorded, including acequias): 2 MANAGEMENT SUMMARY: Questa Citizens South Ditch (HCPI 44457/LA83968) previously determined eligible for National Register.


] Continuation

Only non-contributing portions of the Questa Citizens South Ditch (HCPI 44457/LA83968) are within the Area of Potential Effect.

Thunder Bridge (HCPI 44458) is recommended not eligible for National Register. No further work is necessary.

No adverse effects to Ditch from proposed project. No further work is necessary.

NMCRIS No.:	139651		
LA/HCPI No. HCPI44457 HCPI44458	Field/Agency No. LA83968 CQTP-01 orded revisited sites/HCPI properties:	Eligible? (Y/N/U, applicable criteria A, C, and D po	
LA/HCPI No.	Field/Agency No.	Eligible? (Y/N/U, applicable crit	reria)
	A NUMBER LOG (site form required)	Previously recorded sites (site updat	e form required):
LA No.	Field/Agency No.	LA No. Field/Agency No.	
Areas outside k	nown nearby site boundaries monitored?	[]Yes	[] No, Explain why:
TESTING & EXC	CAVATION LA NUMBER LOG (site form req	uired)	WYNEWALTON IN IN I
Tested LA num	ber(s)	Excavated LA number(s)	
			8





Mr. Clinton Chisler
Mining Act Reclamation Program
Mining and Minerals Division
Energy, Minerals, and Natural Resources Department
1220 South St. Francis Drive
Santa Fe, NM 87505

Subject:

Chevron Questa Mine Tailings Pipeline Removal Project Cultural Resources Survey, Taos County, New Mexico (NMCRIS No. 140384)

Dear Mr. Chisler:

Enclosed please find our cultural resources inventory report for the Chevron Mining, Inc. (CMI) Questa Tailings Pipeline Removal Project in Taos County, New Mexico. The enclosed report covers Stage 2 Section A and portions of Stages 3 thru 8 that are located on CMI property. Five historic structures including the Elevated Trestle (HCPI 44844), Lower Dump Sump (HCPI 44845), Embargo Ditch (HCPI 44846), Acequia Del Molina (HCPI 44847) and Middle Ditch (HCPI 44848) were found within the Area of Potential Effect. The Embargo Ditch (HCPI 448446) is recommended as eligible for the National Register of Historic Places (NRHP) under Criterion C of the National Register Eligibility Criteria. The Embargo Ditch will not be adversely affected as the Tailings Pipeline will be abandoned in place where it crosses the Ditch. The other historic structures are all recommended as not eligible for inclusion in the NRHP as they fail to meet any of the Eligibility Criteria. The proposed project will therefore have No Adverse Effect on Historic Properties.

A copy of this report will also be attached to a Pre-Construction Notification (PCN) for the US Army Corp of Engineers (USACE) to fulfill the conditions for use of Nationwide Permit (NWP) 12. A USACE permit is required as the pipeline crosses the Red River, a jurisdictional waterway, in four locations within the current inventory area. The Embargo Ditch, Acequia Del Molina Ditch, and Middle Ditch are also considered jurisdictional waterways of the United States as they draw water from, and return water to, the Red River. A USACE NWP 12 for utility line activities is required for them as well. The USACE will have 30 days to review the PCN and determine if it is complete.

The report has been filed electronically with the New Mexico SHPO through the New Mexico Cultural Resources Information System (NMCRIS). A hard copy of this report has also been forwarded to Bob Estes, Staff Archaeologist at the New

Environmental Business Consulting

Date:

May 29, 2018

Contact:

Dulaney Barclay

Phone:

720-344-3830

Email:

dulaney.barclay@arcadis.co m

Our ref:

B0046795.0075

Mr. Clinton Chisler May 29, 2018

Mexico Historic Preservation Division, for concurrence with the recommendations of eligibility and effect. The SHPO will have up to 30 days to comment and/or concur with these findings. Please feel free to contact me if you have any questions or concerns.

Sincerely,

Dulaney Barclay Senior Archaeologist

Arcadis U.S., Inc.

Copies:

Bob Estes, New Mexico Historic Preservation Division, Santa Fe, NM US Army Corp of Engineers, Albuquerque District, Albuquerque, NM

NMCRIS No.: 140384

NMCRIS INVESTIGATION ABSTRACT FORM (NIAF)

1. NMCRIS	2a. Lead Agency:	2b. Other Age	ncy(ies):	3. Lead Ag	ency	Report No.:
Activity No.:	NM Energy, Minerals & Natl.					
140384	Res. Dept. Mining and Minerals Division					
4. Title of Report:				5	. Туре	of Report
Questa Tailings Pip	eline Cultural Resources Inventor	y Stages 2 Thru 8, Ta	aos County, New Me	exico	Nega	tive ,
Author(s)					Positi	ve
Dulaney Barclay						
Bulancy Barciay						
6. Investigation Ty	pe		1 1 14 1000 4 40 10			
Research Design	✓ Archaeological Survey/Inve	ntory Architectural	Survey/Inventory	Test Excav	ation	Excavation
Collections/Non-I	150 III	sion Based on Previo	(15) D (2)	 verview/Lit Re		Monitoring
Ethnographic Stu				Other		
	ndertaking (what does the proj					
Arcadie II S Inc. co	inducted an inventory of approxim	nately 2.6 miles of the	Ougeta Tailings Pir	nalina that avi	tande h	otween the
					1] Continuation
8. Dates of Investig	gation: from: 05-Apr-2018	to: 16-May-2018	9. Report Date:	29-May-20	18	
10. Performing Ag	ency/Consultant: ARCADIS			•		
Principal Investig	ator: Dulaney Barclay					
Field Supervisor:	Dulaney Barclay					
Field Personnel N	lames:					
Historian / Other:						
11. Performing Ag	ency/Consultant Report No.:	,				
12. Applicable Cu	tural Resource Permit No(s):					

13. Client/Customer (project proponent):	
Chevron Mining Inc.	
Contact: Gabriel Herrera	
Address: PO Box 469, Questa, NM 87556	Phone: (575) 586-7571
14. Client/Customer Project No.:	
15. Land Ownership Status (must be indicated on project map):	
Land Owner (By Agency)	Acres Surveyed Acres in
Chevron Mining Inc.	32.90 32.90
	TOTALS 32,90 32,90
16 Becarda Casrab(sa).	
16. Records Search(es):	
Date(s) of HPD/ARMS File Review: Name of Reviewer(s):	
12/8/2017; 3/5/2018; 3/6/2018 Dulaney Barclay	
Date(s) of Other Agency File Review: Name of Reviewer(s):	Agency:
47 Company Dates	
17. Survey Data:	O 92 in the NMCDIC standard
	D 83 is the NMCRIS standard.
✓ USGS 7.5' (1:24,000) topo map ☐ Other topo map, Scale:	
✓ GPS Unit Accuracy ✓<1.0m ☐ 1-10m ☐ 10-100m ☐ >100 Other Source Graphic(s):	Om Aerial Photo(s)
Other Source Graphine(s).	
b. USGS 7.5' Topographic Map Name	USGS Quad Code
Questa, NM	36105-F5
	00405 54
Red River, NM	36105-F4


f. Other Description (e.g. well pad footages, mile markers, plats, land grant name, etc.):

NMCRIS No.: 140384

24. I certify the information provided above is correct and acc	curate and meets all applicable agency standards.
Principal Investigator/Qualified Supervisor: Printed Na	me: Dulaney Barclay
Signature: Duling Binch Date: 5/2 25. Reviewing Agency Reviewer's Name/Date:	29/18 Title: Principal Investigator 26. SHPO Reviewer's Name/Date:
Accepted [] Rejected []	HPD Log #:
	Date sent to ARMS:
CULTURAL RESOUR	CE FINDINGS
[fill in appropriate section	n(s)]
SURVEY RESULTS:	The second secon
Archaeological Sites discovered and registered: 0	
Archaeological Sites discovered and NOT registered: 0	
Previously recorded archaeological sites revisited (site updated)	
Previously recorded archaeological sites not relocated (site u	pdate form required): 0
TOTAL ARCHAEOLOGICAL SITES (visited & recorded): 0	
Total isolates recorded: 0	Non-selective isolate recording?
HCPI properties discovered and registered: 5	
HCPI properties discovered and NOT registered: 0	
Previously recorded HCPI properties revisited: 0	
Previously recorded HCPI properties not relocated: 0	
TOTAL HCPI PROPERTIES (visited & recorded, including aced	quias): 5
	esources is evaluated as eligible for inclusion in the National Register National Register under Criterion C as representative of middle to late

	140384		
HCPI44844		N	
HCPI44845		N	
HCPI44846		Y, Criterion C	
HCPI44847		N	
HCPI44848		N	
Previously reco	orded revisited sites/HCPI properties:		
LA/HCPI No.	Field/Agency No.	Eligible? (Y/N/U, applicable criteria)	
MONITORING I	LA NUMBER LOG (site form required)		
Sites Discovered (site form required):		Previously recorded sites (site update form required):	
LA No.	Field/Agency No.		
	Field/Agency No.	LA No. Field/Agency No.	
Areas outside l	known nearby site boundaries monitored?	LA No. Field/Agency No.	[] No, Explain why:
		[]Yes	
	known nearby site boundaries monitored? CAVATION LA NUMBER LOG (site form req	[]Yes	
TESTING & EXC	known nearby site boundaries monitored? CAVATION LA NUMBER LOG (site form req	[] Yes	

.





- Headgate for Unnamed Ditch No. 2
- Headgate on Embargo Ditch
- West End of Segment
- East End of Segment

Embargo Ditch


Unnamed Ditch No. 1

Unnamed Ditch No. 2

Questa Tailings Pipeline Removal Project

Cultural Resources Location Map







Cattle Guard Elevated Trestle Middle Ditch

Molina Ditch

Tailings Pipeline Two-track Road

Sump Dump Area

Barrow Area Reservoir

Underground Access

Well Pump Well Pump Shed

Questa Tailings Pipeline Removal Project

Cultural Resources Location Map



APPENDIX B

ASBESTOS AND LEAD SAMPLING LAB DATA

TestAmerica THE LEADER IN ENVIRONMENTAL TESTING

ANALYTICAL REPORT

TestAmerica Laboratories, Inc.

TestAmerica Denver 4955 Yarrow Street Arvada, CO 80002 Tel: (303)736-0100

TestAmerica Job ID: 280-100940-1

Client Project/Site: Questa Pipeline - Lead and Asbestos

For:

Trihydro Corporation 1252 Commerce Drive Laramie, Wyoming 82070

Attn: Tony Kupilik

Authorized for release by: 9/21/2017 4:43:36 PM Michelle Johnston, Project Manager II (303)736-0110 michelle.johnston@testamericainc.com

Designee for

Donna Rydberg, Senior Project Manager (303)736-0192

donna.rydberg@testamericainc.com

----- LINKS ------

Review your project results through Total Access

Have a Question?



Visit us at: www.testamericainc.com

The test results in this report meet all 2003 NELAC and 2009 TNI requirements for accredited parameters, exceptions are noted in this report. This report may not be reproduced except in full, and with written approval from the laboratory. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.

This report has been electronically signed and authorized by the signatory. Electronic signature is intended to be the legally binding equivalent of a traditionally handwritten signature.

Results relate only to the items tested and the sample(s) as received by the laboratory.

Client: Trihydro Corporation Project/Site: Questa Pipeline - Lead and Asbestos

Table of Contents

Cover Page	1
Table of Contents	2
Definitions	3
Case Narrative	4
Detection Summary	5
Method Summary	11
Sample Summary	12
Client Sample Results	14
QC Association	17
QC Sample Results	19
Chronicle	20
Subcontract Data	25
Chain of Custody	44
Receipt Checklists	53

3

4

6

9

10

12

13

14

Definitions/Glossary

Client: Trihydro Corporation

Toxicity Equivalent Factor (Dioxin) Toxicity Equivalent Quotient (Dioxin)

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Glossary

RPD

TEF

TEQ

These commonly used abbreviations may or may not be present in this report.
Listed under the "D" column to designate that the result is reported on a dry weight basis
Percent Recovery
Contains Free Liquid
Contains No Free Liquid
Duplicate Error Ratio (normalized absolute difference)
Dilution Factor
Detection Limit (DoD/DOE)
Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
Decision Level Concentration (Radiochemistry)
Estimated Detection Limit (Dioxin)
Limit of Detection (DoD/DOE)
Limit of Quantitation (DoD/DOE)
Minimum Detectable Activity (Radiochemistry)
Minimum Detectable Concentration (Radiochemistry)
Method Detection Limit
Minimum Level (Dioxin)
Not Calculated
Not Detected at the reporting limit (or MDL or EDL if shown)
Practical Quantitation Limit
Quality Control
Relative Error Ratio (Radiochemistry)
Reporting Limit or Requested Limit (Radiochemistry)

Relative Percent Difference, a measure of the relative difference between two points

Case Narrative

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Job ID: 280-100940-1

Laboratory: TestAmerica Denver

Narrative

CASE NARRATIVE

Client: Trihydro Corporation

Project: Questa Pipeline - Lead and Asbestos

Report Number: 280-100940-1

With the exceptions noted as flags or footnotes, standard analytical protocols were followed in the analysis of the samples and no problems were encountered or anomalies observed. In addition all laboratory quality control samples were within established control limits, with any exceptions noted below. Each sample was analyzed to achieve the lowest possible reporting limit within the constraints of the method. In some cases, due to interference or analytes present at high concentrations, samples were diluted. For diluted samples, the reporting limits are adjusted relative to the dilution required.

Calculations are performed before rounding to avoid round-off errors in calculated results.

All holding times were met and proper preservation noted for the methods performed on these samples, unless otherwise detailed in the individual sections below.

RECEIPT

The samples were received on 09/07/2017; the samples arrived in good condition, properly preserved and on ice. The temperature of the coolers at receipt was 22.2 C.

TestAmerica Denver subcontracted the Asbestos analyses to EMLab P&K. A copy of their report has been included.

TOTAL METALS (ICP)

Samples L182817 (280-100940-8), L282817 (280-100940-9), L382817 (280-100940-10), L482817 (280-100940-11), L582817 (280-100940-12), L682817 (280-100940-13), L782817 (280-100940-14), L182917 (280-100940-33), L282917 (280-100940-34), L382917 (280-100940-35), L482917 (280-100940-36), L582917 (280-100940-37), L682917 (280-100940-38), L782917 (280-100940-39), L882917 (280-100940-40), L982917 (280-100940-41), L1082917 (280-100940-42), L1182917 (280-100940-43), L183017 (280-100940-57), L283017 (280-100940-58), BL183017 (280-100940-59), BL283017 (280-100940-60), BL383017 (280-100940-61), BL483017 (280-100940-62), BL583017 (280-100940-63) and BL683017 (280-100940-64) were analyzed for Total Metals (ICP) in accordance with EPA SW-846 Method 6010C. The samples were prepared on 09/11/2017 and analyzed on 09/12/2017 and 09/13/2017.

A deviation from the Standard Operating Procedure (SOP) occurred. Details are as follows: There was insufficient volume to weigh out the SOP specified 1.0-1.5g for the following samples: L1182917 (280-100940-43), BL183017 (280-100940-59), BL283017 (280-100940-60), BL383017 (280-100940-61), BL483017 (280-100940-62), BL583017 (280-100940-63) and BL683017 (280-100940-64).

Samples L582817 (280-100940-12)[5X], L682817 (280-100940-13)[2X], L382917 (280-100940-35)[2X], L782917 (280-100940-39)[5X], L283017 (280-100940-58)[5X], BL183017 (280-100940-59)[10X], BL283017 (280-100940-60)[10X], BL383017 (280-100940-61)[5X], BL483017 (280-100940-62)[20X], BL583017 (280-100940-63)[5X] and BL683017 (280-100940-64)[5X] required dilution prior to analysis. The reporting limits have been adjusted accordingly.

Insufficient sample volume was available to perform a matrix spike/matrix spike duplicate (MS/MSD) associated with preparation batch 280-387084. Method precision and accuracy have been verified by the acceptable LCS/LCSD analyses data.

Insufficient sample volume was available to perform a matrix spike/matrix spike duplicate (MS/MSD) associated with preparation batch 280-387083. Method precision and accuracy have been verified by the acceptable LCS/LCSD analyses data.

No analytical or quality issues were noted, other than those described above or in the Definitions/Glossary page.

6

9

TU

12

13

14

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

Client Sample ID: A182817 Lab Sample ID: 280-100940-1

No Detections.

Lab Sample ID: 280-100940-2 Client Sample ID: A282817

No Detections.

Client Sample ID: A382817 Lab Sample ID: 280-100940-3

No Detections.

Client Sample ID: A482817 Lab Sample ID: 280-100940-4

No Detections.

Client Sample ID: A582817 Lab Sample ID: 280-100940-5

No Detections.

Client Sample ID: A682817 Lab Sample ID: 280-100940-6

No Detections.

Lab Sample ID: 280-100940-7 Client Sample ID: A782817

No Detections.

Client Sample ID: L182817 Lab Sample ID: 280-100940-8

Analyte		ualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	540		0.77	0.27	mg/Kg	1	_	6010C	Total/NA

Client Sample ID: L282817 Lab Sample ID: 280-100940-9

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	590	0.66	0.23 mg/Kg	1 6010C	Total/NA

Client Sample ID: L382817 Lab Sample ID: 280-100940-10

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	590	0.75	0.26 mg/Kg	1 6010C	Total/NA

Client Sample ID: L482817 Lab Sample ID: 280-100940-11

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	570	0.82	0.28 mg/Kg	1 6010C	Total/NA

Client Sample ID: L582817 Lab Sample ID: 280-100940-12

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	230	4.1	1.4 mg/Kg	5 6010C	Total/NA

Client Sample ID: L682817 Lab Sample ID: 280-100940-13

This Detection Summary does not include radiochemical test results.

TestAmerica Job ID: 280-100940-1

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

Client Sample ID: L682817 (Continued)

Lab Sample ID: 280-100940-13

AnalyteResult
LeadQualifierRLMDL
1.2UnitDil Fac
mg/KgD
2Method
6010CPrep Type
Total/NA

Client Sample ID: L782817 Lab Sample ID: 280-100940-14

 Analyte
 Result
 Qualifier
 RL
 MDL
 Unit
 Dil Fac
 D
 Method
 Prep Type

 Lead
 550
 0.83
 0.83
 0.29
 mg/Kg
 1
 6010C
 Total/NA

Client Sample ID: INS182817 Lab Sample ID: 280-100940-15

No Detections.

Client Sample ID: INS282817 Lab Sample ID: 280-100940-16

No Detections.

Client Sample ID: PL182817 Lab Sample ID: 280-100940-17

No Detections.

Client Sample ID: G182817 Lab Sample ID: 280-100940-18

No Detections.

Client Sample ID: G282817 Lab Sample ID: 280-100940-19

No Detections.

Client Sample ID: G382817 Lab Sample ID: 280-100940-20

No Detections.

Client Sample ID: G482817 Lab Sample ID: 280-100940-21

No Detections.

Client Sample ID: A182917 Lab Sample ID: 280-100940-22

No Detections.

Client Sample ID: A282917 Lab Sample ID: 280-100940-23

No Detections.

Client Sample ID: A382917 Lab Sample ID: 280-100940-24

No Detections.

Client Sample ID: A482917 Lab Sample ID: 280-100940-25

No Detections.

This Detection Summary does not include radiochemical test results.

TestAmerica Denver

Client: Trihydro Corporation

Client Sample ID: A582917

Project/Site: Questa Pipeline - Lead and Asbestos

Lab Sample ID: 280-100940-26

No Detections.

Lab Sample ID: 280-100940-27 Client Sample ID: A682917

No Detections.

Client Sample ID: A782917 Lab Sample ID: 280-100940-28

No Detections.

Client Sample ID: A882917 Lab Sample ID: 280-100940-29

No Detections.

Client Sample ID: A982917 Lab Sample ID: 280-100940-30

No Detections.

Client Sample ID: A1082917 Lab Sample ID: 280-100940-31

No Detections.

Client Sample ID: A1182917 Lab Sample ID: 280-100940-32

No Detections.

Client Sample ID: L182917 Lab Sample ID: 280-100940-33

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	670	0.73	0.25 mg/Kg	1 6010C	Total/NA

Client Sample ID: L282917 Lab Sample ID: 280-100940-34

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	500		0.87	0.30	mg/Kg	1	_	6010C	Total/NA

Client Sample ID: L382917 Lab Sample ID: 280-100940-35

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	480	1.5	0.53 mg/Kg		Total/NA

Client Sample ID: L482917 Lab Sample ID: 280-100940-36

Analyte	Result C	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Р	rep Type
Lead	450	-	0.73	0.25	mg/Kg	1	_	6010C	_ T	otal/NA

Client Sample ID: L582917 Lab Sample ID: 280-100940-37

Analyte	Result Qualifier	RL MDL	Unit	Dil Fac D	Method	Prep Type
Lead	280	0.79 0.27	mg/Kg		6010C	Total/NA

Client Sample ID: L682917 Lab Sample ID: 280-100940-38

This Detection Summary does not include radiochemical test results.

9

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

Client Sample ID: L682917 (Continued)

TestAmerica Job ID: 280-100940-1

Lab Sample ID: 280-100940-38

Dil Fac D Method

6010C

Prep Type

Total/NA

Analyte Result Qualifier RL **MDL** Unit Dil Fac D Method Prep Type 0.77 6010C Lead 120 0.27 mg/Kg Total/NA Client Sample ID: L782917 Lab Sample ID: 280-100940-39 **MDL** Unit Dil Fac D Method Analyte Result Qualifier RL **Prep Type** 5 6010C Lead 810 4.3 1.5 mg/Kg Total/NA Client Sample ID: L882917 Lab Sample ID: 280-100940-40 Analyte Result Qualifier RL **MDL** Unit Dil Fac D Method **Prep Type** Lead 32 0.86 0.30 mg/Kg 6010C Total/NA Client Sample ID: L982917 Lab Sample ID: 280-100940-41 Analyte Result Qualifier RL **MDL** Unit Dil Fac D Method Prep Type 0.78 6010C Lead 430 0.27 mg/Kg Total/NA Client Sample ID: L1082917 Lab Sample ID: 280-100940-42

Client Sample ID: L1182917

Lab Sample ID: 280-100940-43

Analyte Result Qualifier RL MDL Unit Dil Fac D Method Prep Type

RL

0.72

Result Qualifier

460

MDL Unit

0.25 mg/Kg

AnalyteResultQualifierRLMDLUnitDil FacDMethodPrep TypeLead2901.10.38mg/Kg16010CTotal/NA

Client Sample ID: G182917 Lab Sample ID: 280-100940-44

No Detections.

Analyte

Lead

Client Sample ID: G282917 Lab Sample ID: 280-100940-45

No Detections.

Client Sample ID: G382917 Lab Sample ID: 280-100940-46

No Detections.

Client Sample ID: G482917 Lab Sample ID: 280-100940-47

No Detections.

Client Sample ID: PL182917 Lab Sample ID: 280-100940-48

No Detections.

Client Sample ID: A183017 Lab Sample ID: 280-100940-49

No Detections.

This Detection Summary does not include radiochemical test results.

TestAmerica Denver

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

Client Sample ID: A283017 Lab Sample ID: 280-100940-50

No Detections.

Lab Sample ID: 280-100940-51 Client Sample ID: BA183017

No Detections.

Client Sample ID: BA283017 Lab Sample ID: 280-100940-52

No Detections.

Client Sample ID: BA383017 Lab Sample ID: 280-100940-53

No Detections.

Client Sample ID: BA483017 Lab Sample ID: 280-100940-54

No Detections.

Client Sample ID: BA583017 Lab Sample ID: 280-100940-55

No Detections.

Client Sample ID: BA683017 Lab Sample ID: 280-100940-56

No Detections.

Client Sample ID: L183017 Lab Sample ID: 280-100940-57

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	330	0.99	0.34 mg/Kg	1 6010C	Total/NA

Client Sample ID: L283017 Lab Sample ID: 280-100940-58

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	380	5.0	1.7 mg/Kg	5 6010C	Total/NA

Client Sample ID: BL183017 Lab Sample ID: 280-100940-59

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D	Method	Prep Type
Lead	390	9.3	3.2 mg/Kg	10	6010C	Total/NA

Client Sample ID: BL283017 Lab Sample ID: 280-100940-60

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	340	8.3	2.9 mg/Kg	10 6010C	Total/NA

Client Sample ID: BL383017 Lab Sample ID: 280-100940-61

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Lead	250	4.3	1.5 mg/Kg	5 6010C	Total/NA

Client Sample ID: BL483017 Lab Sample ID: 280-100940-62

This Detection Summary does not include radiochemical test results.

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Client Sample ID: BL483017		Lab Sample ID: 280-100940-62					
Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac D Method	Prep Type
Lead	630		15	5.3	mg/Kg	20 6010C	Total/NA
Client Sample ID: BL583017						Lab Sample ID: 280	-100940-63
Analyte	Result	Qualifier	RL		Unit	Dil Fac D Method	Prep Type
Lead	240		5.5	1.9	mg/Kg	5 6010C	Total/NA
Client Sample ID: BL683017						Lab Sample ID: 280	-100940-64
Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac D Method	Prep Type
Lead	5600		5.6	1.9	mg/Kg	5 6010C	Total/NA
Client Sample ID: INS183017	,					Lab Sample ID: 280	-100940-65
No Detections.							
Client Sample ID: INS283017	,					Lab Sample ID: 280	-100940-66
No Detections.							
Client Sample ID: VG183017						Lab Sample ID: 280	-100940-67
No Detections.							
Client Sample ID: VG283017						Lab Sample ID: 280	-100940-68
No Detections.							
Client Sample ID: VG383017						Lab Sample ID: 280	-100940-69
No Detections.							
Client Sample ID: PW183017	1					Lab Sample ID: 280	-100940-70
No Detections.							
Client Sample ID: PW283017	·					Lab Sample ID: 280	-100940-71
No Detections.							
Client Sample ID: PW383017	,					Lab Sample ID: 280	-100940-72
No Detections.							
Client Sample ID: PW483017	,					Lab Sample ID: 280	-100940-73
No Detections.							_

This Detection Summary does not include radiochemical test results.

Method Summary

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Method	Method Description	Protocol	Laboratory
6010C	Metals (ICP)	SW846	TAL DEN
Asbestos - PLM by EPA 600/R-93/116	General Sub Contract Method	NONE	

Protocol References:

(pric

NONE = NONE

SW846 = "Test Methods For Evaluating Solid Waste, Physical/Chemical Methods", Third Edition, November 1986 And Its Updates.

Laboratory References:

= EMLab P&K - Denver, 4955 Yarrow Street, Arvada, CO 80002

TAL DEN = TestAmerica Denver, 4955 Yarrow Street, Arvada, CO 80002, TEL (303)736-0100

- 5

6

O

_

a

10

11

13

12

Sample Summary

Client: Trihydro Corporation Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
280-100940-1	A182817	Solid	08/28/17 13:15	09/07/17 09:15
280-100940-2	A282817	Solid	08/28/17 13:54	09/07/17 09:15
280-100940-3	A382817	Solid	08/28/17 14:20	09/07/17 09:15
280-100940-4	A482817	Solid	08/28/17 14:40	09/07/17 09:15
280-100940-5	A582817	Solid	08/28/17 15:10	09/07/17 09:15
280-100940-6	A682817	Solid	08/28/17 15:35	09/07/17 09:15
280-100940-7	A782817	Solid	08/28/17 16:15	09/07/17 09:15
280-100940-8	L182817	Solid	08/28/17 13:15	09/07/17 09:15
280-100940-9	L282817	Solid	08/28/17 13:54	09/07/17 09:15
280-100940-10	L382817	Solid	08/28/17 14:20	09/07/17 09:15
280-100940-11	L482817	Solid	08/28/17 14:40	09/07/17 09:15
280-100940-12	L582817	Solid	08/28/17 14:50	09/07/17 09:15
280-100940-13	L682817	Solid		09/07/17 09:15
280-100940-14	L782817	Solid		09/07/17 09:15
280-100940-15	INS182817	Solid		09/07/17 09:15
280-100940-16	INS282817	Solid		09/07/17 09:15
280-100940-17	PL182817	Solid		09/07/17 09:15
280-100940-18	G182817	Solid		09/07/17 09:15
280-100940-19	G282817	Solid		09/07/17 09:15
280-100940-20	G382817	Solid		09/07/17 09:15
280-100940-21	G362617 G482817	Solid		09/07/17 09:15
280-100940-21	A182917	Solid		09/07/17 09:15
280-100940-23	A282917	Solid		09/07/17 09:15
280-100940-24	A382917	Solid		09/07/17 09:15
280-100940-25	A482917	Solid		09/07/17 09:15
280-100940-26	A582917	Solid		09/07/17 09:15
280-100940-27	A682917	Solid		09/07/17 09:15
280-100940-28	A782917	Solid		09/07/17 09:15
280-100940-29	A882917	Solid		09/07/17 09:15
280-100940-30	A982917	Solid		09/07/17 09:15
280-100940-31	A1082917	Solid		09/07/17 09:15
280-100940-32	A1182917	Solid	08/29/17 16:40	09/07/17 09:15
280-100940-33	L182917	Solid	08/29/17 08:35	09/07/17 09:15
280-100940-34	L282917	Solid	08/29/17 09:10	09/07/17 09:15
280-100940-35	L382917	Solid	08/29/17 09:45	09/07/17 09:15
280-100940-36	L482917	Solid	08/29/17 10:05	09/07/17 09:15
280-100940-37	L582917	Solid	08/29/17 10:25	09/07/17 09:15
280-100940-38	L682917	Solid	08/29/17 11:05	09/07/17 09:15
280-100940-39	L782917	Solid	08/29/17 11:40	09/07/17 09:15
280-100940-40	L882917	Solid	08/29/17 11:55	09/07/17 09:15
280-100940-41	L982917	Solid	08/29/17 12:30	09/07/17 09:15
280-100940-42	L1082917	Solid	08/29/17 15:10	09/07/17 09:15
280-100940-43	L1182917	Solid	08/29/17 16:40	09/07/17 09:15
280-100940-44	G182917	Solid	08/29/17 09:20	09/07/17 09:15
280-100940-45	G282917	Solid	08/29/17 09:25	
280-100940-46	G382917	Solid	08/29/17 10:20	
280-100940-47	G482917	Solid	08/29/17 10:25	
280-100940-48	PL182917	Solid	08/29/17 10:30	
280-100940-49	A183017	Solid	08/30/17 09:40	
280-100940-50	A283017	Solid	08/30/17 11:10	
280-100940-51	BA183017	Solid	08/30/17 11:15	
			08/30/17 11:13	
280-100940-52	BA283017	Solid	00/30/17 11.20	03/01/11 09.15

TestAmerica Denver

Sample Summary

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Lab Sample ID	Client Sample ID	Matrix	Collected Received
280-100940-54	BA483017	Solid	08/30/17 11:30 09/07/17 09:15
280-100940-55	BA583017	Solid	08/30/17 11:40 09/07/17 09:15
280-100940-56	BA683017	Solid	08/30/17 11:50 09/07/17 09:15
280-100940-57	L183017	Solid	08/30/17 09:40 09/07/17 09:15
280-100940-58	L283017	Solid	08/30/17 11:10 09/07/17 09:15
280-100940-59	BL183017	Solid	08/30/17 11:15 09/07/17 09:15
280-100940-60	BL283017	Solid	08/30/17 11:20 09/07/17 09:15
280-100940-61	BL383017	Solid	08/30/17 11:25 09/07/17 09:15
280-100940-62	BL483017	Solid	08/30/17 11:30 09/07/17 09:15
280-100940-63	BL583017	Solid	08/30/17 11:40 09/07/17 09:15
280-100940-64	BL683017	Solid	08/30/17 11:50 09/07/17 09:15
280-100940-65	INS183017	Solid	08/30/17 09:10 09/07/17 09:15
280-100940-66	INS283017	Solid	08/30/17 09:15 09/07/17 09:15
280-100940-67	VG183017	Solid	08/30/17 09:20 09/07/17 09:15
280-100940-68	VG283017	Solid	08/30/17 09:30 09/07/17 09:15
280-100940-69	VG383017	Solid	08/30/17 09:40 09/07/17 09:15
280-100940-70	PW183017	Solid	08/30/17 15:10 09/07/17 09:15
280-100940-71	PW283017	Solid	08/30/17 15:20 09/07/17 09:15
280-100940-72	PW383017	Solid	08/30/17 15:30 09/07/17 09:15
280-100940-73	PW483017	Solid	08/30/17 15:40 09/07/17 09:15

3

o

9

10

10

14

Client Sample Results

Client: Trihydro Corporation TestAmerica Job ID: 280-100940-1

Project/Site: Questa Pipeline - Lead and Asbestos

Method:	6010C	- Metals	(ICP)
---------	-------	----------	-------

Client Sample ID: L182817	Lab Sample ID: 280-100940-8
Date Collected: 08/28/17 13:15	Matrix: Solid
Date Received: 09/07/17 09:15	

te Received: 09/07/17 09:15

Analyte	Result Q	Qualifier RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	540	0.77	0.27	mg/Kg	_	09/11/17 13:30	09/12/17 02:35	1

Client Sample ID: L282817 Lab Sample ID: 280-100940-9 Date Collected: 08/28/17 13:54 **Matrix: Solid**

Date Received: 09/07/17 09:15

Analyte	Result Qualifie	er RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	590	0.66	0.23	mg/Kg		09/11/17 13:30	09/12/17 02:37	1

Client Sample ID: L382817 Lab Sample ID: 280-100940-10 **Matrix: Solid**

Date Collected: 08/28/17 14:20 Date Received: 09/07/17 09:15

Analyte	Result	Qualifier	RL	MDL	Unit	D)	Prepared	Analyzed	Dil Fac
Lead	590		0.75	0.26	mg/Kg		09	9/11/17 13:30	09/12/17 02:40	1

Client Sample ID: L482817 Lab Sample ID: 280-100940-11 Date Collected: 08/28/17 14:40 **Matrix: Solid**

Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	570	0.82	0.28 mg/Kg		09/11/17 13:30	09/12/17 02:42	1

Client Sample ID: L582817 Lab Sample ID: 280-100940-12 Date Collected: 08/28/17 14:50 **Matrix: Solid**

Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	230	4.1	1.4 mg/Kg		09/11/17 13:30	09/13/17 07:21	5

Client Sample ID: L682817 Lab Sample ID: 280-100940-13 Date Collected: 08/28/17 15:35 **Matrix: Solid**

Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	29	1.2	0.42 mg/Kg		09/11/17 13:30	09/13/17 07:24	2

Client Sample ID: L782817 Lab Sample ID: 280-100940-14 Date Collected: 08/28/17 16:15 **Matrix: Solid**

Date Received: 09/07/17 09:15

Analyte	Result C	Qualifier RI	. MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	550	0.83	0.29	mg/Kg	_	09/11/17 13:30	09/12/17 03:00	1

Client Sample ID: L182917 Lab Sample ID: 280-100940-33 Date Collected: 08/29/17 08:35 **Matrix: Solid**

Date Received: 09/07/17 09:15

Date Received. 03/07/17 03.13							
Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	670	0.73	0.25 mg/Kg		09/11/17 13:30	09/12/17 03:03	1

Client Sample ID: L282917 Lab Sample ID: 280-100940-34 Date Collected: 08/29/17 09:10 **Matrix: Solid**

Date Received: 09/07/17 09:15										
Analyte	Result	Qualifier	RL	MDL	Unit	D	P	repared	Analyzed	Dil Fac
Lead	500		0.87	0.30	mg/Kg		09/1	1/17 13:30	09/12/17 03:05	1

Client Sample Results

Client: Trihydro Corporation TestAmerica Job ID: 280-100940-1

Project/Site: Questa Pipeline - Lead and Asbestos

Method: 6010C - Metals (ICP)

Client Sample ID: L382917	Lab Sample ID: 280-100940-35
Date Collected: 08/29/17 09:45	Matrix: Solid

Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	480	1.5	0.53 mg/Kg		09/11/17 13:30	09/13/17 07:44	2

Client Sample ID: L482917 Lab Sample ID: 280-100940-36

Date Collected: 08/29/17 10:05 Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL	Unit	D)	Prepared	Analyzed	Dil Fac
Lead	450	0.73	0.25	mg/Kg		(09/11/17 13:30	09/12/17 03:10	1

Client Sample ID: L582917 Lab Sample ID: 280-100940-37 **Matrix: Solid**

Date Collected: 08/29/17 10:25 Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	280	0.79	0.27	mg/Kg		09/11/17 13:30	09/12/17 03:12	1

Client Sample ID: L682917 Lab Sample ID: 280-100940-38 Date Collected: 08/29/17 11:05 **Matrix: Solid**

Date Received: 09/07/17 09:15

Date Neceived. 03/01/11 03.13									
Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	120		0.77	0.27	mg/Kg		09/11/17 13:30	09/12/17 03:15	1

Client Sample ID: L782917 Lab Sample ID: 280-100940-39 Date Collected: 08/29/17 11:40 **Matrix: Solid**

Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	810	4.3	1.5 mg/Kg		09/11/17 13:30	09/13/17 14:37	5

Client Sample ID: L882917 Lab Sample ID: 280-100940-40

Date Collected: 08/29/17 11:55 Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	32	0.86	0.30 mg/Kg		09/11/17 13:30	09/12/17 03:43	1

Client Sample ID: L982917 Lab Sample ID: 280-100940-41 **Matrix: Solid**

Date Collected: 08/29/17 12:30

Date Received: 09/07/17 09:15									
Analyte	Result C	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	430		0.78	0.27	mg/Kg		09/11/17 13:30	09/12/17 03:45	1

Client Sample ID: L1082917 Lab Sample ID: 280-100940-42 Date Collected: 08/29/17 15:10 **Matrix: Solid**

Date Received: 09/07/17 09:15

Date Received, 03/01/11 03.13									
Analyte	Result Q	ualifier RI	. MDL	Unit	D	Prepared	Analyzed	Dil Fac	
Lead	460	0.7	0.25	mg/Kg	_	09/11/17 13:30	09/12/17 03:48	1	

Client Sample ID: L1182917 Lab Sample ID: 280-100940-43 **Matrix: Solid**

Date Collected: 08/29/17 16:40 Date Received: 09/07/17 09:15

Date Received. 03/07/17 03.13						
Analyte	Result Qualifier	RL	MDL Unit	D Prepared	Analyzed	Dil Fac
Lead	290	1.1	0.38 mg/Kg	09/11/17 13:30	09/12/17 03:50	1

Matrix: Solid

Matrix: Solid

Client Sample Results

Client: Trihydro Corporation TestAmerica Job ID: 280-100940-1

Project/Site: Questa Pipeline - Lead and Asbestos

Method: 6010C - Metals (ICP)

Client Sample ID: L183017	Lab Sample ID: 280-100940-57
Date Collected: 08/30/17 09:40	Matrix: Solid

Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	330	0.99	0.34 mg/Kg		09/11/17 13:30	09/12/17 03:53	

Client Sample ID: L283017

Lab Sample ID: 280-100940-58

Date Collected: 08/30/17 11:10 Date Received: 09/07/17 09:15

 Analyte
 Result Lead
 Qualifier
 RL Store
 MDL Unit mg/Kg
 D mg/Kg
 Prepared D9/11/17 13:30
 Analyzed Malyzed Dil Fac D9/13/17 06:16
 D mg/Kg
 90/11/17 13:30
 09/13/17 06:16
 5

Date Collected: 08/30/17 11:15 Date Received: 09/07/17 09:15

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	390		9.3	3.2	mg/Kg		09/11/17 13:30	09/13/17 06:28	10

Date Received: 09/07/17 09:15

 Analyte
 Result Lead
 Qualifier
 RL 8.3
 MDL mg/Kg
 Unit Depth mg/Kg
 D mg/Kg
 Prepared prepared poly11/17 13:30
 Analyzed poly13/17 06:31
 Dil Fac poly13/17 06:31

Client Sample ID: BL383017 Lab Sample ID: 280-100940-61

Date Collected: 08/30/17 11:25
Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	250	4.3	1.5 mg/Kg		09/11/17 13:30	09/13/17 06:33	5

Client Sample ID: BL483017 Lab Sample ID: 280-100940-62
Date Collected: 08/30/17 11:30 Matrix: Solid

Date Collected: 08/30/17 11:30 Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	630	15	5.3 mg/Kg		09/11/17 13:30	09/13/17 08:09	20

Client Sample ID: BL583017 Lab Sample ID: 280-100940-63

Date Collected: 08/30/17 11:40 Matrix: Solid

Date Collected: 08/30/17 11:40 Date Received: 09/07/17 09:15

Analyte	Result Qualifier	RL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Lead	240	5.5	1.9 mg/Kg		09/11/17 13:30	09/13/17 06:38	5

Client Sample ID: BL683017 Lab Sample ID: 280-100940-64

Date Collected: 08/30/17 11:50
Date Received: 09/07/17 09:15

Analyte	Result Qualifie	er RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	5600	5.6	1.9	mg/Kg		09/11/17 13:30	09/13/17 06:46	5

Matrix: Solid

Matrix: Solid

Matrix: Solid

QC Association Summary

Client: Trihydro Corporation

TestAmerica Job ID: 280-100940-1 Project/Site: Questa Pipeline - Lead and Asbestos

Metals

Prep Batch: 387083

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
280-100940-39	L782917	Total/NA	Solid	3050B	
280-100940-40	L882917	Total/NA	Solid	3050B	
280-100940-41	L982917	Total/NA	Solid	3050B	
280-100940-42	L1082917	Total/NA	Solid	3050B	
280-100940-43	L1182917	Total/NA	Solid	3050B	
280-100940-57	L183017	Total/NA	Solid	3050B	
280-100940-58	L283017	Total/NA	Solid	3050B	
280-100940-59	BL183017	Total/NA	Solid	3050B	
280-100940-60	BL283017	Total/NA	Solid	3050B	
280-100940-61	BL383017	Total/NA	Solid	3050B	
280-100940-62	BL483017	Total/NA	Solid	3050B	
280-100940-63	BL583017	Total/NA	Solid	3050B	
280-100940-64	BL683017	Total/NA	Solid	3050B	
MB 280-387083/1-A	Method Blank	Total/NA	Solid	3050B	
LCS 280-387083/2-A	Lab Control Sample	Total/NA	Solid	3050B	
LCSD 280-387083/3-A	Lab Control Sample Dup	Total/NA	Solid	3050B	

Prep Batch: 387084

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
280-100940-8	L182817	Total/NA	Solid	3050B	
280-100940-9	L282817	Total/NA	Solid	3050B	
280-100940-10	L382817	Total/NA	Solid	3050B	
280-100940-11	L482817	Total/NA	Solid	3050B	
280-100940-12	L582817	Total/NA	Solid	3050B	
280-100940-13	L682817	Total/NA	Solid	3050B	
280-100940-14	L782817	Total/NA	Solid	3050B	
280-100940-33	L182917	Total/NA	Solid	3050B	
280-100940-34	L282917	Total/NA	Solid	3050B	
280-100940-35	L382917	Total/NA	Solid	3050B	
280-100940-36	L482917	Total/NA	Solid	3050B	
280-100940-37	L582917	Total/NA	Solid	3050B	
280-100940-38	L682917	Total/NA	Solid	3050B	
MB 280-387084/1-A	Method Blank	Total/NA	Solid	3050B	
LCS 280-387084/2-A	Lab Control Sample	Total/NA	Solid	3050B	
LCSD 280-387084/3-A	Lab Control Sample Dup	Total/NA	Solid	3050B	

Analysis Batch: 387317

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
280-100940-8	L182817	Total/NA	Solid	6010C	387084
280-100940-9	L282817	Total/NA	Solid	6010C	387084
280-100940-10	L382817	Total/NA	Solid	6010C	387084
280-100940-11	L482817	Total/NA	Solid	6010C	387084
280-100940-14	L782817	Total/NA	Solid	6010C	387084
280-100940-33	L182917	Total/NA	Solid	6010C	387084
280-100940-34	L282917	Total/NA	Solid	6010C	387084
280-100940-36	L482917	Total/NA	Solid	6010C	387084
280-100940-37	L582917	Total/NA	Solid	6010C	387084
280-100940-38	L682917	Total/NA	Solid	6010C	387084
280-100940-40	L882917	Total/NA	Solid	6010C	387083
280-100940-41	L982917	Total/NA	Solid	6010C	387083
280-100940-42	L1082917	Total/NA	Solid	6010C	387083

TestAmerica Denver

Page 17 of 53

QC Association Summary

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Metals (Continued)

Analysis Batch: 387317 (Continued)

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
280-100940-43	L1182917	Total/NA	Solid	6010C	387083
280-100940-57	L183017	Total/NA	Solid	6010C	387083
MB 280-387083/1-A	Method Blank	Total/NA	Solid	6010C	387083
MB 280-387084/1-A	Method Blank	Total/NA	Solid	6010C	387084
LCS 280-387083/2-A	Lab Control Sample	Total/NA	Solid	6010C	387083
LCS 280-387084/2-A	Lab Control Sample	Total/NA	Solid	6010C	387084
LCSD 280-387083/3-A	Lab Control Sample Dup	Total/NA	Solid	6010C	387083
LCSD 280-387084/3-A	Lab Control Sample Dup	Total/NA	Solid	6010C	387084

Analysis Batch: 387473

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
280-100940-12	L582817	Total/NA	Solid	6010C	387084
280-100940-13	L682817	Total/NA	Solid	6010C	387084
280-100940-35	L382917	Total/NA	Solid	6010C	387084
280-100940-58	L283017	Total/NA	Solid	6010C	387083
280-100940-59	BL183017	Total/NA	Solid	6010C	387083
280-100940-60	BL283017	Total/NA	Solid	6010C	387083
280-100940-61	BL383017	Total/NA	Solid	6010C	387083
280-100940-62	BL483017	Total/NA	Solid	6010C	387083
280-100940-63	BL583017	Total/NA	Solid	6010C	387083
280-100940-64	BL683017	Total/NA	Solid	6010C	387083

Analysis Batch: 387616

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
280-100940-39	L782917	Total/NA	Solid	6010C	387083

3

A

0

8

9

10

11

13

14

Prep Batch: 387083

10

Lead

Lead

Method: 6010C - Metals (ICP)

Lab Sample ID: MB 280-387083/1-A

Client Sample ID: Method Blank

Matrix: Solid

Prep Type: Total/NA

Analysis Batch: 387317

 Analyte
 Result Lead
 Qualifier ND
 RL ND
 MDL MDL MIT (MDL) (M

Lab Sample ID: LCS 280-387083/2-A

Matrix: Solid

Analysis Batch: 387317

Spike

Client Sample ID: Lab Control Sample
Prep Type: Total/NA
Prep Batch: 387083
%Rec.

 Analyte
 Added
 Result 50.0
 Qualifier Foundation
 Unit Foundation
 Description
 Write Foundation
 Limits Foundation

 Lead
 50.0
 50.2
 mg/Kg
 100
 86 - 110

50.0

Lab Sample ID: LCSD 280-387083/3-A Client Sample ID: Lab Control Sample Dup

Matrix: Solid Prep Type: Total/NA **Analysis Batch: 387317** Prep Batch: 387083 Spike LCSD LCSD %Rec. **RPD** Added Result Qualifier Limits RPD Limit Analyte Unit D %Rec

Lab Sample ID: MB 280-387084/1-A Client Sample ID: Method Blank

50.4

50.7

mg/Kg

mg/Kg

101

101

86 - 110

86 - 110

Matrix: Solid Prep Type: Total/NA
Analysis Batch: 387317 Prep Batch: 387084

Analysis Batch: 387317

MB MB

 Analyte
 Result Lead
 Qualifier
 RL ND
 MDL Unit mg/Kg
 D 09/11/17 13:30
 Prepared Analyzed Molecular Molec

Lab Sample ID: LCS 280-387084/2-A

Matrix: Solid

Analysis Batch: 387317

Spike

Analyte

Client Sample ID: Lab Control Sample
Prep Type: Total/NA

Prep Batch: 387084

Result Qualifier Unit D %Rec Limits

Lab Sample ID: LCSD 280-387084/3-A

Matrix: Solid

Analysis Batch: 387317

Spike LCSD LCSD Sample ID: Lab Control Sample Dup
Prep Type: Total/NA

Prep Batch: 387084

Spike LCSD LCSD %Rec. RPD

Analysis Batch: Description | Prep Batch | Pre

50.0

 Analyte
 Added
 Result Qualifier
 Unit mg/Kg
 D
 %Rec Limits
 RPD Limit RPD
 Limit 20

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Client Sample ID: L182817 Lab Sample ID: 280-100940-8 Date Collected: 08/28/17 13:15

Matrix: Solid

Date Received: 09/07/17 09:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			1.165 g	100 mL	387084	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		1			387317	09/12/17 02:35	CML	TAL DEN

Client Sample ID: L282817 Lab Sample ID: 280-100940-9

Date Collected: 08/28/17 13:54 **Matrix: Solid**

Date Received: 09/07/17 09:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Туре	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			1.371 g	100 mL	387084	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		1			387317	09/12/17 02:37	CML	TAL DEN

Client Sample ID: L382817 Lab Sample ID: 280-100940-10 **Matrix: Solid**

Date Collected: 08/28/17 14:20 Date Received: 09/07/17 09:15

Dil Initial Batch Batch Final Batch Prepared Method **Prep Type** Type Run **Factor** Amount Amount Number or Analyzed Analyst Lab Prep Total/NA 3050B 1.193 g 100 mL 387084 09/11/17 13:30 SEJ TAL DEN 09/12/17 02:40 CML Total/NA Analysis 6010C 387317 TAL DEN 1

Client Sample ID: L482817 Lab Sample ID: 280-100940-11

Date Collected: 08/28/17 14:40

Date Received: 09/07/17 09:15

_	Batch	Batch	_	Dil	Initial	Final	Batch	Prepared		
Prep Type	Туре	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			1.101 g	100 mL	387084	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		1			387317	09/12/17 02:42	CML	TAL DEN

Client Sample ID: L582817 Lab Sample ID: 280-100940-12 Matrix: Solid

Date Collected: 08/28/17 14:50

Date Received: 09/07/17 09:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			1.096 g	100 mL	387084	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		5			387473	09/13/17 07:21	CRR	TAL DEN

Lab Sample ID: 280-100940-13 Client Sample ID: L682817 **Matrix: Solid**

Date Collected: 08/28/17 15:35

Date Received: 09/07/17 09:15

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			1.491 g	100 mL	387084	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		2			387473	09/13/17 07:24	CRR	TAL DEN

TestAmerica Denver

Matrix: Solid

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Client Sample ID: L782817

Date Collected: 08/28/17 16:15 Date Received: 09/07/17 09:15 Lab Sample ID: 280-100940-14

Matrix: Solid

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Туре	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			1.078 g	100 mL	387084	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		1			387317	09/12/17 03:00	CML	TAL DEN

Client Sample ID: L182917 Lab Sample ID: 280-100940-33

Date Collected: 08/29/17 08:35
Date Received: 09/07/17 09:15

Matrix: Solid

Dil Batch Batch Initial Final **Batch** Prepared **Prep Type** Type Method Run **Factor Amount Amount** Number or Analyzed **Analyst** Lab Total/NA Prep 3050B 1.226 q 100 mL 387084 09/11/17 13:30 SEJ TAL DEN Total/NA Analysis 6010C 387317 09/12/17 03:03 CML TAL DEN 1

Client Sample ID: L282917 Lab Sample ID: 280-100940-34

Date Collected: 08/29/17 09:10 Eas Campio 15: 255 165545 54

Date Received: 09/07/17 09:10 Matrix: Solid

Dil Initial Batch Batch Batch Final Prepared Method **Prep Type** Type Run **Factor Amount** Amount Number or Analyzed **Analyst** Lab Total/NA 3050B 1.033 g 100 mL 387084 09/11/17 13:30 SEJ TAL DEN Prep Total/NA Analysis 6010C 387317 09/12/17 03:05 CML TAL DEN 1

Client Sample ID: L382917 Lab Sample ID: 280-100940-35

Date Collected: 08/29/17 09:45 Date Received: 09/07/17 09:15 Matrix: Solid

Batch Batch Dil Initial Final Batch Prepared **Prep Type** Type Method Run **Factor** Amount Amount Number or Analyzed **Analyst** Lab Total/NA Prep 3050B 1.171 g 100 mL 387084 09/11/17 13:30 SEJ TAL DEN Total/NA Analysis 6010C 2 387473 09/13/17 07:44 CRR TAL DEN

Client Sample ID: L482917 Lab Sample ID: 280-100940-36

Date Collected: 08/29/17 10:05 Matrix: Solid

Date Received: 09/07/17 09:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			1.227 g	100 mL	387084	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		1			387317	09/12/17 03:10	CML	TAL DEN

Client Sample ID: L582917 Lab Sample ID: 280-100940-37

Date Collected: 08/29/17 10:25 Matrix: Solid

Date Received: 09/07/17 09:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			1.134 g	100 mL	387084	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		1			387317	09/12/17 03:12	CML	TAL DEN

TestAmerica Denver

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Client Sample ID: L682917

Date Collected: 08/29/17 11:05 Date Received: 09/07/17 09:15 Lab Sample ID: 280-100940-38

Matrix: Solid

Matrix: Solid

Matrix: Solid

Matrix: Solid

Batch Dil Initial Final Batch Batch **Prepared Prep Type** Type Method Run **Factor** Amount **Amount** Number or Analyzed Analyst Lab Total/NA Prep 3050B 1.164 g 100 mL 387084 09/11/17 13:30 SEJ TAL DEN Total/NA Analysis 6010C 387317 09/12/17 03:15 CML TAL DEN 1

Client Sample ID: L782917 Lab Sample ID: 280-100940-39

Date Collected: 08/29/17 11:40 Date Received: 09/07/17 09:15 Matrix: Solid

Dil Batch Batch Initial Final **Batch** Prepared **Prep Type** Type Method Run **Factor Amount Amount** Number or Analyzed **Analyst** Lab Total/NA Prep 3050B 1.049 q 100 mL 387083 09/11/17 13:30 SEJ TAL DEN Total/NA Analysis 6010C 5 387616 09/13/17 14:37 CML TAL DEN

Client Sample ID: L882917 Lab Sample ID: 280-100940-40

Date Collected: 08/29/17 11:55

Date Received: 09/07/17 09:15

Dil Batch Batch Initial Final Batch **Prepared** Method **Prep Type** Type Run **Factor Amount** Amount Number or Analyzed **Analyst** Lab Total/NA 3050B 100 mL 387083 09/11/17 13:30 SEJ TAL DEN Prep 1.044 g Total/NA Analysis 6010C 387317 09/12/17 03:43 CML TAL DEN 1

Client Sample ID: L982917

Date Collected: 08/29/17 12:30

Lab Sample ID: 280-100940-41

Matrix: Solid

Date Collected: 08/29/17 12:30 Date Received: 09/07/17 09:15

Batch Batch Dil Initial Final Batch Prepared **Prep Type** Type Method Run **Factor** Amount Amount Number or Analyzed **Analyst** Lab 3050B Total/NA Prep 1.160 g 100 mL 387083 09/11/17 13:30 SEJ TAL DEN Total/NA Analysis 6010C 1 387317 09/12/17 03:45 CML TAL DEN

Client Sample ID: L1082917 Lab Sample ID: 280-100940-42

Date Collected: 08/29/17 15:10

Date Received: 09/07/17 09:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			1.257 g	100 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		1			387317	09/12/17 03:48	CML	TAL DEN

Client Sample ID: L1182917 Lab Sample ID: 280-100940-43

Date Collected: 08/29/17 16:40

Date Received: 09/07/17 09:15

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			0.825 g	100 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		1			387317	09/12/17 03:50	CML	TAL DEN

TestAmerica Denver

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Client Sample ID: L183017

Date Collected: 08/30/17 09:40 Date Received: 09/07/17 09:15

Lab Sample ID: 280-100940-57

Matrix: Solid

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Туре	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			0.905 g	100 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		1			387317	09/12/17 03:53	CML	TAL DEN

Lab Sample ID: 280-100940-58 Client Sample ID: L283017

Date Collected: 08/30/17 11:10 **Matrix: Solid**

Date Received: 09/07/17 09:15

_	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			0.901 g	100 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		5			387473	09/13/17 06:16	CRR	TAL DEN

Client Sample ID: BL183017 Lab Sample ID: 280-100940-59

Date Collected: 08/30/17 11:15 **Matrix: Solid**

Date Received: 09/07/17 09:15

_	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			0.482 g	50 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		10			387473	09/13/17 06:28	CRR	TAL DEN

Client Sample ID: BL283017 Lab Sample ID: 280-100940-60 **Matrix: Solid**

Date Collected: 08/30/17 11:20 Date Received: 09/07/17 09:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			0.541 g	50 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		10			387473	09/13/17 06:31	CRR	TAL DEN

Lab Sample ID: 280-100940-61 Client Sample ID: BL383017

Date Collected: 08/30/17 11:25

Date Received: 09/07/17 09:15

_	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			0.526 g	50 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		5			387473	09/13/17 06:33	CRR	TAL DEN

Lab Sample ID: 280-100940-62 Client Sample ID: BL483017

Date Collected: 08/30/17 11:30

Date Received: 09/07/17 09:15

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			0.588 g	50 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		20			387473	09/13/17 08:09	CRR	TAL DEN

TestAmerica Denver

Matrix: Solid

Matrix: Solid

Client: Trihydro Corporation

Project/Site: Questa Pipeline - Lead and Asbestos

TestAmerica Job ID: 280-100940-1

Lab Sample ID: 280-100940-63

Matrice Callel

Matrix: Solid

Date Collected: 08/30/17 11:40 Date Received: 09/07/17 09:15

Client Sample ID: BL583017

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			0.814 g	100 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		5			387473	09/13/17 06:38	CRR	TAL DEN

Client Sample ID: BL683017 Lab Sample ID: 280-100940-64

Date Collected: 08/30/17 11:50 Matrix: Solid

Date Received: 09/07/17 09:15

_	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Туре	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	3050B			0.402 g	50 mL	387083	09/11/17 13:30	SEJ	TAL DEN
Total/NA	Analysis	6010C		5			387473	09/13/17 06:46	CRR	TAL DEN

Laboratory References:

= EMLab P&K - Denver, 4955 Yarrow Street, Arvada, CO 80002

TAL DEN = TestAmerica Denver, 4955 Yarrow Street, Arvada, CO 80002, TEL (303)736-0100

5

0

7

0

1 N

13

1



Report for:

Donna Rydberg TestAmerica-Denver 4955 Yarrow Street Arvada, CO 80002

Regarding: Project: 280-100940-1; Questa Pipeline- Lead and Asbestos

EMĹ ID: 1790994

Approved by:

Dates of Analysis: Asbestos PLM: 09-19-2017

Approved Signatory Noah Lazarte

Service SOPs: Asbestos PLM (EPA Methods 600/R-93/116 & 600/M4-82-020, SOP EM-AS-S-1267)

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. The results relate only to the items tested. The results include an inherent uncertainty of measurement associated with estimating percentages by polarized light microscopy. Measurement uncertainty data for sample results with >1% asbestos concentration can be provided when requested.

EMLab P&K ("the Company") shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Total Samples Submitted: 47

Total Samples Analyzed: 47

Lab ID-Version 1: 8373424-1

Lab ID-Version 1: 8373425-1

Lab ID-Version 1: 8373426-1

Lab ID-Version 1: 8373427-1

Total Samples with Layer Asbestos Content > 1%: 4

Location: 280-100940-1, A182817

Sample Layers	Asbestos Content
Gray Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-2, A282817

Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-3, A382817

Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-4, A482817

	•
Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

 \ddagger A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC

EMLab ID: 1790994, Page 2 of 13

Lab ID-Version 1: 8373430-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-5, A582817 Lab ID-Version 1: 8373428-1

	•
Sample Layers	Asbestos Content
Red Non-Fibrous Material	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-6, A682817	Lab ID-Version‡: 8373429-1
Sample Layers	Asbestos Content
Gray Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-7, A782817

20040000 200 100 10 7,11702017	•
Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-15, INS182817	Lab ID-Version‡: 8373431-1
Sample Layers	Asbestos Content
Yellow Insulation	ND
Composite Non-Asbestos Content:	90% Glass Fibers
_	7% Cellulose
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-16, INS282817Lab ID-Version‡: 8373432-1

Sample Layers	Asbestos Content
Yellow Insulation	ND
Composite Non-Asbestos Content:	95% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 280-100940-17, PL182817

Lab ID-Version‡: 8373433-1

Sample Layers	Asbestos Content
Brown Non-Fibrous Material	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-18, G182817

Lab ID-Version :: 8373434-1

Sample Layers	Asbestos Content
Brown Non-Fibrous Material	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-19, G282817

Lab ID-Version‡: 8373435-1

Sample Layers	Asbestos Content
Brown Non-Fibrous Material	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Lab ID-Version 1: 8373438-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-20, G382817 Lab ID-Version 1: 8373436-1

Sample Layers	Asbestos Content
Brown Non-Fibrous Material	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-21, G482817

Lab ID-Version 1: 8373437-1 Sample Layers **Asbestos Content** Brown Non-Fibrous Material ND Sample Composite Homogeneity: Good

Location: 280-100940-22, A182817

Sample Layers **Asbestos Content Brown Compound** ND **Sample Composite Homogeneity:** Good

Location: 280-100940-23, A282817	Lab ID-Version‡: 8373439-1
Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC

EMLab ID: 1790994, Page 5 of 13

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-24, A382817Lab ID-Version‡: 8373440-1

Sample Layers	Asbestos Content
Gray Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-25, A482817Lab ID-Version‡: 8373441-1

Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-26, A582817Lab ID-Version‡: 8373442-1

Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-27, A682817Lab ID-Version‡: 8373443-1

Sample Layers	Asbestos Content
Gray Compound	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC EMLab ID: 1790994, Page 6 of 13

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-28, A782817Lab ID-Version‡: 8373444-1

Sample Layers	Asbestos Content
Gray Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-29, A882817Lab ID-Version‡: 8373445-1

Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-30, A982817Lab ID-Version‡: 8373446-1

Sample Layers	Asbestos Content
Gray Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-31, A1082817Lab ID-Version‡: 8373447-1

Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC EMLab ID: 1790994, Page 7 of 13

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-32, A1182817Lab ID-Version‡: 8373448-1

Sample Layers	Asbestos Content
Brown Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-44, G182917

Lab ID-Version‡: 8373449-1

Sample Layers	Asbestos Content
Brown Non-Fibrous Material	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-45, G282917

Lab ID-Version 1: 8373450-1

Sample Layers	Asbestos Content
Brown Non-Fibrous Material	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-46, G382917

Lab ID-Version‡: 8373451-1

Sample Layers	Asbestos Content
Brown Non-Fibrous Material	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

Lab ID-Version 1: 8373454-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-47, G482917 Lab ID-Version 1: 8373452-1

20000000 200 200 10 11, 0 1025 21	•
Sample Layers	Asbestos Content
Brown Non-Fibrous Material	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-48, PL182917

Lab ID-Version 1: 8373453-1 Sample Layers **Asbestos Content** Brown Non-Fibrous Material ND Sample Composite Homogeneity: Good

Location: 280-100940-49, A183017

Sample Layers	Asbestos Content
Gray Compound	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-50, A283017	Lab ID-Version‡: 8373455-1
Sample Layers	Asbestos Content
Red Non-Fibrous Material	ND
Sample Composite Homogeneity: Good	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC

EMLab ID: 1790994, Page 9 of 13

Lab ID-Version 1: 8373458-1

Lab ID-Version 1: 8373459-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-51, BA183017 Lab ID-Version 1: 8373456-1

20000000 200 200 10 01, 211100 01.	··· · · · · · · · · · · · · · · · · ·
Sample Layers	Asbestos Content
Brown/Black Non-Fibrous Material with Paint	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-52, BA283017

Lab ID-Version 1: 8373457-1 Sample Layers **Asbestos Content** Brown/Black Non-Fibrous Material with Paint ND Sample Composite Homogeneity: Good

Location: 280-100940-53, BA383017

200000000000000000000000000000000000000	
Sample Layers	Asbestos Content
Brown/Black Non-Fibrous Material with Paint	ND
Sample Composite Homogeneity	Good

Location: 280-100940-54, BA483017

Sample Layers	Asbestos Content
Brown/Black Non-Fibrous Material with Paint	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC

EMLab ID: 1790994, Page 10 of 13

Lab ID-Version 1: 8373462-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-55, BA583017 Lab ID-Version 1: 8373460-1

Sample Layers	Asbestos Content
Yellow Coating	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-56, BA683017	Lab ID-Version‡: 8373461-1
Sample Layers	Asbestos Content
Yellow Coating	ND
Sample Composite Homogeneity:	Good

Location: 280-100940-65, INS183017

Sample Layers	Asbestos Content
Multicolored Insulation	ND
Composite Non-Asbestos Content:	95% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 280-100940-66, INS283017	Lab ID-Version‡: 8373463-1
Sample Layers	Asbestos Content
Yellow Insulation	ND
Composite Non-Asbestos Content:	95% Glass Fibers
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC

EMLab ID: 1790994, Page 11 of 13

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-67, VG183017Lab ID-Version‡: 8373464-1

Sample Layers	Asbestos Content
Black Non-Fibrous Material	ND
Composite Non-Asbestos Content:	3% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 280-100940-68, VG283017

Lab ID-Version‡: 8373465-1

Sample Layers	Asbestos Content
Black Non-Fibrous Material	ND
Composite Non-Asbestos Content:	3% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 280-100940-69, VG383017

Lab ID-Version :: 8373466-1

Sample Layers	Asbestos Content
Black Non-Fibrous Material	ND
Composite Non-Asbestos Content:	3% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 280-100940-70, PW183017

Lab ID-Version‡: 8373467-1

Sample Layers	Asbestos Content
Gray Felt	40% Chrysotile
Black Tar	ND
Composite Non-Asbestos Content:	20% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC

EMLab ID: 1790994, Page 12 of 13

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: TestAmerica-Denver C/O: Donna Rydberg

Re: 280-100940-1; Questa Pipeline- Lead and

Asbestos

Date of Sampling: 08-28-2017 Date of Receipt: 09-08-2017 Date of Report: 09-19-2017

ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Location: 280-100940-71, PW283017Lab ID-Version‡: 8373468-1

Sample Layers	Asbestos Content
Gray Felt	50% Chrysotile
Black Tar	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 280-100940-72, PW383017

Lab ID-Version‡: 8373469-1

Sample Layers	Asbestos Content
Gray Felt	40% Chrysotile
Black Tar	ND
Composite Non-Asbestos Content:	20% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 280-100940-73, PW483017

Lab ID-Version‡: 8373470-1

Sample Layers	Asbestos Content
Gray Felt	50% Chrysotile
Black Tar	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC

EMLab ID: 1790994, Page 13 of 13

TestAmerica Denver

Chain of Custody Record

ARTT C- Jane Change				1							
Arvada, CO 80002	C	Chain of Custody Record	Custo	dy Ke	òrd	_				THE LEWOLD IN DA	HE LEADER IN ENGINEMENTAL TERTHO
France (and) rate of the france (and) rate (and) rate (and)	Samplan			Zieb Pini	Rvdbero, Donna R		ु	Carrier Tracking Notes:	a):	GOG No. 280-411382,1	
Client Certaict Shipping/Receiving	Phone:	:		e-kail: donna-n	e-keil: donna.rydberg@testamorica	maricainc.com		siate of Origin: Colorado		Page 1 of 6	
Company. EMILAS P&K			i	Z Å	Accretations Required (So NELAP - Oregon	ired (See nate): n				280-100940-1	
Address: 4955 Yarrow Street,	Duo Date Roquestod: 9/19/2017	a .			!	Analys	Analysis Requested	sted		A - HCL M	oden: MHezare
Cris: Arvada	TAT Requested (days):	ya);		3333	a per ic				*****	B. NaOH C. Zh Acetrio	N - Abne O - AdNoD2
5416, Zfr: CD, 80002		:		SS\$\$33	8 (prid 116 (p			-	—-	E-MACH	0 · Na2800
Phones	3			···	9911 R-99				*****	G - Amerikir H - Abourbic Acid	
Email:	WOW.			3620	60GR	001/90994	994		_	•	U - Actions V - MCAA
Project Name:	Project #: 28017197			8 (X 6)	y EP)				******	,,,,,,,,,,,	Z - color (specify)
Sile:	ssown;			3230		- 	_	_ _ _	 	Opier	
				St 53	los - l				33373		
		Sample (C	Sample 1		(Asbęs er) / Asbę				(4) N (6)		
Sample Identification - Client ID (Leb ID)	Sample Udio	X	Property and Codes	23	X 9						
A182817 (280-100940-1)	└ ─	┢		Solid	×				it-seed	15000	
A282817 (280-190940-2)	8/28/17	13:54 (Movetein		Solid	×				2004	9832	
A382817 (260-100940-3)	8/28/17	14:20 M ountain		Solid	×				33600		
AA82817 (280-100940-4)	8/28/17	Meuntain		Solid	×					1035	
A582817 (280-100940-5)	8/28/17	15;10 Mosuntain		Solid	×				1000		:
A682817 (280-100940-6)	8/28/17	15:35 Mourtain		Solid	×	_			5000	1	
A782817 (280-100940-7)	8/28/17	16:15 Mountain		Solid	×				10000		
INS182817 (280-100940-15)	8/28/17	15:56 Mountain		Solid	×		<u> </u>		27000	\$1000	
INS282817 (260-100940-16)	8/29/17	15:55 Mountain		Solid	×	_			7000	3530	
Note: Since laboratory accordinations are earlyed to change. TedAmerica Laborator os, are, places the ownerably of motivat, analytic & according completes upon over purposed in borretors. The samp to adjocate in a change in according to a physical provided to the provided of the provided of the provided in according to a physical provided of the pr	to dela, rejuin the st to dela, rejuin the st	ownership of mell 6d, the samples n igned Chain of Cu	had, analyte & p huat be enlipped latedy atteating t	cored fallon on Speck to the Ter Speeld complice	mplanse upon o nadel islamos nadel of esta	ul pubaontrad lobi lary or other instru siten Laboratorios.	orptones. This ictions will be p inc.	camp'o shipmeni Oxided - Any cha	la forwarded un nges to scaradii	der chain-of-dupitedy, ston pixiup phouid be	if the inboratory does not a brought to YostAmerica
Possible Hazard Identification					Sample Disposal (255 00 day	o assessed if eamp	ietor ora Baix	A too may be assessed if samples are retained larger than 1 months	1 months
Deliverable Requested: I, II, III, IV. Other (spearly)	Primary Deliverable Renk: 2	abio Rank: 2			Special Instructions	ĝ	Requirements:	ļ			
Empty Kit Relinquished by:		Cate:		TI.	Time:			Method of Shipmork:	ייים ויא:		
Relinquished by:	ប៉ូនដូបីima;		ğ	Сотролу	Received by:	<i>,</i>	$\left \cdot \right $	V	$^{2}/\!$	18/17 1400) Company of Person
Haingu shad by:	Date/Time:		Ç	Сопропу	Received by:			ι¢	ņe γ		Company.
Reinquished by:	Cate/Timox		Š	Company	Received by:	δv		100	Date/Time	•	Company
Custody Seal No.:					Cooler Temperalu		(e) *C and Other Romerka;	. <u> </u>	: :: : :: :		

TestAmerica Denver											To ct ∧	305.2
4955 Yarrow Street Arvada, CO 80002 Phone (303) 736-0100 Fax (303) 431-7171	Ω	Chain of Custody Record	f Cust	ody R	ecord						THE LEADER IN E	LMETEYBER IN EKNILONWKALYT STREET
Client Information (Sub Contract Lab)	Sempler:			Rydberg.	erg. Donna	ת ת		Carrie	Carrier Tracking No(s):	(e):	280-411382.2	
	Figino:			dono C-Mali	: a.rydberg@	C-Mail: donne.rydberg@lestamericalne.com	inc.com	Colo	State of Origin: Colorado		Page 2 of 6	
Gonbany: EMLab P&K					Accreditations Hacult NELAP - Oragon	Accreditations Hoculred (See note): NELAP - Oregon	o ricko):				_ko.rc 280-100940-1	
Addiss: 4955 Yamow Street	Due Date Requested: 9/19/2017						Analysis	Requested	ě		Preservation Codes	
City. Arvado	TAT Requested (day)	÷							_		B-NaOH	N - Name O - ASNROZ
Size, Zp; CO, 80002								i –	-		D- NING ACE	P-N2048
Phane:	PO				93/11	羹	25年的电影中的电影				G - Amenty	S-H2SO4 T-118P Declarative from
Email:	wo#:				EOU/R	8	001790994	4				V-MCAA
Project None;	Project #: 28017197				y EPA					·	L-EDA	2 - other (specify)
Sile:	SSOVA				SD (Y		- -	_	_		Other:	
			Sample		elesed a Misika abastos Asbesto					<u> </u>	i stationi	
				-	916 UB [structions/Note:
CHILD CONTROL CONTROL CONTROL				CQ.	X						\mathbb{X}	
PL182817 (280-100940-17)		15:55 Mountain		Solid	×							
G182817 (280-100940-18)	8/28/17	14:50 Mountain		Solld	×							
G282817 (280-1009-0-19)	8/28/17	14:50 Mountain		Solid	×							
G392817 (280-1009-0-20)	8/28/17	Mountain		Solid	×							
G482817 (280-100940-21)	8/28/17	16:40 Mountain		Solid	×		·-					
A182917 (280-100940-22)	8/29/17	08:35 Mauntain		Solld	×						38	
A282917 (280-1009A0-23)	8/29/17	os:10 Mountain		Solla	×							
A382917 (280-100940-24)	8/25/17	09:45 Mountain		Solld	×		 		_			
AA82917 (280-100940-25)	8/29/17	10:05 Mountsin		Solid	×							
Note: State Solowary actrediations are autyout to change, Touchmonce Laberatories, inc., paced the dwherebip of mather, analyte & exceptitation compliance upon out autocontract, the period of principal provided under chain-excustory, if the state and the provided under the provided. Any change to accrediation status should be around to TestAmenta aboratory or other instructions will be provided. Any change to accrediation status should be around to TestAmenta and complicance to TestAmenta Laberatorion, inc. attention immediately. If all requested accrediations are current to date, return the aligned Chain of Custody attention to TestAmenta Laberatorion, inc.	salerioo, inc. placed the ex sale/mail/x being enblyzed ont to dote, return the eign	wherehip of mai to the samples of the Chain of Co	thac, analyte i must be chipp valedy artestir	A eccreditation ad back to the ig to eakl comp	compliance t TaslAmerica tikunos to Te	pan aut aubooi aboratory or of symerkes Labo	ntract laborata her instruction praterios, inc.	rea. The per p will be prov	npla shipman Cod. Any ch	ingos to acco	i ynder chain-of-cuolody. If editallon stalus should as s	r the leberatory does not resught to TestAmerica
Possible Hazard Identification					Sample	Sample Disposal ((A foo may	be assessed if san	od if sam] 20 20 20 20 20 20 20 20	(A fee may be assessed if samples are retained longer than 1	1 month)
Doliverable Requesteds I, II, III, IV, Other (specify)	Primary Deliverable Rank: 2)le Rank; 2			Special	Special instructions	s/QC Requirements:	ements:	ŀ			
Empty Kit Reunquiched by:		Date:			Time:				Method of Showard)Marit		
Ranquehed by:	Date/Times			Campany	Rec	Received by:		V	2	Date/Time: 9	18/17 MOS	Emulah Den
Agingushod by,	DalaTima			Company	P	Received by:			9	DeterTime:		Company
Rollinguished by:	Dale/Time:			Campony	¥00	Hacewood by:			R	Событите:	į	Company
Custody Seats Infact: Custody Secti No.;					လူ	Coder Temperatur	ro(s) *C and Other Romarka:	ner Romarka		:: 		:

TestAmerica Denver	<u> </u>		,		•						₩	ĭş ≯	<u>Test</u> America	S
4955 Yamow Sirbet Arvada, CO 80002	<u>C</u>	hain c	ens.	Chain of Custody Record	ecord						341	Edword IN E	the Leader in Environmental Justices	rashtia rashtia
- 13	Samolon			Rudber	a. Donana	73		Canter	Carrier Tracking No(o):	큣	280-41	COC No; 280-411382,3		
Clent Contact Shipping/Repolying	Phone;			donne donne	ਰ-ਅਸ: donna.rydberg@testamerica	estamerica	ine.com	State of Origin: Colorado	do origin:		Page	Page 3 of 6		
Company:					Accreditations Required (See NELAP - Oragion	Asquired (See agan	nate;				280-1	280-100940-1		L
ADES Vernous Street	Duo Dato Roquestod: 9/19/2017	•					λnalysis	Requested	<u>,</u>		Preserv	Preservation Codes:	M·Hayara	
CD):	TAT Requested (days):	*			per c	\dashv					OΦ.	Acelole	N-None	
Sito, zici					ā (price						, in 0	E-NoHSO4	D-N62603	
Phone:	PO#:				(9 9)	<u> </u>					₩ IO	G - Amehlar H - Asparaka Acid	S - 42504 T - 18504	tycrate
Emall;	WO III				NO.	오클	766062VC	94		_	T E -	- Cal Water	V - MCAA	
Proper Name: Chapte Placing - Load and Aspestos	Project #: 28017187				es os by EP					_	_	¥	Z - gihar (specify)	ž
Seq:	SSOWA				ISO3	_	<u>.</u> -	- - -	- -	- 		'	i	
	_	Sample	Sample Type (C=comp.	Matrix (whenever,	ele FRIARE STORE MS/N JB (Asbestos yer)) Asbest						of a least of	,		
Sample dentification - Great to (Factor)		X	a Speed	Phaservation Code?	X				338888	200 (NO.	X			
A582917 (280-100940-26)	_	Mountain		Solid	×									
A682917 (290-100940-27)	8/29/17	11:05 Mountain		Solld	×			_						
A782817 (280-100940-28)	8/29/17	11:40 Meyatein		Solid	×	-				F				
A882917 (280-100940-2B)	8/29/17	Mountain Mountain		Solid	×		-		ļ					
A982917 (280-100940-30)	8/25/17	12:30 Mountain		Solid	×				F	F				
A1082817 (280-100940-31)	8/29/17	15:10 Mountain		Splid	×	-			-					
A1182917 (280-1009/v0-32)	8/29/17	16:40 Paountain		Spild	×			<u> </u>	L	-				
G182917 (280-100940-44)	8/29/17	09:20 Mountain		Splid	×									
G282917 (280-400940-45)	8/29/17	Mostatala Mostatala		Solid	×	_					鏊			
Note: Since laberatory accreditations are subject to change, Test/works Laberatories, int., places the extractive descripted analyse & accreditation compliants upon out autocontroct laberatories. This sample shipment is forwarded under chain-droutled, if the abbridge description of the provided in the Section of Origin to Section of Origin to some provided analyzed, the period back to the Test/world abbridge of the provided. Any change to extractibition saturated by brought to Februaries and controlled abbridge of Test/mortes and the provided of the pr	itories, inc. pieces Prok iprimoprix being enalyze ni to dele, resum the ele	emership of n d, the sample gred Chain of	nethod, energy s, must be shy Custedy atker	e & accreditate sped back to the	jn complante u o Tediámerico i oplicance to Ted	gen out autocor aberstany ar of bymerics, Labo	ilroct laborato her instruction xekarios, inc.	cles, This san swill be provi	gleshþmart 19d. Anycha	ngoo to occur	under chair ditalian stal	ra spenja po i	prought to Testern	ale al
Possible Hazard Identification				j	Sample	Sample Disposal (A f	A foo may ent	A foe may be assessed if samples are retained langer ant Disposel By Lab Archive For	Disposel By Lab		Archive For	nger then a	Months	
Daliverable Requested: 1, II, III, IV, Other (specify)	Primary Deliverable Rank: 2	ble Rank: 1	~		Special	Special Instructions	OC Reguirements:					İ		
Empty Kit Rollingushed by:		Date:			Time:				Mathat of Shipreon:	prent:			Company	
Railinquiation by:	Catal Linds			Campany	7.0	Rocawed by:	1	$\ $	Įν	9	4118	380		8
Springuished by:	Detailline			Company	Hox	Hopgived by:			- <u>-</u>	Cone a me:			Confessor	
Ralinquished by:	CaleTimo.			Company	Reco	Received by:				DoğuMin'a:	j		Company	
Custody Seals Intact: Custody Seal No.:					20	Cade: Temporabet	s(s) "C and Other Remarks:	họr Romarko:	:			[.: •	: :::

TestAmerica Denver		-								T)	} } }
4955 Yarrow Street Aprado, CO 80002	C	hain c	of Cus	Chain of Custody Record	ecord					THE CONTRACT MEN	THE CONDER ME DANAGOMMENTAL TESTING
Client Information (Sub Contract Lab)	Sampar;			Rydberg.	M: Yang, Donna	₹	Carner Trodung No(s):) ND(8):	NO	CCC Ng. 280-411382.4	
- 1	Priorie:			donna E-Mai:	laʻrAqpedē@ I:	E-Mal: donng.rydberg@testemerkelinc.com	State of Origin: Colorado			Page 4 of 6	
Company EMI ab P&K					VETV5 - Owden	Regulad (Sas nots):			13 C	Jab#: 280-100940-1	
Address: 4955 Yerrow Street	Die Date Requested: B/19/2017	-				Analysis	Requested			ž	05:
City. Arvedo	TAT Requested (days):	<u>.</u>			e per				***		O ASNEDZ
State, 207.					6 (pcic					E, North CA	D. MAZEGO
Phane:	PO#:				14163			_	***	Ä	S - K2504 T - TSP Dodecahydrato
Engl:	WO #:				6001					J-DI Walet	V-MCAA
Project Name: Ownste Pipeline - Lead and Achestos	Hoyaca n: 28017197				ly EP,	001790994					Z - other (spedity)
S PRO:	SSDW#:				80 ()					Others	
		Sample	Sample Type (Cecomp,	Matrix (Nombre) Descripted	ich Fillende Hocal Mish B (Asbestos er)) Asbesto				eal Number		
Sample identification - Client ID (Lab ID)	Official Care	X		alloh-Code	X						
G382917 (280-100940-46)		10:20 Mountain		Solid	×				***		
G482817 (280-100940-47)	8/29/17	10:25 Mountain		Solid	×				***		
PL182917 (280-100840-48)	8/20/17	10:30 Mountain		Solid	×				***		
A183017 (280-100940-48)	8/30/17	09:40 Mountain		Solid	×				***		
A283017 (280-100940-50)	8/30/17	antao Mountain		Solid	×				***		
BA183017 (280-100940-51)	8/30/17	าาสุทธิ เ พื่อนกไม่เก		Solid	×				×.		
BA283017 (280-100940-52)	8/30/17	11:20 Mountain		Solid	×						
BA983017 (280-100940-53)	8/30/17	11;25 Mountain		Solld	×				**		
BA483017 (280-100940-54)	8/30/17	11:30 Mountain		Solld	×						
Note: Since laboratory accredizations are subject to change. Tookknow Laboratories, Inc. places the awnorable of medical, analytic & accreditation compliance upon out subscendard, above to analytic places the samples must be shipped back to the Testivenerica laboratory or other instruction currently mention accreditation in the State of Chipin taket above for analytic planta to be opped Chipin of Chipin and the Testivenerical laboratories, Inc. places the samples must be shipped back to the Testivenerical laboratories, inc. places the samples must be shipped back to the Testivenerical laboratories, inc. places the samples must be shipped back to the Testivenerical laboratories, inc.	jories, inc. places the a joirnate x being consiyes it to date, return the eig	whorehip of n d, the sample ned Chain of	nethod, prinkly) o mue! be ship Gualledy affee	o & accreditation of the section of	n compliance i Testivmento ipicance to Te	ipen out subcontract apocelories. The sample shipment is forwarded under chain-phousizedy. If the laboratory date not laboratory or other instructions will be provided. Any distripte to proceed tailor states should be brought to fast/America advantage to populate understand, inc.	The sample ship be provided. Am	y changes to sec y	a od Apikor	chain-gi-cuetody. If the metalus abould be bro	the laboratory date not bught to Yastemerica
Possible Hazerd identification					Sampl	Sample Disposal (A fee may be assessed if samples are retained longer than 1 Return To Client Disposal By Leb Archive For	Disposed If son	ob saldwa	Archive For	d longer than 1 r o For	month) Months
Deliverable Requested: I, II, III, IV, Other (appealy)	Primary Deliverable Rank: 2	ble Rank: 2			Specia	ns/QC Requiren	त्रोद्धः				
Empty Kit Relinquished by:		Dale:			Тіте:		Metabd o	Metabol of Billipment:			
Reinquianed by.	Data/Time;			Surduco	12 oc	Recalined by:		Comparison 5	18/17	1400	Estate Mc
Reinquished by:	Data/Time:		į	Company	8	Repaired by:		Descrime:			Company
Rai riquated by:	Dalto/Time;			AumdunA	X60	tealined by:		Çafarî ime;			Company
Custody Seals Intact: Custody Seal No.:	:		··.·i		Coc	Cooler Temperurure(s) *C and Other Remarks:	omarks:			:	· ·:·

THE LEADER IN CHIRDINAMENTAL TESTING

TestAmerica Denver	ļ			-				ost×	festAmerica
4955 Yerrow Street Arvada, GO 60002	ç	iain of C	Chain of Custody Record	ecord				THE CONDER IN C	HE LEADER IN CHYPROMAENTAL TESTINO
rax (Aub) 401-1111	Sampler		Lab Pike	Lab Pike Rydham Donna R		Corner Treaking Najs;	ajs);	COC No. 260-411382.5	
General Cleri Gentack Shipping/Revalving	Phone:		G-Mail:	c-wai: donna.rydberg@festomericei	stamerlceinc.com	Sipto & Orgin; Colorado		Page 5 of 6	
Company.				Accreditations Required (See NELAP - Oragion	squred (See note):			280-100940-1	:
Address: 4955 Yarrow Street	Dug Disto Requested: 9/19/2017				Analysis Rec	Requested		A-HCL M	M-Hoons
any. Arvada	YAT Requested (days):	H						D - NoOH	O ASSOCO
Sinte, ZI): CO, 60002					-	· · · -		E NoHSOK	7 - 200050 0 - 200050 0 - 200050
Prono:	PQ II:			t-93/1		_		G - AmeNor H - Adequitie Add	S - H2SO4 T - TSP Orderallydrane
Email:	WOA			MEAN.				J - DI Wafer	W - DH + A
Project Name: Ouesta Pipeline - Load and Asbestos	7917187 Project #:	:		64 A	10007790994 10007790994	4	at at a		2 - other (stedly)
	:#MOSS		!	\$8) (- PLN	-			OF BY	
		Sample	Matrix (mount)	e FMAIg One Mac (Asbesto (I) Asbest			al Munice	,	
Sample Identification - Client ID (Lab ID)	Sample Date	83 –	BOTTO COURS	X E			X F	***	Special instructions/Note:
BA583017 (280-100940-55)		Ρ	Solid	×					
8A685017 (280-100940-56)	8/30/17	Majoraja Majoraja	Solid	×				0.000	
INS183017 (280-100940-65)	8/30/17 N	Mountain	Solid	×					
INS283017 (280-100940-66)	8/30/17 N	Mountain	Solid	×					
VG183017 (280-100940-67)	8/30/17 N	MSMOSin MSMOSin	Solid	×					i
VG283017 (280-100940-68)	8/30/17 h	Mountain	Solld	×					
VGS83017 (280-100940-89)	8/30/17	09:40 Mountain	Solid	×					:
PW183017 (280-100940-70)	8/30/17	Mountain	Solid	×					
PW263017 (280-100840-71)	8/30/17	15:20 Moudain I	Solid	×				2555	
Note: Since independent and subject to change, Teat/morter Laparateries, inc. placed the ownership of method, analyte & accredistion companies out subcontract (aparaters, The sample informant is forwarded under chain-of-custory, if we because of a resistant in the state of Cright index to the provided with the right of the provided which the right of the provided with the right of t	ca Loborstyries, inc. placed the ownership of method, analyte & accreditation complants upon out subcon psycloposismostik being enelyzed, the samples must be abapted back to the TostAmerica laboratory or off ero current to date, return the algred Chain of Cudody stiteding to paid complicance to TealAmerica Labo	narchip of melhod, the complet must ad Chain of Guelod	anelyte & accreditation be shaped back to the y atteating to apid comp	compliance upo Tospamentos lab Vicence to Testa	n out subcontract laterworks, in out subcontract laterworks, will enable the will unarrow will unarrow Laterworks aborateries, bro.	The sample shipms be provided. Any o	ert is forwarded und hanges to accredital	or chain-of-quetody. It ikin atatus ahould be i	trought to Tepléments
Possible Hazard identification			i	Sample C	Sample Dispose! (A fee may be assessed if samples are retained longer than 1 month)	Disposal By Lab	nples are retain	tained longer then t Archive For	Months
Deliverable Requested: I, II, III, IV, Other (specify)	Primary Deliverable Rank:	e Rank: 2		Special In	Special Instructions/QC Requirements:	nta:			
Empty Kit Rollinguished by:	D	Date:	Ш	Ilmo:		Method of Shipmonia	nipmont		
Helinquiphed by:	Owto/Time):		Сотропу	Receive	Received by	V	-0	8/17/400	がまる
Reinquinhad by:	Dale/Time:		Company	Repolived by:	ad by:		Dissertime:		Company
Reinquehed by:	Dalg/Times		Company	Hocowed by			Detailline		Cempany
Custody Scala Intact: Custody Scal No.:		.: .: .: ::		· .	Coder Tempereture(s) *C and Other Rensance:	onsofte:		: 	

			·	thanker.	C and Olher Remarks:	parabuna(a) °C z	Cooler Temporature(a)	·:				. : . :-:		hact: Custody Sept No.:	Custody Seals Intact:
Company			Date/Time			۲	Received by:		Company			Date/Time;	-		Rainquished by:
Aurdino			Signature:			ň	Received by:		Company			Date-Time:			Reinquished by:
Emlab Ben	00\$1C118	7,	Defections;	V]* },	Received by:		Company			Dented limes:			Relinquished by:
			Moored of Shipment	Меспра				Time:			Dato:			shed by:	Empty Kit Relinquished by:
				i g:	C Requirements:	ictions/QC R	Special Instructions/Q	Sp		2	abkı Rook:	Primary Delwerable Rank:		Deliverable Requested; I. II. IV. Other (specify)	Deliverable Reque
month) Months	too may be assessed if samples are retained longer than 1 month) t Disposel By Lab Archive For Monte	re rotatined long	samples a	o essessed if san Disposal By Lab	may be at	Yosal (A foo Yo Cliant	Sample Disposal (A Roturn To Clion	_ <u>&</u>						identification	Passible Hazard Identification Unconfirmed
fithe laboratory does not rought to TeatAmerica	bahol-custody, n status shoud to b	accod under c	h preent is forw Mry Changes to	Na sampre at to provided. A	borotaries. T Judiora will b Nine	it aubeentract in Yery or other and tea Laboratories	iante upon du herita laboret a lo Testármor	be Teaber Sampleance	year back to saling to said o	r mothod, enely see must be sh of Custody atk	awnerahip o and, the comp algreed Chain	les, inc. pieces the motik being snely o date, return the i	America Laborator for enalysiskoptok dens are current t	Vidio: State liboratory extendiations are entired to charge, Teathreafor Liboratorios, inc. place the evergably of mothod, analyte & accordiation compliance upon out subcentrate. This sample is present is ferranced under destroying a place the evergably of the institution will be presented that in the State of Origin fored above for energy everythic testing religions, the entired to the testing that the shipper back to the freely every or other antifuction will be presided. Any changes to accordiation are countril to daily return the algreed Chain of Custody attenting to said complicance to the freely active the said and the shipper back to the freely every or other antifuction will be presided. Any changes to accordiation are countril to daily return the algreed Chain of Custody attenting to said complicance to the freely every every the freely every the freel	Note: Since laboratory currently maintain accor Laboratories, inc. otter
		***					E								
		***						H							
		- ::::::::::::::::::::::::::::::::::::						_					_		
		388						H							
		**	-				- -								
		35			-										
	,	383					×		Salid	1	15:40 Mountain	8/30/17		00940-73)	PW483017 (280-100940-73)
						_	×		Solid			8/30/17		00940-72)	PW383017 (280-100940-72)
		X X					ŵ	\times	· Bresemodica; Code:	₩	X				
natruellong/Note:	Sogelalia	24)(8)		_			SUB (Astest layer))/ Aste	Feld Fálog	Matrix (Wante		Sample	Sample Date		rton - Client (D (Lab ID)	Sample identifica
	Other:		<u> </u>				00 PU	1		1	1	880%%			- C. C.
2 - other (specify)	- 63% - 546						ь ю	164 () La (168 () La				Project #: 28017197		Project Name: Questa Pipelice - Lead and Acheetos	Project Name: Questa Pipolino -
	J DI Water				46604	0017	A 600 PA 600	S ON H				35 Om			Empl.:
	G - Anichor A - Anichor						R-931	1				PO#:			Phone:
D-N62045	D-Nine Add			-			116 (ஓரி	****						:	Statio, Z.p.: CO, 80002
O.AsNbOO	C-ZnAcalele		=				per c	XXXX XXXX			days);	TAT Requested (days):			City:
)des:	Preservation Codes:			Requested	analysis Rec	Ana		_			6.	Due Date Requested: 9/19/2017		et, ,	Addroop: 4955 Yarrow Street,
	льь <i>и</i> : 280-100940-1		 		, #	ured (See nee); in	Accreditations Required (See NELAP - Oregan	VED.X							EMEab P&K
	Poge 6 of 6		gin:	State or Origin: Colorado	11	americalno.com	E-Mail; donna.rydborg@tostamerical	E-Mail; donna.rydi	o. m			Pigner		io	Clent Certait: Shipping/Receiving
	COC No; 280-411382.6		ading No(a):	Corrier Fracking No(s):			Donna R	ă	n c			Samplen		tion (Sub Contract Lab)	Cilent Information
TestAmerica	TestA	_					ord	Reco	stody	Chain of Custody Record	Chain			TestAmerica Denver 4955 Yarrow Street Avvada, CO 80002 Phone (303) 736-0100 Fax (303) 431-7171	TestAmerica Denver 4955 Yarrow Street Arvada, CO 80002 Phone (303) 736-0100 Fax (30

Control Horizontal Control Hor	TestAmerica Denver 4955 Yarrow Street Arvada, CO 80002 Phone (303) 736-0100 Fax (303) 431-7171	Chain of Custo	of Custody Record	TestAmerica
	Client Information	Sampler	Lab PM: Rydberg, Donna R	
Corporation	Client Contact. Tony Kupilik	7	E-Mail: donna.rydberg@testamericainc.com	Page: Page 1 of 1
To Day T	Company: Trihydro Corporation		Analysis	
10 DAY	Address: 1252 Commerce Drive	Due Date Requested:		Preservation Code
10 DAY	City: Laramie	TAT Requested (days):		
Comparison	State, Zip: WY, 82070	10 DAY		
17	Phone:	PO#: Purchase Order Requested		
Septiment Designed Sample Date Sample Sample Sample Sample Sample Sample Sample Sample Sample Carbon Sample Carbon Sample Carbon Sample Carbon Sample Carbon Sample	Email: [kupjlik@trihydro.com	252WO	(ON	J - Di Water
Sample Date	Project Name: Questa Pipeline - Lead and Asbestos	37	Yes or	L-EDA
Sample Date Sample Watrix Sample Cappean Cap	olta:	:::OOOM:::) asv	
	Samula Idontification	Sample Type Sample (C=comp,	ield Filtered Netform MS/N	
### Setz8(17 13155 G S X B Second Interest of Secon	Odinje identification	Preserva	X	
8/28/17 1354 G S X	A182817	1315		
8/28/17 1410 G S X		1354		
8/28/17 1440 G S X 280-100940 Chain of Custody 8/28/17 1570 G S X 280-100940 Chain of Custody 8/28/17 1575 G S X 280-100940 Chain of Custody 8/28/17 1575 G S X 280-100940 Chain of Custody 8/28/17 1575 G S X 280-100940 Chain of Custody 8/28/17 1575 G S X 280-100940 Chain of Custody 9/28/17 1575 G S X S S 1575 Date/Time Date/Time Date/Time Date/Time 1576 Date/Time Dat		1420		
8128/17 1570 G	48	0440		
	58	1570		
Sample Disposal (A fee may be assessed if samples are retained longer than 1 respective for the poison B to Unknown Rediological Special Instructions/QC Requirements: Date:	A682817	1535	×	0940 Chain of Custody
Sample Disposal (A fee may be assessed if samples are retained longer than 1 respective for Special Instructions/OC Requirements: Date: Date:	A782817	1615	×	-
Date: Date: Date: Date: Date: Date: DateTime: ateTime: DateTime: DateTime: DateTime: DateTime: DateTime: DateTime: DateTime: DateTime: DateTime: DateTime: DateTime: Date	/			
Sample Disposal (A fee may be assessed if samples are retained longer than 1 r. Section 1 Special Instructions/QC Requirements: LEYEL II Date/Time: Date/Time: Date/Time: Date/Time: Date/Time: Date/Time: Cooler Temperature(s) "Cand Other Bemarks: Cooler Temperature(s) "Cand Ot		/		
Sample Disposal (A fee may be assessed if samples are retained longer than 1 in Received by: Date: Time:				
Date/Time: Date/Date/Date/Date/Date/Date/Date/Date/				
Date: Date: DateTime: DateTime	Possible Hazard Identification Non-Hazard Flammable Skin Irritant	Poison B Unknown	Sample Disposal (A fee may	De assessed if samples are retained longer than 1 month) **Disposal By Lab** Archive For Months
Date/Time; Date: Time; Time; Method of Shipment. Date/Time; Date/Time	Deliverable Requested: I, II, III, IV, Other (specify)	11 272	Special Instructions/QC Requir	
Custody Seal No.: Date/Time; Company Received by: Date/Time; Date/Time; Company Received by: Date/Time; Date/Time; Date/Time; Date/Time; Date/Time; Date/Time; Company Received by: Coupany Received by: Date/Time;	Empty Kit Relinquished by:	Date:	Time:	
Costody Seal No.: Date/Time: Company Received by: Cooler Temperature(s) "C and Other Bemarks:	Relinquished by:	19 (1500	(Receiv	17 0955
als Intact: Custody Seal No.: Date/Time: Contrant Con	Relinquished by:			
Custody Seal No.: Cooler Temperature(s) "C and Other Bernaries by 3r 9			Received by:	Date/Time;
			Temperature(s)	read by 3r 91
			1 1	

N - None
O - ANADOZ
P - NaZO4S
Q - NaZSO3
R - NaZS203
S - HZSO4
U - Acetone
U - Acetone
V - MCAA
W - pH 4-5
Z - other (specify) **TestAmerica** Sompany Special Instructions/Note: Months Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)

Return To Client Disposal By Lab Archive For Mont
Special Instructions/QC Requirements: 280-67249-22759.1 Preservation Codes G - Amchlor H - Ascorbic Acid 0360 C - Zn Acetate D - Nitric Acid Page 1 of 1 Job #: E - NaHSO4 F - MeOH I - Ice J - DI Water K-EDTA L-EDA Total Number of containers Date/Time: Method of Shipment Carrier Tracking No(s) Analysis Requested Cooler Temperature(s) "C and Other Remarks E-Mall: donna.rydberg@testamericainc.com Received by: Lab PM: Rydberg, Donna R × QA3 × Chain of Custody Record (on to sey) GSM/SM miorie ield Filtered Sample (Yes or No) Preservation Code: Matrix 5 5 SO S 5 Po#: 17 - 252 WO - L Purchase Order Requested Radiological フィフィ Type (C=comp, G=grab) Sample 5 11-252 WO-L 9 J J J J 9/6/17@ 1500 Date/Time 16151 1450 1535 8/28/17 1440 8/28/17/1420 745-Sample 8128/17 1315 8128/17 1354 10 DAYS Date: KUPILIK Poison B Unknown (AT Requested (days): Due Date Requested: Sample Date 8/28/17 11/82/8 8/28/17 (307) L EVEL 11 Project #: 28017197 Date/Time: SOW#: Skin Irritant Deliverable Requested: I, II, III, IV, Other (specify) Custody Seal No. Phone (303) 736-0100 Fax (303) 431-7171 Questa Pipeline - Lead and Asbestos Non-Hazard Flammable Possible Hazard Identification 182817 Empty Kit Relinquished by: 8281 281 T. KUPILIK 38281 8281 Custody Seals Intact:
A Yes A No 28281 18281 Sample Identification Client Information Address: 1252 Commerce Drive lkupilik@trihydro.com Company: Trihydro Corporation Arvada, CO 80002 ω telinquished by: 10 **Tony Kupilik** 9 State, Zip: WY, 82070 aramie.

TestAmerica Denver

4955 Yarrow Street

13

N - None
O - AsNa02
P - Na2045
Q - Na2045
Q - Na2523
R - Na2523
R - Na2523
V - WGAA
W - pH 4-5
Z - other (specify) **TestAmerica** Special Instructions/Note: ompany Months Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)

Return To Client Disposal By Lab Archive For Mont Special Instructions/QC Requirements: Preservation Codes G - Amchlor H - Ascorbic Acid A - HCL B - NaOH C - Zn Acetate D - Nitric Acid Page: Page 1 of 1 E - NaHSO4 F - MeOH I - Ice J - DI Water K-EDTA L-EDA Total Number of containers Date/Time: Aethod of Shipment Analysis Requested Cooler Temperature(s) "C and Other Remarks E-Mail: donna.rydberg@testamericainc.com Received by: Lab PM: Rydberg, Donna R SISESTOS Chain of Custody Record Field Filtered Sample (Yes or No) Type (wwwater, Sepold. (C=comp, Owwaster) (G=grab) (BT=Tissue, A=Att) (C=grab) Preservation Code: Matrix Company Radiological Sample 17252W0-L (307) 745-7474 J 9/6/17 (8) 1500 Bate/Time: 0201 0151 1155 8129117 0835 1005 1025 0945 230 0150 Sample 1105 140 10 DAY Date: Deison B Unknown RUPILI K TAT Requested (days): Due Date Requested: Sample Date Project #: 28017197 Date/Time: SOW#: LEVEL Skin Irritant Deliverable Requested: I, II, III, IV, Other (specify) Custody Seal No. コイント ーストレ Phone (303) 736-0100 Fax (303) 431-7171 Questa Pipeline - Lead and Asbesfos Flammable Possible Hazard Identification TestAmerica Denver A1182517 A982917 A1082917 Empty Kit Relinquished by: 11628 11628 C1828 L1628 L162 Custody Seals Intact: 4282917 KUPILIK nquished by. 38291 Sample Identification 82917 Client Information 1252 Commerce Drive tkupilik@trihydro.com Company: Trihydro Corporation Arvada, CO 80002 Non-Hazard 4955 Yarrow Street 10E) 80 elinquished by: Tony Kupilik State, Zip: WY, 82070 SE A8 AZ AY A aramie

N - None
O - Ashaoz
P - NazOds
Q - NazSO3
R - NazS203
S - H2SO4
T - TSP Dodecahydrate
U - Acetone
V - MCAA
W - pH 4-5
Z - other (specify) **TestAmerica** THE LEADER IN ENVIRONMENTAL TESTING Special Instructions/Note: Company Preservation Codes A - HCL
B - NaOH
C - Zn Acetate
C - Nitric Acid
E - NahSO4
F - MeOH
G - Amchlor
H - Ascorbic Acid Page 1 of 1 J - DI Water K - EDTA L - EDA Total Number of containers ethod of Shipment Analysis Requested Cooler Temperature(s) °C and Other Remarks Special Instructions/QC Requirements Lab PM:
Rydberg, Donna R
E-Mall:
donna.rydberg@testamericainc.com Received by: Q Chain of Custody Record Perform MS/MSD (Yes or No) Field Filtered Sample (Yes or No) A moan Preservation Code: Winwater, Smaothd, Onvestiefolf, Matrix Company Sample
Type
(C=comp,
G=grab) Radiological 17-252W0-L J (307) 745-7474 9/6/17 @ 1500 Date/Time. 1005 1025 1105 1640 230 1510 8/29/17 0835 2490 1155 0150 1140 Sample KUPILIK 10 DAY Date Poison B Unknown TAT Requested (days): Due Date Requested: Sample Date Project #: 28017197 SSOW#: Jate/Time: 2786 Skin Irritant Deliverable Requested: I, II, III, IV, Other (specify) Custody Seals Intact: Custody Seal No. Arvada, CO 80002 Phone (303) 736-0100 Fax (303) 431-7171 Questa Pipeline - Lead and Asbestos Non-Hazard Flammable Possible Hazard Identification **TestAmerica Denver** 11528 716280 582917 Empty Kit Relinquished by: T. KUPILIK 382917 282917 L1628 48291 15289 15288 78291 Sample Identification Client Information 1252 Commerce Drive tkupilik@trihydra.com Company: Trihydro Corporation 4955 Yarrow Street alinquished by: Client Contact: Tony Kupilik State, Zip: WY, 82070 O aramie.

i estAmerica Denver			TectAn	TectAmerica
4955 Yarrow Street Arvada, CO 80002 Phone (303) 736-0100 Eax (303) 431-7171	Chain of Cust	ain of Custody Record	THE LEADER IN ENVI	THE LEADER IN ENVIRONMENTAL TESTING
Client Information	Sampler: Ku Pi Li K	i erg, Donna R	Carrier Tracking No(s): COC No:	
Client Contact: Tony Kupilik	Phone (301)745-7474	E-Mail: donna.rydberg@testamericainc.com	Page: Page 1 of 1	
Company: Trihydro Corporation		Analysis Requested		
Address; 1252 Commerce Drive	Due Date Requested:		Cod	16
Oity: Laramie	TAT Requested (days):		B NaOH N C - Zn Acetate C	M - Hexane N - None O - AsNaO2
State, Zip: WY, 82070	10 047			P - Na204S Q - Na2SO3
Phone:	PO #:	(40	Poid	R - NaZSZO3 S - HZSO4 T - TSP Dodecahudrate
Email: tkupilik@trihydro.com	1-522 WO-1	S OF NO	I - Ice J - DI Water	U - Acetone V - MCAA
Project Name: Questa Pipeline - Lead and Asbestos	Project #: 28017197	10 58	K-EDIA L-EDA	w - pH 4-5 Z - other (specify)
Site:	ssow#.	y) as	oo to Offer	
Sample Identification	Sample Type Sample (C=comp.	Matrix (Waveted Serie) (1) Serie) (1) MSM miohed Serie) (1) MSM moohed Serie) (1)	redmuk leto	errosi con Masso.
Sample Identification	Preserva	X		Special instructions/Note:
A183017	8/34/7 0940 6	S S		
A283017	0111			
BA183017	1115			
13A283017	1120			
134383017	1125			
134483017	1130			
134583017	1140			
134683017	105111	→ — — — — — — — — — — — — — — — — — — —		
	/	1		
		1		
	,	1		
Possible Hazard Identification Non-Hazard Flammable Skin Irritant	Poison B Kunknown Radiological	Sample Disposal (A fee may be assess: Return To Client	Sample Disposal (A fee may be assessed if samples are retained longer than 1 month) Return To Client S Disposal By Lab Archive For Mon	month) Months
Deliverable Requested: I, II, III, IV, Other (specify)	L 2486 11	Special Instructions/QC Requirements:		
Empty Kit Relinquished by:	Date:	110 11		
Relinquished by TT KUPILIK Relinquished by	9/6/17 @ 1500	Company Received by Company Received by	Date/Time:	Company
the management of the state of	Paris Print a		Date Charles	Contract of the Contract of th
	Dater ime:	Company Received by:	Date time:	Company
Custody Seals Intact: Custody Seal No.:		Cooler Temperature(s) °C and Other Remarks.		

Content Information	l estAmerica Denver 4955 Yarrow Street Arvada, CO 80002 Phone (303) 736-0100 Fax (303) 431-7171	Chain of Cus	Chain of Custody Record		TestAmerica
Control Cont	Client Information	_	Lab PM: Rydberg, Donna R	Carrier Tracking No(s):	
Common teacher Comm	Client Contact: Tony Kupilik	745-747	E-Mail: donna.rydberg@testamericainc.com		1 of 1
Control Cont	Company: Trihydro Corporation		Analys	sis Requested	Job #;
Sample Harmifleation	Address: 1252 Commerce Drive	Due Date Requested:			000
1	Olly: Laramie	TAT Requested (days):			
Sample Identification Sample Date Samp	State, Zip: WY, 82070				
Control Cont	Phone:		(0		70
Sumple Martin Projective Lead and Atherities Storyer Sumple Date Time Sumple Martin Sumple Sumple Martin Sumple Sumple Martin Sumple Sumple Martin Sumple Martin Sumple Sumple Martin Sumple Sumple Martin Sumple	Email: (kupilik@trihydro.com	252W0			1-tce J-DI Water
Sample Identification Sample Date Sample Date Sample Date Sample Identification III	Project Name: Questa Pipeline - Lead and Asbestos				K-EDIA L-EDA
Sample Carpon Sample Carpon Sample Carpon C	Site:	SSOW#:	A) as		
1110 1110	Sample Identification	Sample	Matrix (Wayner, Strong) Strong, Ornerston, O		
1110 1110		X	X		
1110	٦	7 0940			
3	٢		×		
13		11151	X		
1130		1120	×		
11 40	W	1125	.×.		
1140	BL483017	1130	,×		
V. Other (specify)		01140	×		
Sample Disposal (A fee may be assessed if samples are retained longer than 1		-	×.×		
We Skin Irritant Poison B Unknown Radiological Sample Disposal (A fee may be assessed if samples are retained longer than 1 or Client Disposal By Lab Archive For Special Instructions/QC Requirements: Date/Ime: Date/Ime: Company Received by: Date/Ime: Date/Ime: Company Received by: Date/Ime: Date/Ime: Date/Ime: Company Received by: Date/Ime: Date		/	1		
Sample Disposal (A fee may be assessed if samples are retained longer than 1 retained lon		/	1		
Sample Disposal (Afree may be assessed if samples are retained longer than 17		7			
by: Date: Date: Time: Date: Time: Date: Time: Date: Time: Date/Time: Date	le l	Poison B Unknown		may be assessed if samples are re	etained longer than 1 month) Archive For Months
by: Date: Time: Method of Shipment: Obate/Time: Company Received by: Company Company Date/Time: Da	Deliverable Requested: 1, 11, 111, IV, Other (specify)	LEVEL 11	Special Instructions/QC Re		
Custody Seal No.: Company Received by: Conjer Temperature(s)*C and Other Remarks: Date/Time: Date	Empty Kit Relinquished by:		Time:	Method of Shipment:	
Date/Time: Company Received by: Date/Time: D	Reinquished by: Reinquished by:	170	A Receive	~	0515
Custody Seal No.:	Reinquished by:	Date/Time:		Date/Time:	Company
			Cooler Temperature(s) "C a	nd Other Remarks:	

	Sampler:	Lab PM:	Carrier Tracking No(s):	COC NO:
Client Information	RUPILIA	Rydberg, Donna R		
Client Contact: Tony Kupilik	(301) 145- 1474	E-Mail: donna.rydberg@testamericainc.com	uu	Page: Page 1 of 1
Company: Trihydro Corporation		Anal	Analysis Requested	Job #:
Address. 1252 Commerce Drive	Due Date Requested:			Pos
City. Laramie	TAT Requested (days):			B - NaOH N - None C - Zn Acetate O - AsNaO2
State, Zip: WY, 82070	10 DAY			
Phone:	PO#:	(c		G-Amchlor S-H2SO4 H-Ascorbic Acid T-TSP Dodecativitiate
Email: tkupilik@trihydro.com	1-252 WO-L	(oN		J - Di Water
Project Name: Questa Pipeline - Lead and Asbestos	Project #: 28017197	10 88		L-EDA
Site:	SSOW#:	A) as		of co Other:
Sample Identification	Sample Sample (Scomp.)	Matrix (Wowder, Specific Matrix D) Previous (Wooder, Specific Matrix D) Previous (AS)		Number Special Instructions/Note:
	X	ation Code:		
INST B3017	8/30/17 0910 G	S		
INSZB3017	1 5180	×		
VG183017		χ/γ		
VG283017	0630	X/X		
VG383017	0 840	×		
PW183017	1210			
PW283017	0751	, X		
PW 383017	1530	×		
PW483017	V 0240	ンメ		
	/	1		
	/ / /	\ \ \ \		
Possible Hazard Identification Non-Hazard Planmable Skin Irritant	Poison B Kunknown Radiological		essed if samples are re	stained longer than 1 month) Archive For Months
	LEYEL 11	Special Instructions/QC Requirements	Requirements:	
inquished by.	Date:	Time: 0 1	Method of Shipment:	
Reinquished by. T. Koシルル	9/6/17 @ 1500	J	Date/Time: /	17 09(0
Relinquished by:	Date/Time:	Company Received by:	Date/Time:	Company
Relinquished by:	Date/Time:	Company Received by:	Date/Time:	Company
Custody Seals Intact: Custody Seal No.:		Cooler Temperature(s) "C and Other Remarks	C and Other Remarks:	
A Yes A No				

Client: Trihydro Corporation Job Number: 280-100940-1

List Source: TestAmerica Denver


Login Number: 100940 List Number: 1

Creator: True, Joshua A

orditor. True, obstitut A		
Question	Answer	Comment
Radioactivity wasn't checked or is = background as measured by a survey meter.</td <td>N/A</td> <td></td>	N/A	
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	N/A	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	N/A	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	N/A	

APPENDIX C

BORROW AREA MAP



APPENDIX D

EXAMPLE FIELD AND HEALTH AND SAFETY FORMS

Pre-Fieldwork Safety-Readiness Review Form

For all field projects

	For all	field projects				
		Names and initials of required	participants:			
		1. BUL, BUM, or TL:				
Trihydro		2. Project Director:				
Irinyaro		 Project Manager: Field Supervisor: 				
CORPORATION		5. Safety Officer/Lead:				
Business unit name	:	o. Outerly Officer Ecoud.				
Client name	-	Names and initials of other p	articipants:			
Project name and number		Project-team members:				
Date review performed	:	2. Contractor(s):				
Scheduled project-start date	:	3. Subcontractor(s):				
Scheduled project-end date	:					
	Work-Related Hazards					
Work-Scope Tasks	(refer to the 3x5 Hazard-Assessment Triangle)					
Work-Scope Tasks	(roter to the exertable recomment rhangle)	Anticipated Ha	ızard-Mitigatioı	1 Measures		
	<u> </u>					
Pre-Fieldwork Safety-Readiness Review Checklist			Yes	No	N/A	CAN
1 Has the project team secured the necessary safe	ty and other work permits required to complete the p	roposed work?				
	prepared and/or updated, and have all project-team	•				
	e they prepared and/or updated their HASP and JSA					
Has the project team been reminded that JSAs not team, and marked up where appropriate before st	eed to be prepared by the project's subject-matter extering and during work each day?	perts, reviewed by all members of the project				
	is a plan to manage lone worker safety in place and	communicated with the project toom?				
		. ,				
	one coverage? [If not, request a phone booster from	Autumn Bainer.]				
7 Has a hand-safety evaluation been completed for	this project?					
8 Has each work space been evaluated (and docum	nented) for the possible presence of confined-space	work conditions?				
9 Have team membersincluding contractors and s	ubcontractorsreviewed and understand the project-	-site hazards and requirements?				
10 Do all project-team membersincluding contractor	rs and subcontractorsunderstand Stop Work Author	prity and the "Slow Down" approach?				
<u> </u>	ector, etc.) and emergency-response equipment bee					
+	m members familiar with the vehicle types and opera	tion?				
13 If a client site-specific orientation is required, have	e all team members completed the required training?					
14 Have SSE mentors been assigned and provided	with instructions for overseeing each SSE team men	nber?				
18 Has the project team been reminded that journey-management plans (JMPs) should be used during the project where appropriate? 19 Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? 20 Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? 21 Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated?						
Have topics been developed and assignments made for the daily project-safety meetings, including discussing potential daily- and task-specific hazards? Has the plan for performing and reporting observations, near misses, and incidents been communicated? Has the project team been reminded that journey-management plans (JMPs) should be used during the project where appropriate? Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated?						
Have topics been developed and assignments made for the daily project-safety meetings, including discussing potential daily- and task-specific hazards? Has the plan for performing and reporting observations, near misses, and incidents been communicated? Has the project team been reminded that journey-management plans (JMPs) should be used during the project where appropriate? Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated?						
Have topics been developed and assignments made for the daily project-safety meetings, including discussing potential daily- and task-specific hazards? Has the plan for performing and reporting observations, near misses, and incidents been communicated? Has the project team been reminded that journey-management plans (JMPs) should be used during the project where appropriate? Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated?						
hazards? Has the plan for performing and reporting observations, near misses, and incidents been communicated? Has the project team been reminded that journey-management plans (JMPs) should be used during the project where appropriate? Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated?						
hazards? Has the plan for performing and reporting observations, near misses, and incidents been communicated? B Has the project team been reminded that journey-management plans (JMPs) should be used during the project where appropriate? Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated?						
Has the plan for performing and reporting observations, near misses, and incidents been communicated? 18 Has the project team been reminded that journey-management plans (JMPs) should be used during the project where appropriate? 19 Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? 20 Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? 21 Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated? 22 Has the Trihydro Excavation, Drilling, and Utility-Locating Checklist been completed for each drilling/excavation project? 23 Have all amployees expection to express or perform drilling/excavation work completed the Trihydro "Subsurface Utility Location and Excavation Safety."						
Has the project team been reminded that journey-management plans (JMPs) should be used during the project where appropriate? Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated? Has the Trihydro Excavation, Drilling, and Utility-Locating Checklist been completed for each drilling/excavation project? Have all employees expecting to oversee or perform drilling/excavation work completed the Trihydro "Subsurface Utility Location and Excavation Safety"						
18 Has the project team been reminded that journey-management plans (JMPs) should be used during the project where appropriate? 19 Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? 20 Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? 21 Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated? 22 Has the Trihydro Excavation, Drilling, and Utility-Locating Checklist been completed for each drilling/excavation project? 23 Have all amployees expecting to express or perform drilling/excavation work completed the Trihydro "Subsurface Utility Location and Excavation Safety."						
19 Is a traffic-management plan needed for this project and has it been completed and communicated to the project team? 20 Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? 21 Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated? 22 Has the Trihydro Excavation, Drilling, and Utility-Locating Checklist been completed for each drilling/excavation project? 23 Have all employees expecting to oversee or perform drilling/excavation work completed the Trihydro "Subsurface Utility Location and Excavation Safety Best Practices" training session?						
Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated? Has the Trihydro Excavation, Drilling, and Utility-Locating Checklist been completed for each drilling/excavation project? Have all employees expecting to oversee or perform drilling/excavation work completed the Trihydro "Subsurface Utility Location and Excavation Safety Best Practices" training session?						
20 Have procedures for work in or near hazardous areas (e.g., trenches, confined spaces, active units) been communicated? 21 Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated? 22 Has the Trihydro Excavation, Drilling, and Utility-Locating Checklist been completed for each drilling/excavation project? 23 Have all employees expecting to oversee or perform drilling/excavation work completed the Trihydro "Subsurface Utility Location and Excavation Safety Best Practices" training session? 24 Have utility locates been assigned and/or performed in accordance with Trihydro and client procedures?						
21 Have procedures for work in or around equipment (e.g., lockout / tag out, swinging, rotating, backing) been communicated? 22 Has the Trihydro Excavation, Drilling, and Utility-Locating Checklist been completed for each drilling/excavation project? 23 Have all employees expecting to oversee or perform drilling/excavation work completed the Trihydro "Subsurface Utility Location and Excavation Safety Best Practices" training session?						
Have all employees expecting to oversee or perform drilling/excavation work completed the Trihydro "Subsurface Utility Location and Excavation Safety Best Practices" training session? Have utility locates been assigned and/or performed in accordance with Trihydro and client procedures? Is a plan in place for communicating, managing, and reporting changed conditions (e.g., hazards, weather, team roles)?						
	site-specific hazards and developed a plan(s) to elim	-				
	to be on site for the onboarding, kickoff, and initial s					
	k types, > one week duration, etc.)? If so, please inc be on site in the "Review / Non-CAN Item Comments					
	ed, qualified, selected, and approved by the BUL bas	sed on Trihydro and/or client-specific				
requirements?						
Is a safety audit with a Senior Manager planned for	or the early stages of all major field projects? If so,	please indicate the Senior Manager's name and				
	dit in the "Review / Non-CAN Item Comments" box b					
Eindings / Corrective Assign No. 4-4 (CAN) C	oru,		I .			[
Findings / Corrective-Action Needed (CAN) Summ	aı y		I_	_	_	1
CAN Item No.			Responsible	Target	Completed	
(i.e., 1 through 30 from the checklist above)	Description	of CAN Item	Person	Date	Date	Initials
	+					
			<u> </u>			
Review / Non-CAN Item Comments:						
					<u> </u>	
1						

Pre-Fieldwork Safety-Readiness Review Form

For all field projects

Instructions:

1. While using this form, attempts should be made to address or correct the items warranting Corrective Action Needed (CAN) at the time of the evaluation. If this is not practical, each CAN item / finding should be documented above, including assignment of an individual responsible for addressing the CAN item and a target completion date. Once all of the CAN items have been completed, the Project Manager should review them with the responsible TL, BUM, or BUL and secure sign-off initials that each CAN item has been addressed satisfactorily.

2. Copies of this form should be retained by the responsible TL, BUM, and/or BUL and submitted to the Trihydro H&S Team via e-mail HealthSafety@Trihydro.com or fax (307) 755-4959. Please contact the Trihydro H&S Team for help conducting pre-fieldwork safety-readiness reviews, or if you have questions, suggestions, or comments about the forms.

JOB SAFETY ANALYSIS



JSA Version Date: February 29, 2012							
Job Description: Driving							
Project: Questa		Site Location: Site wide					
Development Team Please include the team members employer and email if not employed by Trihydro Corporation:	Position/Title:				Primary Contact		
1. Pat Henricks	Geologist				(307) 760-9447		
2.							
3.							
Reviewed By Please include the reviewers employer and email if not employed by Trihydro Corporation:	Position				Review Date (MM/DD/YYYY)		
1. Todd Forry	Health and Safet	y Manager			10/25/2012		
2. Torrey Fox	Geologist	Geologist					
3.							
Personal Protective Equipment (PPE)	Needed:	eded:					
Eye and Face Protection	Body Protection		Fall	l Protection	on		
☐ Safety Glasses	☐ Fire Retardant (Coveralls		☐ Barriers/Guard Rails			
☐ Face Shield	☐ Poly-coated Tyv	vek Coveralls	☐ Safety Net				
☐ Chemical Goggles	☐ Chemical Resis	tant Coveralls	☐ Personal Fall Arrest System				
Head Protection	☐ Chemical Resis	tant Apron	Respiratory Protection				
☐ Hard Hat	☐ Reflective Safet	ty Vest	☐ Half-Face Air Purifying Respirator				
Hearing Protection	☐ Cooling Vest		☐ Full-Face Air Purifying Respira				
☐ Ear Plugs	☐ Long sleeved sl	hirt	☐ Chemical Cartridge				
☐ Ear Muffs	Biological Protect	ion	☐ Particulate Filter				
Hand Protection	☐ Snake Gaiters			Cartridge	/Filter Combo		
☐ Industrial Work Gloves	Sunscreen			Ammonia	Cartridge		
☐ Chemical Resistant Gloves							
☐ Laceration Resistant Gloves	Asbestos	Filter (P-100)					
Foot Protection	☐ Air Monitoring E	quipment			Air Purifying Respirator		
☐ Leather Boots		(PA	PR) (con	tact H&S dept.)			
☐ Steel-Toed Boots	_		Air Respirator (SAR)				
☐ Chemical Resistant Boots	☐ Level B (contact H&S dept.) (contact H&S dept.)						
Water Safety	Level A (contac	ct H&S dept.)			ained Breathing		
☐ Personal Flotation Device	Decontamination I	Decontamination Materials			Apparatus (SCBA) (contact H&S		
☐ Waders	☐ Equipment Dec	ontamination	dept.)				
	☐ Personnel Deco	ontamination		Other:			
☑ Other: First aid/vehicle kit		cones		Other:			

Revised January 2014 1 of 7

Routine or non- routine journey management plan (JMP) – check (all drivers)	×	X X	A. B.	Personal Injury (Gravity)	A.	Check the JMP before	
				Property damage or physical injury (Motion)	B.	proceeding to the vehicle. Assess if journey is needed due to weather conditions (e.g., snow, ice, rain, wind). Check before each vehicle trip around the site since work areas can be changed throughout the day.	
	x	X X	A.	Vehicle failure; Accident or injury (Gravity) (Motion) Personal Injury or accident;	A.	Fill out vehicle inspection form for any vehicles used for the day. DO NOT use vehicle until issues are addressed. • Clean mirrors and windows. Inspect the interior of the vehicle; including seat belts and gauges. • Remove any clutter or items that may affect your driving, visibility or pedal control. • Follow appropriate maintenance schedule for your vehicle. • Verify insurance card, registration, and inspection. • Refer to the owner/operator manual generally kept in the glove box. • Verify presence of spill kit, first aid kit, and fire extinguisher within inspection period GOAL: before entering your	

Revised January 2014 2 of 7

Job Steps	ŀ	lazaı	rd(s)		Potential Hazard(s)		Critical Action(s)	Responsible Person
Configure coating	26			X	A Porconal Injury Visibility		Adjust coating to a	
Configure seating and controls and lock doors (all drivers)				X	A. Personal Injury Visibility; poor driver ergonomics and/or poor driver control (Motion)	A.	Adjust seating to a comfortable position and so that you can easily reach the pedals and steering wheel. • Adjust all mirrors. • Wear seat belt. • If you haven't operated this vehicle before, become familiar with all the controls and where everything is located in the vehicle. • Look for blind spots in your viewing area. • Refer to the owner's manual if necessary.	
Starting vehicle (all drivers)				X	A. Unexpected vehicle movement; engine damage or failure (Motion)	A.	Before starting, ensure that the vehicle is in park and the parking brake is applied. • After starting, check all gauges for proper temperatures, pressures, etc.	
Pulling away from parked area (all drivers)		x		X	A. Collision with other vehicles, objects or persons (Gravity) (Motion)	A.	Check mirrors and over the shoulder before pulling away. • Vehicle should be situated so the first movement is forward, however if backing, either use a spotter or blow horn to warn others. • Proceed cautiously.	
Driving (all drivers)		x		X	A. Vehicle strikes; vehicle accidents; equipment damage (Gravity) (Motion) B. Collision with wildlife (Biological)	A.	Follow JMP applicable to your journey. Review driving JSA. Plan your route, review maps before leaving. Obey all laws of the land as well as site procedures.	

Revised January 2014 3 of 7

Job Steps	Hazard(s)	Potential Hazard(s)	Critical Action(s)	Responsible Person
Parking	X X	A. Pedestrian collision /	Follow posted speed limit. Be prepared to 'expect the unexpected'. You never know what someone else (or animals) might do. NEVER drive under the influence of drugs or alcohol. Follow posted signs at other locations. Never operate the vehicle if you are abnormally tired. Cell phone usage is prohibited while driving a vehicle, including hands free devices such as headset and speaker phones. Implement 'first move forward' by backing into locations upon arrival. Be observant of pedestrians (main field office area) and other traffic around you. Engage parking brake once vehicle is parked. Do not place equipment/supplies above mirror line of sight (i.e., inside cab and or truck bed). Pull off the road if necessary during bad weather. B. Scan the area for wildlife including dogs, cats, deer, cows, horses, elk, coyotes, fox's, badgers, and prairie dogs while traveling on site. Watch road sides for movement and pull vehicle to side of road if animal observed. Be particularly aware of animals present in roadway during dusk and morning.	
(all drivers)	X X	Property damage(Gravity)(Motion)	spots when available • Use signals before pulling from curb and during any change of lane or turn	

Revised January 2014 4 of 7

Job Steps	Н	Hazard(s)		Hazard(s)		s) Potential Hazard(s)		Critical Action(s)		Responsible Person
Post drive (all drivers)		x X		x	A.	Personal Injury / Property damage (Gravity)(Motion)	Α.	 Back into parking space when possible and safe Maintain a cushion of safety from fixed objects when parking Set parking brake if on incline; chock wheels if working on steep slopes Report vehicle problems to company representative or rental car agency. 		

Revised January 2014 5 of 7





As the Supervisor my signature below indicates that the requirements, conditions, and procedures listed above are in place and have been verified and reviewed with the affected personnel prior to the start of work.

Supervisor Name (print):	Signature	Date
Prior to work, I have read and understand the Pl also understand the job steps, potential hazards this JSA on site and identify daily variances and task site that contain pen-and-ink changes ("dirty	, and critical actions identified for employee tunderstand I can make pen and ink changes	task and hazard awareness. I agree to have s to meet those variances. JSAs used at the
Name (print):	Signature	Date

Revised January 2014 6 of 7

END OF DAY

REVISIONS TO JSA (Any tasks that were "dirtied up")

Date	Job Step #	REVISION	Does JS to be u perman	SA need pdated nently?	Responsible Person
	•		Yes	No	

Revised January 2014 7 of 7

DAILY TAILGATE SAFETY MEETING



NOTE: A new tailgate meeting must be conducted if conditions, location, or personnel change. _____ Time: ____ a.m. p.m. Location: _____(city, state) Date: _____ Client: _____ Project Name: _____ Current Objective/Description: **Commitment to Safety** I will protect myself for me, my family, Trihydro, clients, and contractors by watching for and mitigating risky behaviors, exercising stop-work authority to prevent incidents and injuries and by complying with Trihydro and client policies, procedures, and JSAs/JLAs I understand that safety is my personal responsibility and that working safely is a key component in providing quality work. 3. I will set an example for my fellow employees, contractors, clients, and family by working safely. I will drive defensively and "Safely for My Family," abiding by Trihydro and client policies and applicable laws and regulations. I will "slow down" appropriately to work at a pace that will allow me and others to complete each task efficiently and safely. I will hold myself accountable for my safety and the safety of those around me. I will think about the safety of me, my coworkers, contractors, and our clients before I conduct each task. * Stop Work Authority (SWA) – "Everyone has the authority and obligation to immediately stop all unsafe work." Identify High-Hazard Work: Hot Work Elevated/overhead work Boat / over-water operations Work involving equipment within 15' of active overhead electrical line or LOTO Excavations - any Demolition, removal of pole supporting an electric pipelines and buried structures **Confined Space Entry** Drilling - any **Associated and Identified Hazards:** ☐ Pinch points ☐ High-pressure processes ☐ Earthquake ☐ Abrasions, cuts, scrapes ☐ High-temperature processes ☐ Power tools ☐ Electrical ☐ High wind ☐ Pulled into ☐ Allergies (self & co-workers) ☐ Asbestos ☐ Equipment failure Laceration ☐ Radiation/X-ray ☐ Security ☐ Biological ☐ Ergonomic ☐ Lightning ☐ Buried utilities ☐ Excavations in area? Severe weather Loud noise ☐ Falling □ Scaffolds ☐ Burn hazards ☐ Machine guarding ☐ Fire/explosion ☐ Slips, trips, falls ☐ Chemical exposure ☐ Subsurface utilities ☐ Cold stress ☐ H₂S ☐ No locking/fixed blades ☐ Traffic ☐ Compressed gases ☐ Hand injury Overexertion □ Crane or lifting equipment Overhead utilities ☐ Water Heat stress □ Drilling in area? ☐ Pedestrian ☐ Heavy equipment Other: See it! Identify Current Objective Hazards: Assess Trihydro's 3 Most Assess Trihydro's 5 Most Other Hazards Serious Risks Frequent Risks Traffic/Heavy Equipment Hand Injuries Weather Hazardous Atmosphere Lifting Working at Heights **Utility Contact** Biological Hazards Chemical Exposure Slips, trips, falls

Daily Tailgate Safety Meeting Created: June 30, 2011

Personal Protective Equipme	ent (PPE):							
☐ Hard hat	☐ Arm sleeves	☐ Dust mask	Other special equipment:					
☐ Safety glasses	☐ High visibility vest	Respirator						
☐ Safety toed boots	☐ Rain gear	Cartridges/filters: ☐ VOC/H₂S esca	De					
☐ Ear plugs (as needed)	☐ Rubber boots	☐ H ₂ S monitor						
☐ Face shield	□ SCBA	☐ Bump test ☐ FRCs/Nomex						
☐ Fall protection	☐ Snake chaps	☐ Tyvek [®]						
☐ Gloves (as needed)	☐ Sunscreen (as needed)	☐ Insect repellant						
☐ Gloves (as fieeded)	Sunscieen (as needed)	*Do not apply DEET to FI	RCs* \square					
Before Beginning Work:								
☐ Sign in and out of process unit ☐] N/A	☐ Review the JSA ar	nd "dirty up" if necessary					
☐ HASP reviewed & acknowledged		Weather forecast: Wind Direction:	☐ Hot ☐ Cold ☐ Incle	ment				
☐ Locate the nearest evacuation poin	nt and a secondary location		wearing proper PPE					
☐ Identify the nearest fire extinguishe first aid kit, and Material Safety Dat		☐ Perform a "self che	eck" on each personal H ₂	S monitor				
☐ Identify CPR/AED/first aid certified		☐ Perform a Work-Si	te Self Assessment (WS	SA)				
☐ If lone worker, implement lone work	ker procedures		pard emergency flyer for ible location inside vehicle					
☐ Identify SSE, visitor(s), or guest(s)	□ N/A	☐ Barricade work zor	ne (as needed)					
☐ Determine and acquire necessary	permits	Review WorkCare Injury Accident Program card						
Permit required:		☐ PPE Action Levels (PID: 10ppm)						
Safe Vehicle Use:								
☐ Pre-inspection complete	☐ Mileage sheet fille	d out	out GOAL sticker in window					
☐ Seat belt	☐ No cell phones us	ed while driving	☐ Spotter used (if available)					
☐ Follow all speed and traffic rules	☐ Parked in a safe lo	ocation	☐ First move forward, backed in					
☐ Emergency brake used	☐ Orange cone used	i	☐ Load secured in vehicle					
☐ Keys left in vehicle	☐ Chock tires (if nee	ded)	☐ 3D-Driving (every 2 years)					
☐ Trailer Safety Inspection form	☐ Other:		Other:					
Site-Specific Comments:								
Positive Reinforcement (R+):								
Signatures								
Signatures: Meeting Conducted By: (designated project on-site safety responder) Company:								
Printed Name	Signature	Company	Attended Mid-Day Safety Focus	Is this worker new on-site?				
1.			☐ Yes ☐ No	☐ Yes ☐ No				
2.			☐ Yes ☐ No	☐ Yes ☐ No				
3.			☐ Yes ☐ No	☐ Yes ☐ No				
4.			☐ Yes ☐ No	☐ Yes ☐ No				
5.			☐ Yes ☐ No	☐ Yes ☐ No				
6.			☐ Yes ☐ No	☐ Yes ☐ No				
7.			☐ Yes ☐ No	☐ Yes ☐ No				
8.			☐ Yes ☐ No	☐ Yes ☐ No				
II.		(· — —					

JOURNEY MANAGEMENT PLAN



Date:	Project Number	er:			Driver:				
Destination:									
Departure Time:				Anticipated Arriva	I Time:				
Total Hours (not to exceed 1	6 hours):		=	Work Hrs	+	Driving Hrs_			
	Plan the journey and notify personnel at destination of your plans. Notify arrival contact if you will not arrive at scheduled time. Keep a copy of this plan with you. Trihydro's main phone number is 307-745-7474. Normal business hours are 8am-5pm, M-F.								
In case of an emergency or incident, contact the Health & Safety Response Team at (307) 755-4888.									
Purpose of Trip									
Hazards									
Pre-Trip Questions									
Is this trip necessary?						☐ Yes	□No		
Is there an alternative that do	oes not involve o	driving?				☐ Yes	☐ No		
If yes, by what means:									
Is someone else already goil	ng to the same o	destination?				☐ Yes	☐ No		
Do I have a map to my destination?									
Has the proper vehicle been	selected?					☐ Yes	☐ No		
Is the vehicle equipped with	emergency supp	olies?				☐ Yes	☐ No		
Do I have current driver train	ing for this trip?					☐ Yes	☐ No		
Am I well rested and alert for	the journey?					☐ Yes	☐ No		
Do I have effective means of	communication	s during my	journey?			☐ Yes	☐ No		
Has a pre-trip vehicle inspec	tion been compl	leted and do	cumented?			☐ Yes	☐ No		
Have road condition reports	been reviewed p	orior to the jo	ourney?			☐ Yes	☐ No		
Weather:	☐ Dry	☐ Windy	☐ Rain	☐ Snow	☐ Icy	☐ Fog	☐ Dust		
Road Conditions:	☐ Dirt Road	I Co	onstruction	☐ Paved	Road	☐ Mixed Cor	nditions		
Night Driving:	☐ Yes	☐ No		Is it essential?	☐ Yes	□No			
Vehicle:	☐ Fleet Veh	nicle	☐ Re	ntal Vehicle	☐ Per	sonal Vehicle			
Make*:	Model*:			Year*:		Color*:			
VIN* or Fleet Number:				License Pla	ite State/Nu	mber*:			
Condition:	☐ Satisfactory								
Vehicle Inspection Form Cor	npleted?		☐ Yes	☐ No					
Vehicle preventive maintena	nce up to date?		☐ Yes	☐ No					

When traveling to the site, contact your supervisor/project manager to confirm your safe arrival. On return journey, contact your supervisor/project manager when you depart from site and upon arrival back to start point to confirm your safe travels.

*For rental or personal vehicle, if available.

December 9, 2010 Page 1 of 2

For Overnight Sta	ys Hotel Name:	Telephone:					
	City:	State:					
Route Planned	(Auto route, train information, and/or flight information): Route/Information Attached Separately	☐ Map Attached Separately					
Unconventional T	raval						
Unconventional T							
☐ Helicopter	 Verify the following: Name is on the aircraft manifest Pilot performs safety briefing prior to takeoff Hats are not worn on flight line 	 Do not approach aircraft from the rear; approach from front quadrant or side Stay clear of tail rotor 					
☐ Private Aircraft	Verify the following:						
	 Name is on the aircraft manifest Pilot performs safety briefing prior to takeoff Hats are not worn on flight line 	 Do not approach aircraft from the rear; approach from front quadrant or side 					
□ Watercraft	Verify the following:						
	 Registration number is on the watercraft manifest Captain performs safety briefing prior to launch 	Personal flotation devices are available/wornNotify supervisor of vessel number					
☐ Other:							
Supervisor/PM App	oroval:	Date:					
Employee site arriv							
Employee site depa							
Employee home an							

December 9, 2010 Page 2 of 2