






R.T. Hicks Consultants, Ltd
 901 Rio Grande Blvd NW Suite F-142
 Albuquerque, NM 87104
 505-266-5004

USGS Topographic Map of Area Around the Pittsburgh Iron
 Lode and Pittsburgh Iron Lode No. 1

Plate 1

El Capitan Precious Metals, Inc.

October, 2014





R.T. Hicks Consultants, Ltd
 901 Rio Grande Blvd NW
 Suite F-142
 Albuquerque, NM 87104
 505-266-5004

USGS Topographic Map (with 2013 Aerial
 Underlay) of Proposed Work Area


Plate 2

El Capitan Precious Metals, Inc.

October, 2014



R.T. Hicks Consultants, Ltd 901 Rio Grande Blvd NW Suite F-142 Albuquerque, NM 87104 505-266-5004	Schematic Diagram Of Phase 1 Mining Area, Pittsburgh Iron Lode and Pittsburgh Iron Lode No. 1	Plate 2a
	El Capitan Precious Metals, Inc.	October, 2014




R.T. Hicks Consultants, Ltd
901 Rio Grande Blvd NW Suite F-142
Albuquerque, NM 87104
505-266-5004

Schematic Diagram Of Phase 2 Mining Area, Pittsburgh Iron Lode and Pittsburgh Iron Lode No. 1

El Capitan Precious Metals, Inc.

Plate 2b

October, 2014



R.T. Hicks Consultants, Ltd
 901 Rio Grande Blvd NW Suite F-142
 Albuquerque, NM 87104
 505-266-5004

Schematic Diagram Of Phase 3 Mining Area, Pittsburgh Iron
 Lode and Pittsburgh Iron Lode No. 1

El Capitan Precious Metals, Inc.

Plate 2c

October, 2014