







GENERAL NOTES:

1. STEEL PLATES AND SHAPES SHALL BE WEATHERING STEEL. WELD ALL JOINTS. CONSTRUCT THE BAT GATE TO ELIMINATE SURFACES ON WHICH MOISTURE OR DEBRIS CAN BE TRAPPED. ALL TUBULAR MEMBERS SHALL BE HERMETICALLY SEALED TO PREVENT THE INCURSION OF MOISTURE, EXCEPT AS OTHERWISE NOTED. ROUND OR CHAMFER ALL EXPOSED SHARP CORNERS AND EDGES.

2. DESTROY EXPOSED THREADS ON ALL BOLTS.

ABANDONED MINE LAND PROGRAM MINING AND MINERALS DIVISION ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

SCALE: AS SHOWN 045-026T, 045-132S, DRAWN BY: DATE:_{OCT. 12, 2006} 047-016T, & 047-038S REVISED:

BAT GATE DETAIL AT 48-INCH DIAMETER CSP

LAKE VALLEY MINE SAFEGUARD PROJECT - PHASE II FIGURE 36