



Appendix 1: Documentation of Indian Creek Culvert


USGS Lidar Point Cloud NM NorthCentral-B2 2016 13SDV335540 LAS 2018
Google Earth Imagery from June 2017
Photos from October 28, 2019







A photograph of a snowy landscape. In the foreground, there is a field of tall, dry, yellowish-brown grass partially covered in snow. A large, dark, corrugated metal culvert pipe is visible on the left side, partially buried in the snow. In the background, a red pickup truck is parked on a snow-covered path. The background is filled with a dense forest of evergreen trees, some of which are covered in snow. The sky is overcast and grey.


**Culvert E
(looking west)
42-inch**




Culvert D
(looking northwest)
36-inch








**Culvert C
(looking north)
30-inch**





A photograph of a snowy forest path. The path is covered in snow with visible tire tracks and leads into a dense forest of evergreen trees. The sky is a pale, overcast blue. The text "Culvert B (looking northwest) 30-inch" is overlaid in the center of the image.

Culvert B
(looking northwest)
30-inch



**Culvert A
(looking north)
36-inch**

