

year	PW77-1 (ac-ft/yr)	pit waterbody (ac-ft/yr)	OBS-63 <sup>a</sup> (ac-ft/yr)	PW79-2 (ac-ft/yr)	TOTAL PUMPING (ac-ft/yr)	pumping comments	Upper CHG diversion into open pit (ac-ft/yr)	RP diversions added to open pit (ac-ft/yr)	Guest House well diversions added to open pit (ac-ft/yr)	comments regarding water added to open pit
1980	0.00	0.00	5.17	67.82	72.99					
1981	0.00	0.00	13.12	75.48	88.60					
1982	0.00	0.00	70.60	41.13	111.73					
1983	0.00	0.00	39.39	71.78	111.17					
1984	85.51	0.00		0.00	85.51	dewatering for mining				
1985	153.90	0.00		0.00	153.90					
1986	175.20	0.00		0.00	175.20					
1987	3.07	0.00		0.00	3.07					
1988	0.00	0.00		0.00	0.00					
1989	0.00	0.00		0.00	0.00					
1990	0.00	0.00		0.00	0.00					
1991	0.00	0.00		0.00	0.00					
1992	0.00	0.00		0.00	0.00					
1993	39.54	0.00		0.00	39.54					
1994	2.14	0.00		0.00	2.14					
1995	7.04	0.00		0.00	7.04	water used for mine site reclamation				
1996	8.72	28.30		0.18	37.20					
1997	0.01	0.00		0.04	0.05					
1998	0.01	0.00		2.94	2.95					
1999	0.19	0.00		8.57	8.76		10.30			
2000	0.00	22.90		2.86	25.76	water removed from open pit due to RO treatment	0.00	0.00		
2001	0.00	22.90		1.41	24.31		0.00	0.00		
2002	0.00	35.10		0.82	35.92		0.00	0.00		
2003	0.00	0.00		1.13	1.13		0.00	0.00		
2004	0.01	0.00		0.04	0.05		0.00	0.00		
2005	0.00	0.00		1.13	1.13		0.00	0.00		
2006	0.00	0.00		1.12	1.12		0.00	0.00		
2007	0.00	0.00		1.15	1.15		0.00	0.00		
2008	0.00	0.00		0.99	0.99		0.00	2.85		1st pilot program
2009	0.01	0.00		0.00	0.01		0.00	4.01		
2010	0.00	0.00		0.40	0.40		0.00	0.00		
2011	0.00	0.00		1.44	1.44		0.00	0.00		
2012	0.00	0.00		2.97	2.97		0.00	2.76		
2013	0.00	0.00		0.00	0.00		0.01	3.03		
2014	0.00	0.00		0.82	0.82		0.00	3.16		
2015	0.00	0.00		2.37	2.37		0.79	4.06	0.34	Guest House well permitted
2016	0.00	0.00		0.24	0.24		0.15	1.04	5.62	
2017	0.00	0.00		0.19	0.19		1.73	1.92	7.20	
2018	0.00	0.00		0.00	0.00		1.54	5.38	0.00	
2019	0.00	2.13		0.45	2.58		20.15	6.16	0.00	
2020	0.01	1.00		0.13	1.14		0.52	2.06	0.00	
2021	0.00	4.00		0.04	4.04		5.24	1.33	0.00	
2022	0.00	7.27		0.64	7.91		0.07	1.64	0.00	Guest House well used only for Residue Pile Remediation