B.O.W. Mine Permit #: OT002MN Date of Inspection: March 21, 2024

OVERVIEW
Name of Operator: BOW Corporation Commodity: Garnet
INSPECTION DETAILS
Purpose of Inspection: Annual Weather Conditions Sunny and warm Lead Inspector: Samantha Rynas Present During Inspection: Ron Kellermueller Game and Fish, Carmen Rose MMD. Time On Silve & Beauti Resident & Touch 20 vice Beauti Mailing & Inspection.
Time: On-Site: 1 Permit Review: 1 Travel: 30mins Report Writing: 1 hr
TOTAL INSPECTION TIME: 3.5 hours
ENFORCEMENT
Action taken: Notice of Violation #: YES □ NO: ⊠ Cessation Order #: YES □ NO: ⊠
ACCESS NOTES:
Site was inspected with other OT county mines.
PERMIT UPDATE
None
INSPECTION NARRATIVE AND PHOTOS
Arrived on site around noon.
On the road walking up to the main site observed some disturbance/damage to a slope leading down into an arroyo.
1 Page

B.O.W. Mine Permit #: OT002MN Date of Inspection: March 21, 2024



FIGURE 2 FROM THE ROAD LOOKING DOWN THE DISTURBANCE



FIGURE 4 FROM MID-POINT DOWN THE SLOPE, LOOKING INTO THE ARROYO



FIGURE 3 LOOKING ACROSS DISTURBANCE ~20FT WIDE



FIGURE 1 LOOKING UP THE HILL

Santa Fe, New Mexico 87505 Telephone: (505) 476-3400

B.O.W. Mine Permit #: OT002MN Date of Inspection: March 21, 2024

Observed one of the previous boreholes along the road as well as a dill bit left behind in some rocks.



FIGURE 6 RED ARROW SHOWS BOREHOLE



FIGURE 5 DRILL BIT

Continued up the hill to the top of the road. Observed the "historic" un-plugged drill holes (2).






The road to the top looked freshly graded. No other observations of note.

3 | Page

B.O.W. Mine Permit #: OT002MN Date of Inspection: March 21, 2024

Map Overview:



ACTION ITEMS

Follow up with operator about slope disturbance. Review to determine possible release of site.

MAINTENANCE ITEMS

None

ENFORCEMENT ACTIONS TAKEN OR TO BE CONSIDERED

None

4 | Page

1220 St. Francis Dr.
Santa Fe, New Mexico 87505
Telephone: (505) 476-3400

B.O.W. Mine Permit #: OT002MN Date of Inspection: March 21, 2024

INSPECTOR'S SIGNATURE: Samantha Rynas DATE: 3/29/2024

5 | Page

1220 St. Francis Dr. Santa Fe, New Mexico 87505 Telephone: (505) 476-3400